

OCTOBER 3, 2019

DIAMANTE, JULIUS
#709 TELLO ST. TONDO MANILA
0906-3492647
252-6069

Sir/Ma'am;

Please find below the quotation for repair of the following unit.

MODEL: KSM-IW10-4F1M

SJR: 0586074

Parts	Amount
Outdoor Sensor	220.00
System Reprocess	3,500.00
Pull Out Delivery	<u>500.00</u>
Total:	4,220.00

Total Estimated Charge:

P 4,220.00

Note:

1. *Replacement Of Outdoor Sensor.*
2. Final charges will be based on actual repair of unit.
3. Repaired units are guaranteed for a period of 90 days (*Parts & Labor*) from date of unit acceptance and for the same encountered defects.
4. If you need assistance don't hesitate to call the under signed (*Angel Arlan De Torres*) at **852-6868 or 0917-806-0920.**
5. Once quotation was confirmed 50% downpayment needs to be deposit before proceeding for repair.
6. The remaining balance of 50% downpayment is to be paid to Kolin technician before install the unit.
7. *Initial Quotation.*


Prepared by:


ANGEL ARLAN DE TORRES
SHOP ASSISTANT

Noted by:

JOEL CORIA
SHOP FOREMAN

Conforme:



SIGNATURE OVER PRINTED NAME

Head Office:

1854 Sta. Rita St., Guadalupe Nuevo, Makati City

www.kolinphil.com.ph

Tel.: (632) 851-2711, 12 or 15

Fax: (632) 852-2170 / Sales Dept. Fax: (632) 852-4791

Kolin Plant:

Blk 3 Lt 5 Main Drive, FCIE Compound, Brgy,

Langkaan I, Dasmariñas, Cavite

Tel.: (632) 749-2118

Fax: (046) 402-0793