

## Go, Jonathan

40 Wack Wack Rd., Wack Wack Village, Brgy. Wack- wack, MANDALUYONG CITY, Metro Manila 0917-5843186 / 0917-3270066

Maam/Sir;

Please find below the estimated quotation for repair of the following unit.

SJR#HO-00259031 MODEL: KSM-25CB1INV

> Amount / QTY Description For replacement fan motor indoor 2,750.00 1,100.00 For replacement blower wheel For replacement rubber bushing 330.00 Labor repair and cleaning 2,400.00 6,580.00 Total

**Total Estimated Charge:** 

6,580.00

Net: \$5,500

## Note:

- 1. For replacement of fan motor indoor, blower wheel, rubber bushing and for cleaning
- 2. Final charges will be based on actual repair of unit.
- 3. Repaired units are guarnateed for a period of 90 days (Parts & Labor) from date of unit acceptance and for the same encountered defects.
- 4. If you need assistance don't hesitate to call the under signed at 8852-6868 & 0917-8118982.

Prepared by:

Rechilla Miole

Field Service Monitoring

Noted by:

FOR KENNETH B. ZAMORA

Supervisor - Field Service

SIGNATURE OVER PRINTED NAME

Conforme:

Kolin Philippines Int'l., Inc.

Plant and Head Office: Blk 3 Lt 5 Main Drive, FCIE Compound, Brgy. Langkaan I, Dasmariñas, Cavite Tel.: (632) 8749-2118 Fax (046) 402-0793 www.kolinphil.com.ph / kolinphilippines Operation Office: 1854 Sta. Rita St., Guadalupe Nuevo, Makati City Tel.: (632) 8851-2711, 12 or 15

Fax: (632) 8852-2170 Sales Dept. Fax: (632) 8852-4791

