



10-Jun-2024

HARDWORKERS MANPOWER SERVICES

ZEN TOWER, 1161 NATIVIDAD LOPEZ (LANDMARK INFRONT OF SM MANILA) BRGY. ERMITA, MANILA CITY
TEL: 0917-8719889 / 0927-2473312

Sir/ Madam,

This is to bill you on the service job done to your unit for the month of NOVEMBER 2023.
Details of the charges are stated below and a copy of the Service Job Report is attached for your references:


DATE ATTENDED	SJR #	QUANTITY/MODEL	SERVICE JOB DONE	AMOUNT
20-Nov-23	HO-00178915	(1) KSM-150B1E	DISMANTLING	2,500.00
20-Nov-23	HO-00178917	(1) KSM-150B1E	LEAK TEST	1,800.00
TOTAL AMOUNT DUE				P 4,300.00

For any clarifications please feel free to call the Undersigned at the telephone number **8852-6473**


Note: If check payment, please prepare check payable to **Kolin Philippines International Inc.**
Account #: BDO - KALAYAAN 011808000428

Note: In case thru Bank Deposit under BDO Account, kindly indicate SJR# for your Bank Reference in the deposit slip and Fax to **(632) 8852-6473** or E-mail to: **kmi_asst@kolinphil.com.ph**

Prepared by:


Janelle S. Lim
KMI - Assistant

Noted by:


Mari N. Flores
KMI - Supervisor

Received by:

Signature over printed name

 **Kolin Philippines Int'l., Inc.**

Plant and Head Office:
Blk 3 Lt 5 Main Drive, FCIE Compound,
Brgy. Langkaan I, Dasmariñas, Cavite
Tel.: (632) 8749-2118
Fax (046) 402-0793
www.kolinphil.com.ph / kolinphilippines

Operation Office:
1854 Sta. Rita St, Guadalupe Nuevo,
Makati City
Tel.: (632) 8851-2711, 12 or 15
Fax: (632) 8852-2170
Sales Dept. Fax: (632) 8852-4791





SERVICE JOB REPORT

No. _____
Previous S.J.R. No. _____

HO-00178915

HC-00378696

[illegible]

K Kolin Philippines Int'l., Inc.

1854 Sta. Rita St., Guadalupe Nuevo, Makati City
Tel. No.: 8852-6868 / Mobile: 0917-811-8982 / Email: service@kolinphil.com.ph
Website: www.kolinphil.com.ph

TPWR 3611

SERVICE JOB REPORT

2

Customer		Hardworkers Manpower Services		Date		11-20-2023	
Address		Zen Tower, 1181 Natividad Lopez (Landmark Infront of SM Manila), Brgy. Ermita		Start Time		01:42 pm	
MANILA CITY, Metro Manila...				End Time		01:44 pm	
Telephone No.		Mobile No.		0917-8719889 / 0927-2473311		Delayed by	
Contact Person		Sammy		Mobile No.		0917-8719889	
Warranty Code		Tel. No.		Warranty Type		C	
Model		Room Size		Job Class		TS LVL 1	
S/N (I)		S/N (O)		Call Origin		IO	
Dealer		DOP		Job Type		FD	
Installer		Complaint		Permit? ☐ Parking? ☒ Appointment? ☐ O.R.? ☐ Ladder? ☐		Notes	
Location		Before		After		VILLAFUERTE Existing copper tube 1/4x1/2 3 wires Customer request asap for leak test	
Mode Setting (Cool)		No. of Visit		1st Action		Tentative Sched	
WAC Setting Temp(16°C-RE)/(10/12-ME)		Findings		11/27/2019		11/24/2023	
SAC/PAC Setting Temp (17°)		400 PSI					
Discharge Temperature (High)							
Intake Temperature (High)							
Ampere							
Wattage (Inverter)							
Voltage							
SAC/PAC Pressure (PSI)							
Part Code		Description		Qty		Unit Price	
		Union Valve 1/4		2pc			
		1/2		2pc			
		Access valve		1pc			
		Silver Pool		1pc			
		Nitrogen					
SR No.		33262		Labor		1,800	
Repair Done		Leak-Testing of Copper tubing		Handling			
Repair Code		400psi		Others			
Date Attended		Nov. 22 - 2023		Total		1,800	
Time Attended		10:15		Amount Paid			
Time Finished		11:30		Balance		1,800	
This serves as temporary receipt when properly filled up by authorized representative.		Check No.		Bank / Branch		for collection	
Served by: Gerry Munday, Neil Villafuerte		By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.					
Lopez		I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.					
BAILERA		Created by:		Conformed by:			
CEMILLO		RECHILLA					
Technician(s)		CSR		Customer		(Signature over printed name)	