

Kolin Philippines Int'l., Inc.


1854 Sta. Rita St., Guadalupe Nuevo, Makati City
Tel. No.: 8852-6868 / Mobile: 0917-811-8982 / Email: service@kolinphil.com.ph
Website: www.kolinphil.com.ph    

TPWR 34141

SERVICE JOB REPORT

HO-00167264 (3)

No.
Previous SJR No.

| | | | | | | | | | | | |
|--|--|--|---------------------------------|--|---------------|---|---|----------|-------|---|--|
| Customer | Panpisco Office | | | | Date | 08-15-2023 | | | | | |
| Address | 246 Escolta St., Binondo, MANILA CITY, Metro Manila | | | | Start Time | 05:49 pm | | | | | |
| | | | | | End Time | 05:53 pm | | | | | |
| Telephone No. | 8242-8765 | Mobile No. | 0917-8921464 | | Relayed by | Bryan Dy | | | | | |
| Contact Person | Dante Chua/ Bryan Dy | Mobile No. | 0917-8921464 | Tel. No. | 8242-8765 | Warranty Type | C | | | | |
| Warranty Code | | | | Room Size | | | Job Class | TS | LVL | 2 | |
| Model | KSM-ZOMB1INV | | | Call Origin | IO | | Job Type | FD | | | |
| S/N (I) | 10891304-10597 | | S/N (O) | | | Permit? <input type="checkbox"/> Parking? <input checked="" type="checkbox"/> Appointment? <input type="checkbox"/> | O.R.? <input type="checkbox"/> Ladder? <input type="checkbox"/> | | | | |
| Dealer | | | DOP | 11/28/2019 | | Notes -BRING NITRO (FOR LEAK TEST) -BRING FREON, EVAPORATOR (painted), ONSULMABLE COPPER TUBE, MAPP GAS, SILVER ROD, VACUUM & ALL OTHER POSS. PRPTS *Last Visit - HO-00115986, July 6, 2022 - recharged freon | | | | | |
| Installer | | | Complaint | EC Error Code | | | | | | | |
| Location | | | Before | After | | | | | | | |
| Mode Setting (Cool) | Cool | | 601 | No. of Visit | 1st action | Tentative Sched | 08/17/2023 | | | | |
| WAC Setting Temp(16°C-RE)/(10/12-ME) | | | Findings | | | | | | | | |
| SAC/PAC Setting Temp (17°) | 17° | | 17° | Error EC As per Customer, Undercharge | | | | | | | |
| Discharge Temperature (High) | 20.1 | | 14.1 | of Freon possible leak | | | | | | | |
| Intake Temperature (High) | 27.6 | | 25.2 | | | | | | | | |
| Ampere | 5.6 | | 9.5 | Recommendation | | | | | | | |
| Wattage (Inverter) | | | For observation. If the problem | | | | | | | | |
| Voltage | 235 | | 195 | occur again Recommended for pull-out | | | | | | | |
| SAC/PAC Pressure (PSI) | 90 | | 100 | pressurize Copper Pipe. | | | | | | | |
| Part Code | | | Description | Qty | Unit Price | Amount | | | | | |
| | | | Freon 110A (F) | 1 | | | | | | | |
| <p>CLEARED 8/19/2023 DATE</p> | | | | | | | | | | | |
| SR No. | | | | | | | | Labor | 2,500 | | |
| Repair Done | Leak Test Evaporator, indoor fittings & outdoor fittings but no leak found. Re-charged | | | | | | | Handling | | | |
| Repair Code | Freon for observation | | | | | | | Others | | | |
| Date Attended | August 17, 2023 | | Date Finished | August 17, 2023 | | Amount Paid | ₱ 2,500.00 | | | | |
| Time Attended | 1:20 pm | | Time Finished | 2:30 pm | | Balance | For Collection c/wf | | | | |
| This serves as temporary receipt when properly filled up by authorized representative. | | | | Check No. | Bank / Branch | | | | | | |
| Serviced by: | | By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations. | | | | | | | | | |
| Fernando Lopez, Kevin Senar | | I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition. | | | | | | | | | |
| Michael Arjay | | Created by: ALVIN DE RIVERA | | Conformed by: Gustav /  | | | | | | | |
| Technician(s) | | CSR | | Customer (Signature over printed name) B-17-23 | | | | | | | |