



FOR : MR. OLIVER M. FILOTEO
 VICE PRESIDENT – FINANCE / HRA
FROM : SERVICE DEPARTMENT
REF. CODE : SVC-000-19-B-091
SUBJECT : STANDARD LABOR FEE & ASC LABOR SUBSIDY
DATE : DECEMBER 16, 2019
CC : SERVICE ACCOUNTING / AIS / ENGR. K. ZAMORA / ENGR. J. MAURICIO / ENGR. N. CORTEZ
 DCO / BOC / BOA / PRODUCT COMPLIANCE OFFICE

Subject : To update standard labor fee and ASC labor subsidy for warranty repair, general cleaning and installation job.

Effectivity : February 01, 2020 and shall be effective until revoked or superseded

	REPAIR CODE	Labor Fee	Rebate Regular ASC	Preferred ASC
Refrigerators / Chillers / Chest Freezers				
1. Check up (function & performance, visual check)	REF01	450.00	350.00	350.00
2. Minor Repair (thermostat)	REF02	1,000.00	600.00	650.00
3. Major Repair (Door gasket, fan motor, defrost heater&timer, thermodisk)	REF03	1,500.00	1,000.00	1,100.00
4. System Reprocess				
4.1 5cu.ft. below	REF04	1,500.00	1,000.00	1,100.00
4.2 5cu.ft. above	REF05	1,800.00	1,100.00	1,200.00
Window Type				
1. Check up (function & performance, visual check)	WAC01	450.00	350.00	350.00
2. General Cleaning (unit inspection, pressure washing, clean filter & drain)	WAC02	800.00	470.00	470.00
2.1 GC + Minor repair	WAC03	1,250.00	740.00	750.00
2.2 GC + Major repair	WAC04	1,350.00	840.00	850.00
3. Minor Repair	WAC06	900.00	540.00	570.00
Minor adjustment/Replacement of filter net, louver, front panel, front case, capacitor, sensor, OLP, compressor wire, swing motor & display board				
4. Major Repair	WAC07	1,100.00	740.00	770.00
With parts replacement not included in minor repair				
Re-bearing of fan motor				
5. System Reprocessing				
System leak, compressor / evaporator / condenser replacement				
5.1 0.6 - 1.5hp	WAC08	2,300.00	1,300.00	1,300.00
5.2 2.0 - 2.5hp	WAC09	2,300.00	1,300.00	1,300.00
5.3 System Reprocess + GC	WAC05	2,600.00	n/a	n/a
6. Installation	WAC10	900.00	n/a	n/a
Wall Mounted Split Type				
1. Check up (function & performance, visual check)	SAC01	450.00	350.00	350.00



 12/16/19



 12/16/19

2. General Cleaning (unit inspection, pressure washing, clean filter & drain)				
2.1	Single Indoor Unit (1 pair)	SAC02	1,500.00	900.00 900.00
2.2	Indoor unit or Outdoor unit	SAC03	750.00	n/a n/a
2.3	Multi-Split (2 indoor units)	SAC04	2,000.00	1,200.00 1,200.00
2.4	w/ pump down	SAC05	2,500.00	n/a n/a
2.5	GC + Minor repair	SAC06	2,100.00	1,300.00 1,350.00
2.6	GC + Major repair	SAC07	2,400.00	1,450.00 1,500.00
3. Minor Repair				
	Minor adjustment/Replacement of filter net, louver, front panel, front case, capacitor, sensor, OLP, compressor wire, swing motor & display board	SAC10	1,250.00	800.00 900.00
4. Major Repair				
	With parts replacement not included in minor repair	SAC11	1,800.00	1,100.00 1,200.00
	Leak test, freon charge, repair drain			
5. Freon Charging (Flush out & recharge refrigerant)				
5.1	1.0 - 3.0hp (non-inverter & inverter)	SAC12	2,500.00	n/a n/a
6. System Reprocessing				
	System leak, compressor / evaporator / condenser replacement			
Non-Inverter				
6.1	1.0 - 2.0hp	SAC13	3,000.00	2,000.00 2,000.00
6.2	2.5 - 3.0hp	SAC14	3,000.00	2,000.00 2,000.00
6.3	System Reprocess + GC (1.0hp-3.0hp)	SAC08	3,750.00	n/a n/a
Inverter				
6.4	1.0 - 2.0hp	SAC15	3,500.00	2,200.00 2,200.00
6.5	2.5 - 3.0hp	SAC16	3,500.00	2,200.00 2,200.00
6.6	System Reprocess + GC (1.0hp-3.0hp)	SAC09	4,250.00	n/a n/a
7. Installation (includes 10ft. copper tube, control wires, breaker, ordinary bracket)				
7.1	Not covered by Promo	SAC17	7,000.00	n/a n/a
7.2	Under Promo	SAC18	7,000.00	2,000.00 2,000.00
7.3	Mounting of IDU & ODU (will use materials of old unit)	SAC19	4,000.00	n/a n/a
7.4	Dismantle & relocate IDU	SAC20	3,300.00	n/a n/a
7.5	Dismantle & relocate ODU	SAC22	4,300.00	n/a n/a

Floor Mounted Split Type

1. Check up (function & performance, visual check)				
		FAC01	600.00	400.00 400.00
2. General Cleaning (unit inspection, pressure washing, clean filter & drain)				
2.1	Indoor unit or Outdoor unit	FAC02	2,000.00	n/a n/a
2.2	w/ pump down	FAC03	1,000.00	n/a n/a
2.3	GC + Minor repair	FAC04	3,500.00	n/a n/a
2.4	GC + Major repair	FAC05	2,800.00	n/a n/a
		FAC06	3,200.00	n/a n/a
3. Minor Repair				
	Minor adjustment/Replacement of filter net, louver, front panel, front case, capacitor, sensor, OLP, compressor wire, swing motor & display board	FAC09	1,500.00	1,000.00 1,100.00
4. Major Repair				
	With parts replacement not included in minor repair	FAC10	2,300.00	1,300.00 1,400.00
	Leak test, freon charge, repair drain			
5. Freon Recharging (Flush out & recharge refrigerant)				
5.1	3.0 - 5.0 tonner (non-inverter & inverter)	FAC11	3,000.00	n/a n/a
6. System Reprocessing				
	System leak, compressor / evaporator / condenser replacement			

 12/16/14



Non-Inverter				
6.1	3.0 tonner	FAC12	3,500.00	2,200.00
6.2	5.0 tonner	FAC13	3,500.00	2,200.00
6.3	System Reprocess + GC (3.0tr-5.0tr)	FAC07	4,500.00	n/a

Inverter				
6.3	3.0 tonner	FAC14	4,000.00	2,400.00
6.4	4.5 - 5 tonner	FAC15	4,000.00	2,400.00
6.5	System Reprocess + GC (3.0tr-5.0tr)	FAC08	5,000.00	n/a

7. Installation (1st 10ft. copper tube, control wires, indoor bracket, breaker)

7.1	3.0 tonner	FAC16	10,000.00	n/a
7.2	4.5 - 5 tonner	FAC17	11,000.00	n/a
7.3	Mounting of IDU & ODU (will use materials of old unit)	FAC18	6,000.00	n/a
7.4	Dismantle & relocate IDU (2.5tr - 5.0tr)	FAC19	4,500.00	n/a
7.5	Dismantle & relocate ODU (2.5tr - 3.0tr)	FAC20	5,500.00	n/a
7.6	Dismantle & relocate ODU (4.5tr - 5.0tr)	FAC22	6,000.00	n/a

Floor Ceiling / Ceiling Cassette

1.	Check up (function & performance, visual check)	CCA01	600.00	400.00
2.	General Cleaning (unit inspection, pressure washing, clean filter & drain)	CCA02	2,800.00	n/a
2.1	Indoor unit or Outdoor unit	CCA03	1,400.00	n/a
2.2	w/ pump down	CCA04	4,500.00	n/a
2.3	GC + Minor repair	CCA05	3,700.00	n/a
2.4	GC + Major repair	CCA06	4,300.00	n/a

3.	Minor Repair	CCA09	1,800.00	1,100.00
----	--------------	-------	----------	----------

Minor adjustment/Replacement of filter net, louver, front panel, front case, capacitor, sensor, OLP, compressor wire, swing motor & display board

4.	Major Repair	CCA10	3,000.00	1,700.00
----	--------------	-------	----------	----------

With parts replacement **not included** in minor repair
Leak test, freon charge, repair drain

5.	Freon Recharging (Flush out & recharge refrigerant)	CCA11	3,000.00	n/a
5.1	2.5 - 5.0 tonner (non-inverter & inverter)			n/a


6. System Reprocessing
System leak, compressor / evaporator / condenser replacement


Non-Inverter				
6.1	3.0 tonner	CCA12	3,500.00	2,200.00
6.2	5 tonner	CCA13	3,500.00	2,200.00
6.3	System Reprocess + GC	CCA07	4,900.00	n/a

Inverter				
6.3	2.0 - 3.0 tonner	CCA14	4,000.00	2,400.00
6.4	5 tonner	CCA15	4,000.00	2,400.00
6.5	System Reprocess + GC	CCA08	5,400.00	n/a


7. Installation (1st 10ft. copper tube, control wires, breaker)


7.1	2.5 tonner	CCA16	11,000.00	n/a
7.2	3.0 tonner	CCA17	12,000.00	n/a
7.3	4.0 - 5.0 tonner	CCA18	13,000.00	n/a
7.4	Mounting of IDU & ODU (will use materials of old unit)	CCA19	7,000.00	n/a
7.5	Dismantle & relocate IDU (2.5tr - 5.0tr)	CCA20	5,300.00	n/a
7.6	Dismantle & relocate ODU (2.5tr - 3.0tr)	CCA21	6,000.00	n/a

 12/16/19



7.7 Dismantle & relocate ODU (4.5tr – 5.0tr)	CCA22	7,000.00	n/a	n/a
Flexmatch Inverter				
1. Check up (function & performance, visual check)	KFS01	600.00	400.00	400.00
2. General Cleaning (unit inspection, pressure washing, clean filter & drain)				
2.1 1st Pair	KFS02	1,500.00	n/a	n/a
2.2 Succeeding Indoor Units	KFS03	1,000.00	n/a	n/a
2.3 w/ pump down	KFS04	3,000.00	n/a	n/a
2.4 GC + Minor repair (1 st pair)	KFS05	2,200.00	n/a	n/a
2.5 GC + Major repair (1 st pair)	KFS06	2,400.00	n/a	n/a
2.6 GC + Minor repair (succeeding IDU)	KFS07	1,600.00	n/a	n/a
2.7 GC + Major repair (succeeding IDU)	KFS08	1,900.00	n/a	n/a
3. Minor Repair	KFS10	1,300.00	800.00	900.00
Minor adjustment/Replacement of filter net, louver, front panel, front case, capacitor, sensor, OLP, compressor wire, swing motor & display board				
4. Major Repair	KFS11	1,800.00	1,100.00	1,200.00
With parts replacement not included in minor repair				
Leak test, freon charge, repair drain				
5. Freon Recharging (Flush out & recharge refrigerant)	KFS12	3,500.00	n/a	n/a
6. System Reprocessing				
System leak, compressor / evaporator / condenser replacement				
6.1 KFS-20DINV / KFS-35DINV / KFS-20DAEM / KFS-30DAEM	KFS13	4,000.00	n/a	n/a
6.2 KFS-45DINV / KFS-55DINV / KFS-40DAEM / KFS-50DAEM	KFS14	4,500.00	n/a	n/a
6.3 System Reprocess + GC	KFS09	5,250.00	n/a	n/a
7. Installation (includes labor, breaker & ordinary bracket)				
7.1 1st Pair	KFS15	7,000.00	n/a	n/a
7.2 Succeeding Indoor Unit	KFS16	2,000.00	n/a	n/a
7.3 Mounting of IDU & ODU (will use materials of old unit)	KFS17	4,000.00	n/a	n/a
Air Curtain				
1. Check up (function & performance, visual check)	KAC01	400.00	n/a	n/a
2. Repair/Replace Parts	KAC02	800.00	n/a	n/a
3. Installation	KAC03	1,000.00	n/a	n/a
Small Appliance (Dehumidifier, Water Dispenser, Air Purifier, Heater)				
1. Check up (function & performance, visual check)	KSM01	400.00	n/a	n/a
2. Repair/Replace Parts	KSM02	800.00	n/a	n/a
3. System Reprocess	KSM03	1,500.00	n/a	n/a
LED TV				
1. Check up (function & performance, visual check)	KLE01	400.00	n/a	n/a
2. Repair/Replace Parts	KLE02	1,000.00	n/a	n/a
Others				
1. Survey				
1.1 Split-Type/Floor/Ceiling Mounted	SUR01	500.00	n/a	n/a
2. Scaffolding Fee				

 12/16/17



2.1 Mobilization	SCF01	1,500.00	n/a	n/a
3. Start Up / Commisioning (per unit)				
3.1 Wall Mounted / Floor / Ceiling Type / Ceiling Cassette	STU01	2,500.00	n/a	n/a
3.2 Flex Match	STU02	3,000.00	n/a	n/a
4. Dismantling Fee				
4.1 1.0-3.0hp (wall mounted split-type – 1pair)	DIS01	2,500.00	n/a	n/a
4.2 2.5-5.0 tonner (floor mounted – 1 pair)	DIS02	3,000.00	n/a	n/a
4.3 2.0-5.0 tonner (floor ceiling / ceiling cassette – 1pair)	DIS03	3,500.00	n/a	n/a
4.4 Window Type		500.00	n/a	n/a
5. Mobilization				
5.1 Pull-out and delivery				
5.1.1 within city limits	HND02	500.00	n/a	n/a
5.1.2 outside city limits (1-25 kms)	HND06	700.00	n/a	n/a
5.1.3 outside city limits (25 kms up)	HND07	800.00	n/a	n/a
5.2 Field Servicing				
5.2.1 within city limits	n/a	n/a	n/a	n/a
5.2.2 outside city limits (1-25 kms)	HND06	700.00	n/a	n/a
5.2.3 outside city limits (25 kms up)	HND07	800.00	n/a	n/a
5.3 Deliver Remote Control	DEL05	150.00	n/a	n/a
6. Fabrication of Bracket				
6.1 Fabricate Bracket (IDU) – Ceiling Type	FAB01	1,500.00	n/a	n/a
6.2 Fabricate Bracket (ODU) – Floor Type	FAB02	2,500.00	n/a	n/a
6.3 Fabricate Bracket (ODU) – Wall Type	FAB03	5,000.00	n/a	n/a
6.4 Fabricate Bracket (ODU) – Catwalk Type	FAB04	6,500.00	n/a	n/a
6.5 Redesign Bracket (ODU)	FAB05	1,500.00	n/a	n/a
6. Chipping works for,copper pipe line / lay-out (per meter)		500.00	n/a	n/a

Guidelines

1. Paid survey fee is deductible upon installation of unit
2. Paid check-up fee is deductible to succeeding repair;
 - 2.1 Succeeding repair occurs within three (3) months from check-up fee payment date
 - 2.2 Customer unit is for second (2nd) action of parts replacement

Prepared by:

Mr. Alvin C. de Rivera
Assistant Service Manager

Approved by:

Mr. Oliver M. Filoteo
Vice President - Finance / HRA