

**BRIGHTON LAND INC.**

DON P. REYES AVE., (LANDMARK: VICTORIA HOMES ELEMENTARY SCHOOL)

TUNASAN, MUNTINLUPA CITY

TEL./MOBILE #: 0997-6677513/0977-7032757

Sir/ Madam,

This is to bill you on the service job done to your unit for the month of September & October 2022.  
Details of the charges are stated below and a copy of the Service Job Report is attached for your references:

DATE	SJR #	MODEL	SERVICE JOB DONE	AMOUNT
16-Sep-22	HO-00124810	KSG-IWF-30WFY-8K1M32-I	Lay-out Copper tubing	14,200.00
16-Sep-22	HO-00124813	KSM-IW10-9L1M	Lay-out Copper tubing	17,200.00
16-Sep-22	HO-00124815	KSM-IW10-9L1M	Lay-out Copper tubing	15,850.00
17-Sep-22	HO-00124806	KSG-IWF-30WFY-8K1M32-I	Lay-out Copper tubing	24,200.00
17-Sep-22	HO-00124808	KSM-IW20-9L1M	Lay-out Copper tubing	14,650.00
17-Sep-22	HO-00124809	KSM-IW20-9L1M	Lay-out Copper tubing	9,100.00
17-Sep-22	HO-00124811	KSG-IWF-30WFY-8K1M32-I	Lay-out Copper tubing	19,200.00
17-Sep-22	HO-00124812	KSM-IW20-9L1M	Lay-out Copper tubing	17,250.00
19-Sep-22	HO-00124816	KSM-IW15-9L1M	Lay-out Copper tubing	19,600.00
29-Sep-22	HO-00124807	KSG-IWF-25WFY-8K1M32-I	Lay-out Copper tubing	28,950.00
29-Sep-22	HO-00124814	KSG-IWF-10WFY-8K1M32-I	Lay-out Copper tubing	24,450.00
14-Oct-22	HO-00127911	KSG-IWF-30WFY-8K1M32-I	Installation	420.00
14-Oct-22	HO-00127912	KSM-IW20-9L1M	Installation	420.00
14-Oct-22	HO-00127914	KSM-IW15-9L1M	Installation	420.00
14-Oct-22	HO-00127915	KSM-IW10-9L1M	Installation	420.00
14-Oct-22	HO-00127916	KSM-IW15-9L1M	Installation	420.00
14-Oct-22	HO-00127917	KSM-IW25-9L1M	Installation	420.00
14-Oct-22	HO-00127918	KSM-IW10-9L1M	Installation	420.00
14-Oct-22	HO-00127920	KSM-IW20-9L1M	Installation	420.00
14-Oct-22	HO-00127921	KSM-IW10-9L1M	Installation	420.00

 **Kolin Philippines Int'l., Inc.**

Plant and Head Office:  
Blk 3 Lt 5 Main Drive, FCIE Compound,  
Brgy. Langkaan I, Dasmariñas, Cavite  
Tel: (632) 8749-2118  
Fax (046) 402-0793  
www.kolinphil.com.ph / kolinphilippines

Operation Office:  
1854 Sta. Rita St., Guadalupe Nuevo,  
Makati City  
Tel: (632) 8851-2711, 12 or 15  
Fax: (632) 8852-2170  
Sales Dept. Fax: (632) 8852-4791





14-Oct-22	HO-00127905	KSG-IWF-30WFY-8K1M32-I	Installation	420.00
14-Oct-22	HO-00127906	KSG-IWF-30WFY-8K1M32-I	Installation	420.00
<b>Total</b>				<b>₱ 209,270.00</b>
<b>Less: Down payment</b>				<b>111,677.30</b>
<b>Less: Down payment</b>				<b>13,729.35</b>
<b>Total amount to be paid</b>				<b>₱ 83,863.35</b>

For any clarifications please feel free to call the Undersigned at the telephone number **8851-27-11**  
**Loc. 309**

**Note:** If check payment, please prepare check payable to **Kolin Philippines International Inc.**

**Account #: BDO - KALAYAAN 011808000428**

**Note:** In case thru Bank Deposit under BDO Account, kindly indicate SJR# for your Bank Reference in the deposit slip and Fax to **(632) 852-2170** or E-mail to: **svcacctg@kolinphil.com.ph**

Prepared by:

*Elena Reyes-Nipes* 05-23-23  
**Ma. Elena Reyes-Nipes**  
Service Accounting Assistant

Noted by:

*Richell V. Hicban* 5/20/23  
**Ms. Richell V. Hicban**  
Service Accounting - Supervisor

**Received by:**

**Signature over printed name**

SERVICE

 **Kolin Philippines Int'l., Inc.**

Plant and Head Office:  
Blk 3 Lt 5 Main Drive, FCIE Compound,  
Brgy. Langkaan I, Dasmariñas, Cavite  
Tel: (632) 8749-2118  
Fax (046) 402-0793  
[www.kolinphil.com.ph](http://www.kolinphil.com.ph) / [kolinphilippines](http://kolinphilippines)

Operation Office:  
1854 Sta. Rita St, Guadalupe Nuevo,  
Makati City  
Tel: (632) 8851-2711, 12 or 15  
Fax: (632) 8852-2170  
Sales Dept. Fax: (632) 8852-4791





# kolin

Kolin Philippines International Inc.  
1854 Sta. Rita St., Alajalde Nuevo, Makati City  
Tel. No. 8852-6868 / Mobile: 0917-8118982 / Email: service@kolinphil.com.ph  
Website: www.kolinphil.com.ph

## SERVICE JOB REPORT

Customer		Brighton Land Inc.		Date		09-15-2022	
Address		Don P. Reyes Ave. (LANDMARK: VICTORIA HOMES ELEMENTARY SCHOOL), TUGAAN, CITY OF MUNTINLUPA, Metro Manila...		Start Time		01:12 pm	
Tel. No.		0997-8677513		End Time		01:22 pm	
Mobile No.		0997-8677513		Relayed by		Engr. Ken	
Contact Person		SIR KIX		Warranty Type		INST	
Model		KSG-IWT-30W-FY-8K1M32-1		Job Class		ID	
S/N (I)		RECEPTION LOBBY 3		Job Type		ID	
Dealer		SUB-Manila Imperial Motor ...		Permit? <input type="checkbox"/> Parking? <input type="checkbox"/> Appointment? <input type="checkbox"/> O.R.? <input type="checkbox"/> Ladder? <input type="checkbox"/>		Notes: TALAVERA	
Installer		Complaint		For Installation			
Before		After		No. of Visit		Tentative Sched	
Mode Setting (Cool)				Findings			
WAC Setting Temp(16°C-RE)/(10-ME)							
SAC/PAC   Setting Temp (17°)							
Discharge Temperature (High)							
Intake Temperature (High)				Recommendation			
Ampere				for lay-out. C. tube			
WAC   Wattage (Inverter)							
Voltage							
SAC/PAC   Pressure							
Part Code	Description	Qty	Unit Price	Amount			
	C. TUBE 1/4 x 5/8	20 ft	400	4,000			
	R. COND 2.0mm x 4C	27 ft	100	1,700			
	PVC PIPE 3/4 x 10	1					
	PVC ELBOW 2/4	3					
	stickless tape	1					
	pipino clamp (S)	5					
	clay (D)	5					
LIQUIDATED							
DATE: 9/19/2022							
SR No.	initial charot	Labor		8,500			
Repair Done	lay-out C. TUBING.	Handling					
Repair Code		Others					
Date Attended	Sept. 16, 2022	Date Finished	Sept. 16, 2022	Total		14,200	
Time Attended	9:00 AM	Time Finished	2:30 PM	Amount Paid			
This serves as temporary receipt when properly filled up by authorized representative.		Check No.		Balance		14,200	
Bank / Branch		to collect					
Serviced by:		By signing below, I allow KPII to collect, store & process my personal information as necessary to avail of service & fully understand that my personal information shall be used in accordance w/ Philippine Data Privacy Act & its implementing rules & regulations.					
TALAVERA		I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.					
Valk		Created by: JULONGBARIT		Conformed by: JALON		Customer (Signature over printed name)	
Technician(s)		CSR					



Customer	Brighton Land Inc.				Date	09-15-2022			
Address	Don P. Reyes Ave, (LANDMARK: VICTORIA HOMES ELEMENTARY SCHOOL),				Start Time	CITY 01:12 pm			
OF MUNTINLUPA, Metro Manila...					End Time	01:22 pm			
Tel. No.					Relayed by	Engr. Ken			
Mobile No.	0997-6677513				Warranty Type	C			
Contact Person	SIR KIX	Mobile No.	0997-6677513	Tel. No.	Job Class				INST
Model	KSG-IWF-10WFI-8K1M32-I			Call Origin	Job Type				FD
S/N (I)	MEETING ROOM 1	S/N (O)			Permit?	Parking?	Appointment?	O.R.?	Ladder?
Dealer	SUB-Manila Imperial Motor ...		DOP	08/25/2022	Notes: TALavera				
Installer			Complaint	For installation					
	Before	After	No. of Visit	1st Action	Tentative Sched				
Mode Setting (Cool)			Findings						
WAC Setting Temp(16°C-RE)/(10-ME)									
SAC/PAC   Setting Temp (17°)									
Discharge Temperature (High)									
Intake Temperature (High)			Recommendation						
Ampere			for lay-out C. tube						
WAC   Wattage (Inverter)			40-42						
Voltage									
SAC/PAC   Pressure									
Part Code	Description			Qty	Unit Price	Amount			
	C. tube 3/8 x 1/4			30ft	350	7,000			
	R. COM 2.0mm x 4C			37ft	100	2,700			
	stickless tape			1					
	PVC PIPE 3/8 x 10			1					
	PVC ELBOW 3/8			2					
	Clamp (S)			5					
	Clamp (D)			5					
<div style="border: 2px solid black; padding: 5px; display: inline-block;"> <b>LIQUIDATED</b>              BY: <i>[Signature]</i> 9/19/2022              DATE:           </div>									
SR No.	INITIAL CHANGE				Labor	7,500			
Repair Done	lay-out C. tube				Handling				
Repair Code					Others				
Date Attended	9-16-22	Date Finished	9-16-22	Amount Paid	17,200				
Time Attended	9:00 AM	Time Finished	2:30 PM	Balance	17,200				
This serves as temporary receipt when properly filled up by authorized representative.				Check No.	Bank / Branch		for collection		
Serviced by:		By signing below, I allow KPII to collect, store & process my personal information as necessary to avail of service & fully understood that my personal information shall be used in accordance w/ Philippine Data Privacy Act & its implementing rules & regulations.							
talavera		I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.							
vake		Created by:		Conformed by:		Customer			
munday		RODEN PULONGBARIT		[Signature]		(Signature over printed name)			
Technician(s)		CSR							



Customer		Brighton Land Inc.		Date		09-15-2022	
Address		Don P. Reyes Ave, (LANDMARK: VICTORIA HOMES ELEMENTARY SCHOOL),		Start Time		01:12 pm	
		OF MUNTINLUPA, Metro Manila...		End Time		01:22 pm	
Tel. No.				Relayed by		Engr. Ken	
Mobile No.		0997-6677513		Warranty Type		C	
Contact Person		SIR KIX		Mobile No.		997-6677513	
		Tel. No.				Job Class	
Model		KSG-WF-10WFY-8K1M32-I		Call Origin		Job Type	
S/N (I)		MEETING ROOM 2		S/N (O)			
Dealer		SUB-Manila Imperial Motor ...		DOP		08/25/2022	
Installer				Complaint		For installation	
		Before		After		No. of Visit	
						Tentative Sched	
Mode Setting (Cool)				Findings			
WAC Setting Temp(16°C-RE)/(10-ME)							
SAC/PAC   Setting Temp (17°)							
Discharge Temperature (High)							
Intake Temperature (High)				Recommendation			
Ampere				for lay-out		C. TUBE	
WAC   Wattage (Inverter)							
Voltage							
SAC/PAC   Pressure							
Part Code		Description		Qty		Unit Price	
		c. tube 1/4 x 2/8		27 FT		350	
		d. cond 2.0mm x 4C		34 FT		100	
		PVC PIPE 3/4 x 10		1			
		PVC elbow 3/4		2			
		stickless tape		11			
		clay (s)		5			
		clay (o)		5			
SR No.		initial charge		Labor		7,500	
Repair Done		lay-out. tubing		Handling			
				Others			
Repair Code				Total		15,850	
Date Attended		Sept 16, 2022		Date Finished		Sept. 16, 2022	
Time Attended		9:00 am		Time Finished		2:30 pm	
Amount Paid				Balance		15,850	
This serves as temporary receipt when properly filled up by authorized representative.		Check No.		Bank / Branch		pop collection	
Serviced by:		By signing below, I allow KPII to collect, store & process my personal information as necessary to avail of service & fully understood that my personal information shall be used in accordance w/ Philippine Data Privacy Act & its implementing rules & regulations.					
I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.							
Created by:		Conformed by:					
RODEN PULONGBARIT		JHON					
Technician(s)		CSR		Customer (Signature over printed name)			



# kolin

Kolin Philippines International Inc.  
1854 Sta. Rita St. Talavera Nuevo, Makati City  
Tel. No. 8852-6800 / Mobile: 0917-8118982 / Email: service@kolinphil.com.ph  
Website: www.kolinphil.com.ph

## SERVICE JOB REPORT

Customer		Brighton Land Inc.		No.		HO-00124806	
Address		Don P. Reyes Ave. (LANDMARK: VICTORIA HOMES ELEMENTARY SCHOOL) OF MUNTINI LIPA, Metro Manila		Previous SJR No.		HO-00114872	
Tel. No.				Date		09-15-2022	
Mobile No.		0997-6677513		Start Time		04:11 pm	
Contact Person		SIR KIX		End Time		04:21 pm	
Model		KSG-IWF-30W-FY-8K1M32-1		Relayed by		Engr. Ken	
S/N (I)		RECEPTION/LOBBY 1		Warranty Type		C	
Dealer		SUB-Manila Imperial Motor		Job Class		INST	
Installer		Complaint		Job Type		ID	
Before		After		Permit? <input type="checkbox"/> Parking? <input type="checkbox"/> Appointment? <input type="checkbox"/> O.R.? <input type="checkbox"/> Ladder? <input type="checkbox"/>			
Mode Setting (Cool)				Notes:		TALAVERA	
WAC   Setting Temp (16°C-RE)/(10-ME)				No. of Visit		Tentative Sched	
SAC/PAC   Setting Temp (17°)				Findings		09/16/2022	
Discharge Temperature (High)				Recommendation			
Intake Temperature (High)				Ampere		for lay-out C. tube	
WAC   Wattage (Inverter)				Voltage			
SAC/PAC   Pressure							
Part Code	Description	Qty	Unit Price	Amount			
	C. tube 1/4 x 5/8	40ft	400	12,000			
	1" COIL 2.0mm x 40	47ft	100	3,700			
	Stick & tape	1	500	500			
	PVC PIPE 3/4 x 10	1	20	20			
	PVC ELBOW 3/4	2	10	20			
	Clamp (S)	1	50	50			
	Clamp (D)	1	50	50			
LABORATED							
BY: 9/19/2022							
DATE:							
SR No.	initial change	Labor	8,500				
Repair Done	lay-out C. tube	Handling					
Repair Code		Others					
Date Attended	Sept. 17, 2022	Date Finished	Sept. 17, 2022	Amount Paid	24,200		
Time Attended	8:57 AM	Time Finished	2:30 PM	Balance	24,200		
This serves as temporary receipt when properly filled up by authorized representative.		Check No.			Bank / Branch	For collection	
Serviced by:		By signing below, I allow KPII to collect, store & process my personal information as necessary to avail of service & fully understood that my personal information shall be used in accordance w/ Philippine Data Privacy Act & its implementing rules & regulations.					
Talavera, Maria		I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.					
Valle, B.S.		Created by:	Conformed by:				
Technician(s)		RODEN PULONGBARIT	Customer				
		CSR	(Signature over printed name)				



Customer		Date	
Address		Start Time	
Tel. No.		End Time	
Mobile No.		Relayed by	
Contact Person	Mobile No.	Tel. No.	Warranty Type
Model	Call Origin	Job Class	
S/N (I)	S/N (O)	Permit? <input type="checkbox"/>	Parking? <input type="checkbox"/>
Dealer	DOP	Appointment? <input type="checkbox"/>	O.R.? <input type="checkbox"/>
Installer	Complaint	Ladder? <input type="checkbox"/>	
Before		After	
Mode Setting (Cool)		Findings	
WAC Setting Temp(16°C-RE)/(10-ME)			
SAC/PAC   Setting Temp (17°)			
Discharge Temperature (High)			
Intake Temperature (High)		Recommendation	
Ampere			
WAC   Wattage (Inverter)			
Voltage			
SAC/PAC   Pressure			
Part Code	Description	Qty	Unit Price
	C. TUBE 1/2 x 1/4	25 ft	350
	h. cord 2.0mm x 4c	25 ft	100
	Insulation 2 1/8 x 3/4	25	350
	Stickless tape	1	
	PIPING clasp (0)	5	
	" " (5)	5	
	PVC PIPE 3/4 x 10	1	
	ELBOW 3/4	1	
<div style="border: 1px solid black; padding: 5px;"> <b>Liquidated</b>              BY: <u>[Signature]</u> 9/19/2022              DATE: <u>9/19/2022</u> </div>			
SR No.	INITIAL CHANGE	Labor	7.500
Repair Done	lay-out C. TUBE	Handling	
Repair Code		Others	
Date Attended	Sept. 17, 2022	Date Finished	Sept. 17, 2022
Time Attended	8:57	Time Finished	2:30
This serves as temporary receipt when properly filled up by authorized representative.		Check No.	Bank / Branch
Serviced by:		By signing below, I allow KPII to collect, store & process my personal information as necessary to avail of service & fully understand that my personal information shall be used in accordance w/ Philippine Data Privacy Act & its implementing rules & regulations.	
Talavera Medina		I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.	
Vallu R.J.		Created by:	Conformed by:
Technician(s)		RODEN PULONGBARIT	Customer
		CSR	(Signature over printed name)



Customer		Date		No.		Previous SJR No.	
Address		Start Time		Date		HO-00124809	
Tel. No.		End Time		Relayed by		09-15-2022	
Mobile No.		Warranty Type		Job Class		Inst	
Contact Person	Mobile No.	Tel. No.	Job Type	Permit?	Parking?	Appointment?	O.R.?
Model	Call Origin	Notes:	Ladder?				
S/N (I)	S/N (O)						
Dealer	DOP						
Installer	Complaint						
Before	After	No. of Visit	Tentative Sched				
Mode Setting (Cool)	Findings						
WAC Setting Temp(16°C-RE)/(10-ME)							
SAC/PAC   Setting Temp (17°)							
Discharge Temperature (High)							
Intake Temperature (High)	Recommendation						
Ampere	for lay-out. C. tube						
WAC   Wattage (Inverter)							
Voltage							
SAC/PAC   Pressure							
Part Code	Description	Qty	Unit Price	Amount			
	C. tube 1/2 x 1/4	12 ft	350	700			
	A. cap 2.0mm x 4C	10 ft	100	900			
	Stickless tape	1					
	Clamp (S)	5					
	" (D)	5					
	PVC PIPE 3/4 x 10	1					
	PVC ELBOW 3/4	1					
<div style="border: 1px solid black; padding: 5px; display: inline-block;"> <b>LIQUIDATED</b>              BY: <u>                    </u>              DATE: <u>                    </u> </div>							
SR No.	Initial	Change	Labor	7500			
Repair Done	lay-out	C. tubing.	Handling				
Repair Code			Others				
Date Attended	Date Finished	Amount Paid	Total	9,100			
Time Attended	Time Finished	Balance	9,100				
This serves as temporary receipt when properly filled up by authorized representative.		Check No.	Bank / Branch	for collection			
Serviced by:		By signing below, I allow KPII to collect, store & process my personal information as necessary to avail of service & fully understood that my personal information shall be used in accordance w/ Philippine Data Privacy Act & its implementing rules & regulations.					
I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.							
Created by:		Conformed by:					
RODEN PULONGBARIT		Customer					
Technician(s)		(Signature over printed name)					



Customer		BRIGHTON LAND INC.		Date		09-15-2022	
Address		Don P. Reyes Ave. (LANDMARK: VICTORIA HOMES ELEMENTARY SCHOOL), TUNASAN, CITY OF MUNTINLUPA, Metro Manila...		Start Time		01:11 pm	
Tel. No.		0997-6677513		End Time		01:22 pm	
Mobile No.		0997-6677513		Relayed by		Engr. Ron	
Contact Person		SIR KIX		Warranty Type		C	
Model		KSG-IWF-30W-FY-8K1M32-1		Job Class		INST	
S/N (I)		RECEPTION LOBBY 2		Job Type		ID	
Dealer		SUB-Manila Imperial Motor ...		Permit? <input type="checkbox"/> Parking? <input type="checkbox"/> Appointment? <input type="checkbox"/> O.R.? <input type="checkbox"/> Ladder? <input type="checkbox"/>			
Installer		Complaint		Notes:		TALAVERA	
Before		After		No. of Visit		Tentative Sched	
Mode Setting (Cool)				Findings			
WAC Setting Temp(16°C-RE)/(10-ME)							
SAC/PAC   Setting Temp (17°)							
Discharge Temperature (High)							
Intake Temperature (High)				Recommendation			
Ampere				for lay-out - C. tube			
WAC   Wattage (Inverter)							
Voltage							
SAC/PAC   Pressure							
Part Code	Description	Qty	Unit Price	Amount			
	C. tube 1/4 x 5/8	30#	400	8,000			
	1. Cond 2.0mm x 40	37#	100	2,700			
	stickless type	1					
	PVC PIPE 3/4 x 10	1					
	PVC tubow 3/4	1					
	clamp (S)	5					
	clamp (D)	5					
LIQUIDATED							
DATE: 9/19/2022							
SR No.	Initial Time	Labor		8,500			
Repair Done	lay-out. C. tubing	Handling					
Repair Code		Others					
Date Attended	Sept. 17. 2022	Date Finished	Sept. 17. 2022	Total		19,200	
Time Attended	8:00 AM - 5:40 PM	Time Finished	2:30 PM	Amount Paid			
This serves as temporary receipt when properly filled up by authorized representative.		Check No.	Bank / Branch	for collection			
Serviced by:		By signing below, I allow KPII to collect, store & process my personal information as necessary to avail of service & fully understand that my personal information shall be used in accordance w/ Philippine Data Privacy Act & its implementing rules & regulations.					
TALAVERA MENDING		I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.					
VALLI R. J.		Created by:		Conformed by:		Customer	
Technician(s)		CSR		(Signature over printed name)			



Customer		Brighton Land Inc.		Date		09-15-2022	
Address		Don P. Reyes Ave, (LANDMARK: VICTORIA HOMES ELEMENTARY SCHOOL), TUGUEGARAO CITY		Start Time		01:12 pm	
		OF MUNTINLUPA, Metro Manila...		End Time		01:22 pm	
Tel. No.				Relayed by		Engr. Ken	
Mobile No.		0997-6677513		Warranty Type		C	
Contact Person		SIR KIX		Job Class		INST	
Model		KSG-IWF-15W-FY-8K1M32-I		Job Type		FD	
S/N (I)		MEETING ROOM 3		S/N (O)			
Dealer		SUB-Manila Imperial Motor ...		DOP		08/25/2022	
Installer				Complaint		For Installation	
		Before		After		No. of Visit	
						Tentative Sched	
Mode Setting (Cool)						Findings	
WAC Setting Temp(16°C-RE)/(10-ME)							
SAC/PAC   Setting Temp (17°)							
Discharge Temperature (High)							
Intake Temperature (High)						Recommendation	
Ampere						for lay-out.	
WAC   Wattage (Inverter)							
Voltage							
SAC/PAC   Pressure							
Part Code		Description		Qty		Unit Price	
		C. tube 1/4 x 9/8		27 ft		350	
		h. cond 2.0mm x 4C		34 ft		100	
		stickless tape		1			
		R. insulation 2 1/8 x 3/4		4		350	
		PVC PIPE 3/4 x 10		1			
		PVC elbow 3/4		2			
		Clamp (SI)		5			
		Clamp (DI)		5			
SR No.		Initial Charge		Labor		7,500	
Repair Done		Lay-out C. tube		Handling			
				Others			
Repair Code				Total		17,250	
Date Attended		Sept. 17, 2022		Date Finished		Sept. 17, 2022	
Time Attended		8:57		Time Finished		2:30 pm	
Amount Paid				Balance		17,250	
This serves as temporary receipt when properly filled up by authorized representative.		Check No.		Bank / Branch		for collection	
Serviced by:		By signing below, I allow KPII to collect, store & process my personal information as necessary to avail of service & fully understood that my personal information shall be used in accordance w/ Philippine Data Privacy Act & its implementing rules & regulations.					
Talaue		I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.					
Vale		Created by: ROYAL LONGBARIT					
Technician(s)		Conformed by: Reynaldo Dizon					
		Customer (Signature over printed name)					



No. **HO-00124816**  
Previous SJR No. **HO-00114973**

Customer	Brighton Land Inc.			Date	09-15-2022		
Address	Don P. Reyes Ave. (LANDMARK: VICTORIA HOMES ELEMENTARY SCHOOL),			Start Time	Tulunan, CITY 01:12 pm		
	OF MUNTINLUPA, Metro Manila...			End Time	01:22 pm		
Tel. No.				Relayed by	Engr. Ken		
Mobile No.	0997-6677513			Warranty Type	C		
Contact Person	SIR KIX	Mobile No.	997-6677513	Tel. No.			
Model	KSM-1715-9LIM KSG-WF-15WFY-8K1M32-I			Call Origin	D		
S/N (I)	MEETING ROOM 4		S/N (O)			Permit? <input type="checkbox"/>	Parking? <input type="checkbox"/>
Dealer	SUB-Manila Imperial Motor ...		DOP	08/25/2022		Appointment? <input type="checkbox"/>	O.R.? <input type="checkbox"/> Ladder? <input type="checkbox"/>
Installer			Complaint	For Installation			
	Before	After	No. of Visit	1st Action		Tentative Sched	09/16/2022

Mode Setting (Cool)		Findings
WAC Setting Temp(16°C-RE)/(10-ME)		
SAC/PAC   Setting Temp (17°)		
Discharge Temperature (High)		
Intake Temperature (High)		Recommendation
Ampere		for lay-out C. Tube
WAC   Wattage (Inverter)		
Voltage	TC -	
SAC/PAC   Pressure		

Part Code	Description	Qty	Unit Price	Amount
	C. tube 1/4 x 3/8	33ft	250	8,050
	h. con 20mm x 4C	40ft	100	3,000
	h. insulation 2 1/8 x 3/4	3	350	1,050
	stickless tape	3		
	PVC PIPE 3/4 x 10	1		
	PVC ELBOW 3/4	2		
	clamps (S)	5		
	clamps (D)	5		
<div> <div>LIQUIDATED</div> <div>9/19/2022</div> </div>				
SR No.	Initial	Change	Labor	7,500
Repair Done	lay-out	CTUABLE	Handling	
Repair Code			Others	
Date Attended	Sept. 19, 2022	Date Finished	Total	19,600
Time Attended	9:17 am	Time Finished	Amount Paid	
			Balance	19,600
This serves as temporary receipt when properly filled up by authorized representative.		Check No.	Bank / Branch	for collection

Serviced by:	By signing below, I allow KPIL to collect, store & process my personal information as necessary to avail of service & fully understood that my personal information shall be used in accordance w/ Philippine Data Privacy Act & its implementing rules & regulations.		
Talavera	I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.		
Valle	Created by:	Conformed by:	
	RODEN PULONGBARIT	Reynardo Dayday	
Technician(s)	CSR	Customer	(Signature over printed name)



Customer		Freighton Land Inc.		Date		09-15-2022	
Address		Don P. Reyes Ave. (LANDMARK: VICTORIA HOMES ELEMENTARY SCHOOL)		Start Time		01:12 pm	
		OF MUNTINLUPA, Metro Manila...		End Time		01:21 pm	
Tel. No.				Relayed by		Engr. Ken	
Mobile No.		0997-6677513		Warranty Type		C	
Contact Person		SIR KIX		Mobile No.		0997-6677513	
Model		KSG-IWF-25WFEY-8K1M32-I		Call Origin		ID	
S/N (I)		RECEPTION/ LOBBY 4		S/N (O)			
Dealer		SUB-Manila Imperial Motor		DOP		08/25/2022	
Installer				Complaint		For Installation	
		Before		After		No. of Visit	
Mode Setting (Cool)				Findings		Tentative Sched	
WAC Setting Temp(16°C-RE)/(10-ME)						09/16/2022	
SAC/PAC   Setting Temp (17°)							
Discharge Temperature (High)							
Intake Temperature (High)						Recommendation	
Ampere						for lay-out - C. tube	
WAC   Wattage (Inverter)							
Voltage							
SAC/PAC   Pressure							
Part Code		Description		Qty		Unit Price	
		C. tube 1/2 X 1/4		46 ft		400	
		R. insulation 2 1/8 X 3/4		5		250	
		R. cond 2.2mm X 40		53 ft		60	
		Gaskets		1			
		PVC PIPE 3/4 X 10		1			
		PVC elbow 2 1/2		2			
		Clamp (S)		5			
		Clamp (D)		5			
SR No.		INITIAL CHANGE		Labor		\$ 8,500	
Repair Done		lay-out C. tube		Handling			
Repair Code				Others			
Date Attended		Sept. 27, 2022		Total		\$ 26,950	
Time Attended		9:15 AM		Amount Paid			
Time Finished		2:20 PM		Balance		\$ 28,950	
This serves as temporary receipt when properly filled up by authorized representative.		Check No.		Bank / Branch		for collection	
Serviced by:		By signing below, I allow KPII to collect, store & process my personal information as necessary to avail of service & fully understood that my personal information shall be used in accordance w/ Philippine Data Privacy Act & its implementing rules & regulations.					
Tadavera		I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.					
Vale		Created by: RODEN PULONGBARIT					
Technician(s)		Conformed by: Customer (Signature over printed name)					



Customer	Brighton Land Inc.				Date	09-15-2022			
Address	Don P. Reyes Ave. (LANDMARK: VICTORIA HOMES ELEMENTARY SCHOOL),				Start Time	01:12 pm			
OF MUNTINLUPA, Metro Manila...					End Time	01:22 pm			
Tel. No.					Relayed by	Engr. Ken			
Mobile No.	0997-6677513				Warranty Type	C			
Contact Person	SIR KIX	Mobile No.	997-6677513	Tel. No.		Job Class	INST		
Model	KSG-IWF-10W-FY-8K1M32-I			Call Origin	10	Job Type	FD		
S/N (I)	CASHIER	S/N (O)		Permit?	<input type="checkbox"/>	Parking?	<input type="checkbox"/>	Appointment?	<input type="checkbox"/>
Dealer	SUB-Manila Imperial Motor ...			DOP	08/25/2022	Notes:	TALAVERA		
Installer				Complaint	For installation				
	Before	After		No. of Visit	1st Action	Tentative Sched	09/16/2022		
Mode Setting (Cool)					Findings				
WAC   Setting Temp (16°C-RE)/(10-ME)									
SAC/PAC   Setting Temp (17°C)									
Discharge Temperature (High)									
Intake Temperature (High)					Recommendation				
Ampere					for lay-out. C-tube				
WAC   Wattage (Inverter)									
Voltage									
SAC/PAC   Pressure									
Part Code	Description			Qty	Unit Price	Amount			
	C-tube 3/8 x 1/4			43 ft	250	11,550			
	R. Cond 2.0mm x 4C			50 ft	160	4,000			
	R. insulation 2 1/8 x 3/4			4	350	1,400			
	Schrader tape			1					
	Clap (S)			5					
	Clap (S)			5					
	PIPE 3/4 x 10			1					
	pre elbow 3/4			2					
<div style="border: 2px solid red; padding: 5px; display: inline-block;"> <b>LIQUIDATED</b>              9/29/2022              DATE:           </div>									
SR No.	1011111111				Labor	7,500			
Repair Done	Lay-out C-tube				Handling				
Repair Code					Others				
Date Attended	Sept. 21, 2022		Date Finished	Sept. 20, 2022		Amount Paid	24,450		
Time Attended	1:15 AM		Time Finished	2:10 PM		Balance	24,450		
This serves as temporary receipt when properly filled up by authorized representative.					Check No.	for collection			
Served by:			By signing below, I allow KPII to collect, store & process my personal information as necessary to avail of service & fully understood that my personal information shall be used in accordance w/ Philippine Data Privacy Act & its implementing rules & regulations.						
TALAVERA			I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.						
Value			Created by:			Conformed by:			
BURNED			ROLEN PULONGBARIT			Customer			
Technician(s)			CSR			(Signature over printed name)			



Customer		Date		No. HO-00127911	
Address		Start Time		Previous SJR No. HO-00117787	
OF MUNTINLUPA, Metro Manila...		End Time		10-11-2022	
Tel. No.		Relayed by		Engr. Ken	
Mobile No. 0997-6677513		Warranty Type		C	
Contact Person	Mobile No.	Tel. No.	Job Class	INST	
Model	Call Origin	Job Type	FD		
S/N (I)	S/N (O)	Permit?	Parking?	Appointment?	O.R.?
Dealer	DOP	Notes:			
Installer	Complaint	TALAVERA			
Before	After	No. of Visit	Tentative Sched	10/14/2022	
Mode Setting (Cool)		Findings			
WAC Setting Temp(16°C-RE)/(10-ME)					
SAC/PAC   Setting Temp (17°)					
Discharge Temperature (High)					
Intake Temperature (High)		Recommendation			
Ampere		for installation outdoor unit			
WAC   Wattage (Inverter)					
Voltage					
SAC/PAC   Pressure					
Part Code	Description	Qty	Unit Price	Amount	
	A. cond 3.5mm x 81	7ft	60	420	
	C. Breaker 30 Amp.	1			
	Fluor bracket	1			
	Fluor (R) 32	1			
<div style="border: 2px solid black; padding: 5px; display: inline-block;"> <b>LIQUIDATED</b>              DATE: 10/17/2022           </div>					
SR No.	Labor				
Repair Done	Installation outdoor unit / for start-up		Handling		
Repair Code	Total		420		
Date Attended	Date Finished	Amount Paid			
Time Attended	Time Finished	Balance		420	
This serves as temporary receipt when properly filled up by authorized representative.		Check No.	Bank / Branch		
Serviced by:		By signing below, I allow KPII to collect, store & process my personal information as necessary to avail of service & fully understood that my personal information shall be used in accordance w/ Philippine Data Privacy Act & its implementing rules & regulations.			
I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.		Created by:			
Technician(s)		Conformed by:			
CSR		Customer			
		(Signature over printed name)			



## SERVICE JOB REPORT

KOLIN						No.		HO-00127012	
Tel. No. 8852-686... Mobile: 0917-8118982 / Email: service@kolinphil.com.ph Website: www.kolinphil.com.ph						Previous SJR No.			
Customer						Date		10-11-2022	
Address						Start Time		12:26 pm	
OF MUNTINI LPA, Metro Manila...						End Time		12:32 pm	
Tel. No.						Relayed by		Engr. Ken	
Mobile No.						Warranty Type		C	
Contact Person			Mobile No.		Tel. No.	Job Class		INST	
Model			Call Origin		Job Type		FD		
S/N (I)			S/N (O)	Permit?	Parking?	Appointment?	O.R.?	Ladder?	
Dealer			DOP	Notes:					
Installer			Complaint	TALAVERA					
Before			After	No. of Visit	Tentative Sched				
Mode Setting (Cool)			Findings						
WAC Setting Temp(16°C-RE)/(10-ME)									
SAC/PAC   Setting Temp (17°)									
Discharge Temperature (High)									
Intake Temperature (High)			Recommendation						
Ampere			for installation outdoor unit						
WAC   Wattage (Inverter)									
Voltage									
SAC/PAC   Pressure									
Part Code		Description	Qty	Unit Price	Amount				
n. corn		3.5mm x 4C	7PC	60	420				
C. Breaker		30amp.	1						
Floor bracket			1						
LIQUIDATED									
DATE									
SR No.		Labor							
Repair Done		Handling							
Repair Code		Others							
Date Attended		Date Finished	Total		420				
Time Attended		Time Finished	Amount Paid						
This serves as temporary receipt when properly filled up by authorized representative.		Check No.	Balance		420				
Bank / Branch		Fa collection							
Serviced by:		By signing below, I allow KPII to collect, store & process my personal information as necessary to avail of service & fully understood that my personal information shall be used in accordance w/ Philippine Data Privacy Act & its implementing rules & regulations. I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.							
Technician(s)		Created by:		Conformed by:		Customer			
RODEN PULONGBARIT		CSR		(Signature over printed name)					



## SERVICE JOB REPORT

No. HO-00127914

Previous SJR No. H0-00117797

[illegible]



Customer		Brighton Land Inc.		Date		10-11-2022	
Address		Don P. Reyes Ave. (LANDMARK: VICTORIA HOMES ELEMENTARY SCHOOL),		Start Time		CITY 02:26 pm	
		OF MUNTINLUPA, Metro Manila...		End Time		02:33 pm	
Tel. No.				Relayed by		Engr. Ken	
Mobile No.		0997-6677513		Warranty Type		C	
Contact Person		SIR KIX		Mobile No.		997-6677513	
Model		KSM-IW10-9L1M-I		Tel. No.			
S/N (I)		18532112-10024		Call Origin		10	
S/N (O)				Job Class		INST	
Dealer		SUB-Manila Imperial Motor ...		Job Type		FD	
Installer				Permit? <input type="checkbox"/> Parking? <input type="checkbox"/> Appointment? <input type="checkbox"/> O.R.? <input type="checkbox"/> Ladder? <input type="checkbox"/>			
Complaint		For Installation		Notes:		TALAVERA	
Before		After		No. of Visits		Tentative Sched	
				1st Action		10/14/2022	
Mode Setting (Cool)				Findings			
WAC Setting Temp(16°C-RE)/(10-ME)							
SAC/PAC   Setting Temp (17°)							
Discharge Temperature (High)							
Intake Temperature (High)				Recommendation			
Ampere				for installation outdoor unit			
WAC   Wattage (Inverter)							
Voltage							
SAC/PAC   Pressure							
Part Code		Description		Qty		Unit Price	
		h. conn 3.5mm x 3C		7 FT		60	
		c. bracket 20Amp		1			
		Floor bracket		1			
SR No.				Labor			
Repair Done		Installation outdoor unit / to		Handling			
		start - up		Others			
Repair Code				Total		# 420	
Date Attended		Oct. 14, 2022		Date Finished		Oct 17, 2022	
Time Attended		12:20 pm		Time Finished		1:40	
This serves as temporary receipt when properly filled up by authorized representative.		Check No.		Bank / Branch		to collector	
Serviced by:		By signing below, I allow KPII to collect, store & process my personal information as necessary to avail of service & fully understood that my personal information shall be used in accordance w/ Philippine Data Privacy Act & its implementing rules & regulations.					
TALAVERA		I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.					
valk		Created by:		Conformed by:			
Technician(s)		RODEN PULONGBARIT		Customer			
		CSR		(Signature over printed name)			



Customer		Brighton Land Inc.		Date		10-11-2022	
Address		Don P. Reyes Ave. (LANDMARK: VICTORIA HOMES ELEMENTARY SCHOOL),		Start Time		10:26 pm	
		OF MUNTINLUPA, Metro Manila...		End Time		02:33 pm	
Tel. No.				Relayed by		Engr. Ken	
Mobile No.		0997-6677513		Warranty Type		C	
Contact Person	SIR KIX	Mobile No.	997-6677513	Tel. No.		Job Class	INST
Model	KSM-IW15-9L1M-I	Call Origin	10	Job Type		FD	
S/N (I)	18562112-11230	S/N (O)	18562112-1128	Permit?	<input type="checkbox"/>	Parking?	<input type="checkbox"/>
Dealer	SUB-Manila Imperial Motor ...	DOP	08/26/2022	Appointment?	<input type="checkbox"/>	O.R.?	<input type="checkbox"/>
Installer		Complaint	For installation	Notes:	TALAVERA		
	Before	After	No. of Visit	1st Action	Tentative Sched	10/14/2022	
Mode Setting (Cool)	Cool			Findings			
WAC Setting Temp(16°C-RE)/(10-ME)							
SAC/PAC   Setting Temp (17°)	17						
Discharge Temperature (High)	16.1						
Intake Temperature (High)	29			Recommendation			
Ampere	5.7			for installation outdoor unit			
WAC   Wattage (Inverter)							
Voltage	220						
SAC/PAC   Pressure	40psi						
Part Code	Description			Qty	Unit Price	Amount	
	C. Breaker 20 Amp			1			
	R. conn 3.5mm x 4C			7 ft	60	420	
	Sticker two bracket outdoor			1			
<div style="border: 2px solid black; padding: 5px; display: inline-block;"> <b>LIQUIDATED</b>              10/17/2022           </div>							
SR No.				Labor			
Repair Done	Installation outdoor unit.			Handling			
	Start up. Unit normal			Others			
Repair Code	Operative			Total	420		
Date Attended	Oct. 14, 2022	Date Finished	Oct. 14, 2022	Amount Paid			
Time Attended	12:20pm	Time Finished	1:40	Balance	420		
This serves as temporary receipt when properly filled up by authorized representative.				Check No.	Bank / Branch		
Serviced by:				By signing below, I allow KPII to collect, store & process my personal information as necessary to avail of service & fully understood that my personal information shall be used in accordance w/ Philippine Data Privacy Act & its implementing rules & regulations.			
Talavera				I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.			
Valu				Created by: RODEN PULONGBARIT			
Technician(s)				Conformed by: Customer (Signature over printed name)			



[illegible]



Customer		Brighton Land Inc.		Date		10-11-2022	
Address		Don P. Reyes Ave. (LANDMARK: VICTORIA HOMES ELEMENTARY SCHOOL) OF MUNTINLUPA, Metro Manila		Start Time		Tunasan, CITY 02:26 pm	
Tel. No.				End Time		02:33 pm	
Mobile No.		0997-6677513		Relayed by		Engr. Ken	
Contact Person		SIR KIX		Mobile No.		0997-6677513	
Model		KSM-DW10-9L 1M-L		Tel. No.			
S/N (I)		1832112-10541		Call Origin		10	
Dealer		SUB Manila Imperial Motor		Job Class		INST	
Installer				Job Type		FD	
Complaint		For Installation		Permit? <input type="checkbox"/> Parking? <input type="checkbox"/> Appointment? <input type="checkbox"/> O.R.? <input type="checkbox"/> Ladder? <input type="checkbox"/>			
Before		After		Notes:		TALAVERA	
Mode Setting (Cool)				No. of Visit		Tentative Sched	
WAC Setting Temp(16°C-RE)/(10-ME)				1st Action		10/14/2022	
SAC/PAC   Setting Temp (17°)				Findings			
Discharge Temperature (High)							
Intake Temperature (High)				Recommendation			
Ampere				Installation outdoor unit			
WAC   Wattage (Inverter)							
Voltage							
SAC/PAC   Pressure							
Part Code		Description		Qty		Unit Price	
		N. COND 3.5mm x 30		7 ft		60	
		C. breaker 20 Amp.		1		40	
		Floor bracket		1			
SR No.				Labor			
Repair Done		Installation outdoor unit / to. split up.		Handling			
Repair Code				Others			
Date Attended		Oct. 14, 2022		Total		420	
Time Attended		12:20 pm		Amount Paid		420	
Time Finished		1:40		Balance		420	
This serves as temporary receipt when properly filled up by authorized representative.		Check No.		Bank / Branch		for collection	
Serviced by:		By signing below, I allow KPII to collect, store & process my personal information as necessary to avail of service & fully understood that my personal information shall be used in accordance w/ Philippine Data Privacy Act & its implementing rules & regulations.					
TALAVERA		I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.					
VALLA		Created by:		Conformed by:			
Technician(s)		RODEN PULONGBARIT		Customer			
		CSR		(Signature over printed name)			



Customer		Brighton Land Inc.		Date		10-11-2022	
Address		Don P. Reyes Ave. (LANDMARK: VICTORIA HOMES ELEMENTARY SCHOOL) OF MUNTINLUPA, Metro Manila...		Start Time		12:26 pm	
Tel. No.				End Time		12:34 pm	
Mobile No.		0997 6877513		Relayed by		Engr. Ken	
Contact Person		SIR KIX		Warranty Type		C	
Model		KSM IW20 9L1M1		Job Class		INST	
S/N (I)		18572112-10629		Call Origin		ID	
Dealer		SUB Manila Imperial Motor ...		Job Type		FD	
Installer		Complaint		Notes:		TALAVERA	
Before		After		No. of Visit		Tentative Sched	
Mode Setting (Cool)		Cool		1st Action		10/14/2022	
WAC Setting Temp(16°C-RE)/(10-ME)				Findings			
SAC/PAC   Setting Temp (17°)		17		Recommendation			
Discharge Temperature (High)		15.1		for installation outdoor unit			
Intake Temperature (High)		29					
Ampere		8.2					
WAC   Wattage (Inverter)							
Voltage		230					
SAC/PAC   Pressure		40					
Part Code		Description		Qty		Unit Price	
		A. CUTO 3.5mm x 4C		7FT		60	
		C. Breaker 30 amp		1			
		Floor bracket		1			
		Stickers tape		5			
SR No.				Labor			
Repair Done		Installation outdoor bracket unit for start-up, unit normal operation		Handling			
Repair Code				Others			
Date Attended		Oct. 14, 2022		Total		40	
Time Attended		12:20 pm		Amount Paid			
				Balance		40	
This serves as temporary receipt when properly filled up by authorized representative.		Check No.		Bank / Branch		for collection	
Serviced by:		By signing below, I allow KPII to collect, store & process my personal information as necessary to avail of service & fully understood that my personal information shall be used in accordance w/ Philippine Data Privacy Act & its implementing rules & regulations.					
TALAVERA		I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.					
Vale		Created by:		Conformed by:			
Technician(s)		RODEN PULONGBARIT		Customer			
		CSR		(Signature over printed name)			



Customer		Brighton Land Inc.		No.		Previous SJR No.		HO-00127921	
Address		Bun B. Reyes Ave. (LANDMARK: VICTORIA HOMES ELEMENTARY SCHOOL), OF MUNTINLUPA, Metro Manila...		Date		10-11-2022		10-11-2022	
Tel. No.				Start Time		10:26 pm			
Mobile No.		0997-8877513		End Time		12:34 pm			
Contact Person		SIR KIX		Relayed by		Engr. Ken			
Model		KSM DWID SLIM 1		Warranty Type		C			
S/N (I)		18532112-10460		Job Class		INST			
Dealer		CASHIER		Job Type		FD			
Installer		SUD-Manila Imperial Motor ...		Permit? <input type="checkbox"/> Parking? <input type="checkbox"/> Appointment? <input type="checkbox"/> O.R.? <input type="checkbox"/> Ladder? <input type="checkbox"/>					
Complaint		09/26/2022		Notes:		TALAVERA			
Before		After		No. of Visit		Tentative Sched			
Mode Setting (Cool)				1st Action		Findings		10/14/2022	
WAC Setting Temp(16°C-RE)/(10-ME)									
SAC/PAC   Setting Temp (17°)									
Discharge Temperature (High)									
Intake Temperature (High)						Recommendation			
Ampere				for installation outdoor unit					
WAC   Wattage (Inverter)									
Voltage									
SAC/PAC   Pressure									
Part Code		Description		Qty		Unit Price		Amount	
		h. coro 3.5mm x 30		7m		60		420	
		C. Barakur 20 mpy.		1					
		Floor bracket		1					
		Stainless type		5					
SR No.				Labor					
Repair Done		Installation outdoor unit / fan		Handling					
		Star - up		Others					
Repair Code				Total		420			
Date Attended		Oct. 14, 2022		Date Finished		Oct. 17, 2022		Amount Paid	
Time Attended		12:20 pm		Time Finished		1:40		Balance	
								420	
This serves as temporary receipt when properly filled up by authorized representative.		Check No.		Bank / Branch		for collect			
Serviced by:		By signing below, I allow KPII to collect, store & process my personal information as necessary to avail of service & fully understood that my personal information shall be used in accordance w/ Philippine Data Privacy Act & its implementing rules & regulations.							
TALAVERA		I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.							
Vale		Created by:		Conformed by:					
Technician(s)		RODEN PULONGBARIT		Customer					
		CSR		(Signature over printed name)					



Yellow - Guard / Claim Stub



Customer				Date			
Address Brighton Land Inc.  Don P. Reyes Ave. (LANDMARK: VICTORIA HOMES ELEMENTARY SCHOOL),				Start Time 10-11-2022			
Tel. No.				End Time CITY			
Mobile No.				Relayed by			
Contact Person				Warranty Type			
Model				Job Class			
S/N (I)				Job Type			
Dealer				Permit? <input type="checkbox"/> Parking? <input type="checkbox"/> Appointment? <input type="checkbox"/>			
Installer				O.R.? <input type="checkbox"/> Ladder? <input type="checkbox"/>			
Complaint				Notes:			
Before				Tentative Sched			
Mode Setting (Cool)				Findings			
WAC   Setting Temp (16°C-RE) (10-ME)							
SAC/PAC   Setting Temp (17°)							
Discharge Temperature (High)							
Intake Temperature (High)				Recommendation			
Ampere							
WAC   Wattage (Inverter)							
Voltage							
SAC/PAC   Pressure							
Part Code		Description		Qty	Unit Price	Amount	
		P. Board 3.5mm x 3L		77	Leo	\$ 420	
		Installation door bracket		1			
<div>Liquidated BY: [Signature] DATE: 10/17/2022</div>							
SR No.				Labor			
Repair Done		Installation outdoor unit (staff up. unit normal operation)		Handling			
Repair Code				Others			
Date Attended		Date Finished		Total		\$ 420	
Time Attended		Time Finished		Amount Paid			
This serves as temporary receipt when properly filled up by authorized representative.		Check No.		Balance		\$ 420	
		Bank / Branch		for collection - do			
Serviced by: Talavera Vale		By signing below, I allow KPII to collect, store & process my personal information as necessary to avail of service & fully understood that my personal information shall be used in accordance w/ Philippine Data Privacy Act & its implementing rules & regulations. I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.					
Technician(s) RODEN PUL CSRBARIT		Created by:		Conformed by:		Customer (Signature over printed name)	