

3. Start Up / Commisioning (per unit)				
3.1	Wall Mounted / Floor / Ceiling Type / Ceiling Cassette	STU01	2,500.00	n/a
3.2	Flex Match	STU02	3,000.00	n/a
4. Dismantling Fee				
4.1	1.0-3.0hp (wall mounted split-type – 1pair)	DIS01	2,500.00	n/a
4.2	2.5-5.0 tonner (floor mounted – 1 pair)	DIS02	3,000.00	n/a
4.3	2.0-5.0 tonner (floor ceiling / ceiling cassette – 1pair)	DIS03	3,500.00	n/a
4.4	Window Type		500.00	n/a
5. Mobilization				
5.1	Pull-out and delivery			
	5.1.1 within city limits	HND02	500.00	n/a
	5.1.2 outside city limits (1-25 kms)	HND06	700.00	n/a
	5.1.3 outside city limits (25 kms up)	HND07	800.00	n/a
5.2	Field Servicing			
	5.2.1 within city limits	n/a	n/a	n/a
	5.2.2 outside city limits (1-25 kms)	HND06	700.00	n/a
	5.2.3 outside city limits (25 kms up)	HND07	800.00	n/a
5.3	Deliver Remote Control	DEL05	150.00	n/a
6. Fabrication of Bracket				
6.1	Fabricate Bracket (IDU) – Ceiling Type	FAB01	1,500.00	n/a
6.2	Fabricate Bracket (ODU) – Floor Type	FAB02	2,500.00	n/a
6.3	Fabricate Bracket (ODU) – Wall Type	FAB03	5,000.00	n/a
6.4	Fabricate Bracket (ODU) – Catwalk Type	FAB04	6,500.00	n/a
6.5	Redesign Bracket (ODU)	FAB05	1,500.00	n/a
6. Chipping works for copper pipe line / lay-out (per meter)			500.00	n/a

Guidelines

1. Paid survey fee is deductible upon installation of unit
2. Paid check-up fee is deductible to succeeding repair;
 - 2.1 Succeeding repair occurs within three (3) months from check-up fee payment date
 - 2.2 Customer unit is for second (2nd) action of parts replacement

Prepared by:

Mr. Alvin C. de Rivera
Assistant Service Manager

Approved by:

Mr. Oliver M. Filoteo
Vice President – Finance / HRA