

JANUARY 15, 2020

RKH AIRCONDITIONING SERVICES
#54 A. MABINI ST. BRGY. MJ RIZAL MANDALUYONG CITY
0947-8419898

Sir/Ma'am;

Kindly see the quotation below for more details.

MODEL: KSM-10CBIINV

SJR: HO-5248

Part Code:	Parts Description	Qty	Amount	Total Amount
TK1014990220	Fan Capacitor 1.5uf	1	165.00	165.00
Repair Code	Repair Done	Labor		
SAC10	Labor			1,000.00
	Total:			1,165.00

Total Initial Charge:

P 1,165.00

Note:

1. *Replacement Of Fan Capacitor.*
2. Final charges will be based on actual repair of unit.
3. Repaired units are guaranteed for a period of 90 days (*Parts & Labor*) from date of unit acceptance and for the same encountered defects.
4. If you need assistance don't hesitate to call the under signed (*Angel Arlan De Torres*) at **852-6868 or 0917-806-0920.**
5. Once quotation is confirmed 50% downpayment needs to be deposit before proceeding for repair. However, problem(s) may occur once after or during replacement of part(s).
6. The remaining balance of 50% downpayment is to be paid to Kolin technician before installing the unit.
7. Confirmation must be complied on or before 2 days otherwise your unit will be delivered back to you.
8. *Initial Quotation.*

Prepared by:

ANGEL ARLAN DE TORRES
SHOP ASSISTANT

Noted by:

JOEL CORIA
SHOP FOREMAN

Verified by:

BRYAN JED O. ARCILLA
SERVICE ACCOUNTING ASST.

Conforme:

SIGNATURE OVER PRINTED NAME

NO DOWNPAYMENT

Head Office:

1854 Sta. Rita St., Guadalupe Nuevo, Makati City

www.kolinphil.com.ph

Tel.: (632) 851-2711, 12 or 15

Fax: (632) 852-2170 / Sales Dept. Fax: (632) 852-4791

Kolin Plant:

Blk 3 Lt 5 Main Drive, FCIE Compound: Brgy.

Langkaan I, Dasmariñas, Cavite

Tel.: (632) 749-2118

Fax: (046) 402-0793