

MR. JARRETT YAO 53 ISAGANI ST., BRGY. SAN JOSE, QUEZON CITY TEL#: 0917-8102158

Dear Ma'am/Sir.

Kolin Marketing Inc., is extremely honored for your endorsement of Kolin brand and we are please to offer you with a special price/s for the following items.

A. EQUIPMENT & INSTALLATION

** RECOMMENDATION

QTY	U/M	MODEL / DESCRIPTION	SRP	DISCOUNTED		AMOUNT
1	UNIT/S	MODEL: KLG-IF70-5G1M32 KOLIN FLOOR MOUNTED AIRCONDITIONER 61,200 Kj/h (5.0TR) FULL DC INVERTER R-32 SINGLE PHASE	173,995.00	127,716.10	PHP	127,716.10
TOTAL	UNIT COST				PHP	127,716.10
ESTIMA	TED COST O	F INSTALLATION (please see attached)			PHP	19,295.00
OTHERS	S: DELIVERY	CHARGE			PHP	600.00
TOTAL	ESTIMATED	COST OF THE PROJECT			PHP	147,611.10

** CUSTOMER'S CHOICE

QTY	U/M	MODEL / DESCRIPTION	SRP	DISCOUNTED		AMOUNT
1	UNIT/S	MODEL: KSG-IWF-30WFY-8K1M32 KOLIN WALL MOUNTED PRIMUS GOLD AIRCONDITIONER 29,500 Kj/h (3.0HP) FULL DC INVERTER W/ WIFI R-32	76,595.00	55,744.10	РНР	55,744.10
TOTAL	UNIT COST				PHP	55,744.10
ESTIMA	TED COST O	F INSTALLATION (please see attached)			PHP	13,795.00
OTHER:	S: DELIVERY	CHARGE			PHP	600.00
TOTAL	ESTIMATED	COST OF THE PROJECT			PHP	70,139.10

TERMS OF PAYMENT:

FULL PAYMENT OF UNIT AND DELIVERY CHARGE. IF CHECK, SUBJECT FOR 3 DAYS CLEARING.

WARRANTY:

FOR FLOOR MOUNTED: ONE (1) YEAR FREE PARTS AND LABOR, FIVE (5) YEARS WARRANTY ON COMPRESSOR. FOR SPLIT TYPE: ONE (1) YEAR FREE PARTS AND LABOR, THREE YEARS (3) MAIN PCB, TEN (10) YEARS WARRANTY ON COMPRESSOR.

NOTES: *** Need to sign waiver agreement due to under capacity of unit choice.

PRICES ARE SUBJECT TO CHANGE WITHOUT PRIOR NOTICE.

PRICES IS VAT INCLUSIVE.

We thank you for giving opportunity to offer our product and services, hoping we receive your purchase order.

If you need assistance, don't hesitate to call the under signed at 0917-807-8607 or email at kmi_asst@kolinphil.com.ph

Very Truly Yours,

JANELLEN SLIM KML-ASSISTANT

Noted by;

MART NA WIEL R. FLORES KMI-SUPERVISOR

KMI-QUOTE-09-24-0800 REG-22%/8K/4K

MS. EDITHA M. FLORES AVP - FINANCE

Conforme:

Kolin Marketing, Inc.

1854 Sta. Rita St., Guadalupe Nuevo, Makati City

Tel.: (632) 8852-6473

Fax: (632) 8852-2170 / (632) 8852-4792 www.kolinphil.com.ph / kolinphilippines





Customer Name : UXTYOT YAO Address :	Lilled Cah	WE OWNER	Date SJR	: 9-13 No.: 14	3 74
Establishment Type : Residential Commercial		Area Surveyed	-	THE MINE	46
Recommended Product Model:	- 150-5611 EXO MAENIDS	~37 (KSb-	IWF - 39	onta 8 KI	M32)
	Cooling Capacit		STAMES	CANT	
Floor Area: sqm. Ceiling Height: mtr.		per meter in excess ong capacity compute		the	
Floor Area:	<u></u>	x	550 Btu/h	D01700	Btu/h
Ceiling Height (excess of 3 mtrs.)	*	×	20%		Btu/h
Window Direct Sunlight		x	20% - 50%		Btu/h
		^	2070 - 0070	30	
Total Cooling Capacity				Luf too	Btu/h
Add : Additional Heat Load					
No. of Person	7	×	300 Btu/h	Hoo	Btu/h
No. of Ordinary Light (<40w)	2-5	_ ^ x	200 Btu/h	4000	Btu/h
No. of Special Light (>40w)		^	400 Btu/h	1000	Btu/h
No. of Refrigerator (< 6 cu.ft.)	3	^	400 Btu/h		Btu/h
No. of Refrigerator (> 6 cu.ft.)	- 1		800 Btu/h	1600	
No. of Cooking Range		_ x		1600	Btu/h
No. of Laptop Computer		x	1500 Btu/h		Btu/h
No. of Desktop Computer	1	'x	150 Btu/h 400 Btu/h	1/1/25	Btu/h
No. of Printer WARL DISTA SEL		_ x	500 Btu/h	400	Btu/h
No. of Photocopier MYCHANTYE		X	1000 Btu/h	1000	Btu/h
Total Cooling Capacity				ret ar	
rotal cooling capacity				700	Btu/h
Recommended Cooling Capacity				139300	Btu/h
Note : Compressor warranty will be reduce recommended cooling capacity or pip	d to yr. if air	-conditioner purchase d the maximum allov	ed is lower the	an the	
	Scope of Worl	Agreement			
Copper tube lay-out	Expose	Embedded			
2. Chipping	Included	Not Include	d		
3. Fabricated Bracket	Yes Sho		7No		
4. Service Ledge	Yes	No	1110		
5. Dismantling of existing Aircon	Included	Not Include	d		
6. Ducting	Yes	No			
Dimension :	7.03	LINO			
7. Plastering, carpentry and restoration work	re are to be done t	—			
8. Wiring of electrical supply from main pane			by the syste		
Processing of mechanical plan, working p					
10. Other concern; DKWATU	E XIM RE	CONTENT OF GOILE	WAIT-	/ ·	
CMST3WF2 V	RIMEST	1 HO NOR	1 PSTX	N. FY2	
				Charles State	

															000	000	
		france		-5	-6 -)		X	()							T
			-						1	1							-
	-										1	İ	1	<u> </u>		 	-
					1	AND WATER	4				<u> </u>	 		<u> </u>			
3	-8				F	CU						 -					-
											1						
	/	1									1.6			/	 		
	,	42	Ş					7						1			-
	3	7												<u>'</u>	 		
1		/							,						 ļ		
					3	<u> </u>		********)	reewst.	/				 		
						4									 		

Indoor Unit Location		PIGHT CORPTR OF XYEX. SXWE COXTLOS
Outdoor Unit Location		AT THE PAGE OF LIMITE, SAME LOXIDER
Pipe Length	:	D-17
Special Note	:	

	Installation Cost Estimate			
Material D	escription	Qty.	Unit Cost	Total Cost
Copper Tube (excess of 10 ft.)	2330, 2430, 2520, 3520, 4620	AT	400	18/00
Wire (Royal Cord-signal wire) (excess of	10ft.) 2.0mmx4C	1/2	1/000	1000
Wire (Royal Cord - Breaker to ODU)	3.5mm / 5.5mm x 3C	74	1000	1110
Circuit Breaker	20A, 30A, 40A/1ph, 40A/3ph	1777	1000	7000
Bracket (ODU)	(Imptd. / Fabricated); (Floor / Wall)	Maria de la companya		1000
Bracket (WAC)	Angle Type			
PVC Pipe (drain)	1/2" , 3/4"			
PVC Pipe (electrical)	3/4" , 1"		 	
Drain Pump	JH , 1			
Drain Pump Hose WING		J.F. Fr	17.	FVC
Chipping Works	mtr.	111	14	175
Dismantling Fee (existing air-conditioner)	Z Ans	1		145 (5)
Initial Charge	711			500
	TOTAL EST	MATE	P 1376	7(-

Note:

- Initial Charge includes labor, 10ft. Copper tube, 10ft. Royal cord, Circuit breaker, Outdoor Bracket (SAC), Indoor Bracket (PAC) and Consumable materials.
- 2. Survey fee will be deducted in the installation fee.

Prepared by:

Signature Over Printed Name

Customer Conforme:

Signature Over Printed Name

SEPTEMBER 13, 2024 JARRET YAO 53 Isagani St. Brgy. San Jose, Quezon City

Please be informed that the air-conditioner you intend to purchase is under capacity as compared to the following unit that we proposed:

Location Area		Kolin's Recommendation	Customer's Choice	Remarks		
LIVING DINING	54 sam	KLG-IF70-5G1M32	KSG-IWE-30WEY8K1M32	Calculated 4.3hp		
LIVING DIVING	34 Sqiii	KEG-1F70-3G11VI32	K3G-1WF-30WF16K1W32	under by 1.3hp		

Since the unit of your choice is under capacity, it is probable that you may experience the following;

- 1. Capacity of the unit to cool the area will take longer or it will not cool the area at all that may lead to your dissatisfaction with the cooling performance of our unit.
- 2. Power consumption will be higher due to frequent running of compressor for not reaching the desired temperature within the normal parameter.
- 3. Useful life of compressor will be shortened due to excessive running beyond the normal run cycle.

Considering the above conditions, we regret to inform you that we cannot guarantee the efficient performance of unit. Also, One (1) year warranty for parts (compressor-1year).

For your guidance and information

Prepared by:

Jeoffrey T. Dadios

Surveyor

Approved by:

Sept.16,2024

Mr. Alvin de Rivera Service Manager Noted by:

Engr. Kerneth Zamora Service Supervisor - Field

and Shop Operation

Customer Conforme:

Signature Over Printed Name