

MR. STEVE ROMASATA
UNIT 3002 PARK TRIANGLE RES. 32nd ST. COR. 11th AVE. BRGY. FORT BONIFACIO, TAGUIG CITY
TEL#: 0917-5326738 / 0917-7001574
Email: ruliboro@gmail.com

Dear Ma'am/Sir,

Kolin Marketing Inc., is extremely honored for your endorsement of Kolin brand and we are please to offer you with a special price/s for the following items.

A. EQUIPMENT & INSTALLATION

QTY	U/M	MODEL / DESCRIPTION	SRP	DISCOUNTED		AMOUNT
1	UNIT/S	MODEL: KSM-IW25-WCT10M1M32 KOLIN WALL MOUNTED CERTUS AIRCONDITIONER 23,210 Kj/h (2.5HP) REGULAR INVERTER W/ WIFI R-32	49,995.00	34,996.10	PHP	34,996.10
1	UNIT/S	MODEL: KSM-IW20-WCT10M1M32 KOLIN WALL MOUNTED CERTUS SERIES AIRCONDITIONER 18,990 Kj/h (2.0HP) REGULAR INVERTER R-32	41,995.00	28,756.10	PHP	28,756.10
2	UNIT/S	MODEL: KSM-IW10-WCT10M1M32 KOLIN WALL MOUNTED CERTUS SERIES AIRCONDITIONER 9,800 Kj/h (1.0HP) REGULAR INVERTER R-32	29,995.00	19,396.10	PHP	38,792.20
TOTAL		PHP	102,544.40			
ESTIMATED COST OF INSTALLATION (please see attached)						45,200.00
OTHERS: DELIVERY CHARGE						600.00
TOTAL ESTIMATED COST OF THE PROJECT						148,344.40

TERMS OF PAYMENT:

FULL PAYMENT OF UNIT AND DELIVERY CHARGE. IF CHECK, SUBJECT FOR 3 DAYS CLEARING.

WARRANTY:

FOR SPLIT TYPE: ONE (1) YEAR FREE PARTS AND LABOR, THREE YEARS (3) MAIN PCB, TEN (10) YEARS WARRANTY ON COMPRESSOR.

NOTES: *** Need to sign waiver agreement due to under capacity of unit choice.

PRICES ARE SUBJECT TO CHANGE WITHOUT PRIOR NOTICE.

PRICES IS VAT INCLUSIVE.

We thank you for giving opportunity to offer our product and services, hoping we receive your purchase order.

If you need assistance, don't hesitate to call the under signed at 0917-807-8607 or email at kmi_asst@kolinphil.com.ph

Very Truly Yours,

JANELLEN S LIM

Noted by:

MART MAN HANGEL R. E.

KMI-QUOTE-10-24-0862 REG-22%/4K MS. EDITHA M. FLORES

AVP - FINANCE

Conforme:

JOSEPIASTEVE C. R<mark>OMASANT</mark>A

SIGNATURE OVER PRINTED NAME

Kolin Marketing, Inc.

1854 Sta. Rita St., Guadalupe Nuevo, Makati City

Tel.: (632) 8852-6473

Fax: (632) 8852-2170 / (632) 8852-4792 www.kolinphil.com.ph / kolinphilippines

OCTOBER 07, 2024 STEVE ROMASANTA

Unit 3002 Park Triangle Res. 32nd St. Cor 11th Ave. Brgy Fort Bonifacio, Taguig City 0917 532 6738

ruliboro@gmail.com / viber 0917-7001574

MODEL

Qty

KSM-IW25-WCT10M1M32 1 KSM-IW20-WCT10M1M32 1 KSM-IW10-WCT10M1M32 2

REV1 -CERTUS

	/DINING/KITCHEN					Area	47	sqm
ACU 1	2.5HP Wall Mounted inverter	KSM-IV	V25-	WCT0M1M32				
	Estimated Pipe Length =							
	Estimated Royal Cord Length =							
	Initial Charge						P	7,500.00
	Includes:							
	Labor							
	10ft Copper Tube							
	10ft Royal Cord							
	Outdoor Bracket (Floor)							
	Consumables							
	Installation Materials Description		Qty	Pri	ce per qty	Subtotal		
	Royal Cord (ACCU-Breaker)	3.5mm x 3C	5 ft	P	60.00/ft	₱ 300.00		
	Leaktest	1/4" x 1/2"	1 set	P	1,800.00/set	P 1,800.00		
	Circuit Breaker waterproof	20hp /1ph	1 pc/s	P	1,000.00/pc	₱ 1,000.00	P	3,100.00
	Estimated Charges	and several advisery of the se					P	10,600.00
BEDRO	DOM1					Area	10	sqm
CU 2	1.0HP Wall Mounted inverter		16011.0	V40	WCT10M1M32			
400 2	1.0111 Wall Mounted Inventer		KSIVI-IV	V 1 U-				
		10 ft	KSM-IV	<i>V</i> / U-				
		4 02000 4500	KSM-W	V 10-				
	Estimated Pipe Length =	4 02000 4500	KSM-IV	<i>V</i> 10-			P	7,500.00
	Estimated Pipe Length = Estimated Royal Cord Length :	4 02000 4500	KSM-IV	V 10-			P	7,500.00
	Estimated Pipe Length = Estimated Royal Cord Length : Initial Charge	4 02000 4500	KSM-IV	V 10-			P	7,500.00
	Estimated Pipe Length = Estimated Royal Cord Length = Initial Charge Includes:	4 02000 4500	KSM-IV	¥10-			P	7,500.00
	Estimated Pipe Length = Estimated Royal Cord Length : Initial Charge Includes: Labor	4 02000 4500	KSM-IV	¥10-			P	7,500.00
	Estimated Pipe Length = Estimated Royal Cord Length : Initial Charge Includes: Labor 10ft Copper Tube 10ft Royal Cord	4 02000 4500	KSM-IV	V 10-			P	7,500.00
	Estimated Pipe Length = Estimated Royal Cord Length : Initial Charge Includes: Labor 10ft Copper Tube	4 02000 4500	KSM-IV	V 10-			P	7,500.00
	Estimated Pipe Length = Estimated Royal Cord Length : Initial Charge Includes: Labor 10ft Copper Tube 10ft Royal Cord Outdoor Bracket (Floor)	4 02000 4500			ice per qty	Subtotal	P	7,500.00
	Estimated Pipe Length = Estimated Royal Cord Length : Initial Charge Includes: Labor 10ft Copper Tube 10ft Royal Cord Outdoor Bracket (Floor) Consumables	= 10 ft		Pri		Subtotal 300.00	P	7,500.00
	Estimated Pipe Length = Estimated Royal Cord Length : Initial Charge Includes: Labor 10ft Copper Tube 10ft Royal Cord Outdoor Bracket (Floor) Consumables Installation Materials	= 10 ft Description	Qty	Pri	ice per qty		P	7,500.00
	Estimated Pipe Length = Estimated Royal Cord Length : Initial Charge Includes: Labor 10ft Copper Tube 10ft Royal Cord Outdoor Bracket (Floor) Consumables Installation Materials Royal Cord (ACCU-Breaker)	Description 3.5mm x 3C	Qty 5 ft	Pri	ice per qty 60.00/ft	₱ 300.00		7,500.00

BEDRO	BEDROOM2				Area			12	sqm
ACU 3	1.0 HP Wall Mounted Inverter	KSG-IV	KSG-IWF-10WFY8K1M32						
	Estimated Pipe Length =								
	Estimated Royal Cord Length	= 10 ft							
	Initial Charge							P	7,500.00
	Includes:								
	Labor								
	10ft Copper Tube								
	10ft Royal Cord								
	Outdoor Bracket (Floor)								
	Consumables								
	Installation Materials	Description	Qty	Pri	ice per qty	Si	ubtotal		
	Royal Cord (ACCU-Breaker)	3.5mm x 3c	5 ft	P	60.00/ft	P	300.00		
	Circuit Breaker waterproof	20hp /1ph	1 pc/s	P	1,000.00/pc	P	1,000.00		
	Leaktest	1/4" x 3/8"	1 set	P	1,800.00/set	P	1,800.00		
	Outdoor bracket	Fabricated floor	1 pc/s	P	2,500.00/pc	P	2,500.00		
	PVC blue	3/4" x 10'	2 pc/s	P	150.00/pc	P	300.00	P	5,900.00
	Estimated Charges							P	13,400.00
MASTE	IASTER BEDROOM						Area	20	sqm
ACU 4	2.0 HP Wall Mounted Inverter		KSG-IV	VF-2	OWFY8K1M32				
	Estimated Pipe Length =								
	Estimated Royal Cord Length								
	Initial Charge							P	7,500.00
	Includes:								
	Labor								
	10ft Copper Tube								
	10ft Royal Cord								

Estimated Charges P 10,600.00

5 ft ₱

1 set ₱

1 pc/s P

Qty Price per qty

60.00/ft

1,000.00/pc 1,800.00/set Subtotal

₱ 300.00

₱ 1,000.00

₱ 1,800.00

₱ 3,100.00

Description

3.5mm x 3c

30hp /1ph


1/4" x 1/2"

Outdoor Bracket (Floor) Consumables Installation Materials

Royal Cord (ACCU-Breaker)

Circuit Breaker waterproof

Leaktest



Validity: This quotation is valid for a period of fifteen (15) days from the date thereof, subject to our confirmation thereafter.

Installation notes:

- 1 Location of indoor and outdoor units were agreed by the customer and Kolin's surveyor.
- 2 AC drain line will be tapped to the nearest drain provision provided by the customer's contractor.
- 3 Upon approval schedule pressure leaktest of existing coppertube, if pressure drops, recommends to lay out new copper
- 4 Bring the fabricated bracket for bedroom1. fabricated from shop.
- 5 BEDROOM 2 drainline need to adjust lower to 4 inches.
- 6 Working days: Monday to Saturday, 8am-5pm with parking. Need working permit.
- 7 Mechanical Plans, Permits, Electrical permits not included.
- 8 Deflectors, masonry, carpentry, chipping & plastering (finishing & restoration) are not included in the installation.
- 9 Air conditioning drain line and Electrical power supply (feeder line) 220v/60hz/1ph, should be provided by customer's contractor

10 Final charges will be based on actual installation.

Prepared by:

Jeoffrey Dadios Field Surveyor

Reviewed by:

Engr Kenneth Zamora Service Supervisor Shop and Field Operation

Custom

ROMASANTA Signature Over Printed Name

October 7, 2024 STEVE ROMASANTA Unit 3002 Park Triangle Res. 32nd St. Cor 11th Ave. Brgy Fort Bonifacio, Taguig City 0917 532 6738 ruliboro@gmail.com / viber 0917-7001574

Please be informed that the air-conditioner you intend to purchase is under capacity as compared to the following unit that we proposed:

Location	Area	Kolin's Recommendation	Customer's Choice	Remarks		
LIVING/DINING	47 sam	KSM-IW20-WCT10M1M32	KSM-IW25-WCT10M1M32	Calculated 3.6hp		
LIVING/DINING	47 34111	2 UNITS	K3IVI-IVV23-VVCI IOIVIIIVI32	under by 1.1hp		

Since the unit of your choice is under capacity, it is probable that you may experience the following;

- 1. Capacity of the unit to cool the area will take longer or it will not cool the area at all that may lead to your dissatisfaction with the cooling performance of our unit.
- 2. Power consumption will be higher due to frequent running of compressor for not reaching the desired temperature within the normal parameter.
- 3. Useful life of compressor will be shortened due to excessive running beyond the normal run cycle.

Considering the above conditions, we regret to inform you that we cannot guarantee the efficient performance of unit. Also, One (1) year warranty for parts (compressor wty - VOID).

For your guidance and information

Prepared by:

Noted by:

Jeoffrey Dadios

Surveyor

Engr. Kenneth Zamora Service Supervisor - Field

and Shop Operation

Approved by:

Customer Conforme:

Mr. Alvin de Rivera Service Manager Signature Over Printed Name