



## KOLIN PHILIPPINES INTERNATIONAL INC.

1854 Sta. Rita St., Guadalupe Nuevo,  
1212 Makati City  
EMAIL ADDRESS: [inhouse.shop@kolinphil.com.ph](mailto:inhouse.shop@kolinphil.com.ph)  
TEL.: (02)8-9625610  
MOBILE: (+63)9178060920

### REPAIR COST ESTIMATE

**CUSTOMER:**  
**MONACO PLANT 1**  
NY COMPOUND LUGMOK RD. BRGY.  
BAGBAGUIN CALOOCAN CITY, METRO MANILA  
TEL#: 8365-4562 loc. 210 / 224  
MOBILE: 0956-8197074

DATE:	JANUARY 30, 2025
SJR #:	HO-00239586
MODEL:	KAG-120RS
DOP:	N/A
SERIAL#:	N/A

#### TERMS AND CONDITION

1. The repair will proceed after indicating acceptance of this quote with 50% downpayment.
2. Customer shall conform within 2 working days otherwise unit will be considered refuse to repair hence, unit will be delivered back un-repaired with fitting charges.
3. Kindly deposit your 50% down-payment to the bank account: Reference SJR# HO-00239586 (Not Bills Payment)

#### BDO

Account Name: Kolin Philippines International Inc.

Account Number: 0118-0800-0428

4. Should any additional work or materials be found necessary in the course of these repairs or subsequent testing, it will be necessary to make an extra charge. Where this additional work involves a substantial increase in the amount estimated, a supplementary estimate will be submitted for acceptance.
5. Repaired units are guaranteed for a period of 90 days (*Parts & Labor*) from date of unit acceptance and for the same encountered defects.
6. If you have any questions about this price quote, please contact under signed *Paolo Jose Lu* (02)8-9625610 or (+63)9178060920 and "inhouse.shop@kolinphil.com.ph".
7. Payment of remaining 50% balance will be due upon delivery/pick-up of unit.
8. Please email the signed price quote to the address above.

*Customer Acceptance and return. (sign below)*

X

Print Name:

DESCRIPTION	AMOUNT
[LABOR] System Reprocess + General Cleaning (Parts Replacement/ Dirty Unit)	P 2,600.00
[PARTS] Evaporator (Leaking)	P 3,300.00
[PARTS] Metal Partition /Condenser Side/ (Rusted)	P 660.00
[PARTS] Metal Partition /Evaporator Side/ (Rusted)	P 770.00
[PARTS] Fan Motor Bracket (Rusted) PARTS NOT AVAILABLE	P 0.00
[PARTS] Top Cover(Rusted) PARTS NOT AVAILABLE	P 0.00
Handling Fee within Metro Manila	P 500.00
SUBTOTAL	P 7,830.00
GRAND TOTAL	P 7,830.00

Prepared by:

PAOLO JOSE LU  
SHOP ASSISTANT

Noted by:

ENGR. KENNETH ZAMORA  
SERVICE SUPERVISOR


Reviewed by:

GARIE PUIG  
SHOP FOREMAN

20% - parts

10% - Labor

2/14/25



Kolin Philippines Int'l, Inc.

Plant and Head Office:  
Blk 3 Lt 5 Main Drive, FCIE Compound,  
Brgy. Langkaan I, Dasmariñas, Cavite  
Tel: (632) 8749-2118  
Fax (046) 402-0793  
[www.kolinphil.com.ph](http://www.kolinphil.com.ph) / [kolinphilippines](http://kolinphilippines)

Operation Office:  
1854 Sta. Rita St, Guadalupe Nuevo,  
Makati City  
Tel: (632) 8851-2711, 12 or 15  
Fax: (632) 8852-2170  
Sales Dept. Fax: (632) 8852-4791