

August 2, 2024

MS. CECILLE RIVERA 21 STA. FE ST., KAPITOLYO, PASIG CITY TEL #: 0998-5592167

Dear Ma'am/Sir,

Kolin Marketing Inc., is extremely honored for your endorsement of Kolin brand and we are please to offer you with a special price/s for the following items.

A. EQUIPMENT & INSTALLATION

QTY	U/M	MODEL / DESCRIPTION	SRP	DISCOUNTED		AMOUNT
1	UNIT/S	MODEL: KSM-IW15-WCT10M1M32 KOLIN WALL MOUNTED CERTUS SERIES AIRCONDITIONER 12,660 Kj/h (1.5HP) REGULAR INVERTER R-32	32,995.00	21,736.10	РНР	21,736.10
TOTAL UNIT COST						21,736.10
ESTIMATED COST OF INSTALLATION (please see attached)						12,765.00
OTHERS: DELIVERY CHARGE						600.00
TOTAL ESTIMATED COST OF THE PROJECT						35,101.10

TERMS OF PAYMENT:

FULL PAYMENT OF UNIT AND DELIVERY CHARGE. IF CHECK, SUBJECT FOR 3 DAYS CLEARING.

WARRANTY:

FOR SPLIT TYPE: ONE (1) YEAR FREE PARTS AND LABOR, THREE YEARS (3) MAIN PCB, TEN (10) YEARS WARRANTY ON COMPRESSOR.

NOTES: PRICES ARE SUBJECT TO CHANGE WITHOUT PRIOR NOTICE.

PRICES IS VAT INCLUSIVE.

** Cost of Installation is Package with the Unit(s), this cost cannot avail separately.

We thank you for giving opportunity to offer our product and services, hoping we receive your purchase order.

If you need assistance, don't hesitate to call the under signed at 0917-807-8607 or email at kmi_asst@kolinphil.com.ph

Very Truly Yours,

JANELLEN S. LIM KMI-ASSISTANT

Noted by:

MART NATHANIEL R. FLORES

KMI-SUPERVISOR

KMI-QUOTE-08-24-0688 REG-22%/4K

Kolin Marketing, Inc.

1854 Sta. Rita St., Guadalupe Nuevo, Makati City

www.kolinphil.com.ph Tel.: (632) 8852-6473

Fax: (632) 8852-2170 / (632) 8852-4792

Approved By:

MS. EDITHA M. FLORES

AVP - FINANCE

Conforme:

SIGNATURE OVER PRINTED NAME

Bringing comfort to your home.

KOLIN Philippines International Inc. Survey Form

Nº 003508

Establishment Type : Residential		Area Surveyed		THE BAD	Poor
Commercial	Ma Alvila's bla	Area Surveyed	1:		
Recommended Product Model :	M-IMIZ - MS	-11 up 17 132			
	Cooling Capacity	Computation		22	
Floor Area: Colling Height: Sqm. Sqm.	note: add 20% per initial cooling	meter in excess capacity computer		the	• •
Floor Area :	(4)	x	550 Btu/h	A00	Btu/h
Ceiling Height (excess of 3 mtrs.):		x	20%		Btu/h
Vindow Direct Sunlight		x	20% - 50%		Btu/h
otal Cooling Capacity				7760	Btu/h
Add : Additional Heat Load					
lo. of Person	2	×	300 Btu/h	1600	Btu/h
lo. of Ordinary Light (<40w)		×	200 Btu/h	200	Btu/h
lo. of Special Light (>40w)		×	400 Btu/h		Btu/h
lo. of Refrigerator (< 6 cu.ft.)		×	400 Btu/h		Btu/h
lo. of Refrigerator (> 6 cu.ft.)		. x	800 Btu/h		Btu/h
lo. of Cooking Range		x	1500 Btu/h	Salara Salara	Btu/h
lo. of Laptop Computer		×	150 Btu/h		Btu/h
lo. of Desktop Computer	11-1	×	400 Btu/h	800	Btu/h
lo. of Printer	I amount of	×	500 Btu/h	Joo	Btu/h
lo, of Photocopier		×	1000 Btu/h		Btu/h
otal Cooling Capacity				D / (Q), (6)	Btu/h
otal Cooling Capacity				1.1	Diani
Recommended Cooling Capacity				7200	Btu/h
Note: Compressor warranty will be reduce recommended cooling capacity or p	ipe lay-out is beyond i	the maximum allo		an the	
	Scope of Work	Agreement			
1. Copper tube lay-out	Expose	Embedded	d		
2. Chipping	Included .	Not Includ			
3. Fabricated Bracket	Yes Shop	Site /	No -		
1. Service Ledge	Yes	No			
5. Dismantling of existing Aircon	Included	Not Includ	ed _		
5. Ducting	Yes	No			
Dimension :					
Plastering, carpentry and restoration wo	rks are to be done by	the customer.			
	nel to air-conditioning	unit are to be dor	ne by the custo	mer.	
Wiring of electrical supply from main pa		mit are to be done	by the custom	ner.	
9. Processing of mechanical plan, working					
3. Wiring of electrical supply from main particles 9. Processing of mechanical plan, working 10. Other concern; DISWART		HOTTAN 1	OF HEN		

																35
	+													 		
	<u> </u>	ļ		ļ										 		
											1					
1	1			1												
	+		ļ						11 1		 					
	<u> </u>		/	-			-	West Table	11.		ļ	ļ		 		
1			1	-				ΞĎ	7							
	1	3:	1					1.6								
	+			-			1	15			†	1		 		
			ļ,				1				 			 		
	1			1	- 4	ļ -	1				1			 		
							-								. 4.	
	+		1	 	1					 	†			 		
			ļ	ļ	ļ		ļ	ļ			 			 		
											ļ		ļ	 		
	+	 	1	1	†		1	<u> </u>			İ	1				
		-	1	-	1	16. 12	1	1		1	1_	1	1			<u> </u>

Indoor Unit Location

Outdoor Unit Location

Pipe Length

Special Note

INTOF DONE, SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SAME CONTROL

SA

Material Description	Qty.	Unit Cost	Total Cost
Copper Tube (excess of 10 ft.) 2330, (2430,) 2520, 3520, 4620	州	1:350	491
Wire (Royal Cord-signal wire) (excess of 10ft.) 2.0mmx4C	9 m	1100	940 9
Wire (Royal Cord - Breaker to ODU) 3.5mm / 5.5mm x 3C	TATI	1.00	740
Circuit Breaker 20A, 30A, 40A/1ph, 40A/3ph			
Bracket (ODU) ([mptd] / Fabricated); (Floor / Wall)			1998
Bracket (WAC) Angle Type			
PVC Pipe (drain) 1/2", 3/4"	1	170	HO.
PVC Pipe (electrical) 3/4", 1"	Control of the second		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
Drain Pump		100	1
Drain Pump Hose WHATO //	7	1 M	IP
Chipping Works Mr.	Service 1		A
Dismantling Fee (existing air-conditioner)			1300
Initial Charge			1+100

Note

 Initial Charge includes labor, 10ft. Copper tube, 10ft. Royal cord, Circuit breaker, Outdoor Bracket (SAC), Indoor Bracket (PAC) and Consumable materials.

2. Survey fee will be deducted in the installation fee.

Prepared by:

Signature Over Printed Name

Customer Conforme:

Signature Over Printed Name