



20-Aug-2024

PATTS COLLEGE OF AERONAUTICS  
ATTN: MS. GLORIA MACALALAD  
LOMBOS ST., BRGY. SAN ISIDRO, PARAÑAQUE CITY  
TEL: 0933-8120909/0995-3650589

Sir/ Madam,

This is to bill you on the service job done to your unit for the month of JULY 2024.  
Details of the charges are stated below and a copy of the Service Job Report is attached for your references:


DATE ATTENDED	SJR #	QUANTITY/MODEL	SERVICE JOB DONE	AMOUNT
05-Jul-24	HO-00211486	(1) KSM-SW25-6H1M32-I	INSTALLATION	9,910.00
05-Jul-24	HO-00211751	(1) KSM-SW25-6H1M32-I	INSTALLATION	9,510.00
05-Jul-24	HO-00211752	(1) KSM-SW25-6H1M32-I	INSTALLATION	9,110.00
05-Jul-24	HO-00211753	(1) KSM-SW25-6H1M32-I	INSTALLATION	9,510.00
05-Jul-24	HO-00211763	(1) KSM-SW25-6H1M32-I	INSTALLATION	9,110.00
05-Jul-24	HO-00211767	(1) KSM-SW25-6H1M32-I	INSTALLATION	9,510.00
05-Jul-24	HO-00211769	(1) KSM-SW25-6H1M32-I	INSTALLATION	9,910.00
05-Jul-24	HO-00211771	(1) KSM-SW25-6H1M32-I	INSTALLATION	9,510.00
05-Jul-24	HO-00211772	(1) KSM-SW25-6H1M32-I	INSTALLATION	9,910.00
05-Jul-24	HO-00211773	(1) KSM-SW25-6H1M32-I	INSTALLATION	9,610.00
05-Jul-24	HO-00211775	(1) KSM-SW25-6H1M32-I	INSTALLATION	9,910.00
05-Jul-24	HO-00211777	(1) KSM-SW25-6H1M32-I	INSTALLATION	9,910.00
05-Jul-24	HO-00211782	(1) KSM-SW25-6H1M32-I	INSTALLATION	21,160.00
TOTAL AMOUNT DUE				<u><u>P. 136,580.00</u></u>

For any clarifications please feel free to call the Undersigned at the telephone number **8852-6473**


**Note:** If check payment, please prepare check payable to **Kolin Philippines International Inc.**  
**Account #: BDO - KALAYAAN 011808000428**

**Note:** In case thru Bank Deposit under BDO Account, kindly indicate SJR# for your Bank Reference in the deposit slip and Fax to **(632) 8852-6473** or E-mail to: **kmi\_asst@kolinphil.com.ph**

Prepared by:

  
**Janellen S. Lim**  
KMI - Assisitant

Noted by:

  
**Mart Nathaniel R. Flores**  
KMI - Supervisor

Received by:

Signature over printed name



**K Kolin Philippines Int'l., Inc.**

Plant and Head Office:  
Blk 3 Lt 5 Main Drive, FCIE Compound,  
Brgy. Langkaan I, Dasmariñas, Cavite  
Tel: (632) 8749-2118  
Fax (046) 402-0793  
 [www.kolinphil.com.ph](http://www.kolinphil.com.ph) / [kolinphilippines](http://kolinphilippines)





Operation Office:  
1854 Sta. Rita St., Guadalupe Nuevo,  
Makati City  
Tel.: (632) 8851-2711, 12 or 15  
Fax: (632) 8852-2170  
Sales Dept. Fax: (632) 8852-4791



Customer		Patts College Of Aeronautics		Date		07-01-2024	
Address		Lombos St., Brgy. San Isidro, PARAÑAQUE CITY, Metro Manila		Start Time		05:13 pm	
				End Time		05:16 pm	
Telephone No.		8825-8823 / 8825-8824		Mobile No.		0933-8120909 / 0995-36505	
Contact Person		Gloria Macalalad		Mobile No.		0933-8120918	
Warranty Code				Room Size			
Model		KSM-SW25-6H1M32-J		Call Origin		IO	
S/N (I)		16292301-10688		S/N (O)		16302301-10855	
Dealer		KMI		DOP		06/24/2024	
Installer				Complaint		For installation	
Location		OFFICE OF STUDENT AFFAIRS		Before		After	
Mode Setting (Cool)				No. of Visit		1st Action	
WAC   Setting Temp(16°C-RE)/(10/12-ME)				Tentative Sched		07/04/2024	
SAC/PAC   Setting Temp (17°)				Findings			
Discharge Temperature (High)							
Intake Temperature (High)							
Ampere				Recommendation			
Wattage (Inverter)							
Voltage							
SAC/PAC   Pressure (PSI)							
Part Code		Description		Qty		Unit Price	
		Processing fee agreement #					
		NO: 2024-07-378					
SR No.				Labor			
Repair Done		Findings - Ongoing installation, Recommendation - , Repair Done -		Handling			
		Done installation		Others			
Repair Code		CHIR-3		Total			
Date Attended		07/05/2024 - 07-01-24		Date Finished		07/05/2024 - 07-20-2024	
Time Attended		12:00 am		Time Finished		12:00 am	
This serves as temporary receipt when properly filled up by authorized representative.		Check No.		Bank / Branch			
Serviced by: NVFS		By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.					
		I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.					
		Created by:		Conformed by:			
Technician(s)		GRACE PIELAGO CSR		Customer (Signature over printed name)			





1854 Sta. Rita St., Guadalupe Nuevo, Makati City  
Tel. No.: 8852-6868 / Mobile: 0917-811-8982 / Email: [service@kolinphil.com.ph](mailto:service@kolinphil.com.ph)  
Website: [www.kolinphil.com.ph](http://www.kolinphil.com.ph)     [kolinphilippines](https://www.youtube.com/kolinphilippines)

## SERVICE JOB REPORT

[illegible]





No.  
Previous SJR No.

SVC-SJR-02-020123

White - Customer

Blue - Accounting

Green - Service



Customer		Patts College Of Aeronautics		Date		HO-00211753	
Address		Lombos St., Brgy. San Isidro, PARAÑAQUE CITY, Metro Manila		Previous SJR No.		HO-00195437	
Telephone No.		8825-8823 / 8825-8824		Mobile No.		0933-8120909 / 0995-365058	
Contact Person		Mobile No.		Tel. No.		Warranty Type	
Warranty Code		Room Size		Job Class		INST LVL 2	
Model		KSM-SW25-6H1M32-I		Call Origin		Job Type	
S/N (I)		16292202-10360		S/N (O)		16302311-10661	
Dealer		KMI		DOP		06/20/2024	
Installer		NVFS		Complaint		For Installation	
Location		AERO LECTURE ROOM 47 SQM. L...		Before		After	
Mode Setting (Cool)				No. of Visit		1st Action	
WAC   Setting Temp(16°C-RE)/(10/12-ME)				Tentative Sched		07/04/2024	
SAC/PAC   Setting Temp (17°)				Findings			
Discharge Temperature (High)							
Intake Temperature (High)							
Ampere				Recommendation			
Wattage (Inverter)							
Voltage							
SAC/PAC   Pressure (PSI)							
Part Code		Description		Qty		Unit Price	
		PF. NO. 2024-07-0378					
SR No.				Labor			
Repair Done		Findings - Installation, , Recommendation - for installation, , Repair Done - done		Handling			
Repair Code		SAC18-3 - Installation - 2.5HP - 3.0HP Inverter and Non Inverter (includes 10ft. copper tube, 10ft. royal cord, rubber insulation, ordinary bracket, drainhose / PVC drain pipe 3/4")		Total			
Date Attended		07/05/2024		Amount Paid			
Time Attended		12:00 am		Balance			
This serves as temporary receipt when properly filled up by authorized representative.		Check No.		Bank / Branch			
Serviced by: NVFS		By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.					
		I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.					
Technician(s)		Created by: GRACE PIELAGO CSR		Conformed by: Customer (Signature over printed name)			





1854 Sta. Rita St., Guadalupe Nuevo, Makati City  
Tel. No.: 8852-6868 / Mobile: 0917-811-8982 / Email: [service@kolinphil.com.ph](mailto:service@kolinphil.com.ph)  
Website: [www.kolinphil.com.ph](http://www.kolinphil.com.ph)     [kolinphilippines](#)

## SERVICE JOB REPORT

[illegible]



Customer		Patts College Of Aeronautics		Date		07-02-2024	
Address		Lombos St., Brgy. San Isidro, PARAÑAQUE CITY, Metro Manila		Start Time		03:04 pm	
				End Time		03:10 pm	
Telephone No.		8825-8823 / 8825-8824		Mobile No.		0933-8120909 / 0995-365058	
Contact Person		Mobile No.		Tel. No.		Warranty Type	
Warranty Code				Room Size		Job Class	
Model		KSM-SW25-GH1M32-I		Call Origin		IO	
S/N (I)		16292203-10176		S/N (O)		16302203-10150	
Dealer		KMI		DOP		06/20/2024	
Installer		NVFS		Complaint		For Installation	
Location		AIRFRAME LECTURE ROOM 4750...		Before		After	
Mode Setting (Cool)				No. of Visit		1st Action	
WAC   Setting Temp(16°C-RE)/(10/12-ME)				Findings		Tentative Sched	
SAC/PAC   Setting Temp (17°)						07/04/2024	
Discharge Temperature (High)							
Intake Temperature (High)							
Ampere						Recommendation	
Wattage (Inverter)							
Voltage							
SAC/PAC   Pressure (PSI)							
Part Code		Description		Qty		Unit Price	
		PF: NO. 2024-07-0378					
SR No.				Labor			
Repair Done		Findings - Installation, , , Recommendation - for installation, , , Repair Done - done installation		Handling			
Repair Code		SAC18-3 - Installation - 2.5HP - 3.0HP Inverter and Non Inverter (includes 10ft. copper tube, 10ft. royal cord, rubber insulation, ordinary bracket, drainhose / PVC drain pipe 3/4")		Total			
Date Attended		07/05/2024		Date Finished		08-05-24	
Time Attended		12:00 am		Time Finished		12:00 am	
This serves as temporary receipt when properly filled up by authorized representative.		Check No.		Bank / Branch			
Serviced by: NVFS		By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.					
		I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.					
Technician(s)		Created by: GRACE PIELAGO CSR		Conformed by: Customer (Signature over printed name)			



Customer		Pats College Of Aeronautics		Date		07-02-2024	
Address		Lombos St., Brgy. San Isidro, PARAÑAQUE CITY, Metro Manila		Start Time		03:10 pm	
				End Time		03:14 pm	
Telephone No.		8825-8823 / 8825-8824		Mobile No.		0933-8120909 / 0995-365058	
Contact Person		Mobile No.		Tel. No.		Warranty Type	
Warranty Code				Room Size		Job Class	
Model		KSM-SW25-6H1M32-I		Call Origin		Job Type	
S/N (I)		16 292203-10340		S/N (O)		16 302211-10745	
Dealer		KMI		DOP		06/20/2024	
Installer		NVFS		Complaint		For Installation	
Location		POWERPLANT LECT Before		After			
Mode Setting (Cool)				No. of Visit		1st Action	
WAC   Setting Temp(16°C-RE)/(10/12-ME)				Tentative Sched		07/02/2024	
SAC/PAC   Setting Temp (17°)				Findings			
Discharge Temperature (High)							
Intake Temperature (High)							
Ampere				Recommendation			
Wattage (Inverter)							
Voltage							
SAC/PAC   Pressure (PSI)							
Part Code		Description		Qty		Unit Price	
SR No.				Labor			
Repair Done		Findings - Installation, , Recommendation - for installation, , Repair Done - done		Handling			
				Others			
Repair Code		SAC18-3 - Installation - 2.5HP - 3.0HP Inverter and Non Inverter (includes 10ft. copper		Total tube,			
Date Attended		07/05/2024		Date Finished		08-05-24	
Time Attended		12:00 am		Time Finished		12:00 am	
This serves as temporary receipt when properly filled up by authorized representative.		Check No.		Bank / Branch			
Serviced by: NVFS		By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.					
		I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.					
Technician(s)		Created by:		Conformed by:			
		GRACE PELAGO		Customer			
		CSR		(Signature over printed name)			



Customer		Patis College Of Aeronautics		Date		07-02-2024	
Address		Lombos St., Brgy. San Isidro, PARAÑAQUE CITY, Metro Manila		Start Time		03:15 pm	
				End Time		03:17 pm	
Telephone No.		8825-8823 / 8825-8824		Mobile No.		0933-8120909 / 0995-3650589	
Contact Person		Mobile No.		Tel. No.		Warranty Type	
Warranty Code				Room Size		Job Class	
Model		KSM-SW25-6H1M32-I		Call Origin		Job Type	
S/N (I)		16292203-10368		S/N (O)		16302203-10417	
Dealer		DOP		Permit?		Parking?	
Installer		Complaint		Appointment?		O.R.?	
Location		Before		After		Ladder?	
Mode Setting (Cool)				No. of Visit		Tentative Sched	
WAC   Setting Temp(16°C-RE)/(10/12-ME)				1st Action		07/04/2024	
SAC/PAC   Setting Temp (17°)				Findings			
Discharge Temperature (High)							
Intake Temperature (High)							
Ampere				Recommendation			
Wattage (Inverter)							
Voltage							
SAC/PAC   Pressure (PSI)							
Part Code		Description		Qty		Unit Price	
		PF: NO: 2024-07-378					
SR No.				Labor			
Repair Done		Findings - Installation, , , Recommendation - for installation, , , Repair Done - done		Handling			
Repair Code		SAC18-3 - Installation - 2.5HP - 3.0HP Inverter and Non Inverter (includes 10ft. copper tube, 10ft. royal cord, rubber insulation, ordinary bracket, drain hose / PVC drain pipe 3/4")		Total			
Date Attended		07-04-24		Date Finished		08-05-24	
Time Attended		12:00 pm		Time Finished		12:10 am	
This serves as temporary receipt when properly filled up by authorized representative.		Check No.		Bank / Branch			
Serviced by: NVFS		By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.					
		I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.					
		Created by:		Conformed by:			
Technician(s)		GRACE PIELAGO CSR		Customer (Signature over printed name)			





## SERVICE JOB REPORT

Customer		Patis College Of Aeronautics				Date		07-02-2024			
Address		Lombos St., Brgy. San Isidro, PARAÑAQUE CITY, Metro Manila				Start Time		03:17 pm			
						End Time		03:19 pm			
Telephone No.		8825-8823 / 8825-8824		Mobile No.		0933-8120909 / 0995-3650585		Relayed by		Ms. Donna / KMI	
Contact Person		Mobile No.		Tel. No.				Warranty Type		C	
Warranty Code				Room Size				Job Class		INST LVL 2	
Model		KSM-SW25-6H1M32-I		Call Origin		IO		Job Type		FD	
S/N (I)		16292211-10526		S/N (O)		16202203-10127		Permit? <input type="checkbox"/>		Parking? <input type="checkbox"/>	
Dealer		KMI		DOP		06/20/2024		Notes		NVFS * 14 units for installation * EDD: 06/26/2024 * ECG Referral	
Installer		NVFS		Complaint		For Installation		Appointment? <input type="checkbox"/>		O.R. <input type="checkbox"/>	
Location		AVIONICS LECTURE ROOM 4832...		Before		After		Ladder? <input type="checkbox"/>			
Mode Setting (Cool)				No. of Visit		1st Action		Tentative Sched		07/04/2024	
WAC   Setting Temp(16°C-RE)/(10/12-ME)								Findings			
SAC/PAC   Setting Temp (17°)											
Discharge Temperature (High)											
Intake Temperature (High)											
Ampere								Recommendation			
Wattage (Inverter)											
Voltage											
SAC/PAC   Pressure (PSI)											
Part Code		Description				Qty		Unit Price		Amount	
		PF: No: 2024-07-378									
SR No.								Labor			
Repair Done		Findings - Installation, , Recommendation - for installation, , Repair Done - done						Handling			
								Others			
Repair Code		SAC18-3 - Installation - 2.5HP - 3.0HP Inverter and Non Inverter (includes 10ft copper tube,						Total			
Date Attended		07/05/2024		Date Finished		07/15/2024		Amount Paid			
Time Attended		12:00 am		Time Finished		12:00 am		Balance			
This serves as temporary receipt when properly filled up by authorized representative.				Check No.				Bank / Branch			
Serviced by: NVFS		By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.									
		I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.									
		Created by:				Conformed by:					
		GRACE PIELAGO									
Technician(s)		CSR				Customer (Signature over printed name)					



Customer		Patts College Of Aeronautics		Date		07-02-2024	
Address		Lombos St., Brgy. San Isidro, PARANAQUE CITY, Metro Manila		Start Time		03:20 pm	
				End Time		03:21 pm	
Telephone No.		6825-8823 / 8825-8824		Mobile No.		0933-8120909 / 0995-365058	
Contact Person		Mobile No.		Tel. No.		Warranty Type	
Warranty Code				Room Size		Job Class	
Model		KSM-SW25-6H1M32-I		Call Origin		Job Type	
S/N (I)		S/N (O)		Permit? <input type="checkbox"/> Parking? <input type="checkbox"/> Appointment? <input type="checkbox"/> O.R.? <input type="checkbox"/> Ladder? <input type="checkbox"/>			
Dealer		DOP		Notes			
Installer		Complaint		For installation			
Location		POWERPLANT 4F		Before After			
Mode Setting (Cool)				No. of Visit		Tentative Sched	
WAC   Setting Temp(16°C-RE)/(10/12-ME)				Findings			
SAC/PAC   Setting Temp (17°)							
Discharge Temperature (High)							
Intake Temperature (High)							
Ampere				Recommendation			
Wattage (Inverter)							
Voltage							
SAC/PAC   Pressure (PSI)							
Part Code		Description		Qty		Unit Price	
		PF: NO: 2024-07-378					
SR No.				Labor			
Repair Done		Findings Installation, , , Recommendation for installation, , , Repair Done done installation		Handling			
Repair Code		SAC18-3- Installation - 2.5HP - 3.0HP Inverter and Non Inverter (includes 10ft. cop		Total tube,			
Date Attended		Date Finished		Amount Paid			
Time Attended		Time Finished		Balance			
This serves as temporary receipt when properly filled up by authorized representative.				Check No.		Bank / Branch	
Serviced by:		By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.					
		I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.					
		Created by:		Conformed by:			
Technician(s)		GRACE PIELAGO CSR		Customer (Signature over printed name)			



Customer		Patt's College Of Aeronautics		Date		07-02-2024	
Address		Lombos St., Brgy. San Isidro, PARAÑAQUE CITY, Metro Manila		Start Time		03:21 pm	
				End Time		03:22 pm	
Telephone No.		8825-8823 / 8825-8824		Mobile No.		0933-8120909 / 0995-3650589	
Contact Person		Mobile No.		Tel. No.		Warranty Type	
Warranty Code				Room Size		Job Class	
Model		KSM-SW25-6H1M32-I		Call Origin		Job Type	
S/N (I)		1639221-10585		S/N (O)		16302301-10854	
Dealer		KMI		DOP		06/20/2024	
Installer				Complaint		For Installation	
Location		POWERPLANT GP 2650M		Before		After	
Mode Setting (Cool)				No. of Visit		Tentative Sched	
WAC   Setting Temp(16°C-RE)/(10/12-ME)				1st Action		07/04/2024	
SAC/PAC   Setting Temp (17°)				Findings			
Discharge Temperature (High)							
Intake Temperature (High)							
Ampere				Recommendation			
Wattage (Inverter)							
Voltage							
SAC/PAC   Pressure (PSI)							
Part Code		Description		Qty		Unit Price	
		PF NO: 2024-07-378					
SR No.				Labor			
Repair Done		Findings - Installation, , , Recommendation - for Installation, , , Repair Done - done		Handling			
Repair Code		SAC18-3 - Installation - 2.5HP - 3.0HP Inverter and Non Inverter (includes 10ft. copper tube		Total			
Date Attended		07-10-24		Date Finished		08-05-24	
Time Attended		12:00 am		Time Finished		12:00 am	
This serves as temporary receipt when properly filled up by authorized representative.		Check No.		Bank / Branch			
Serviced by: NVFS		By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.					
		I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.					
Technician(s)		GRACE PIELAGO		Conformed by:			
		CSR		Customer (Signature over printed name)			





1854 Sta. Rita St., Guadalupe Nuevo, Makati City  
Tel. No.: 8852-6868 / Mobile: 0917-811-8982 / Email: [service@kolinphil.com.ph](mailto:service@kolinphil.com.ph)  
Website: [www.kolinphil.com.ph](http://www.kolinphil.com.ph)     [kolinphilippines](#)

## SERVICE JOB REPORT

No.	HO-00211777
Previous SJR No.	HO-00195437

Customer		Pats College Of Aeronautics				Date		07-02-2024			
Address		Lombos St., Bgy. San Isidro, PARAÑAQUE CITY, Metro Manila				Start Time		03:23 pm			
						End Time		03:26 pm			
Telephone No.		8825-8823 / 8825-8824		Mobile No.		0933-8120909 / 0995-3650583		Relayed by		Ms. Donna / KMI	
Contact Person		Mobile No.		Tel. No.				Warranty Type		C	
Warranty Code				Room Size				Job Class		INST LVL 1	
Model		KSM-SW25-6H1M32-I		Call Origin		IO		Job Type		FD	
S/N (I)		14292203-10395		S/N (O)		14202301-10399		Permit? <input type="checkbox"/>		Parking? <input type="checkbox"/>	
Dealer		KMI		DOP		06/20/2024		Appointment? <input type="checkbox"/>		O.R.? <input type="checkbox"/>	
Installer		NVFS		Complaint		For installation		Notes		NVFS * 14 units for installation * EDD: 06/26/2024 * ECG Referral	
Location		AVIONICS 4F 24SCM		Before		After					
Mode Setting (Cool)						No. of Visit		1st Action		Tentative Sched	
WAC   Setting Temp(16°C-RE)/(10/12-ME)								Findings		07/04/2024	
SAC/PAC   Setting Temp (17°)											
Discharge Temperature (High)											
Intake Temperature (High)											
Ampere								Recommendation			
Wattage (Inverter)											
Voltage											
SAC/PAC   Pressure (PSI)											
Part Code		Description				Qty		Unit Price		Amount	
		PR-NO: 2024-07-378									
SR No.								Labor			
Repair Done		Findings - Installation, , Recommendation - for installation, , Repair Done - done						Handling			
								Others			
Repair Code		SAC18-3 - Installation - 2.5HP - 3.0HP Inverter and Non Inverter (includes 10ft. copper tube, 10ft. royal cord, rubber insulation, ordinary bracket, drainhose / PVC drain pipe 3/4")						Total			
Date Attended		07-08-24		Date Finished		08-05-24		Amount Paid			
Time Attended		12:00 am		Time Finished		2:00 am		Balance			
This serves as temporary receipt when properly filled up by authorized representative.				Check No.				Bank / Branch			
Serviced by: NVFS		By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.									
		I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.									
		Created by:				Conformed by:					
Technician(s)		GRACE PIELAGO CSR				Customer (Signature over printed name)					



Customer	Pais College Of Aeronautics			Date	07-02-2024					
Address	Lombos St., Brgy. San Isidro, PARAÑAQUE CITY, Metro Manila			Start Time	03:26 pm					
				End Time	03:28 pm					
Telephone No.	8825-8823 / 8825-8824		Mobile No.	0933-8120909 / 0995-365058		Relayed by		Ms. Donna / KMI		
Contact Person		Mobile No.		Tel. No.		Warranty Type	C			
Warranty Code				Room Size		Job Class	INST	LVL 2		
Model	KSM-SW25-6H1M32-I			Call Origin	IO	Job Type	FD			
S/N (I)	16292011-10720		S/N (O)	16302301-10899		Permit?	Parking?	Appointment?	O.R.?	Ladder?
Dealer	KMI		DOP	06/20/2024		Notes NVFS * 14 units for installation * EDD: 06/26/2024 * ECS Referral				
Installer	NVFS		Complaint	For Installation						
Location	AIRFRAME 4F 23SQM		Before	After						
Mode Setting (Cool)				No. of Visit	1st Action	Tentative Sched	07/04/2024			
WAC   Setting Temp(16°C-RE)/(10/12-ME)				Findings						
SAC/PAC   Setting Temp (17°)										
Discharge Temperature (High)										
Intake Temperature (High)										
Ampere				Recommendation						
Wattage (Inverter)										
Voltage										
SAC/PAC   Pressure (PSI)										
Part Code	Description			Qty	Unit Price	Amount				
	PF No: 2024-07-378									
SR No.						Labor				
Repair Done	Findings: Installation, ... Recommendation: for installation, ... Repair Done: done					Handling				
						Others				
Repair Code	SAC18-3 - Installation - 2.5HP - 3.0HP Inverter and Non Inverter (includes 10ft. cop					Total tube.				
Date Attended	07/05/2024		Date Finished	5/2024		Amount Paid				
Time Attended	12:00 am		Time Finished	0 am		Balance				
This serves as temporary receipt when properly filled up by authorized representative.				Check No.		Bank / Branch				
Serviced by: NVFS	By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.									
	I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.									
	Created by:			Conformed by:						
	GRACE PIELAGO CSR			Customer (Signature over printed name)						
Technician(s)										





**N.V.F.S. MAINTENANCE AIRCON & REFRIGERATION SYSTEM TRADING**  
MANILA: Office Unit O Monserat St B.F. Homes Phase 1 Sucat Rd Paranaque  
+639171163534 | +639272062600 | +632 85146379 | +632 88719509  
E-mail: sales@about-nvfs.ph | inquiry@about-nvfs.ph  
www.nvfs.ph.com  
TIN Number: 305-342-355-00000

### BILLING STATEMENT

TO: PATTS College Of Aeronautics  
ADDRESS, Lombo St., Brgy. San Isidro, Paranaque City, Metro Manila

REFERENCE NO:  
DATE: July 19, 2024

CUSTOMER NO:

Code No:	BRAND AND ITEM DESCRIPTION	QTY	UNIT	SRP UNIT AND INSTALLATION	GROSS AMOUNT	DISCOUNT	NET PRICE
	<b>AIRCONDITION UNITS INSTALLATION FOR THE 1st 10 FT</b>						
1	ACU 1 : Location : (AVIONICS TOOL ROOM) Kolin -KSM-CW25-6H1M32 2.5 HP Non -Inverter Wall Mount Split Type						
11	Installation for the 1st 10ft	1	SET	P5,500.00	P5,500.00		P5,500.00
	Exclusions :						
29.2	*Copper Tube & Rubber Insulation 2.0 - 3TR with 1/2 Thickness Rubber Insulation	5	FT	P400.00	P2,000.00		P2,000.00
30.2.3	* Royal Cord 5.5mm2 x 3C ODU Breaker/ Ft	8	FT	P70.00	P560.00		P560.00
30.1	* Royal Cord 2.0mm2 x 4C Communication wire / Ft	7	FT	P100.00	P700.00		P700.00
30.7.1	* Supply and Installation of Nema 3R Whether Proof Enclosure w/ 30 Amp Breaker	1	PC	P1,000.00	P1,000.00		P1,000.00
31.16	* PVC Pipe Blue For Drain 3/4 Including Elbow's & T's	1	PC	P150.00	P150.00		P150.00
					<b>Total Cost:</b>		<b>P9,910.00</b>
	<b>ACU 2 : Location : (AVIONICS LECTURE ROOM) Kolin -KSM-CW25-6H1M32 2.5 HP Non -Inverter Wall Mount Split Type</b>						
11	Installation for the 1st 10ft	1	SET	P5,500.00	P5,500.00		P5,500.00
	Exclusions :						
29.2	*Copper Tube & Rubber Insulation 2.0 - 3TR with 1/2 Thickness Rubber Insulation	4	FT	P400.00	P1,600.00		P1,600.00
30.2.3	* Royal Cord 5.5mm2 x 3C ODU Breaker/ Ft	8	FT	P70.00	P560.00		P560.00
30.1	* Royal Cord 2.0mm2 x 4C Communication wire / Ft	7	FT	P100.00	P700.00		P700.00
30.7.1	* Supply and Installation of Nema 3R Whether Proof Enclosure w/ 30 Amp Breaker	1	PC	P1,000.00	P1,000.00		P1,000.00
31.16	* PVC Pipe Blue For Drain 3/4 Including Elbow's & T's	1	PC	P150.00	P150.00		P150.00
					<b>Total Cost:</b>		<b>P9,510.00</b>
	<b>ACU 3 : Location : (AVIONICS LECTURE ROOM) Kolin -KSM-CW25-6H1M32 2.5 HP Non -Inverter Wall Mount Split Type</b>						
11	Installation for the 1st 10ft	1	SET	P5,500.00	P5,500.00		P5,500.00
	Exclusions :						
29.2	*Copper Tube & Rubber Insulation 2.0 - 3TR with 1/2 Thickness Rubber Insulation	3	FT	P400.00	P1,200.00		P1,200.00
30.2.3	* Royal Cord 5.5mm2 x 3C ODU Breaker/ Ft	8	FT	P70.00	P560.00		P560.00
30.1	* Royal Cord 2.0mm2 x 4C Communication wire / Ft	7	FT	P100.00	P700.00		P700.00
30.7.1	* Supply and Installation of Nema 3R Whether Proof Enclosure w/ 30 Amp Breaker	1	PC	P1,000.00	P1,000.00		P1,000.00
31.16	* PVC Pipe Blue For Drain 3/4 Including Elbow's & T's	1	PC	P150.00	P150.00		P150.00
					<b>Total Cost:</b>		<b>P9,110.00</b>
	<b>ACU 4 : Location : (POWER PLANT LECTURE ROOM 4th Floor) Kolin -KSM-CW25-6H1M32 2.5 HP Non -Inverter Wall Mount Split Type</b>						
11	Installation for the 1st 10ft	1	SET	P5,500.00	P5,500.00		P5,500.00
	Exclusions :						
29.2	*Copper Tube & Rubber Insulation 2.0 - 3TR with 1/2 Thickness Rubber Insulation	4	FT	P400.00	P1,600.00		P1,600.00
30.2.3	* Royal Cord 5.5mm2 x 3C ODU Breaker/ Ft	8	FT	P70.00	P560.00		P560.00
30.1	* Royal Cord 2.0mm2 x 4C Communication wire / Ft	7	FT	P100.00	P700.00		P700.00
30.7.1	* Supply and Installation of Nema 3R Whether Proof Enclosure w/ 30 Amp Breaker	1	PC	P1,000.00	P1,000.00		P1,000.00
31.16	* PVC Pipe Blue For Drain 3/4 Including Elbow's & T's	1	PC	P150.00	P150.00		P150.00
					<b>Total Cost:</b>		<b>P9,510.00</b>



5	<b>ACU 5 : Location : (POWER PLANT LECTURE ROOM) Kolin -KSM-CW25-6H1M32 2.5 HP Non -Inverter Wall Mount Split Type</b>								
11	Installation for the 1st 10ft	1	SET	P5,500.00	P5,500.00				P5,500.00
	Exclusions :								
29.2	*Copper Tube & Rubber Insulation 2.0 - 3TR with 1/2 Thickness Rubber Insulation	3	FT	P400.00	P1,200.00				P1,200.00
30.2.3	* Royal Cord 5.5mm2 x 3C ODU Breaker/ Ft	8	FT	P70.00	P560.00				P560.00
30.1	* Royal Cord 2.0mm2 x 4C Communication wire / Ft	7	FT	P100.00	P700.00				P700.00
30.7.1	* Supply and Installation of Nema 3R Whether Proof Enclosure w/ 30 Amp Breaker	1	PC	P1,000.00	P1,000.00				P1,000.00
31.16	* PVC Pipe Blue For Drain 3/4 Including Elbow's & T's	1	PC	P150.00	P150.00				P150.00
					<b>Total Cost:</b>				<b>P9,110.00</b>
6	<b>ACU 6 : Location : (AIR FRAME LECTURE ROOM) Kolin -KSM-CW25-6H1M32 2.5 HP Non -Inverter Wall Mount Split Type</b>								
11	Installation for the 1st 10ft	1	SET	P5,500.00	P5,500.00				P5,500.00
	Exclusions :								
29.2	*Copper Tube & Rubber Insulation 2.0 - 3TR with 1/2 Thickness Rubber Insulation	4	FT	P400.00	P1,600.00				P1,600.00
30.2.3	* Royal Cord 5.5mm2 x 3C ODU Breaker/ Ft	8	FT	P70.00	P560.00				P560.00
30.1	* Royal Cord 2.0mm2 x 4C Communication wire / Ft	7	FT	P100.00	P700.00				P700.00
30.7.1	* Supply and Installation of Nema 3R Whether Proof Enclosure w/ 30 Amp Breaker	1	PC	P1,000.00	P1,000.00				P1,000.00
31.16	* PVC Pipe Blue For Drain 3/4 Including Elbow's & T's	1	PC	P150.00	P150.00				P150.00
					<b>Total Cost:</b>				<b>P9,510.00</b>
7	<b>ACU 7 : Location : (AIR FRAME TOOL ROOM) Kolin -KSM-CW25-6H1M32 2.5 HP Non -Inverter Wall Mount Split Type</b>								
11	Installation for the 1st 10ft	1	SET	P5,500.00	P5,500.00				P5,500.00
	Exclusions :								
29.2	*Copper Tube & Rubber Insulation 2.0 - 3TR with 1/2 Thickness Rubber Insulation	5	FT	P400.00	P2,000.00				P2,000.00
30.2.3	* Royal Cord 5.5mm2 x 3C ODU Breaker/ Ft	8	FT	P70.00	P560.00				P560.00
30.1	* Royal Cord 2.0mm2 x 4C Communication wire / Ft	7	FT	P100.00	P700.00				P700.00
30.7.1	* Supply and Installation of Nema 3R Whether Proof Enclosure w/ 30 Amp Breaker	1	PC	P1,000.00	P1,000.00				P1,000.00
31.16	* PVC Pipe Blue For Drain 3/4 Including Elbow's & T's	1	PC	P150.00	P150.00				P150.00
					<b>Total Cost:</b>				<b>P9,910.00</b>
8	<b>ACU 8 : Location : (AERO LECTURE ROOM) Kolin -KSM-CW25-6H1M32 2.5 HP Non -Inverter Wall Mount Split Type</b>								
11	Installation for the 1st 10ft	1	SET	P5,500.00	P5,500.00				P5,500.00
	Exclusions :								
29.2	*Copper Tube & Rubber Insulation 2.0 - 3TR with 1/2 Thickness Rubber Insulation	4	FT	P400.00	P1,600.00				P1,600.00
30.2.3	* Royal Cord 5.5mm2 x 3C ODU Breaker/ Ft	8	FT	P70.00	P560.00				P560.00
30.1	* Royal Cord 2.0mm2 x 4C Communication wire / Ft	7	FT	P100.00	P700.00				P700.00
30.7.1	* Supply and Installation of Nema 3R Whether Proof Enclosure w/ 30 Amp Breaker	1	PC	P1,000.00	P1,000.00				P1,000.00
31.16	* PVC Pipe Blue For Drain 3/4 Including Elbow's & T's	1	PC	P150.00	P150.00				P150.00
					<b>Total Cost:</b>				<b>P9,510.00</b>
9	<b>ACU 9 : Location : (AERO LECTURE ROOM) Kolin -KSM-CW25-6H1M32 2.5 HP Non -Inverter Wall Mount Split Type</b>								
11	Installation for the 1st 10ft	1	SET	P5,500.00	P5,500.00				P5,500.00
	Exclusions :								
29.2	*Copper Tube & Rubber Insulation 2.0 - 3TR with 1/2 Thickness Rubber Insulation	5	FT	P400.00	P2,000.00				P2,000.00
30.2.3	* Royal Cord 5.5mm2 x 3C ODU Breaker/ Ft	8	FT	P70.00	P560.00				P560.00
30.1	* Royal Cord 2.0mm2 x 4C Communication wire / Ft	7	FT	P100.00	P700.00				P700.00
30.7.1	* Supply and Installation of Nema 3R Whether Proof Enclosure w/ 30 Amp Breaker	1	PC	P1,000.00	P1,000.00				P1,000.00
31.16	* PVC Pipe Blue For Drain 3/4 Including Elbow's & T's	1	PC	P150.00	P150.00				P150.00
					<b>Total Cost:</b>				<b>P9,910.00</b>



10	ACU 10 : Location : (AIR FRAME LECTURE ROOM) Kolin -KSM-CW25-6H1M32 2.5 HP Non -Invereter Wall Mount Split Type					
11	Installation for the 1st 10ft	1	SET	P5,500.00	P5,500.00	P5,500.00
	Exclusions :					
29.2	*Copper Tube & Rubber Insulation 2.0 - 3TR with 1/2 Thickness Rubber Insulation	3	FT	P400.00	P1,200.00	P1,200.00
30.2.3	* Royal Cord 5.5mm2 x 3C ODU Breaker/ Ft	8	FT	P70.00	P560.00	P560.00
30.1	* Royal Cord 2.0mm2 x 4C Communication wire / Ft	7	FT	P100.00	P700.00	P700.00
30.7.1	* Supply and Installation of Nema 3R Whether Proof Enclosure w/ 30 Amp Breaker	1	PC	P1,000.00	P1,000.00	P1,000.00
31.16	* PVC Pipe Blue For Drain 3/4 Including Elbow's & T's	2	PC	P150.00	P300.00	P300.00
11	Installation iRubber Insulation	1	pc	P350.00	P350.00	P350.00
				Total Cost:		P9,610.00
11	ACU 11: Location : (POWER PLANT TOOL 1ST FLOOR ROOM)Kolin -KSM-CW25-6H1M32 2.5 HP Non -Invereter Wall Mount Split Type					
11	Installation for the 1st 10ft	1	SET	P5,500.00	P5,500.00	P5,500.00
	Exclusions :					
29.2	*Copper Tube & Rubber Insulation 2.0 - 3TR with 1/2 Thickness Rubber Insulation	5	FT	P400.00	P2,000.00	P2,000.00
30.2.3	* Royal Cord 5.5mm2 x 3C ODU Breaker/ Ft	8	FT	P70.00	P560.00	P560.00
30.1	* Royal Cord 2.0mm2 x 4C Communication wire / Ft	7	FT	P100.00	P700.00	P700.00
30.7.1	* Supply and Instalation of Nema 3R Whether Proof Enclosure w/ 30 Amp Breaker	1	PC	P1,000.00	P1,000.00	P1,000.00
31.16	* PVC Pipe Blue For Drain 3/4 Including Elbow's & T's	1	PC	P150.00	P150.00	P150.00
				Total Cost:		P9,910.00
12	ACU 12: Location (POWER PLANT TOOL ROOM ) KOLIN - KSM-CW25-6H1M32 2.5 HP Non Inverter Wall Mount Split Type					
11	Installation for the 1st 10ft	1	SET	P5,500.00	P5,500.00	P5,500.00
	Exclusions :					
29.2	*Copper Tube & Rubber Insulation 2.0 - 3TR with 1/2 Thickness Rubber Insulation	5	FT	P400.00	P2,000.00	P2,000.00
30.2.3	* Royal Cord 5.5mm2 x 3C ODU Breaker/ Ft	8	FT	P70.00	P560.00	P560.00
30.1	* Royal Cord 2.0mm2 x 4C Communication wire / Ft	7	FT	P100.00	P700.00	P700.00
30.7.1	* Supply and Installation of Nema 3R Whether Proof Enclosure w/ 30 Amp Breaker	1	PC	P1,000.00	P1,000.00	P1,000.00
31.16	* PVC Pipe Blue For Drain 3/4 Including Elbow's & T's	1	PC	P150.00	P150.00	P150.00
				Total Cost:		P9,910.00
13	ACU 13: Location : (OFFICE OF STUDENT AFFAIRS) KOLIN - KSM-CW25-6H1M32 2.5 HP Non Inverter Wall Mount Split Type					
11	Installation for the 1st 10ft	1	SET	P5,500.00	P5,500.00	P5,500.00
	Exclusions :					
29.2	*Copper Tube & Rubber Insulation 2.0 - 3TR with 1/2 Thickness Rubber Insulation	5	FT	P400.00	P2,000.00	P2,000.00
30.2.3	* Royal Cord 5.5mm2 x 3C ODU Breaker/ Ft	8	FT	P70.00	P560.00	P560.00
30.1	* Royal Cord 2.0mm2 x 4C Communicabon wire / Ft	67	FT	P100.00	P6,700.00	P6,700.00
30.7.1	* Supply and Installation of Nema 3R Whether Proof Enclosure w/ 30 Amp Breaker	1	PC	P1,000.00	P1,000.00	P1,000.00
31.14	* Full Thread 3 Meters	2	PC	P150.00	P300.00	P300.00
31.15	* Pipe Hanger 3 Inches	14	PC	P150.00	P2,100.00	P2,100.00
31.16	* PVC Pipe Blue For Drain 3/4 Including Elbow's & T's	1	PC	P150.00	P150.00	P150.00
*	*Drain Pump realise	1	PC	P2,750.00	P2,750.00	P2,750.00
*	*Drain Hose Green 1/4	10	FT	P10.00	P100.00	P100.00
				Total Cost:		P21,160.00
	SUPPLY & INSTALLATION COST					
				GRAND TOTAL		P136,580.00



**Mode of Payments**

Cash, Gcash, maya

Bank Transfer or Check Payment under: **NVFS Maintenance Aircon & Refrigeration System Trading**

**BDO Account 004128020472** President's Avenue BF Paranaque Branch

**Metrobank Account 034-7-03452574-5** BF Homes Aguirre Branch

Ryan L. Guerra

NVFS Maintenance Aircon and Refrigeration System Trading

Date :

Conforme:

*Client's Signature over Printed Name / Date*

**AUTHORIZED DEALER OF THE FOLLOWING BRANDS**

 **Kolin** **Panasonic** **TOSOT**  **Whirlpool** **FUJIDEN**  **Kelvinator**  **Carrier** **CONDURA** **AUX** **HK**

**AUTHORIZED SERVICE CENTER OF THE FOLLOWING BRANDS**

 **Kolin** **Panasonic** **TOSOT**