

July 29, 2024

DOMINICAN SISTERS OF REGINA ROSARII 70 SCOUT FERNANDEZ ST. (NEAR CHILI'S RESTO) QUEZON CITY TEL#: (02)8372-5327 / 0919-2694286

Dear Ma'am/Sir,

Kolin Marketing Inc., is extremely honored for your endorsement of Kolin brand and we are please to offer you with a special price/s for the following items.

## A. EQUIPMENT & INSTALLATION

QTY	1100		#441			
QIT	U/M	MODEL / DESCRIPTION	SRP	DISCOUNTED	T	
		MODEL: KSG-IWF-30WFY-8K1M32	- OKF	PRICE		AMOUNT
TOTAL	UNIT/S UNIT COST	KOLIN WALL MOUNTED PRIMUS GOLD AIRCONDITIONER 29,500 Kj/h (3.0HP) FULL DC INVERTER W/ W/LD 23	76,595.00	55,744.10 <b>7</b>	PHP	55,744.10
<b>ESTIMA</b>	TED COST OF	INSTALLATION (please see attached)			PHP	55,744.10
OTHERS	OTHERS: DELIVERY CHARGE					
TOTAL	TOTAL ESTIMATED COST OF THE PROJECT					
					PHP	7 70,459.10

### TERMS OF PAYMENT:

FULL PAYMENT OF UNIT AND DELIVERY CHARGE. IF CHECK, SUBJECT FOR 3 DAYS CLEARING.

## WARRANTY:

FOR SPLIT TYPE: ONE (1) YEAR FREE PARTS AND LABOR, THREE YEARS (3) MAIN PCB, TEN (10) YEARS WARRANTY ON COMPRESSOR.

# NOTES: PRICES ARE SUBJECT TO CHANGE WITHOUT PRIOR NOTICE.

PRICES IS VAT INCLUSIVE.

\*\* Cost of Installation is Package with the Unit(s), this cost cannot avail separately.

We thank you for giving opportunity to offer our product and services, hoping we receive your purchase order.

If you need assistance, don't hesitate to call the under signed at 0917-807-8607 or email at kmi\_asst@kolinphil.com.ph

Very Truly Yours,

JANELLEN S. LIM KMI-ASSISTANT

Noted by:

MART NATHANIEL R. FLORES

KMI-SUPERVISOR

KMI-QUOTE-07-24-0671 REG-22%/4K

Kolin Marketing, Inc.

1854 Sta. Rita St., Guadalupe Nuevo, Makati City

www.kolinphil.com.ph Tel.: (632) 8852-6473

Fax: (632) 8852-2170 / (632) 8852-4792

Approved By:

MS. EDITHAM. FLORES

AVP - FINANCE

Conforme:

SIGNATURE OVER PRINTED NAME

Bringing comfort to your home.

# KOLIN Philippines International Inc. Survey Form

Nº 003505

Establishment Type : Residential		Area Surveye		Ted XMX	Lines
Commercial		Area Surveye	1	THE AMOX	1711/1
Recommended Product Model :	KSG-IMF-30WI	ST- BICIM.	31		
	Cooling Capacity	Computation			
Floor Area: sqm. Ceiling Height: mtr.	note: add 20% per initial cooling	meter in excess capacity comput		he	4
Floor Area :	31	x	550 Btu/h	17010	Btu/h
Ceiling Height (excess of 3 mtrs.):		x	20% [	1	Btu/h
Vindow Direct Sunlight		x	20% - 50% [		Btu/h
Total Cooling Capacity				1360	Btu/h
Add : Additional Heat Load					
No. of Person	20	×	300 Btu/h	6000	Btu/h
No. of Ordinary Light (<40w)	10	×	200 Btu/h	2000	Btu/h
No. of Special Light (>40w)		×	400 Btu/h		Btu/h
lo. of Refrigerator (< 6 cu.ft.)		×	400 Btu/h		Btu/h
No. of Refrigerator (> 6 cu.ft.)		×	800 Btu/h		Btu/h
No. of Cooking Range	e de la companya del companya de la companya de la companya del companya de la co		1500 Btu/h		Btu/h
No. of Laptop Computer	<u> </u>	<b>x</b> ,	150 Btu/h	722	Btu/h
하는데 하는데 없는데 이번 이 없었다. 그리고 있는데 그리고 있다.		. ×		300	
No. of Desktop Computer No. of Printer		. ×	400 Btu/h		Btu/h
		. ×	500 Btu/h	100	Btu/h
No. of Photocopier	-	. х	1000 Btu/h [	580°	Btu/h
Total Cooling Capacity			l	7 4	Btu/h
Recommended Cooling Capacity				NED	Btu/h
Note : Compressor warranty will be re	educed to vr. if air-co	onditioner purcha	sed is lower tha	n the	
recommended cooling capacity					
	Scope of Work	Agreement			
Copper tube lay-out	Expose	Embedde	d		
2. Chipping	Included	Not Includ			
3. Fabricated Bracket	Yes Shop	Site	No .		
I. Service Ledge	Yes	No			
5. Dismantling of existing Aircon	Included	Not Include	ded .		
6. Ducting	Yes	No			
Dimension :		NO			
	in worke are to be done by	the customes			
7. Plastering, carpentry and restoration			no by the crists	mor	
3. Wiring of electrical supply from ma					
9. Processing of mechanical plan, wo		TAIL HOW	e by the custom	EI.	
10. 00.00		12 (42)	WXIIGA	de -	
C-01.	DEAC MONDE	V F 30 A	NEW MALE	411	
Som.	DIMPONE 121/20	CET MO	MEX ONSI	16-	
BYHHG BYHHG	ONTOUR BYLL	I LANGUE	NEX ONZI	TF	

												100	
-	T												
			 -	 	1								 
			1										
	1									as			
		4.0	 	 				<u> </u>					 
								The same of the sa					
		<del>  -</del>	 -					1					 
								-					 
									1=				
		<del>  </del>	 /	 - /	3-			714	ļ <u>-</u>			,	 -
	<u> </u>			 0	- 5		<u> </u>				ļ	ļ	 
	+	<del></del>	 1	 	ļ		1	†				1	-
	<u> </u>	<u> </u>	 4	 	ļ		ļ	ļ			}	ļ	 
							-	5 12				100	
	+	+				4	3, 49	İ					-
					124								

Indoor Unit Location		inite pour. SXW	
Outdoor Unit Location	HISLUNXY,	MEXIL STX/14. 2x1	M LACETOR
Pipe Length	17 FT		

In	stallation Cost Estimate			
Material Descrip	tion	Qty.	Unit Cost	Total Cos
Copper Tube (excess of 10 ft.)	2330, 2430, 2520, 3520, 4620	SFT	400	2000
Wire (Royal Cord-signal wire) (excess of 10ft.)	2.0mmx4C	MATI	100.	1200
Wire (Royal Cord - Breaker to ODU)	3.5mm / 5.5mm x 3C	4 FT	60	140
Circuit Breaker	20A, 30A, 40A/1ph, 40A/3ph	1	1000	11000
Bracket (ODU) WODT-Y	(Imptd. / Fabricated); (Floor (Wall))		NTO	150
Bracket (WAC)	Angle Type			
PVC Pipe (drain)	1/2" , 3/4"		5 体系特别的	<b>学程的</b>
PVC Pipe (electrical)	3/4" , 1"			
Drain Pump	10000000000000000000000000000000000000			
Drain Pump Hose W HITT \		177	N.	17-(
Chipping Works	mtr.			
Dismantling Fee (existing air-conditioner)	. O supplementation	<b>工厂</b> 经第二人		17700
Initial Charge				3500
	IMATE	P 14,11	J-	

### Note

Special Note

- Initial Charge includes labor, 10ft. Copper tube, 10ft. Royal cord, Circuit breaker, Outdoor Bracket (SAC), Indoor Bracket (PAC) and Consumable materials.
- 2. Survey fee will be deducted in the installation fee.

Prepared by:	
HESTERNET ON	2010
Signature Over Prin	ted Name

Customer	Conform	e:		7/2	(0)	1
A/A.	The state of the s		-	11-		*