



1-Jul-2024

STERLING PAPER

2302 STERLING PLACE, PASONG TAMO EXTN., BRGY. PIO DEL PILAR, MAKATI CITY

TEL: 0917-8875714

Sir/ Madam,

This is to bill you on the service job done to your unit for the month of JUNE 2024.

Details of the charges are stated below and a copy of the Service Job Report is attached for your references:

DATE ATTENDED	SJR #	QUANTITY/MODEL	SERVICE JOB DONE	AMOUNT
21-Mar-24	HO-00192485	(1) KLG-IF70-2C1M	PARTS REPLACEMENT	600.00
21-Mar-24	HO-00192487	(1) KLG-IF40-2C1M	PARTS REPLACEMENT	4,500.00
21-Mar-24	HO-00192488	(1) KLG-IF40-2C1M	PARTS REPLACEMENT	2,050.00
21-Mar-24	HO-00192489	(1) KSM-IW15-6H1M	TROUBLESHOOTING	1,800.00
TOTAL				P 8,950.00
LESS: DISCOUNT				(626.50)
TOTAL AMOUNT DUE				P 8,323.50

For any clarifications please feel free to call the Undersigned at the telephone number **8852-6473**

Note: If check payment, please prepare check payable to **Kolin Philippines International Inc.**

Account #: BDO - KALAYAAN

011808000428

Note: In case thru Bank Deposit under BDO Account, kindly indicate SJR# for your Bank Reference in the deposit slip and Fax to **(632) 8852-6473** or E-mail to: **kmi_asst@kolinphil.com.ph**

Prepared by:


Janellen S. Lim
KMI - Assisitant

Noted by:


Mari Nathaniel R. Flores
KMI - Supervisor

Received by:

Signature over printed name

 **Kolin Philippines Int'l., Inc.**

Plant and Head Office:

Blk 3 Lt 5 Main Drive, FCIE Compound,

Brgy. Langkaan I, Dasmariñas, Cavite

Tel.: (632) 8749-2118

Fax (046) 402-0793

 www.kolinphil.com.ph / kolinphilippines

Operation Office:

1854 Sta. Rita St., Guadalupe Nuevo,
Makati City

Tel.: (632) 8851-2711, 12 or 15

Fax: (632) 8852-2170

Sales Dept. Fax: (632) 8852-4791



Customer		Sterling Paper		Date		03-20-2024	
Address		2302 Sterling Place, Pasong Tamo Extn., Brgy. Pio Del Pilar, MAKATI CITY, Manila		Start Time		01:42 pm	
Telephone No.		8813-7828 LOC 227/ 813-7828 LOC. 227		Mobile No.		8830917-8875714	
Contact Person		Ms. Mean		Mobile No.		...	
Warranty Code		...		Room Size		...	
Model		KLG-IF70-2C1M		Call Origin		MH	
S/N (I)		17191609-10020		S/N (O)		...	
Dealer		KMC		DOP		11/27/2019	
Installer		...		Complaint		Dead Set	
Location		Main Building - 4/F Area		Before		After	
Mode Setting (Cool)		...		No. of Visit		1st Action	
WAC Setting Temp (16°C-RE)/(10/12-ME)		...		Tentative Sched		03/25/2024	
SAC/PAC Setting Temp (17°)		...		Findings		...	
Discharge Temperature (High)		...		Recommendation		...	
Intake Temperature (High)		...		For 2nd action / Bring all possible parts		...	
Ampere		...		Bring leadwire & 2 pcs of indoor and outdoor PCB		...	
Wattage (Inverter)		...		...		...	
Voltage		...		...		...	
SAC/PAC Pressure (PSI)		...		...		...	
Part Code		Description		Qty		Unit Price	
Amount		...		...		...	
SR No.		...		Labor		...	
Repair Done		Replaced PCB indoor & outdoor drive board		Handling		...	
Repair Code		filter board but still HS & PG		Others		...	
Date Attended		3-21-24		Date Finished		3-21-24	
Time Attended		10:00 am		Time Finished		2:30 pm	
This serves as temporary receipt when properly filled up by authorized representative.		Check No.		Bank / Branch		...	
Serviced by: Gary Munday, Neil Villafuerte		By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.		Created by:		Conformed by:	
LOPEZ VISTAN		I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.		MARNILLE NORTE		Customer	
MEDINA		Technician(s)		CSR		(Signature over printed name)	




7400 38718

No.
Previous SJR No.

HO-00192487

HO-00182417

Customer	Sterling Paper				Date	03-20-2024	
Address	2302 Sterling Place, Pasong Tamo Extn... Brgy. Pio Del Pilar, MAKATI CITY, Manila				Start Time	01:47 pm	
					End Time	01:48 pm	
Telephone No.	8813-7828 LOC 227/ 813-7828 LOC 227		Mobile No.	0917-8875714		Relayed by	Meann 0917-8751093
Contact Person	Ms. Meann	Mobile No.			Tel. No.		
Warranty Code					Room Size		
Model	KLG-IF40-2C1M		Call Origin	MH		Job Type	FD
S/N (I)	17231805-13457		S/N (O)			Permit? ☐	Parking? ☐
Dealer	IN2		DOP	11/27/2019		Appointment? ☐	O.R.? ☐
Installer			Complaint	Dead Set		Ladder? ☐	
Location	G/F Guard Info Area	Before	After				
Mode Setting (Cool)		Cool	No. of Visit	1st Action	Tentative Sched	03/25/2024	
WAC Setting Temp (16°C-RE)/(10/12-ME)			Findings				
SAC/PAC Setting Temp (17°)		17°C	Defective PCB indoor / E6 error code				
Discharge Temperature (High)		45°C					
Intake Temperature (High)		10°C					
Ampere		14.5 Amp	Recommendation				
Wattage (Inverter)							
Voltage		230V					
SAC/PAC Pressure (PSI)		140 PSI					
Part Code	Description				Qty	Unit Price	Amount
	PCB indoor					2,200	
WARRANTY VOIDED IN 6/22/24 							
SR No.	35546				Labor	2,300.00	
Repair Done	Replaced PCB indoor				Handling	0	
Repair Code					Others	0	
Date Attended	3-21-24		Date Finished	3-21-24		Total	4,500.00
Time Attended	10:00 am		Time Finished	2:30 pm		Amount Paid	
This serves as temporary receipt when properly filled up by authorized representative.				Check No.	Bank / Branch		
Served by: Garry Munday, Neil Villafuerte		By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.					
LOPEZ MEDINA		VISTAN		I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.			
Technician(s)		MARNILLE NORTE		Created by:		Conformed by:	
		CSR		Customer		(Signature over printed name)	

No. **HO-00192498**
Previous SJR No. **HO-00192417**

Customer		Sterling Paper		Date		03-20-2024	
Address		2302 Sterling Place, Pasong Tamo Extn., Brgy. Pio Del Pilar, MAKATI CITY, Manila		Start Time		01:48 pm	
Telephone No.		8813-7828 LOC 227/ 813-7828 LOC. 227 / 503-8830917-8875714		End Time		01:49 pm	
Contact Person		Ms. Mean		Relayed by		Mearn 0917-8751093	
Warranty Code		Room Size		Warranty Type		C	
Model		KLG-IF40-2C1M		Job Class		TS LVL 1	
S/N (I)		17231805-13280		Call Origin		MH	
S/N (O)				Job Type		FD	
Dealer		WZ		Permit? ☐ Parking? ☐ Appointment? ☐ O.R.? ☐ Ladder? ☐			
DOP		01/15/2019		Notes		Team Villafuerte	
Installer		Complaint		F1 Error Code			
Location		Before		After			
Mode Setting (Cool)		Cool		No. of Visit		1st Action	
WAC Setting Temp (16°C-RE)/(10/12-ME)				Tentative Sched		03/25/2024	
SAC/PAC Setting Temp (17°)		17°C		Findings			
Discharge Temperature (High)		20°C		Defective indoor temp. sensor assembly			
Intake Temperature (High)		12°C					
Ampere		14.2A		Recommendation			
Wattage (Inverter)							
Voltage		230V					
SAC/PAC Pressure (PSI)		140PSI					
Part Code		Description		Qty		Unit Price	
		Indoor Temp. sensor assembly		1		P550.00	
SR No.		35048		Labor		P1,500.00	
Repair Done		Replaced indoor temp. sensor assembly		Handling			
Repair Code				Others			
Date Attended		3-21-24		Total		P2,050.00	
Time Attended		10:00 am		Amount Paid			
Time Finished		2:30 pm		Balance		for collection	
This serves as temporary receipt when properly filled up by authorized representative.		Check No.		Bank / Branch			
Serviced by: Gerry Munday, Neil Villafuerte		By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.					
Lopez VISTAN		I hereby agree to the above repair charges incurred to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.					
MEDINA		Created by: MARNIE NORTE		Conformed by: MARNIE NORTE		Customer (Signature over printed name)	

Customer		Sterling Paper		Date		03-20-2024	
Address		2302 Sterling Place, Pasong Tamo Extn., Brgy. Pio Del Pilar, MAKATI CITY, Manila		Start Time		01:49 pm	
Telephone No.		8813-7828 LOC 227/ 813-7828 LOC 227		Mobile No.		8830917-8875714	
Contact Person		Mr. Mean		Mobile No.		...	
Warranty Code		...		Room Size		...	
Model		KSM-IW15-6H1M		Call Origin		MH	
S/N (I)		18251812-11498		S/N (O)		...	
Dealer		...		DOP		11/27/2019	
Installer		...		Complaint		E3 Error Code	
Location		Annex Bldg -3/F Meeting Room		Before		After	
Mode Setting (Cool)		Cool		No. of Visit		1st Action	
WAC Setting Temp (16°C-RE)/(10/12-ME)		...		Tentative Sched		03/25/2024	
SAC/PAC Setting Temp (17°)		17°C		Findings		Under charge refrigerant	
Discharge Temperature (High)		25°C		Intake Temperature (High)		25°C	
Ampere		1.5hp		Recommendation		Unit for observation / for pull out if the same problem occur	
Wattage (Inverter)		...		Voltage		230V	
SAC/PAC Pressure (PSI)		50 Psi		...		140 Psi	
Part Code		Description		Qty		Unit Price	
Amount		...		...		...	
SR No.		...		Labor		P 1,800.00	
Repair Done		Recharging of refrigerant / Leak test (Bubble test) indoor & outdoor / no leak found		Handling		...	
Repair Code		...		Others		...	
Date Attended		3-21-24		Date Finished		3-21-24	
Time Attended		10:00 am		Time Finished		2:30 pm	
This serves as temporary receipt when properly filled up by authorized representative.		Check No.		Bank / Branch		...	
Serviced by: Garry Munday, Neil Villafuerte		By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.					
Lopez		I hereby agree to the above repair charges incurred to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.					
MEDINA		Created by:		Conformed by:			
Technician(s)		MARNILLE NORTE		Customer			
		CSR		(Signature over printed name)			