



25-Jun-2024

MERLGEN EURO DESIGNS INC.

ATTN: MR. ANASTACIO TUGUIB

#148 D. TUAZON, STA. MESA HEIGHTS, BESIDE: HOLIDAY SPA, QUEZON CITY

TEL: 0917-7098076

Sir/ Madam,

This is to bill you on the service job done to your unit for the month of JUNE 2024.

Details of the charges are stated below and a copy of the Service Job Report is attached for your references:

DATE ATTENDED	SJR #	QUANTITY/MODEL	SERVICE JOB DONE	AMOUNT
06-Jun-24	HO-00206367	(1) KFM-400F1J	PARTS REPLACEMENT	3,660.00
	TOTAL		P	3,660.00
	LESS: DISCOUNT			(256.20)
	TOTAL AMOUNT DUE		P	3,403.80

For any clarifications please feel free to call the Undersigned at the telephone number **8852-6473**

Note: If check payment, please prepare check payable to **Kolin Philippines International Inc.**

Account #: BDO - KALAYAAN


011808000428

Note: In case thru Bank Deposit under BDO Account, kindly indicate SJR# for your Bank Reference in the deposit slip and Fax to **(632) 8852-6473** or E-mail to: **kmi_asst@kolinphil.com.ph**

Prepared by:


Janellen S. Lim
KMI - Assisitant

Noted by:


Mari Nathaniel R. Flores
KMI - Supervisor

Received by:

Signature over printed name

 **Kolin Philippines Int'l., Inc.**

Plant and Head Office:
Blk 3 Lt 5 Main Drive, FCIE Compound,
Brgy. Langkaan I, Dasmariñas, Cavite
Tel.: (632) 8749-2118
Fax (046) 402-0793
www.kolinphil.com.ph / kolinphilippines

Operation Office:
1854 Sta. Rita St., Guadalupe Nuevo,
Makati City
Tel.: (632) 8851-2711, 12 or 15
Fax: (632) 8852-2170
Sales Dept. Fax: (632) 8852-4791



Customer		Merger Euro Designs Inc.		Date		06-04-2024	
Address		#148 D. Tuzon, Sta. Mesa Heights, Beside: Holiday Spa, QUEZON CITY, Metro Manila		Start Time		11:10 am	
Telephone No.		Mobile No. 0917-7088078		End Time		11:12 am	
Contact Person		Anastacio Tuguib		Relayed by		ADR	
Warranty Code		Room Size		Warranty Type		C	
Model		KFM-400F1J		Job Class		TS LVL 1	
S/N (I)		S/N (O)		Job Type		FD	
Dealer		DOP		Permit? <input type="checkbox"/> Parking? <input type="checkbox"/> Appointment? <input type="checkbox"/> O.R.? <input type="checkbox"/> Ladder? <input type="checkbox"/>			
Installer		Complaint		Notes: IH Logro - kindly update serial number on-site - pls bring possible parts			
Location		Before		After		P12 Error Code	
Mode Setting (Cool)		No. of Visit		1st Action		Tentative Sched 06/07/2024	
WAC Setting Temp (16°C-RE)/(10/12-ME)		Findings					
SAC/PAC Setting Temp (17°)		19°		Defective Compressor Capacitor			
Discharge Temperature (High)		14.5		Undercharged of Freon, Error P10			
Intake Temperature (High)		23.2					
Ampere		8.1		Recommendation			
Wattage (Inverter)		15.5		Unit for observation			
Voltage		245					
SAC/PAC Pressure (PSI)		20		65			
Part Code		Description		Qty		Unit Price	
		Capacitor 60 uF		1		660	
		Freon R-22		1		660	
		Ref: SJR# 203097					
		LIQUIDATED					
		DATE: 7-25/24					
SR No.		less 7%.		Labor		3,000.00	
Repair Done		Replaced Comp. Capacitor & Re-charged Freon		Handling			
Repair Code				Others			
Date Attended		June 6, 2024		Total		3,660.00	
Time Attended		3:05 pm		Amount Paid		For Collection	
Time Finished		4:30 PM		Balance			
This serves as temporary receipt when properly filled up by authorized representative.		Check No.		Bank / Branch			
Serviced by: Kevin Serrano, Manuel Reyes		By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.					
Kevin Serrano		I hereby agree to the above repair charges incurred to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.					
Manuel Reyes		Created by: LUIS REBUYAS		Conformed by:		Customer: ROWIE DELLOS SANTOS	
Technician(s)		CSR		(Signature over printed name)			