



29-May-2024

ATTN: MR. VINCE TEMPONGKO
 6 FLAMINGO DRIVE VICTORIA VALLEY SUBDDIVISION, MAYAMOT ANTIPOLLO CITY
 MAYAMOT ANTIPOLLO CITY
 TEL: 0917-849-8364


Sir/ Madam,

This is to bill you on the service job done to your unit for the month of FEBRUARY 2022.
 Details of the charges are stated below and a copy of the Service Job Report is attached for your references:

DATE ATTENDED	SJR #	QUANTITY/MODEL	SERVICE JOB DONE	AMOUNT
16-Jun-22	HO-00113422	(1) KLG-IF70-2C1M (FAMILY ROOM)	LAY OUT OF COPPER TUBE	36,150.00
18-Jan-23	HO-00138727	(1) KLG-IF70-2C1M (FAMILY ROOM)	OUTDOOR BRACKET	5,500.00
03-Jul-23	HO-00161085	(1) KLG-IF70-2C1M (FAMILY ROOM)	INSTALLATION OUTDOOR UNIT, BRACKET AND BREAKER	1,490.00
28-Nov-23	HO-00179806	(1) KLG-IF70-2C1M (FAMILY ROOM)	DISMANTLING INDOOR AND LAY OUT ADDITIONAL COPPER TUBE	6,900.00
12-Dec-23	HO-00181462	(1) KLG-IF70-2C1M (FAMILY ROOM)	RELOCATE INDOOR	600.00
16-Jun-22	HO-00113417	(1) KLG-IF40-3D1M (L/D/K)	LAY OUT OF COPPER TUBE	30,850.00
18-Jan-23	HO-00138722	(1) KLG-IF40-3D1M (L/D/K)	OUTDOOR BRACKET	5,000.00
06-Feb-23	HO-00140471	(1) KLG-IF40-3D1M (L/D/K)	ADDITIONAL LAY OUT COPPER TUBE	5,000.00
09-Mar-23	HO-00143724	(1) KLG-IF40-3D1M (L/D/K)	LAY OUT SUPPLY WIRE	1,700.00
16-Jun-22	HO-00113419	(1) KLG-IF40-3D1M (L/D/K)	LAY OUT OF COPPER TUBE	31,750.00
18-Jan-23	HO-00138724	(1) KLG-IF40-3D1M (L/D/K)	OUTDOOR BRACKET	5,000.00
06-Feb-23	HO-00140472	(1) KLG-IF40-3D1M (L/D/K)	ADDITIONAL LAY OUT COPPER TUBE	5,400.00
09-Mar-23	HO-00143725	(1) KLG-IF40-3D1M (L/D/K)	LAY OUT SUPPLY WIRE	2,050.00
16-Jun-22	HO-00113431	(1) KSM-IW25-6H1M (MASTER BEDROOM)	LAY OUT OF COPPER TUBE	24,700.00
06-Feb-23	HO-00140473	(1) KSM-IW25-6H1M (MASTER BEDROOM)	ADDITIONAL LAY OUT COPPER TUBE	6,000.00
09-Mar-23	HO-00143910	(1) KSM-IW25-6H1M (MASTER BEDROOM)	LAY OUT SUPPLY WIRE	2,200.00
16-Jun-22	HO-00113429	(1) KSM-IW15-6H1M (BEDROOM 3)	LAY OUT OF COPPER TUBE	21,350.00
03-Jul-23	HO-00161091	(1) KSM-IW15-6H1M (BEDROOM 3)	INSTALLATION INDOOR AND OUTDOOR UNIT	1,420.00
16-Jun-22	HO-00113428	(1) KSM-IW15-6H1M (BEDROOM 2)	LAY OUT OF COPPER TUBE	16,500.00
14-Jul-22	HO-00113426	(1) KSM-IW15-6H1M (BEDROOM 2)	LAY OUT PVC PIPE	300.00
03-Jul-23	HO-00161090	(1) KSM-IW15-6H1M (BEDROOM 3)	INSTALLATION INDOOR AND OUTDOOR UNIT	1,420.00
16-Jun-22	HO-00113427	(1) KSM-IW15-6H1M (BEDROOM 1)	LAY OUT OF COPPER TUBE	20,400.00
14-Feb-23	HO-00141446	(1) KSM-IW15-6H1M (BEDROOM 1)	ADDITIONAL LAY OUT COPPER TUBE	2,450.00
03-Jul-23	HO-00161089	(1) KSM-IW15-6H1M (BEDROOM 1)	INSTALLATION INDOOR AND OUTDOOR UNIT	1,420.00
06-Jun-24	HO-00111631	(1) KSM-IW15-6H1M (GUEST ROOM)	LAY OUT OF COPPER TUBE	12,900.00
18-Jun-24	HO-00113426	(1) KSM-IW15-6H1M (GUEST ROOM)	INSTALL DOUBLE INSULATION	1,400.00
14-Feb-23	HO-00141442	(1) KSM-IW15-6H1M (GUEST ROOM)	ADDITIONAL LAY OUT COPPER TUBE	2,450.00
03-Jul-23	HO-00161088	(1) KSM-IW15-6H1M (GUEST ROOM)	INSTALLATION OF BREAKER	1,000.00
11-Jul-23	HO-00162537	(1) KSM-IW15-6H1M (GUEST ROOM)	REPLACEMENT OF COPPER TUBE AND INSTALL	2,450.00
06-Jun-24	HO-00111629	(1) KSM-IW20-6H1M (AUDIO ROOM)	LAY OUT OF COPPER TUBE	14,600.00
14-Feb-23	HO-00141443	(1) KSM-IW20-6H1M (AUDIO ROOM)	ADDITIONAL LAY OUT COPPER TUBE	2,450.00
03-Jul-23	HO-00161086	(1) KSM-IW20-6H1M (AUDIO ROOM)	INSTALLATION INDOOR AND OUTDOOR UNIT	1,420.00
06-Jun-24	HO-00113425	(1) KSM-IW20-6H1M (AUDIO ROOM)	LAY OUT OF COPPER TUBE	11,550.00
14-Feb-23	HO-00141444	(1) KSM-IW20-6H1M (AUDIO ROOM)	ADDITIONAL LAY OUT COPPER TUBE	1,400.00
03-Jul-23	HO-00161087	(1) KSM-IW20-6H1M (AUDIO ROOM)	INSTALLATION INDOOR AND OUTDOOR UNIT	1,420.00
TOTAL				288,590.00
LESS: DOWNPAYMENT				(126,735.00)
DISCOUNT ON INSTALLATION				(14,429.50)
TOTAL AMOUNT DUE				147,425.50

Kolin Philippines Inc.
 Plant and Head Office:
 Blk 3 Lt 5 Main Drive, FCIE Compound,
 Brgy. Langkaan I, Dasmarinas, Cavite
 Tel.: (632) 8749-2118
 Fax: (046) 402-0793
www.kolinphil.com.ph / kolinphilippines

Operation Office:
 1854 Sta. Rita St., Guadalupe Nuevo,
 Makati City
 Tel.: (632) 8851-2711, 12 or 15
 Fax: (632) 8852-2170
 Sales Dept. Fax: (632) 8852-4791





For any clarifications please feel free to call the Undersigned at the telephone number **8852-6473**


Note: If check payment, please prepare check payable to **Kolin Philippines International Inc.**
Account #: BDO - KALAYAAN 011808000428

Note: In case thru Bank Deposit under BDO Account, kindly indicate SJR# for your Bank Reference in the deposit slip and Fax to **(632) 8852-6473** or E-mail to: **kmi_asst@kolinphil.com.ph**

Prepared by:


Janellen S. Lim
KMI - Assisitant

Noted by:


Mari Nathaniel R. Flores
KMI - Supervisor

Received by:

Signature over printed name

 **Kolin Philippines Int'l., Inc.**


Plant and Head Office:

Blk 3 Lt 5 Main Drive, FCIE Compound,

Brgy. Langkaan I, Dasmariñas, Cavite

Tel.: (632) 8749-2118

Fax (046) 402-0793

 www.kolinphil.com.ph / kolinphilippines

Operation Office:

1854 Sta. Rita St., Guadalupe Nuevo,

Makati City

Tel.: (632) 8851-2711, 12 or 15

Fax: (632) 8852-2170

Sales Dept. Fax: (632) 8852-4791





Kolin Philippines International Inc.
 1854 Sta. Rita St. Alabang, Alabang, Muntinlupa, Makati City
 Tel. No. 8852-6868 / Mobile: 0917-8118982 / Email: service@kolinphil.com.ph
 Website: www.kolinphil.com.ph

24700


SERVICE JOB REPORT

Customer: <i>Mr. Vince</i>		Date: <i>06-16-2022</i>		
Address: <i>31 Hamingo Drive, Victoria Valley Subd., Brgy. Dela Paz, CITY OF ANTIPOLO, Rizal</i>		Start Time: <i>08:20 pm</i>		
Tel. No.		End Time: <i>08:21 pm</i>		
Mobile No.		Relayed by:		
Contact Person	Mobile No. <i>0927-7841099</i>	Tel. No.	Warranty Type:	
Model: <i>70</i>	Call Origin	Job Class:		
S/N (I)	S/N (O)	Permit? <input type="checkbox"/>	Parking? <input type="checkbox"/>	
Dealer	DOP	Appointment? <input type="checkbox"/>	O.R.? <input type="checkbox"/>	
Installer	Complaint: <i>for installation</i>	Notes: <i>TALAVERA FOR LAYOUT ONLY / E</i>		
Before	After	No. of Visit	Tentative Sched: <i>06/22/2022</i>	
Mode Setting (Cool)		Findings		
WAC Setting Temp (16°C-RE) / (10-ME)				
SAC/PAC Setting Temp (17°)				
Discharge Temperature (High)				
Intake Temperature (High)		Recommendation		
Ampere				
WAC Wattage (Inverter)				
Voltage				
SAC/PAC Pressure				
Part Code	Description	Qty	Unit Price	Amount
	<i>COND 3/8</i>	<i>15</i>	<i>400</i>	<i>19,000</i>
	<i>COND 1/2</i>	<i>10</i>	<i>50</i>	<i>2,600</i>
	<i>stickless pipe</i>	<i>15</i>		
	<i>Clamp (10)</i>	<i>15</i>		
	<i>Clamp (5)</i>	<i>15</i>		
	<i>Pipe 3/4 x 10</i>	<i>2</i>	<i>150</i>	<i>150</i>
	<i>Insulation 7/8 x 3/4</i>	<i>8</i>	<i>200</i>	<i>1,400</i>
SR No. <i>14100004</i>		Labor		<i>14,000</i>
Repair Done <i>lay-out</i>		Handling		
Repair Code <i>POC DRAIN</i>		Others		
Date Attended <i>June 20, 2022</i>		Date Finished <i>June 20, 2022</i>		Total <i>36,150</i>
Time Attended <i>9:20 AM</i>		Time Finished <i>4:00 PM</i>		Amount Paid
This serves as temporary receipt when properly filled up by authorized representative.		Check No.		Balance <i>36,150</i>
Bank / Branch		By signing below, I allow KPII to collect, store & process my personal information as necessary to avail of service & fully understood that my personal information shall be used in accordance w/ Philippine Data Privacy Act & its implementing rules & regulations.		
I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.		Created by: <i>[Signature]</i>		
Technician(s)		Conformed by: <i>[Signature]</i>		
CSR		Customer (Signature over printed name)		

VALIDATED
6/20/2022
 BY: _____
 DATE: _____

36,150

No. HO-00181462
 Previous SJR No. HO-00175848

Customer		Temporada Vince				Date	12-12-2023		
Address		6 Flamingo Drive, Victoria Valley Subd., Brgy. Mayamot, CITY OF ANTIPOLO				Start Time	03:10 pm		
Telephone No.		Mobile No.		0920-9670348 / 0919-6398143		End Time	03:14 pm		
Contact Person	AR DARRYL	Mobile No.	0919-6398143	Tel. No.	0919-6398143	Relayed by	Valle		
Warranty Code				Room Size		Warranty Type	C		
Model	KLG-II-70-201M			Call Origin	IO	Job Class	INST	LVL	1
S/N (I)	17102109-11472	S/N (O)	17202109-11480	Permit?	<input type="checkbox"/>	Parking?	<input type="checkbox"/>	Appointment?	<input type="checkbox"/>
Dealer	KMI	DOP	02/07/2023	Notes: TALavera INSTALLATION OF INDOOR UNIT BRING 1M COPPER TUBE, MAPP GAS, SILVER ROD, FREON, STICKLESS TAPE, AERO TAPE, ELECTRICAL TAPE					
Installer	Richard Talavera	Complaint	For Installation						
Location	FAMILY ROOM	Before	After						
Mode Setting (Cool)				No. of Visit	1st Action	Tentative Sched	12/14/2023		
WAC Setting Temp(16°C-RE)/(10/12-ME)				Findings					
SAC/PAC Setting Temp (17°)									
Discharge Temperature (High)									
Intake Temperature (High)									
Ampere				Recommendation					
Wattage (Inverter)									
Voltage									
SAC/PAC Pressure (PSI)									
Part Code	Description			Qty	Unit Price	Amount			
	Stickless Tape			1					
	Mapp Gas			1					
	Freon 410A			1					
									
SR No.					Labor	600			
Repair Done	Recharge with vacuum install testing and run unit normally operation				Handling				
Repair Code					Others				
Date Attended	12-18-23	Date Finished	12-18-23		Total	600			
Time Attended	09:30 AM	Time Finished	10:20		Amount Paid	0			
This serves as temporary receipt when properly filled up by authorized representative.					Check No.	Bank / Branch			
Serviced by:	Richard Talavera, Ericson	By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.							
I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.		Created by:			Conformed by:				
Technician(s)		RECHILLA CSR			Customer (Signature over printed name)				

Customer: <u>Temponako, Vince</u>		Date: <u>05-16-2022</u>		
Address: <u>Flamingo Drive, Victoria Valley Subd., Brgy. Dela Paz, CITY OF ANTIPOLO, Riz.</u>		Start Time: <u>09:15 pm</u>		
Tel. No.		End Time: <u>09:17 pm</u>		
Mobile No. <u>0920-9670348</u>		Relayed by: <u>Kris</u>		
Contact Person	Mobile No. <u>0927-7941099</u>	Tel. No.	Job Class: <u>INST</u>	
Model: <u>KIG-IF40-3D1M</u>	Call Origin	Job Type: <u>FD</u>		
S/N (I): <u>LIVING/DINING/KITCHEN 1</u>	S/N (O)	Permit? <input type="checkbox"/>	Parking? <input type="checkbox"/>	
Dealer	DOP	Appointment? <input type="checkbox"/>	O.R.? <input type="checkbox"/>	
Installer	Complaint: <u>for installation</u>	Notes: <u>TALavera / FOR LAYOUT ONLY / E</u>		
Before		After	No. of Visit: <u>1</u>	
Mode Setting (Cool)		Findings		
WAC Setting Temp (16°C-RE)/(10-ME)				
SAC/PAC Setting Temp (17°)				
Discharge Temperature (High)				
Intake Temperature (High)		Recommendation		
Ampere		<u>for lay-out / for follow-up</u>		
WAC Wattage (Inverter)		<u>ALL DRAIN LINE.</u>		
Voltage				
SAC/PAC Pressure				
Part Code	Description	Qty	Unit Price	Amount
	<u>C. tube 1/2 x 3/8</u>	<u>53ft</u>	<u>400</u>	<u>17,200</u>
	<u>R. COND 2.0m x 4L</u>	<u>10ft</u>	<u>250</u>	<u>2,500</u>
	<u>PVC PIPE 3/4 x 10</u>	<u>2</u>	<u>150</u>	<u>150</u>
	<u>PVC ELBOW 3/4</u>	<u>4</u>		
	<u>Clamp (S)</u>	<u>5</u>		
	<u>Clamp (S)</u>	<u>5</u>		
	<u>stickless</u>	<u>1</u>		
<div style="border: 2px solid black; padding: 5px; display: inline-block;"> LIQUIDATED DATE: <u>6/27/2022</u> </div>				
SR No.	<u>initial charge</u>		Labor	<u>11,000</u>
Repair Done	<u>lay-out c. tubing and</u>		Handling	
Repair Code	<u>lay-out PVC DRAIN LINE</u>		Others	
Date Attended	<u>JUNE 25, 2022</u>	Date Finished	<u>JUNE 25, 2022</u>	Total
Time Attended	<u>9:00 am</u>	Time Finished	<u>3:30 pm</u>	Amount Paid
This serves as temporary receipt when properly filled up by authorized representative.			Check No.	Balance
Bank / Branch			<u>for collection</u>	
Serviced by:		By signing below, I allow KPII to collect, store & process my personal information as necessary to avail of service & fully understand that my personal information shall be used in accordance w/ Philippine Data Privacy Act & its implementing rules & regulations.		
<u>Mason</u>		I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.		
<u>Valle</u>		Created by:	Conformed by:	
Technician(s)		CSR	Customer (Signature over printed name)	

Customer		Date		No. HO-00138722 /	
Address Tempongko, Vince		Start Time		HO-00130833	
, 6 Flamingo Drive, Victoria Valley Subd., Brgy. Dela Paz, CITY OF ANTIPOLO, Riz		End Time		01-18-2023	
Tel. No.1..		Relayed by		09:38 am	
Mobile No.		Warranty Type		H-SRVEY-DELA CRUZ	
Contact Person	0920-9670348/ 0919- Mobile No.	Tel. No.	Job Class		
Model	AR. DARRYL	0919-6398143	Call Origin	19-6398143	
S/N (I)	KLG-IF40-3D1M	S/N (O)	IC	Permit? <input type="checkbox"/>	Parking? <input type="checkbox"/>
Dealer	LIVING/DINING/KITCHEN 1	DOP	Notes:	Appointment? <input type="checkbox"/>	F.O.R.? <input type="checkbox"/>
Installer	Complaint		TALAVERA - INSTALLATION OF OU		
Mode Setting (Cool)		Before	After	For Install	No. of Visit
WAC Setting Temp(16°C-RE)/(10-ME)		1st Action		Findings	01/20/2023
SAC/PAC Setting Temp (17°)		Tentative Sched			
Discharge Temperature (High)		REMARKS: NEED			
Intake Temperature (High)		Recommendation			
Ampere		the outdoor wall bracket, NEED			
WAC Wattage (Inverter)		ADDITIONAL C-TUBE 3 meters			
Voltage					
SAC/PAC Pressure					
Part Code	Description	Qty	Unit Price	Amount	
<p>CLEARED</p> <p>BY: <i>[Signature]</i></p> <p>DATE: 1/21/23</p>					
SR No.	Repair Done		Labor		5,000
	the outdoor wall bracket and		Handling		
	first coat primer paint		Others		
Repair Code	Date Attended		Total		5,000
	JAN 20, 2023		Amount Paid		
Time Attended	Date Finished		Balance		5,000
	10:00 AM		Time Finished		12:00 PM
This serves as temporary receipt when properly filled up by authorized representative.			Check No.	Bank / Branch	
Serviced by:			By signing below, I allow KPII to collect, store & process my personal information as necessary to avail of service & full understanding that my personal information shall be used in accordance w/ Philippine Data Privacy Act & its implementing rules & regulations.		
TALAVERA		MEJING		I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.	
VALU		BERMO		Created by:	
Technician(s)		RODEN PUL / CSR BARIT		Conformed by:	
				Customer	
				(Signature over printed name)	



Kolin Philippines International Inc.
 1854 Sta. Rita St. Alcala, Marikina City
 Tel. No. 8852-6888 / Mobile: 0917-8118982 / Email: service@kolinphil.com.ph
 Website: www.kolinphil.com.ph

SERVICE JOB REPORT

Customer		Date	
Address		Start Time	
Tel. No.		End Time	
Mobile No.		Relayed by	
Contact Person		Warranty Type	
Model		Job Class	
S/N (I)		Job Type	
Dealer		Notes:	
Installer		Complaint	

Mode Setting (Cool)	Before	After	No. of Visit	Tentative Sched	Findings
WAC Setting Temp(16°C-RE)/(10-ME)					
SAC/PAC Setting Temp (17°)					
Discharge Temperature (High)					
Intake Temperature (High)					Recommendation
Ampere					
WAC Wattage (Inverter)					
Voltage					
SAC/PAC Pressure					

Part Code	Description	Qty	Unit Price	Amount
	3/4 x 1/2 c. tube	10ft	400	4,000
	wrap gas torch	1		
	stickles tape	1		
	2. cond 2.0 max 4C	10ft	100	1,000
	double clamp	10PCS		
	single clamp	10PCS		
	FROM 402			

LIQUIDATED
 2/7/2023
 DATE: _____

SR No.	SR-40-26061	Labor	
Repair Done	Additional lay-out c. tube	Handling	
Repair Code		Others	
Date Attended	FEB 6, 2023	Date Finished	FEB 6, 2023
Time Attended	10:01 AM	Time Finished	3:10 PM
This serves as temporary receipt when properly filled up by authorized representative.		Check No.	Bank / Branch
Amount Paid		Balance	
Total		for collect	

Serviced by:	By signing below, I allow KPII to collect, store & process my personal information as necessary to avail of service & fully understood that my personal information shall be used in accordance w/ Philippine Data Privacy Act & its implementing rules & regulations.		
Technician(s)	I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.		
	Created by:	Conformed by:	Customer
	RODEN PULONGBARIT		(Signature over printed name)



Kolin Philippines International Inc.
 1854 Sta. Rita St., Guadalupe Nuevo, Makati City
 Tel. No. 8852-6868 / Mobile: 0917-8118982 / Email: service@kolinphil.com.ph
 Website: www.kolinphil.com.ph

SERVICE JOB REPORT

No. HO-00143724
 Previous SJR No. HO-00138512

Customer	Tempondoka, Vince			Date	03-09-2023		
Address	6 Flamingo Drive, Victoria Valley Subd., Brgy. Dela Paz, CITY OF ANTIPOLO, RIZAL			Start Time	10:04 am		
Tel. No.				End Time	10:07 am		
Mobile No.	0920-9670348 / 0919-8398143			Relayed by	Engr. Ken		
Contact Person	MR. DARRYL	Mobile No.	0919-8398143	Tel. No.	0919-8398143		
Model	GLG-IF40-3D1M			Call Origin	O		
S/N (I)	LIVING/DINING/KITCHEN 1		S/N (O)			Permit?	<input type="checkbox"/>
Dealer			DOP			Parking?	<input type="checkbox"/>
Installer			Complaint	For installation		Appointment?	<input type="checkbox"/>
				Notes: TALAVERA - FOR INSTALLATION OF F BREAKER & POWER SUPPLY WIRE.			

Before	After	No. of Visit	1st Action	Tentative Sched	03/10/2023
Mode Setting (Cool)				Findings	
WAC Setting Temp (16°C-RE) / (10-ME)					
SAC/PAC Setting Temp (17°)					
Discharge Temperature (High)					
Intake Temperature (High)				Recommendation	
Ampere					
WAC Wattage (Inverter)					
Voltage					
SAC/PAC Pressure					

Part Code	Description	Qty	Unit Price	Amount
A. COMB	5.5 mm - 3C	10tr	70	700
B. Breaker	40 Am	1	1000	1000

SR No.				Labor	
Repair Done	buy-out supply wire			Handling	
Repair Code				Others	
Date Attended	Mar 10, 2023	Date Finished	Mar 10, 2023	Total	1700
Time Attended	11:45 PM	Time Finished	1:15 PM	Amount Paid	
This serves as temporary receipt when properly filled up by authorized representative.				Check No.	
				Bank / Branch	for collection

Serviced by:		By signing below, I allow KPII to collect, store & process my personal information as necessary to avail of service & fully understood that my personal information shall be used in accordance w/ Philippine Data Privacy Act & its implementing rules & regulations.			
Talavera		I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.			
Valki		Created by:	Conformed by:		
Technician(s)		RODEN PULONGBARIT	Customer		
		CSR	(Signature over printed name)		



Kolin Philippines International Inc.
 1854 Sta. Rita St. Alabaster, Makati City
 Tel. No. 8852-6868 Mobile: 0917-8118982 / Email: service@kolinphil.com.ph
 Website: www.kolinphil.com.ph

24643

SERVICE JOB REPORT

Customer		Address		Tel. No.		Mobile No.		Contact Person		Model		S/N (I)		Dealer		Installer							
Date		Start Time		End Time		Relayed by		Warranty Type		Job Class		Job Type		Permit? <input type="checkbox"/>		Parking? <input type="checkbox"/>		Appointment? <input type="checkbox"/>		O.R. <input type="checkbox"/>		Ladder? <input type="checkbox"/>	
No. Previous SJR No.		Tel. No.		Call Origin		Notes:		Complaint		Tentative Sched		Before		After		No. of Visit		Unit		ECV		Action	

Mode Setting (Cool)	Findings
WAC Setting Temp(16°C-RE)/(10-ME)	
SAC/PAC Setting Temp (17°)	
Discharge Temperature (High)	
Intake Temperature (High)	Recommendation
Ampere	for layout.
WAC Wattage (Inverter)	
Voltage	
SAC/PAC Pressure	

Part Code	Description	Qty	Unit Price	Amount
	c. more 1/2 x 1/4	155	400	18,000
	n. com 2.0mm x 40	102	50	2,600
	Stackers tape	15		
	clasp (S)	15		
	clasp (V)	15		
	PVC pipe 3/4 x 10	2	150	150
	PVC elbow 3/4	2		

LIQUIDATED
 BY: [Signature]
 DATE: 6/25/2022

SR No.	initial change	Labor	11,000
Repair Done	lay-out c. tube and PVC PIPE DRAIN LINE	Handling	
Repair Code		Others	
Date Attended	June 24, 2022	Date Finished	June 24, 2022
Time Attended	10:00 AM	Time Finished	5:20 PM
This serves as temporary receipt when properly filled up by authorized representative.		Check No.	Bank / Branch
Amount Paid		31,750.00	
Balance		31,750.00	

Serviced by:		By signing below, I allow KPII to collect, store & process my personal information as necessary to avail of service & fully understood that my personal information shall be used in accordance w/ Philippine Data Privacy Act & its implementing rules & regulations.	
I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.		Created by:	
Technician(s)		Conformed by:	
ARCHIE ARTIGA CSR		Customer (Signature over printed name)	



Kolin Philippines International Inc.
 1854 Sta. Rita St. Alabang, Muntinlupa City
 Tel. No. 8852-6868 Mobile: 0917-8118982 / Email: service@kolinphil.com.ph
 Website: www.kolinphil.com.ph

SERVICE JOB REPORT

Customer		Date		HO-00138724	
Address		Start Time		HO-00138833	
6 Flamingo Drive, Victoria Valley Subd., Brgy. Dela Paz, CITY OF ANTIPOLO, Riz.		End Time		01-18-2023	
Tel. No.		Relayed by		09:39 am	
Mobile No.		Warranty Type		II-SRVEY-DELA CRUZ	
Contact Person	0920-9670348 / 0919-6398143	Mobile No.	Tel. No.	Job Class	L
Model	AP. DARRYL	0919-6398143	Call Origin	0919-6398143	Job Type
S/N (I)	KLG-IF40-3D1M	S/N (O)	Permit?	Parking?	Appointment?
Dealer	LIVING/DINING/KITCHEN 2	DOP	Notes:	O.R.?	Ladder?
Installer	Complaint				TALavera - INSTALLATION OF OU
Mode Setting (Cool)	Before	After	No. of Visit	Tentative Sched	For Installation
WAC Setting Temp(16°C-RE)/(10-ME)	1st Action				Findings
SAC/PAC Setting Temp (17°)	Recommendation				01/20/2023
Discharge Temperature (High)	for FAB. outdoor wall bracket				
Intake Temperature (High)	NEED ADDITIONAL C-TUBE, 3/4 meter				
Ampere					
WAC Wattage (Inverter)					
Voltage					
SAC/PAC Pressure					
Part Code	Description	Qty	Unit Price	Amount	
<p>CLEARED</p> <p>BY <i>[Signature]</i></p> <p>DATE: 1/21/23</p>					
SR No.	Labor			\$ 5,000	
Repair Done	for outdoor wall bracket and			Handling	
Repair Code	rust coated primer paint			Others	
Date Attended	Jan 20, 2023	Date Finished	Jan 20, 2023	Total	
Time Attended	10:00 am	Time Finished	12:00 pm	\$ 5,000	
This serves as temporary receipt when properly filled up by authorized representative.			Check No.	Bank / Branch	
Serviced by:		By signing below, I allow KPII to collect, store & process my personal information as necessary to avail of service & fully understood that my personal information shall be used in accordance w/ Philippine Data Privacy Act & its implementing rules & regulations.			
Talavera	Maring	I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.			
Valle	Bernu	Created by:	Conformed by:		
Technician(s)		Customer		(Signature over printed name)	



Kolin Philippines International Inc.
 1854 Sta. Rita St. Talupe Nuevo, Makati City
 Tel. No. 8852-6888 Mobile: 0917-8118982 / Email: service@kolinphil.com.ph
 Website: www.kolinphil.com.ph

SERVICE JOB REPORT

Customer		Date	
Address: Tampongko, Vince		HO-00131098	
6 Flamingo Drive, Victoria Valley Subd., Brgy. Dela Paz, CITY OF ANTIPOLO, Riz		Start Time: 02-06-2023	
Tel. No.		End Time: 03:24 am	
Mobile No.		Relayed by: 03:26 am	
Contact Person: 0920-9670348 / 0919-8398143		Warranty Type: Engr. Ken	
Mobile No.		Job Class: C	
Model: AR DARRYL		Job Type: INST	
S/N (I): KLG-IF40-3D1M		S/N (O):	
Dealer: LIVING/DINING/KITCHEN 2		Notes:	
Installer:		Complaint: TALAVERA - BRING COPPER TUBE	

Mode Setting (Cool)	Before	After	No. of Visit	Tentative Sched
WAC Setting Temp (16°C-RE)/(10-ME)			1st Action	Findings: 02/06/2023
SAC/PAC Setting Temp (17°)				
Discharge Temperature (High)				
Intake Temperature (High)				Recommendation
Ampere				for ADDITIONAL lay-out C. TUBE
WAC Wattage (Inverter)				
Voltage				
SAC/PAC Pressure				

Part Code	Description	Qty	Unit Price	Amount
	C. TUBE 1/2 x 3/4	11tr	400	4,400
	A. COND 20mm / 4C	10tr	100	1,000
	stickless tape	1		
	map 6x5	1		
	clay (D)	140		
	clay (S)	110		

SR No.	SR-10-26062	Labor	
Repair Done	Additional lay-out C. TUBE	Handling	
Repair Code		Others	
Date Attended	FEB 6. 2023	Date Finished	FEB 6. 2023
Time Attended	10:01 AM	Time Finished	3:00 PM
This serves as temporary receipt when properly filled up by authorized representative.		Check No.	
Serviced by:		Bank / Branch	per collect

Talavera Valle Technician(s)		Dela Cruz CSR	
Created by:		Conformed by:	
(Signature over printed name)		(Signature over printed name)	



Kolin Philippines International Inc.
 1854 Sta. Rita St. Alhambra, Marikina City
 Tel. No. 8852-6811 Mobile: 0917-8118982 / Email: service@kolinphil.com.ph
 Website: www.kolinphil.com.ph

24609

SERVICE JOB REPORT

No. HD-00113431
 Previous SJR No. HD-00100129 **113431**

Customer	Tempongko, Vince			Date	06-16-2022
Address	Flamingo Drive, Victoria Valley Subd., Brgy. Dela Paz, CITY OF ANTIPOLO, Rizal			Start Time	01:30 pm
Tel. No.		End Time	01:31 pm		
Mobile No.	0920-9670348	Relayed by	Kni		
Contact Person		Warranty Type	C		
Mobile No.	0927-7941099	Tel. No.		Job Class	INST
Model	KSM-IW25-SH1M	Call Origin		Job Type	FD
S/N (I)	MASTER'S BEDROOM	S/N (O)		Permit? <input type="checkbox"/>	Parking? <input type="checkbox"/>
Dealer		DOP		Appointment? <input type="checkbox"/>	O.R.? <input type="checkbox"/>
Installer		Complaint	For installation		
			Notes: TALAVERA #FOR LAYOUT ONLY / E		

Before	After	No. of Visit	Tentative Sched	DD: "WAIT FOR ADVISE" NOTE: BEDROOM
			6/22/2022	
Mode Setting (Cool)			Findings	
WAC Setting Temp(16°C-RE)/(10-ME)				
SAC/PAC Setting Temp (17°)				
Discharge Temperature (High)				
Intake Temperature (High)			Recommendation	
Ampere			for lay-out	
WAC Wattage (Inverter)				
Voltage				
SAC/PAC Pressure				

Part Code	Description	Qty	Unit Price	Amount
	C. tube 3/8 x 3/8	50	400	16,000
	n cond 2.0mm x 4C	57	50	2,850
	p. insulation 2 1/8 x 3/4	2	350	700
	PVC PIPE 3/4 x 10'	12	150	1,800
	clamps (V)	1		
	clamps (S)	5		
	Stainless Tape	13		

LIQUIDATED
 BY: *[Signature]*
 DATE: 6/22/2022

SR No.	initial change	Labor	5,500
Repair Done	lay-out C. tube and lay-out drain line	Handling	
Repair Code		Others	
Date Attended	JUNE 24, 2022	Total	79,700
Date Finished	JUNE 24, 2022	Amount Paid	
Time Attended	10:00 pm	Balance	24,700
Time Finished	5:20 pm	Bank / Branch	for collect

This serves as temporary receipt when properly filled up by authorized representative.

Check No. _____ Bank / Branch _____

Serviced by: *Talavera Medina*
Vale Permado

By signing below, I allow KPII to collect, store & process my personal information as necessary to avail of service & fully understood that my personal information shall be used in accordance w/ Philippine Data Privacy Act & its implementing rules & regulations.
 I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.

Created by: *ARCHIE ARTIGA* Conformed by: *JUDITH BARTALBAL*
 Technician(s) CSR Customer
 (Signature over printed name)

Customer		Date		No. Previous SJR No.	
Address		Start Time		HO-00140473	
6 Flamingo Drive, Victoria Valley Subd., Brgy. Dela Paz, CITY OF ANTIPOLO, Rizal		End Time		HO-00131038	
Tel. No.		Relayed by		03:26 am	
Mobile No.		Warranty Type		Engr. Ken	
Contact Person		Tel. No.		Job Class	
Model		Call Origin		Job Type	
S/N (I)		S/N (O)		Permit? <input type="checkbox"/> Parking? <input type="checkbox"/> Appointment? <input type="checkbox"/> O.R.? <input type="checkbox"/> Ladder? <input type="checkbox"/>	
Dealer		DOP		Notes:	
Installer		Complaint		TALAVERA - BRING COPPER TUBE	
Mode Setting (Cool)		1st Action		Findings	
WAC Setting Temp (16°C-RE)/(10-ME)		No. of Visit		Tentative Sched	
SAC/PAC Setting Temp (17°)		For Installation		AL CORD 5 METERS MAP	
Discharge Temperature (High)		Before		After	
Intake Temperature (High)		Recommendation		for additional lay-out	
Ampere		WAC Wattage (Inverter)		C. tube	
Voltage		SAC/PAC Pressure			
Part Code	Description	Qty	Unit Price	Amount	
	C. TUBE 3/8 X 5/8	15	400	6,000	
	W. COIL 2.0mm x 2 1/2	1			
	(thickness)	1			
	Clamp (D)	10			
	Clamp (S)	10			
	map gas forcell	1			
SR No.		Labor			
Repair Done		Handling			
Repair Code		Others			
Date Attended		Total		6,000	
Time Attended		Amount Paid			
This serves as temporary receipt when properly filled up by authorized representative.		Check No.		Bank / Branch	
Created by:		Conformed by:		to collect	

LIQUIDATED
 2/9/23
 BY: [Signature]
 DATE: [Signature]

Customer
 Signature
 Signature



Kolin Philippines International Inc.
 1854 Sta. Rita St., Guadalupe Nuevo, Makati City
 Tel. No. 8852-6868 / Mobile: 0917-8118982 / Email: service@kolinphil.com.ph
 Website: www.kolinphil.com.ph

SERVICE JOB REPORT

No. 43210
 Previous SJR No. HO-0010312

Customer	[Blank]			Date	03-10-2023
Address	[Blank]			Start Time	10:03 am
Tel. No.	[Blank]			End Time	11:07 am
Mobile No.	[Blank]			Relayed by	Engr. Ken
Contact Person	Mobile No.	Tel. No.	Job Class	Warranty Type	[Blank]
Model	Call Origin	Job Type	[Blank]		
S/N (I)	S/N (O)	Permit? <input type="checkbox"/>	Parking? <input type="checkbox"/>	Appointment? <input type="checkbox"/>	O.R.? <input type="checkbox"/> Ladder? <input type="checkbox"/>
Dealer	DOP	Notes:			
Installer	Complaint	TALAMERA FOR INSTALLATION O			

BRING BREAKER & 3M [Blank]	Before	After	No. of Visit	Tentative Sched
Mode Setting (Cool)				Findings
WAC Setting Temp (16°C-RE)/(10-ME)				
SAC/PAC Setting Temp (17°)				
Discharge Temperature (High)				
Intake Temperature (High)				Recommendation
Ampere				
WAC Wattage (Inverter)				for lay-out supply wire
Voltage				
SAC/PAC Pressure				

Part Code	Description	Qty	Unit Price	Amount
	R. COND 3.5 mm x 4c	007	60	1,200 ✓
	C. Breaker 30amp	1	1,000	1,000 ✓

LIQUIDATED
 BY: [Signature]
 DATE: 3/10/23

SR No.	[Blank]			Labor	
Repair Done	lay-out supply wire			Handling	
Repair Code	[Blank]			Others	
Date Attended	Mar 10, 2023	Date Finished	Mar 10, 2023	Total	2,200
Time Attended	11:45 am	Time Finished	1:15 pm	Amount Paid	
This serves as temporary receipt when properly filled up by authorized representative.				Check No.	Bank / Branch

Serviced by: Talavera [Signature]	By signing below, I allow KPII to collect, store & process my personal information as necessary to avail of service & fully understood that my personal information shall be used in accordance w/ Philippine Data Privacy Act & its implementing rules & regulations. I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.
Created by: RODEN PULONGBARIT CSR	Conformed by: [Signature] Customer (Signature over printed name)



Kolin Philippines International Inc.
 1854 Sta. Rita St. Adalupe Nuevo, Makati City
 Tel. No. 8852-6866 Mobile: 0917-8118982 / Email: service@kolinphil.com.ph
 Website: www.kolinphil.com.ph

SERVICE JOB REPORT

No. **HO-00113429**
 Previous SJR No. **HO-00100129**
 Date **06-16-2022**
 Start Time **07:20 pm**
 End Time **08:30 pm**
 Relayed by **KPI**
 Warranty Type **C**
 Job Class **INST**
 Job Type **FB**

Customer: **Tempongka, Vince**
 Address: **6 Flamingo Drive, Victoria Valley Subd., Brgy. Dela Paz, CITY OF ANTIPOLO, Riz.**
 Tel. No. **0920 9670349**
 Mobile No. **0927 7941093**
 Contact Person: **KEM IWIG CHIM**
 Model: **BEDROOM 3**
 S/N (I) **BEDROOM 3** S/N (O) **10**
 Dealer: **DOP** Notes: **TALAVERA FOR LAYOUT ONLY / E**
 Installer: **Complaint**

1st Action **DD: "WAIT FOR ADVISE" NOTE: BEDROOM**
 Tentative Sched **06/22/2022**
 Mode Setting (Cool) **1st Action** Findings
 WAC | Setting Temp (16°C-RE)/(10-ME)
 SAC/PAC | Setting Temp (17°)
 Discharge Temperature (High)
 Intake Temperature (High) Recommendation
 Ampere **for lay out**
 WAC | Wattage (Inverter)
 Voltage
 SAC/PAC | Pressure

Part Code	Description	Qty	Unit Price	Amount
	c. tube 1/2 x 1/4	150	30	14,000
	R. conn 2.6m x 4C	57	50	2,350
	Proctase tape	15 pc		
	clasp (S)	15		
	clasp (D)	15		
	rubber insulation 2 1/8 x 1/4	1	350	350
	PVC PIPE 3/4 x 10	2	150	150

QUOTED
 BY: **[Signature]**
 DATE: **6/20/2022**

SR No. **initial charged** Labor **4,500**
 Repair Done **lay-out c. tubing** Handling
lay-out DRAIN LINE Others
 Repair Code Total **10,850 21,350**
 Date Attended **JUN 20, 2022** Date Finished **JUN 20, 2022** Amount Paid **9,500**
 Time Attended **9:30 am** Time Finished **4:00 pm** Balance **10,850 21,350**

This serves as temporary receipt when properly filled up by authorized representative. Check No. **1** Bank / Branch **for collection**

Serviced by: **Blanca Medina**
Vivie Pascua
 Technician(s)

By signing below, I allow KPI to collect, store & process my personal information as necessary to avail of service & fully understood that my personal information shall be used in accordance w/ Philippine Data Privacy Act & its implementing rules & regulations. I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.

Created by: **ARCHIE ARTIGA** Conformed by: **[Signature]** Customer
 CSR (Signature over printed name)

Customer		Address		Telephone No.		Contact Person		Warranty Code		Model		S/N (I)		S/N (O)		Dealer		Installer		Location		Mode Setting (Cool)		WAC Setting Temp(16°C-RE)/(10/12-ME)		SAC/PAC Setting Temp (17°)		Discharge Temperature (High)		Intake Temperature (High)		Ampere		Wattage (Inverter)		Voltage		SAC/PAC Pressure (PSI)	
Tempogko, Vince		6 Flamingo Drive, Victoria Valley Subd., Brgy. Dela Paz. CITY OF ANTIPOLO, Riz.						DARRYL				KSLH-WV15-6H1M				BEDROOM 3		18252106		73747		BEDROOM 3																	
Date		Start Time		End Time		Relayed by		Warranty Type		Job Class		Job Type		Permit? <input type="checkbox"/>		Parking? <input type="checkbox"/>		Appointment? <input type="checkbox"/>		O.R.? <input type="checkbox"/>		Ladder? <input type="checkbox"/>																	
07-03-2023		07-03-2023		08:31 am		08:38 am		IH Monitoring- Lvs/ E.		L		INST																											
Mobile No.		Tel. No.		Room Size		Call Origin		Notes		Complaint		Before		After		No. of Visit		Tentative Sched		1st Action		Findings																	
0919-8398143		070348/ 0919-8398143		19-8398143				LOPEZ - FOR INSTALLATION OF OUTDOOR UNIT ONLY - BRING BRACKET, BREAKER AND POWER SUPPLY		23981																													
Part Code		Description		Qty		Unit Price		Amount																															
		C. Breaker 20 Amp		1		1,000		1,000																															
		B. Cord 3.5 amp x 30		7ft		60		420																															
SR No.		Repair Done		Repair Code		Date Attended		Time Attended		Date Finished		Time Finished		Check No.		Bank / Branch		Labor		Handling		Others		Total		Amount Paid		Balance											
		Installation indoor & outdoor unit for start-up				July 2, 2023		9:40 am		July 6, 2023		3:30 pm				for collection		Ref. #0-113429						1,420		1,420													
This serves as temporary receipt when properly filled up by authorized representative.		Serviced by:		Created by:		Conformed by:		Customer (Signature over printed name)		I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.																													
Talavera Medina		Valu D.F.																																					



Kolin Philippines International Inc.
 1854 Sta. Rita St. Adalupe Nuevo, Makati City
 Tel. No. 8852-6888 Mobile: 0917-8118982 / Email: service@kolinphil.com.ph
 Website: www.kolinphil.com.ph

24902

SERVICE JOB REPORT

No. **HD-00113428**
 Previous SJR No. **110428**

Customer	Temprigto, Vince			Date	08-18-2022
Address	6 Flamingo Drive, Victoria Valley Subd. Brgy. Dala Paz, CITY OF ANTIPOLLO, RIZAL			Start Time	01:26 pm
Tel. No.				End Time	01:28 pm
Mobile No.	0920-9870348			Relayed by	Kmi
Contact Person		Mobile No.	0927-7941089	Tel. No.	
Model	KSM-IW15-SH1M	Call Origin		Job Class	REST
S/N (I)	BEDROOM 2	S/N (O)		Job Type	FD
Dealer		DOP		Permit? <input type="checkbox"/>	Parking? <input type="checkbox"/>
Installer		Complaint		Appointment? <input type="checkbox"/>	O.R.? <input type="checkbox"/>
1 WAG DAW PONG IAN			Before	After	No. of Visit
TALAVERA / FOR LAYOUT ONLY / E			Notes: DD: "WAIT FOR ADVISE" NOTE- BEDROOM		
			Tentative Sched 06/22/2022		

Mode Setting (Cool)		Findings
WAC Setting Temp (16°C-RE)/(10-ME)		
SAC/PAC Setting Temp (17°)		
Discharge Temperature (High)		
Intake Temperature (High)		Recommendation
Ampere		lay-out
WAC Wattage (Inverter)		
Voltage		
SAC/PAC Pressure		

Part Code	Description	Qty	Unit Price	Amount
	C. TUBE 1/2 X 1/4	1577	350	9,450
	R. COM 2.0mm X 4C	1447	50	1,700
	stickless	-2K		
	clamp (D)	15		
	clamp (S)	5		
	TUBBER INSULATION 2" SW 3/4	2	350	700
	PVC PIPE 3/4 X 10	2	150	150

BY: *[Signature]*
 ME

SR No.	Initial CHARGE			Labor	4,500
Repair Done	lay-out C. TUBING. AM			Handling	
	lay-out DRAIN LINE			Others	
Repair Code				Total	4,500
Date Attended	JUNE 20, 2022	Date Finished	JUNE 20, 2022	Amount Paid	4,500
Time Attended	9:30 AM	Time Finished	4:00 PM	Balance	0
This serves as temporary receipt when properly filled up by authorized representative.				Check No.	1
Bank / Branch				For collector	
Serviced by:		By signing below, I allow KPII to collect, store & process my personal information as necessary to avail of service & fully understood that my personal information shall be used in accordance w/ Philippine Data Privacy Act & its implementing rules & regulations.			
TALAVERA		I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.			
VILLALBA		Created by:		Conformed by:	
ARCHIE ARTIGA		Customer		JULIAN BALMATEBA	
Technician(s)		CSR		(Signature over printed name)	



Kolin Philippines International Inc.
 1854 Sta. Rita St., Guadalupe Nuevo, Makati City
 Tel. No. 8852-6868 / Mobile: 0917-8118982 / Email: service@kolinphil.com.ph
 Website: www.kolinphil.com.ph

SERVICE JOB REPORT

No. 116936
 Previous SJR No. 116936
 Date 07/14/2022
 Start Time 08:30 am
 End Time 08:39 am
 Relayed by Engr Kenneth
 Warranty Type C
 Job Class ISET
 Job Type FD

Customer Tampungko, Vince
 Address 6 Flamingo Drive, Victoria Valley Subd, Brgy. Dala Paz, CITY OF ANTIPOLLO, Riz
 Tel. No.
 Mobile No. 0920-9670348
 Contact Person Mobile No. 0927-7941099 Tel. No.
 Model KSM-IW15-6H1M Call Origin 10
 S/N (I) BEDROOM 2 S/N (O) Permit? Parking? Appointment? O.R.? Ladder?
 Dealer DOP Notes: TALAVERA / FOR LAY-OUT OF DRAI
 Installer Complaint for installation

Before	After	No. of Visit	Tentative Sched
		1st Action	07/15/2022
Mode Setting (Cool)			
WAC Setting Temp(16°C-RE)/(10-ME)			
SAC/PAC Setting Temp (17°)			
Discharge Temperature (High)			
Intake Temperature (High)			
Ampere			
WAC Wattage (Inverter)			
Voltage			
SAC/PAC Pressure			

Part Code	Description	Qty	Unit Price	Amount
	PVC PIPE 3/4 x 10	3	150 #	300
<div style="border: 2px solid black; padding: 5px; display: inline-block;"> LIQUIDATED <small>DATE: 7/15/22</small> </div>				

SR No. Labor
 Repair Done lay-out PVC PIPE Handling
 Repair Code Others
 Date Attended JULY 15, 2022 Date Finished JULY 15, 2022 Amount Paid 300
 Time Attended 9:08 Am Time Finished 10:50 Am Balance 300
 This serves as temporary receipt when properly filled up by authorized representative. Check No. Bank / Branch for collection

By signing below, I allow KPII to collect, store & process my personal information as necessary to avail of service & fully understood that my personal information shall be used in accordance w/ Philippine Data Privacy Act & its implementing rules & regulations.
 I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.

Serviced by: TALAVERA MORINI
 Technician(s) Valle
 Created by: ARCHIE ARTIGA Conformed by: NABBY GREY A.C.
CSR Customer
 (Signature over printed name)

Kolin Philippines Int'l., Inc.

1854 Sta. Rita St., Guadalupe Nuevo, Makati City
 Tel. No.: 8852-6868 / Mobile: 0917-811-8982 / Email: service@kolinphil.com.ph
 Website: www.kolinphil.com.ph

07-07-2023 2:59

SERVICE JOB REPORT

Customer		Date		No. Previous SJR No. HO-00161090 /	
Address Ternpongko, Vince		Start Time 07-03-2023		End Time 08:31 am	
Telephone No.		Mobile No.		Relayed by 08:38 am	
Contact Person		Tel. No. 0919-6398143		Warranty Type Monitoring-Luis' E...	
Warranty Code AR DARRYL		Room Size 19-6398143		Job Class L LVL	
Model		Call Origin		Job Type INST 2	
S/N (I) KSM-RW15-6H1M		S/N (O)		Permit? <input type="checkbox"/> Parking? <input type="checkbox"/> Appointment? <input type="checkbox"/> O.R.? <input type="checkbox"/> Ladder? <input type="checkbox"/>	
Dealer BEDROOM 2		DOP 1826 2106		Notes	
Installer 1825 2106-23464		Complaint 24049		LOPEZ - FOR INSTALLATION OF OUTDOOR UNIT ONLY - BRING BRACKET, BREAKER AT POWER SUPPLY	
Location		Before		After For Installation	
Mode Setting (Cool) ROOM 2		No. of Visit		Tentative Sched	
WAC Setting Temp (16°C-RE)/(10/12-ME)		1st Action		Findings 07/06/2023	
SAC/PAC Setting Temp (17°)					
Discharge Temperature (High)					
Intake Temperature (High)					
Ampere		Recommendation			
Wattage (Inverter)		for installation			
Voltage					
SAC/PAC Pressure (PSI)					
Part Code	Description	Qty	Unit Price	Amount	
	C. Breaker 20 Amp	1	1000	1,000	
	R. Cond 3/8" x 30	7 FT	60	420	
<div style="border: 1px solid black; padding: 5px; display: inline-block;"> LIQUIDATED BY: <i>[Signature]</i> DATE: 7/6/2023 </div>					
Note: Pressure test 420 psi					
SR No.		Labor		Ref-to-113428	
Repair Done		Handling			
Repair Code		Others			
Date Attended July 4, 2023		Date Finished July 6, 2023		Amount Paid	
Time Attended 9:40 am		Time Finished 3:30 pm		Balance 1,420	
This serves as temporary receipt when properly filled up by authorized representative.		Check No.		Bank / Branch for collection	
Serviced by:		By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.			
I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.		Created by:		Conformed by:	
Technician(s)		CSR		Customer (Signature over printed name)	



Kolin Philippines International Inc.
 1854 Sta. Rita St. Alabang, Alabang, Muntinlupa City
 Tel. No. 8852-6868 / Mobile: 0917-8118982 / Email: service@kolinphil.com.ph
 Website: www.kolinphil.com.ph

24901

SERVICE JOB REPORT

Customer: <i>Tempungko, Vince</i>		Date: <i>06-16-2022</i>	
Address: <i>Flamingo Drive, Victoria Valley Subd., Brgy. Dela Paz, CITY OF ANTIPOLO, Rizal</i>		Start Time: <i>08:25 pm</i>	
Tel. No.:		End Time: <i>08:28 pm</i>	
Mobile No. <i>0920-9670348</i>		Relayed by: <i>Kmi</i>	
Contact Person:	Mobile No. <i>0927-7941099</i>	Warranty Type:	
Tel. No.:		Job Class: <i>INST</i>	
Model: <i>KSM-WV15-6H1M</i>	Call Origin:	Job Type: <i>FD</i>	
S/N (I): <i>BEDROOM 1</i>	S/N (O):	Permit? <input type="checkbox"/>	Parking? <input type="checkbox"/>
Dealer:	DOP:	Appointment? <input type="checkbox"/>	O.R.? <input type="checkbox"/>
Installer:	Complaint: <i>For installation</i>	Notes: <i>TAL AVERA (FOR LAYOUT ONLY) / E</i>	

1 WAG DAW PONG (LALAWAN SA 2ND FLOOR AND IN THE UNIT. EGYPT ACTION)	Before	After	No. of Visit	Tentative Sched
				<i>06/22/2022</i>
Mode Setting (Cool)				Findings
WAC Setting Temp (16°C-RE)/(10-ME)				
SAC/PAC Setting Temp (17°)				
Discharge Temperature (High)				
Intake Temperature (High)				Recommendation
Ampere				<i>for lay-out</i>
WAC Wattage (Inverter)				
Voltage				
SAC/PAC Pressure				

Part Code	Description	Qty	Unit Price	Amount
	<i>C. tube 1/2 x 1/4</i>	<i>45 FT</i>	<i>350</i>	<i>15,750</i>
	<i>R. com. 9.0mm x 4C</i>	<i>50 FT</i>	<i>50</i>	<i>2,500</i>
	<i>stickless tape</i>	<i>25 PCS</i>		
	<i>(D) clamp</i>	<i>25</i>		
	<i>(S) clamp</i>	<i>25</i>		
	<i>R. INSULATION 2 1/8 X 3/4</i>	<i>4</i>	<i>350</i>	<i>1,400</i>
	<i>PVC pipe 3/4 X 10'</i>	<i>2</i>	<i>75</i>	<i>150</i>

INVALIDATED
06/20/2022

SR No.:	<i>initial charges</i>	Labor:	<i>4,500</i>
Repair Done:	<i>lay-out and TRAILING AND lay-out PVC DRAIN LINE</i>	Handling:	
Repair Code:		Others:	
Date Attended: <i>JUNE 20, 2022</i>	Date Finished: <i>JUNE 20, 2022</i>	Total:	<i>18,800 20,400</i>
Time Attended: <i>9:30 AM</i>	Time Finished: <i>4:00 PM</i>	Amount Paid:	<i>18,800</i>
This serves as temporary receipt when properly filled up by authorized representative.		Balance:	<i>20,400</i>
Check No.:		Bank / Branch:	<i>for collection</i>
Serviced by: <i>Talavera Miron</i> <i>Valko Rangel</i>		By signing below, I allow KPII to collect, store & process my personal information as necessary to avail of service & fully understood that my personal information shall be used in accordance w/ Philippine Data Privacy Act & its implementing rules & regulations. I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.	
Created by: <i>ARCHIE ARTIGA</i> Technician(s)		Conformed by: <i>JIMMIE BARRALDI</i> Customer (Signature over printed name)	



Kolin Philippines International Inc.
 1854 Sta. Rita St. Alcala, Cavite, Alabang, Marikina, Marikina City
 Tel. No. 8852-6811 / 8852-6812 / 8852-6813 / 8852-6814 / 8852-6815 / 8852-6816 / 8852-6817 / 8852-6818 / 8852-6819 / 8852-6820 / 8852-6821 / 8852-6822 / 8852-6823 / 8852-6824 / 8852-6825 / 8852-6826 / 8852-6827 / 8852-6828 / 8852-6829 / 8852-6830 / 8852-6831 / 8852-6832 / 8852-6833 / 8852-6834 / 8852-6835 / 8852-6836 / 8852-6837 / 8852-6838 / 8852-6839 / 8852-6840 / 8852-6841 / 8852-6842 / 8852-6843 / 8852-6844 / 8852-6845 / 8852-6846 / 8852-6847 / 8852-6848 / 8852-6849 / 8852-6850 / 8852-6851 / 8852-6852 / 8852-6853 / 8852-6854 / 8852-6855 / 8852-6856 / 8852-6857 / 8852-6858 / 8852-6859 / 8852-6860 / 8852-6861 / 8852-6862 / 8852-6863 / 8852-6864 / 8852-6865 / 8852-6866 / 8852-6867 / 8852-6868 / 8852-6869 / 8852-6870 / 8852-6871 / 8852-6872 / 8852-6873 / 8852-6874 / 8852-6875 / 8852-6876 / 8852-6877 / 8852-6878 / 8852-6879 / 8852-6880 / 8852-6881 / 8852-6882 / 8852-6883 / 8852-6884 / 8852-6885 / 8852-6886 / 8852-6887 / 8852-6888 / 8852-6889 / 8852-6890 / 8852-6891 / 8852-6892 / 8852-6893 / 8852-6894 / 8852-6895 / 8852-6896 / 8852-6897 / 8852-6898 / 8852-6899 / 8852-6900 / 8852-6901 / 8852-6902 / 8852-6903 / 8852-6904 / 8852-6905 / 8852-6906 / 8852-6907 / 8852-6908 / 8852-6909 / 8852-6910 / 8852-6911 / 8852-6912 / 8852-6913 / 8852-6914 / 8852-6915 / 8852-6916 / 8852-6917 / 8852-6918 / 8852-6919 / 8852-6920 / 8852-6921 / 8852-6922 / 8852-6923 / 8852-6924 / 8852-6925 / 8852-6926 / 8852-6927 / 8852-6928 / 8852-6929 / 8852-6930 / 8852-6931 / 8852-6932 / 8852-6933 / 8852-6934 / 8852-6935 / 8852-6936 / 8852-6937 / 8852-6938 / 8852-6939 / 8852-6940 / 8852-6941 / 8852-6942 / 8852-6943 / 8852-6944 / 8852-6945 / 8852-6946 / 8852-6947 / 8852-6948 / 8852-6949 / 8852-6950 / 8852-6951 / 8852-6952 / 8852-6953 / 8852-6954 / 8852-6955 / 8852-6956 / 8852-6957 / 8852-6958 / 8852-6959 / 8852-6960 / 8852-6961 / 8852-6962 / 8852-6963 / 8852-6964 / 8852-6965 / 8852-6966 / 8852-6967 / 8852-6968 / 8852-6969 / 8852-6970 / 8852-6971 / 8852-6972 / 8852-6973 / 8852-6974 / 8852-6975 / 8852-6976 / 8852-6977 / 8852-6978 / 8852-6979 / 8852-6980 / 8852-6981 / 8852-6982 / 8852-6983 / 8852-6984 / 8852-6985 / 8852-6986 / 8852-6987 / 8852-6988 / 8852-6989 / 8852-6990 / 8852-6991 / 8852-6992 / 8852-6993 / 8852-6994 / 8852-6995 / 8852-6996 / 8852-6997 / 8852-6998 / 8852-6999 / 8852-7000

SERVICE JOB REPORT

Customer		Date	
Address		Start Time	
Tel. No.		End Time	
Mobile No.		Relayed by	
Contact Person	Mobile No.	Tel. No.	Warranty Type
Model	Call Origin	Job Class	
S/N (I)	S/N (O)	Permit? <input type="checkbox"/>	Parking? <input type="checkbox"/>
Dealer	DOP	Appointment? <input type="checkbox"/>	O.R.? <input type="checkbox"/>
Installer	Complaint	Notes:	
Before		After	
Mode Setting (Cool)		Findings	
WAC Setting Temp(16°C-RE)/(10-ME)		Recommendation	
SAC/PAC Setting Temp (17°)		Ampere	
Discharge Temperature (High)		WAC Wattage (Inverter)	
Intake Temperature (High)		Voltage	
SAC/PAC Pressure		SAC/PAC Pressure	
Part Code	Description	Qty	Unit Price
	Stainless pipe	1	
	1/4 x 1/2 copper tube	7	350
	ACCESS VALVE 1/4	2	
Amount		2,450	
SR No.		Labor	
Repair Done		Handling	
Repair Code		Others	
Date Attended		Total	
Time Attended		Amount Paid	
This serves as temporary receipt when properly filled up by authorized representative.		Balance	
Check No.		Bank / Branch	
Serviced by:		By signing below, I allow KPII to collect, store & process my personal information as necessary to avail of service & fully understood that my personal information shall be used in accordance w/ Philippine Data Privacy Act & its implementing rules & regulations.	
Created by:		I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.	
Conformed by:		Created by:	
Technician(s)		Customer	
CSR		(Signature over printed name)	

Kolin Philippines Int'l., Inc.

1854 Sta. Rita St., Guadalupe Nuevo, Makati City
 Tel. No.: 8852-6868 / Mobile: 0917-811-8982 / Email: service@kolinphil.com.ph
 Website: www.kolinphil.com.ph

SERVICE JOB REPORT

9/17/23 33757

Customer		Date		No.		Previous SJR No.	
Address		Start Time		Date		HO-00158115	
6 Flamingo Drive, Victoria Valley Subd., Brgy. Dela Paz, CITY OF ANTIPOLO, Riz		End Time		Relayed by		07-03-2023	
Telephone No.		Mobile No.		Warranty Type		08:31 am	
Contact Person		Tel. No.		Job Class		IH Monitoring- Luis E...	
Warranty Code		Room Size		Job Type		LVL	
Model		Call Origin		Permit?		Parking?	
S/N (I)		S/N (O)		Appointment?		O.R.?	
Dealer		DOP		Ladder?			
Installer		Complaint		Notes			
Location		Before		LOPEZ - FOR INSTALLATION OF OUTDOOR UNIT ONLY. BRING BRACKET, BREAKER AND POWER SUPPLY			
Mode Setting (Cool)		After		No. of Visit		Tentative Sched	
WAC Setting Temp(16°C-RE)/(10/12-ME)		1st Action		Findings		07/06/2023	
SAC/PAC Setting Temp (17°)							
Discharge Temperature (High)							
Intake Temperature (High)							
Ampere				Recommendation			
Wattage (Inverter)				for installation			
Voltage							
SAC/PAC Pressure (PSI)							
Part Code	Description	Qty	Unit Price	Amount			
	C. Breaker 20 Amp	1	1,000	1,000			
	A. Cond 3.5mm x 1 3/8	17ft	60	1,020			
LIQUIDATED							
NOTE: Pressure test 420 psi							
SR No.		Labor		Ref. #0-113427			
Repair Done		Handling		Installation indoor & outdoor unit for start up			
Repair Code		Others		Total 1,420			
Date Attended		Date Finished		Amount Paid			
Time Attended		Time Finished		Balance 1,420			
This serves as temporary receipt when properly filled up by authorized representative.		Check No.		Bank / Branch			
Serviced by:		By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.					
Technician(s)		Created by:				Conformed by:	
Jalavera Medina		Customer				(Signature over printed name)	



Kolin Philippines International Inc.
 1854 Sta. Rita St. Alajuela Nuevo, Makati City
 Tel. No. 8852-8866 Mobile: 0917-8118982 / Email: service@kolinphil.com.ph
 Website: www.kolinphil.com.ph

24761

SERVICE JOB REPORT

No. 111631
 Previous SJR No. D-00111631

Customer				Date	03-08-2022
Address	Tempongko, Vince			Start Time	03-08-2022
6 Hamingo Drive, Victoria Valley Subd., Brgy. Dela Paz, CITY OF ANTIPOLLO, Riz				End Time	03:45 am
Tel. No.				Relayed by	03:45 am
Mobile No.				Warranty Type	PRM
Contact Person	0920-9670348	Mobile No.		Tel. No.	
Model	0927-7941098		Call Origin	0920-9670348	Job Class
S/N (I)	RSM-IW15-6H1M	S/N (O)		Permit? <input type="checkbox"/>	Parking? <input type="checkbox"/>
Dealer	STUDY/GUEST ROOM		DOP	Appointment? <input type="checkbox"/>	O.R.? <input type="checkbox"/>
Installer			Complaint	TALAVERA / LAYOUT ONLY 4PAX	

Mode Setting (Cool)	Before	After	No. of Visit	1st Action	Findings	06/07/2022
WAC Setting Temp (16°C-RE)/(10-ME)						
SAC/PAC Setting Temp (17°)						
Discharge Temperature (High)						
Intake Temperature (High)					Recommendation	
Ampere					FOR CONFIRMATION OF BEST LOCATION OF OUTDOOR AND DRAIN	
WAC Wattage (Inverter)						
Voltage						
SAC/PAC Pressure						

Part Code	Description	Qty	Unit Price	Amount
	C-TRAP 1/2	2PCS	18x350	6300
	2-CORNER ANGLE 1/2	3PCS	25x50	1400
	1/2 INSULATION 2 1/2	2PCS	2x50	700
	PVC PIPE 3/4	1PC		
	ELBOW 3/4	3PCS		
	5 TAPE	3PCS		

LIQUIDATED
 BY: [Signature]
 DATE: 6/7/22

SR No.				Labor	
Repair Done	LAT-OUT			Handling	
Repair Code				Others	
Date Attended	6-7-22	Date Finished	6-7-22	Total	12900
Time Attended	9:30	Time Finished	3:00	Amount Paid	FOR COLLECTION
This serves as temporary receipt when properly filled up by authorized representative.				Check No.	
				Bank / Branch	

Serviced by: TALAVERA VALLE BERMEO MEDINA	By signing below, I allow KPIL to collect, store & process my personal information as necessary to avail of service & fully understood that my personal information shall be used in accordance w/ Philippine Data Privacy Act & its implementing rules & regulations. I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.
Created by: ARCHIE ARTICA CSR	Conformed by: [Signature] Customer (Signature over printed name)



Kolin Philippines International Inc.
 1854 Sta. Rita St. Alcala, Alcala, Cavite, Laguna, Makati City
 Tel. No. 8852-6611 / Mobile: 0917-8118982 / Email: service@kolinphil.com.ph
 Website: www.kolinphil.com.ph

24696

SERVICE JOB REPORT

Customer: <u>Tampoonko, Vince</u>		Date: <u>06-18-2022</u>		
Address: <u>6 Flamingo Drive, Victoria Valley Subd., Brgy. Dela Paz, CITY OF ANTIPOLO, Riz.</u>		Start Time: <u>01:24 pm</u>		
Tel. No.		End Time: <u>01:25 pm</u>		
Mobile No. <u>0920-9670348</u>		Relayed by: <u>Kin</u>		
Contact Person	Mobile No. <u>927-7941099</u>	Tel. No.	Warranty Type: <u>C</u>	
Model: <u>KSM-IW15-6H1M</u>	Call Origin	Job Class: <u>INST</u>		
S/N (I): <u>STUDY/GUEST ROOM</u>	S/N (O)	Permit? <input type="checkbox"/>	Parking? <input type="checkbox"/>	
Dealer	DOP	Appointment? <input type="checkbox"/>	O.R.? <input type="checkbox"/>	
Installer	Complaint: <u>for installation</u>	Notes: <u>TALAVERA / FOR LAYOUT ONLY / E</u>		
Before	After	No. of Visit	Tentative Sched: <u>06/22/2022</u>	
Mode Setting (Cool)	Findings			
WAC Setting Temp (16°C-RE) / (10-ME)				
SAC/PAC Setting Temp (17°)				
Discharge Temperature (High)				
Intake Temperature (High)	Recommendation			
Ampere	<u>no installation</u>			
WAC Wattage (Inverter)				
Voltage				
SAC/PAC Pressure				
Part Code	Description	Qty	Unit Price	Amount
	<u>Insulation 2 1/8 x 3/4</u>	<u>4</u>	<u>350</u>	<u>1,400</u>
LIQUIDATED 06/22/2022				
SR No.	Labor			
Repair Done	<u>put double insulation</u>		Handling	
Repair Code	Others		Total: <u>1,400</u>	
Date Attended: <u>JUNE 24, 2022</u>	Date Finished	Amount Paid		
Time Attended: <u>10:30 AM</u>	Time Finished: <u>5:20 PM</u>	Balance: <u>1,400</u>		
This serves as temporary receipt when properly filled up by authorized representative.		Check No.	Bank / Branch: <u>for collection</u>	
Serviced by: <u>Talavera, Valle</u>		By signing below, I allow KPII to collect, store & process my personal information as necessary to avail of service & fully understood that my personal information shall be used in accordance w/ Philippine Data Privacy Act & its implementing rules & regulations.		
Technician(s): <u>Medina, Dennis</u>		I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.		
Created by: <u>ARCHIE ARTIGA</u>		Conformed by: <u>Valle</u>		
CSR		Customer (Signature over printed name)		




Kolin Philippines International Inc.
 1854 Sta. Rita St. Alcala, Alcala Nuevo, Makati City
 Tel. No. 8852-6811 / Mobile: 0917-8118982 / Email: service@kolinphil.com.ph
 Website: www.kolinphil.com.ph

SERVICE JOB REPORT

Customer		Date		No. HO-00141442	
Address: Tampungko, Vince		Start Time: 02-14-2023		Previous SJR No. HO-00132004	
6 Flamingo Drive, Victoria Valley Subd., Brgy. Delfa Paz, CITY OF ANTIPOLO, Rizal		End Time: 10:28 am		Relayed by: 11:00 am	
Tel. No.		Mobile No.		Warranty Type: Engr. Ken	
Contact Person: AR. DARRYL		Tel. No. 0919-6398143		Job Class	
Model: KSM-IW15-6H1M		Call Origin: 0919-6398143		Job Type: INST	
S/N (I): KSM-IW15-6H1M		S/N (O)		Permit? <input type="checkbox"/> Parking? <input type="checkbox"/> Appointment? <input type="checkbox"/> O.R.? <input type="checkbox"/> Ladder? <input type="checkbox"/>	
Dealer: STUDY/GUEST ROOM		DOP		Notes:	
Installer		Complaint		TALAVERA - INSTALLATION OF IN	
Mode Setting (Cool)		Before		After	
WAC Setting Temp (16°C-RE)/(10-ME)		ROYAL CORD 2 METERS / NAPP GAS / NITROGEN		1st Action	
SAC/PAC Setting Temp (17°)				Findings: 02/15/2023	
Discharge Temperature (High)					
Intake Temperature (High)				Recommendation	
Ampere				for installation indoor unit	
WAC Wattage (Inverter)					
Voltage					
SAC/PAC Pressure					
Part Code	Description	Qty	Unit Price	Amount	
	a. tube 1/4 x 1/2	7pc	350	2,450	
	chickcase type	2			
	map GAS torch	1			
	tubh 410 (A)				
BY:		DATE: 2/15/2023			
SR No.	HO-26262	Labor	Ref. #0-111631		
Repair Done	Installation indoor unit, bracing additional C. tube.	Handling			
Repair Code		Others			
Date Attended	FEB 15, 2023	Total	2,450		
Time Attended	9:30 am	Amount Paid			
Date Finished	FEB 15, 2023	Balance	2,450		
Time Finished	3:50 pm	Check No.			
This serves as temporary receipt when properly filled up by authorized representative.		Bank / Branch	to collect		
Serviced by: Talavera Medina		By signing below, I allow KPII to collect, store & process my personal information as necessary to avail of service & fully understood that my personal information shall be used in accordance w/ Philippine Data Privacy Act & its implementing rules & regulations.			
Valle Lopez		I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.			
Technician(s)		Created by: RODEN PULOSBANT	Conformed by:		
		CSR	Customer (Signature over printed name)		

07-09-23 33756

Customer		Date	
Address		Start Time	
Telephone No.		End Time	
Contact Person	Mobile No.	Relayed by	Warranty Type
Warranty Code	Room Size	Job Class	LVL
Model	Call Origin	Job Type	
S/N (I)	S/N (O)	Permit? <input type="checkbox"/>	Parking? <input type="checkbox"/>
Dealer	DOP	Appointment? <input type="checkbox"/>	O.R.? <input type="checkbox"/>
Installer	Complaint	Ladder? <input type="checkbox"/>	
Location	Before	After	Notes
Mode Setting (Cool)	No. of Visit	Tentative Sched	
WAC Setting Temp(16°C-RE)/(10/12-ME)	1st Action	Findings	07/06/2023
SAC/PAC Setting Temp (17°)			
Discharge Temperature (High)			
Intake Temperature (High)			
Ampere			Recommendation
Wattage (Inverter)			Fan leak testing
Voltage			
SAC/PAC Pressure (PSI)			

Part Code	Description	Qty	Unit Price	Amount
	C. Breaker 20Amp	1	1,000	1,000
				
Note: NEED FOR CHIPPING AND OPEN UP CEILING, NEED TO FIND THE LEAK.				

SR No.	Labor
Repair Done	Handling
Repair Code	Others
Date Attended	Date Finished
Time Attended	Time Finished
This serves as temporary receipt when properly filled up by authorized representative.	
Check No.	Bank / Branch

Serviced by: Talavera Medina Valle N.P.	By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations. I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.
Technician(s)	Customer (Signature over printed name)
CSR	

24208

SERVICE JOB REPORT

Customer		Date		No. Previous SJR No. HD-00111629 /	
Address		Start Time		HD-00098583	
Tel. No.		End Time		08-08-2022	
Mobile No.		Relayed by		08:41 am	
Contact Person		Warranty Type		08:42 am	
Model		Job Class		KOL	
S/N (I)		Job Type		KOL	
Dealer		Notes:		TALAWEBA / LAYOUT ONLY (PAX	
Installer		Complaint		W/PARKING EGY REFERRAL W/DP BASED	
Mode Setting (Cool)		Findings		ON SURVEY QUOTATION Before After No. of Visit Tentative Sched	
WAC Setting Temp (16°C-RE)/(10-ME)		Recommendation		08/07/2022	
SAC/PAC Setting Temp (17°)		FOR CONFIRMATION OF			
Discharge Temperature (High)		OUTDOOR LOCATION AND			
Intake Temperature (High)		DRAIN LINE			
Ampere					
WAC Wattage (Inverter)					
Voltage					
SAC/PAC Pressure					
Part Code	Description	Qty	Unit Price	Amount	
	Cable 1/4 x 1/2	34 FT	24 X 350	8,400	
	CORD 4x2mm	44 FT	34 X 50	1,700	
	PVP PIPE 3/4	3 FT	-	-	
	Shape	4 PCS	-	-	
SR No.		Labor		4,500	
Repair Done		Handling			
Repair Code		Others			
Date Attended		Total		14,600	
Time Attended		Amount Paid		for collection	
This serves as temporary receipt when properly filled up by authorized representative.		Balance		14,600	
Check No.		Bank / Branch			
Serviced by:		By signing below, I allow KPII to collect, store & process my personal information as necessary to avail of service & fully understood that my personal information shall be used in accordance w/ Philippine Data Privacy Act & its implementing rules & regulations.			
Created by:		I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.			
Conformed by:		Customer			
Technician(s)		(Signature over printed name)			

LIQUIDATED
 BY: [Signature]
 DATE: 6/7/2022



Kolin Philippines International Inc.
 1854 Sta. Rita St. Alcala Nuevo, Makati City
 Tel. No. 8852-6811 Mobile: 0917-8118982 / Email: service@kolinphil.com.ph
 Website: www.kolinphil.com.ph

SERVICE JOB REPORT

Customer		Date	
Address		Start Time	
Tel. No.		End Time	
Mobile No.		Relayed by	
Contact Person		Warranty Type	
Model		Job Class	
S/N (I)		Job Type	
Dealer		Permit? <input type="checkbox"/> Parking? <input type="checkbox"/> Appointment? <input type="checkbox"/> O.R.? <input type="checkbox"/> Ladder? <input type="checkbox"/>	
Installer		Notes:	

Mode Setting (Cool)	Before	After	No. of Visit	Tentative Sched
WAC Setting Temp (16°C-RE)/(10-ME)			1st Action	Findings
SAC/PAC Setting Temp (17°)				02/15/2023
Discharge Temperature (High)				
Intake Temperature (High)				Recommendation
Ampere				
WAC Wattage (Inverter)				
Voltage				
SAC/PAC Pressure				

Part Code	Description	Qty	Unit Price	Amount
	tube 1/4 x 1/4	7	30	210
	flexless tape	2		
	map GAS Blow torch	1		

LIQUIDATED
 BY: [Signature]
 DATE: 2/16/2023

SR No.	#0-20261	Labor	Ref. #0-11629
Repair Done	installation indoor unit	Handling	
	blowing c. tube	Others	
Repair Code		Total	2,450
Date Attended	Feb 15, 2023	Date Finished	Feb 15, 2023
Time Attended	9:30 AM	Time Finished	3:50 PM
This serves as temporary receipt when properly filled up by authorized representative.		Check No.	Bank / Branch

Serviced by: Talavera Lopez Valle Serrano Medina	Technician(s)	By signing below, I allow KPII to collect, store & process my personal information as necessary to avail of service & fully understood that my personal information shall be used in accordance w/ Philippine Data Privacy Act & its implementing rules & regulations. I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition. Created by: RODEN PUI CSR BARIT	Conformed by: [Signature] Customer (Signature over printed name)
---	---------------	---	---

Kolin Philippines Int'l., Inc.

1854 Sta. Rita St., Guadalupe Nuevo, Makati City
 Tel. No.: 8852-6888 / Mobile: 0917-811-8982 / Email: service@kolinphil.com.ph
 Website: www.kolinphil.com.ph

SERVICE JOB REPORT

Customer		Address		Telephone No.		Contact Person		Warranty Code		Model		S/N (I)		Dealer		Installer		Location		Mode Setting (Cool)		WAC Setting Temp(16°C-RE)/(10/12-ME)		SAC/PAC Setting Temp (17°)		Discharge Temperature (High)		Intake Temperature (High)		Ampere		Wattage (Inverter)		Voltage		SAC/PAC Pressure (PSI)							
Tempoglad, Vince		8 Flamingo Drive, Victoria Valley Subd., Brgy. Dana Par. CITY OF ANTIPOLO, Riz.				AR DARRYL				KSH41W20GH1M		AUDIO ROOM		1827 2002 - 16483				AUDIO ROOM 1																									
No. Previous SJR No.		Date		Start Time		End Time		Relayed by		Warranty Type		Job Class		Job Type		Permit? <input type="checkbox"/>		Parking? <input type="checkbox"/>		Appointment? <input type="checkbox"/>		O.R.? <input type="checkbox"/>		Ladder? <input type="checkbox"/>		Notes		Complaint		Before		After		No. of Visit		Tentative Sched		Findings					
HO-00161088		07-03-2023		08:31 am		09:38 am		Monitoring Lvl/E		L		INST		EP														LOPEZ - FOR INSTALLATION OF OUTDOOR UNIT ONLY - BRING BRACKET, BREAKER AND POWER SUPPLY		For installation								1st Action		07/06/2023			
Mobile No.		Tel. No.		Room Size		Call Origin		Mobile No.		Tel. No.		Room Size		Call Origin		Mobile No.		Tel. No.		Room Size		Call Origin		Mobile No.		Tel. No.		Room Size		Call Origin		Mobile No.		Tel. No.		Room Size		Call Origin					
0919-8386143		0919-8386143		0919-8386143		0919-8386143		0919-8386143		0919-8386143		0919-8386143		0919-8386143		0919-8386143		0919-8386143		0919-8386143		0919-8386143		0919-8386143		0919-8386143		0919-8386143		0919-8386143		0919-8386143		0919-8386143		0919-8386143		0919-8386143					
S/N (O)		DOP		Notes		Complaint		Before		After		No. of Visit		Tentative Sched		Findings		Recommendation		for installation / for start-up																							
1828 2001		16013				For installation																																					
Part Code		Description		Qty		Unit Price		Amount																																			
		R. cond 3.5m x 3.6		7 Ft		40		280																																			
		C. breaker 30 Amp		1		1,000		1,000																																			
LIQUIDATED																																											
BY: [Signature]		DATE: 7/6/2023																																									
4071		Pressure test 470 psi																																									
SR No.		Repair Done		Repair Code		Date Attended		Time Attended		Date Finished		Time Finished		Check No.		Bank / Branch		Labor		Handling		Others		Total		Amount Paid		Balance		Created by:		Conformed by:		Customer (Signature over printed name)									
		Installation indoor & outdoor unit for start-up				July 4, 2023		9:40 AM		July 6, 2023		3:30 PM				to collector		Ref. #0-111629						1,470		1,470		Technician(s)		RODEN PULOGSANT		Customer											



Kolin Philippines International Inc.
 1854 Sta. Rita St. Adalupe Nuevo, Makati City
 Tel. No. 8852-6811 Mobile: 0917-8118982 / Email: service@kolinphil.com.ph
 Website: www.kolinphil.com.ph

SERVICE JOB REPORT

No. HO-00113425
 Previous SJR No. HO-00100128 **113425**

Customer	Tempongko, Vince			Date	09-16-2022			
Address	Flamingo Drive, Victoria Valley Subd., Rrgy. Dela Paz, CITY OF ANTIPOLO, Riz			Start Time	01:23 pm			
				End Time	01:24 pm			
Tel. No.				Relayed by	Kini			
Mobile No.	0920-9670348			Warranty Type	C			
Contact Person		Mobile No.	027-7941099	Tel. No.				
Model	KSM-IW20-SH1M			Call Origin				
S/N (I)	AUDIO ROOM 2		S/N (O)	Permit? <input type="checkbox"/>	Parking? <input type="checkbox"/>	Appointment? <input type="checkbox"/>	O.R.? <input type="checkbox"/>	Ladder? <input type="checkbox"/>
Dealer				Notes:	TALAVERA / FOR LAYOUT ONLY / E			
Installer				Complaint	for installation			

Mode Setting (Cool)	Before	After	No. of Visits	Tentative Sched	09/22/2022
WAC Setting Temp (16°C-RE)/(10-ME)					
SAC/PAC Setting Temp (17°)					
Discharge Temperature (High)					
Intake Temperature (High)					
Ampere					
WAC Wattage (Inverter)					
Voltage					
SAC/PAC Pressure					

Part Code	Description	Qty	Unit Price	Amount
	C. PIPE 3/2 x 1/4	20FT	300	5,600
	P. COND 2.5mm x 4C	33FT	50	1,150
	PVC PIPE 3/4 x 10	3	100	300
	Clamp (0)	5		
	Stickless pipe	4		

LIQUIDATED
 BY: [Signature]
 DATE: 9/16/2022

SR No.	Initial change			Labor	4,500
Repair Done	lay out c. tubing and			Handling	
Repair Code	lay-out PVC PIPE PHASE line			Others	
Date Attended	June 25, 2022	Date Finished	June 25, 2022	Total	10,500
Time Attended	9:00 AM	Time Finished	3:30 PM	Amount Paid	
This serves as temporary receipt when properly filled up by authorized representative.				Balance	11,550
Check No.				Bank / Branch	pro. collection

Serviced by:	By signing below, I allow KPII to collect, store & process my personal information as necessary to avail of service & fully understood that my personal information shall be used in accordance w/ Philippine Data Privacy Act & its implementing rules & regulations.		
Talavera Medina	I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.		
Will Bermed	Created by:	Conformed by:	Customer
Technician(s)	ARCHIE ARTIGA	[Signature]	(Signature over printed name)
	CSR		



Kolin Philippines International Inc.
 1854 Sta. Rita St. Alabang, Muntinlupa, Makati City
 Tel. No. 8852-6888 / Mobile: 0917-8118982 / Email: service@kolinphil.com.ph
 Website: www.kolinphil.com.ph

SERVICE JOB REPORT

Customer		Address		Tel. No.		Mobile No.		Contact Person		Model		S/N (I)		S/N (O)		Dealer		Installer		Mode Setting (Cool)		WAC Setting Temp (16°C-RE) (10-ME)		SAC/PAC Setting Temp (17°C)		Discharge Temperature (High)		Intake Temperature (High)		Ampere		WAC Wattage (Inverter)		Voltage		SAC/PAC Pressure			
Tempongko, Vince		6 Flamingo Drive, Victoria Valley Subd., Brgy. Dela Paz, CITY OF ANTIPOLO, RIZAL						0920-9670348 / 0919-6398143		AR DARRYL		KSM-IW20-SH1M				NOOK		AUDIO ROOM 2		ROYAL CORD 2 METERS / MAPP GAS / NITROGEN		1st Action																	
Date		Start Time		End Time		Relayed by		Warranty Type		Job Class		Job Type		Permit? <input type="checkbox"/>		Parking? <input type="checkbox"/>		Appointment? <input type="checkbox"/>		O.R.? <input type="checkbox"/>		Ladder? <input type="checkbox"/>																	
HO-00141444 / HO-00132004		02-14-2023		10:31 am		11:00 am		Engr. Ken		0		INST																											
Complaint		Before		After		For install		No. of Visit		Tentative Sched		BRING COPPER TUBE AND																											
TALAVERA - INSTALLATION OF IN										02/15/2023																													
Part Code		Description		Qty		Unit Price		Amount																															
		C. TUBE 1/4 x 1/2		4ft		350		1,400																															
		STICKRESS type		1																																			
SR No.		Repair Done		Repair Code		Date Attended		Time Attended		Date Finished		Time Finished		Amount Paid		Balance		Check No.		Bank / Branch		Labor		Handling		Others		Total		Amount Paid		Balance		Check No.		Bank / Branch			
HO-21240		Installation indoor & bracing C. TUBE - ADDITIONAL				FEB 15, 2023		9:30 AM		FEB 15, 2023		3:50 PM		1,400		1,400						Ref. HO-113425						1,400		1,400		1,400		1,400		1,400			
This serves as temporary receipt when properly filled up by authorized representative.		Created by:		Conformed by:																																			
Serviced by:		TALAVERA		LOPEZ		KILLER		MORAN		RODEN PULCSR BARIT		Customer		(Signature over printed name)																									

Customer		Date		No.		Previous SJR No.	
Address Ternpongko, Vinca		Start Time 07-03-2023		HO-00161092		HO-00158119	
6 Flamingo Drive, Victoria Valley Subd., Brgy. Dela Paz, CITY OF ANTIPOLO, RIZ.		End Time 08:31 am		Relayed by 08:38 am			
Telephone No.	Mobile No.	Warranty Type IM Monitoring- Luis/ E...		Job Class L		LVL	
Contact Person	Mobile No.	Tel. No. 0919-6398143	Room Size 0919-6398143	Job Type INST		2	
Warranty Code AR DARRYL	0919-6398143	Room Size	0919-6398143	Job Type		INST 2	
Model	Call Origin	Permit? <input type="checkbox"/> Parking? <input type="checkbox"/> Appointment? <input type="checkbox"/>		O.R.? <input type="checkbox"/> Ladder? <input type="checkbox"/>			
S/N (I) KSM-IW25-5H1M	S/N (O) 1830 200210	Dealer MASTER'S BEDROOM		DOP 14444		Notes	
Installer 18292103-15309	Complaint	LOPEZ - FOR INSTALLATION OF OUTDOOR UNIT ONLY - BRING BRACKET, BREAKER AND POWER SUPPLY					
Location	Before	After	For Installation				
Mode Setting (Cool)	MASTER'S BEDROOM	No. of Visit	Tentative Sched				
WAC Setting Temp (16°C-RE)/(10/12-ME)	1st Action		Findings		07/06/2023		
SAC/PAC Setting Temp (17°)							
Discharge Temperature (High)							
Intake Temperature (High)							
Ampere	Recommendation						
Wattage (Inverter)	for installation						
Voltage							
SAC/PAC Pressure (PSI)							
Part Code	Description	Qty	Unit Price	Amount			
<p>CLEARED BY: [Signature] DATE: 7/6/2023</p> <p>NOTE: PRESSURE TEST 420 PSI</p>							
SR No.	Labor		Ref. # - 113421				
Repair Done	Installation indoor & outdoor unit. for start-up		Handling				
Repair Code	Others		Total				
Date Attended	July 2, 2023	Date Finished	July 6, 2023	Amount Paid			
Time Attended	9:40 AM	Time Finished	3:30 PM	Balance			
This serves as temporary receipt when properly filled up by authorized representative.		Check No.	Bank / Branch				
Serviced by:		By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.					
Talarca Medina		I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.					
Vella H. J.		Created by:	Conformed by:				
Technician(s)		CSR		Customer (Signature over printed name)			