

May 30, 2024

MR. ERIK HO
UNIT 3705 BRISOL TOWER CONDO PARKWAY AVE. COR. CORPORATE AVE. FILINVEST, ALABANG
TEL#: 0917-7281668
Email: lohuimin@gmail.com

Dear Ma'am/Sir,

Kolin Marketing Inc., is extremely honored for your endorsement of Kolin brand and we are please to offer you with a special price/s for the following items.

A. EQUIPMENT & INSTALLATION

QTY	U/M	MODEL / DESCRIPTION	SRP	DISCOUNTED PRICE		AMOUNT
1	UNIT/S	MODEL: KSG-IWF-30WFY-8K1M32 KOLIN WALL MOUNTED PRIMUS GOLD AIRCONDITIONER 29,500 Kj/h (3.0HP) FULL DC INVERTER W/ WIFI R-32	74,995.00	54,496.10	РНР	54,496.10
1	UNIT/S	MODEL: KSG-IWF-20WFY-8K1M32 KOLIN WALL MOUNTED PRIMUS GOLD AIRCONDITIONER 19,000 Kj/h (2.0HP) FULL DC INVERTER W/ WIFI R-32	58,395.00	41,548.10	РНР	41,548.10
1	UNIT/S	MODEL: KSG-IWF-15WFY-8K1M32 KOLIN WALL MOUNTED PRIMUS GOLD AIRCONDITIONER 12,960 KJ/h (1.5HP) FULL DC INVERTER W/ WIFI R-32	45,795.00	31,720.10	PHP	31,720.10
TOTAL	UNIT COST	PHP	127,764.30			
ESTIMA	TED COST O	PHP	46,200.00			
OTHERS: DELIVERY CHARGE						600.00
TOTAL ESTIMATED COST OF THE PROJECT						174,564.30

TERMS OF PAYMENT:

FULL PAYMENT OF UNIT AND DELIVERY CHARGE. IF CHECK, SUBJECT FOR 3 DAYS CLEARING.

WARRANTY:

FOR SPLIT TYPE : ONE (1) YEAR FREE PARTS AND LABOR, THREE YEARS (3) MAIN PCB , TEN (10) YEARS WARRANTY ON COMPRESSOR.

NOTES: PRICES ARE SUBJECT TO CHANGE WITHOUT PRIOR NOTICE.

PRICES IS VAT INCLUSIVE.

- ** Cost of Installation is Package with the Unit(s), this cost cannot avail separately.
- ** INSTALLATION C/O ASC

We thank you for giving opportunity to offer our product and services, hoping we receive your purchase order.

If you need assistance, don't hesitate to call the under signed at 0917-807-8607 or email at kmi_asst@kolinphil.com.ph

Very Truly Yours,

JANELLEN S. LIM KMI-ASSISTANT

Noted by,

MART NATHANIEL R. FLORES

KMI-SUPERVISOR

KMI-QUOTE-05-24-0500 TYT-22%/4K AVP - FINANCE

MS. EDITHA M. FLORES

Conforme:

SIGNATURE OVER PRINTED NAME

ANNIVERSARY

Kolin Marketing, Inc.

1854 Sta. Rita St., Guadalupe Nuevo, Makati City www.kolinphil.com.ph

Tel.: (632) 8852-6473

Fax: (632) 8852-2170 / (632) 8852-4792

Bringing comfort to your home.

May 29, 2024
ERIK HO
Unit 3705 Bristol Tower Condo. Parkway Ave. Cor. Corporate Ave. Filinvest, Alabang 0917-7281668
| Ohuimin@gmail.com

Qty

MODEL KSG-IWF-30WFY8K1M32 KSG-IWF-20WFY8K1M32 KSG-IWF-15WFY8K1M32

1 1 1

Estima Estima Initial Incli I	Wall Mounted Inverter				Area	46 sqm
Estima Initial Inclu I			KSG-IWF-	-30WFY8K1M32		
Initial Incli L		30 ft				
Incl L 1	ated Royal Cord Length =	35 ft				
L 1	Charge					₱ 4,700.00
1	udes:					Less Outdoor
	abor					Bracket
-	10ft Copper Tube					
- 1	10ft Royal Cord					
(Consumables					
Install	ation Materials	Description	Qtv P	rice per qty	Subtotal	
Coppe	er Tube	Ø 1/4" x Ø 5/8"	20 ft P		₱ 8,000.00	
Royal	Cord (comm. wire)	2.mm2 x 4C	25 ft ₱		₱ 2,500.00	
	Cord (ACCU-Breaker)	3.5mm x 3c	5 ft ₱		₱ 300.00	
	or bracket	Modified	1 pc/s F		P 1,500.00	
Disma	ntle	1.0HP Wall Mounted	2 set		5 ,000.00	
PVC b	lue	3/4" x 10'	2 pc/s P		₱ 300.00	P 17,600.00
		755339 6-7917V, 78				11,000.00
Estim	ated Charges					₱ 22,300.00
ASTER BEDE					Area	17 sqm
	Wall Mounted Inverter		KSG-IWF-	-20WFY8K1M32		•
		20 ft				
	ated Royal Cord Length =	25 ft				
	Charge					₱ 3,700.00
	udes:					Less Outdoor
	abor					Bracket
1	10ft Copper Tube					
1	10ft Royal Cord					
(Consumables					
Install	ation Materials	Description	Qty P	rice per qty	Subtotal	
Coppe	r Tube	Ø 1/4" x Ø 1/2"	10 ft ₱		₱ 3,500.00	
Royal	Cord (comm. wire)	2.mm2 x 4C	15 ft P	100.00/ft	₱ 1,500.00	
Royal	Cord (ACCU-Breaker)	3.5mm x 3c	5 ft 🟴	60.00/ft	₱ 300.00	
Outdo	or bracket	Modified	1 pc/s ₱	1,500.00/pc	₱ 1,500.00	
Disma	ntle	1.5HP Wall Mounted	1 set P		₱ 2,500.00	
PVC b	lue	3/4" x 10'	2 pc/s P		₱ 300.00	₱ 9,600.00
r-serres.						
Estima	ated Charges					₱ 13,300.00
IDS ROOM					Area	11 sqm
CU 3 1.5 HP	Wall Mounted Inverter		KSG-IWF-	-15WFY8K1M32		
		14 ft				
	ated Royal Cord Length =	19 ft				
Estima	Charge					₱ 3,700.00
	udes:					Less Outdoor
Initial Incl	abor					Bracket
Initial Incl	LUDUI					
Initial Inclu L	Oft Copper Tube					
Initial Inclu L 1						
Initial Inclu L 1	Oft Copper Tube					
Initial Inclu L 1 1	0ft Copper Tube 10ft Royal Cord	Description	Qtv P	rice per atv	Subtotal	
Initial Inclu 1 1 1 Install	0ft Copper Tube 10ft Royal Cord Consumables	Description Ø 1/4" x Ø 3/8"		Price per qty	Subtotal	
Initial Inclu L 1 1 1 Coppe	Oft Copper Tube Oft Royal Cord Consumables ation Materials		4 ft P	350.00/ft	₱ 1,400.00	
Initial Inclu L 1 1 1 Coppe Royal	Oft Copper Tube Oft Royal Cord Consumables ation Materials or Tube Cord (comm. wire)	Ø 1/4" x Ø 3/8"	4 ft P 9 ft P	350.00/ft 100.00/ft	₱ 1,400.00 ₱ 900.00	
Initial Inclu L 1 1 Coppe Royal Royal	Oft Copper Tube Oft Royal Cord Consumables ation Materials or Tube Cord (comm. wire) Cord (ACCU-Breaker)	Ø 1/4" x Ø 3/8" 2.mm2 x 4C	4 ft P 9 ft P 5 ft P	350.00/ft 100.00/ft 60.00/ft	₱ 1,400.00 ₱ 900.00 ₱ 300.00	
Initial Inclu L 1 1 Coppe Royal Royal	Oft Copper Tube Oft Royal Cord Consumables ation Materials Tube Cord (comm. wire) Cord (ACCU-Breaker) or bracket	Ø 1/4" x Ø 3/8" 2.mm2 x 4C 3.5mm x 3c Modified	4 ft P 9 ft P 5 ft P 1 pc/s P	350.00/ft 100.00/ft 60.00/ft 1,500.00/pc	₱ 1,400.00 ₱ 900.00 ₱ 300.00 ₱ 1,500.00	
Initial Inclu L 1 1 Coppe Royal Royal Outdoo	Oft Copper Tube Oft Royal Cord Consumables ation Materials Tube Cord (comm. wire) Cord (ACCU-Breaker) or bracket ntle	Ø 1/4" x Ø 3/8" 2.mm2 x 4C 3.5mm x 3c	4 ft P 9 ft P 5 ft P	350.00/ft 100.00/ft 60.00/ft 1,500.00/pc 2,500.00/set	₱ 1,400.00 ₱ 900.00 ₱ 300.00	₱ 6,900.00

May 29, 2024 Ho, Erik Unit 3705 Bristoł Tower Condo. Parkway Ave. Cor. Corporate Ave. Filinvest, Alabang 0917-7281668 Iohuimin@gmail.com

Please be informed that the air-conditioner you intend to purchase is under capacity as compared to the following unit that we proposed:

Location	Area	Kolin's Recommendation	Customer's Choice	Remarks
LIVING/DINING	46 sqm	KLG-IF40-5G1M32	KSG-IWF-30WFY8K1M32	Calculated 3.4hp
LIVING/DINING			K3G-IWI-30WI IBKIWI32	under by 0.4hp

Since the unit of your choice is under capacity, it is probable that you may experience the following;

- 1. Capacity of the unit to cool the area will take longer or it will not cool the area at all that may lead to your dissatisfaction with the cooling performance of our unit.
- 2. Power consumption will be higher due to frequent running of compressor for not reaching the desired temperature within the normal parameter.
- 3. Useful life of compressor will be shortened due to excessive running beyond the normal run cycle.

Considering the above conditions, we regret to inform you that we cannot guarantee the efficient performance of unit. Also, One (1) year warranty for parts (compressor-10year).

For your guidance and information

Prepared by:

Jeoffrey T. Dadios

Surveyor

Approved by

1 112

Mr. Alvin de Rivera Service Manager Noted by:

Engr. Kepneth Zamora Service Supervisor - Field

and Shop Operation

Customer Conforme:

Signature Over Printed Name