

UNITEC RESOURCES INC. ATTN: ENGR. MANNY

FILINVEST CYBERZONE BAY CITY, DIOSDADO MACAPAGAL BOULEVARD, PASAY CITY

TEL: 0956-5232314

Sir/ Madam,

This is to bill you on the service job done to your unit for the month of SEPTEMBER 2024.

Details of the charges are stated below and a copy of the Service Job Report is attached for your references:

DATE ATTENDED	SJR#	QUANTITY/MODEL	SERVICE JOB DONE	AMOUNT
14-Sep-24	HO-00221834	(1) KSM-IW20-WCT10M1M32	INSTALLATION	7,500.00
14-Sep-24	HO-00221835	(1) KSM-IW20-WCT10M1M32	DISMANTLING	8,100.00
	TOTAL		×i	P 15,600.00
	LESS: SURVEY FEE			(500.00)
	TOTAL AMOUNT DUE			P 15,100.00

For any clarifications please feel free to call the Undersigned at the telephone number 8852-6473

Note: If check payment, please prepare check payable to Kolin Philippines International Inc.

Account #: BDO - KALAYAAN 011808000428

**Note:** In case thru Bank Deposit under BDO Account, kindly inidicate SJR# for your Bank Reference in the deposit slip and Fax to (632) 8852-6473 or E-mail to: kmi\_asst@kolinphil.com.ph

Prepared by:

Janellen S. Lim KMI - Assisitant

Received by:

Signature over printed name

Kolin Philippines Int'l., Inc.

Plant and Head Office:

Blk 3 Lt 5 Main Drive, FCIE Compound,
Brgy, Langkaan I, Dasmariñas, Cavite
Tel.: (632) 8749-2118
Fax (046) 402-0793

www.kolinphil.com.ph / kolinphilippines

Operation Office: 1854 Sta. Rita St., Guadalupe Nuevo, Makati City Tel.: (632) 8851-2711, 12 or 15 Fax: (632) 8852-2170 Sales Dept. Fax: (632) 8852-4791



Mart Nathaniel R. Flores



## Kolin Philippines Int'l., Inc.

## SERVICE JOB REPORT

1694 Stat. Kita St., Guadatipe Nuevo, Makati City Pel. No.: 8852-6868 / Mobile: 0917-811-8982 / Email: service@kolinphil.com.ph Vebsite: www.kolinphil.com.ph							No. HO-00221834 Previous SJR No. HO-00219939			4				
Customer		United Resources Inc.						Date	09-11-2024					
Address	, Filinvest Cyberzone Bay City Diosdado Macapagal Boulevard , , Brgy. , PASAY							Start Time	02:02 pm					
TY, Met	Metro Manila							End Time	02:05 pm					
Telephone No.	Mobile No.				0956-5	956-5232314		Relayed by	Janelien Lim / KMI					
Contact Person	Engr. Manny	Mobile No	.0956-5232	2314	Tel. No.			Warranty Type	anty Type C					
Warranty Code					Room Size			Job Class	INST	LVL	4			
Model	KSM-IW20-WCT10M1M32				Call Origin	10		Job Type	FD	FD				
S/N (i)	18652404-1556	18652404-15560			14-15585	Permit?	Parking?	Appointment?	0.R <sub>k</sub> ?	Ladder'	? 🗌			
Dealer	KMI		S/N (O)	09/04/20	Notes 1st Quad FOR			INSTALL LOOK	FOR ENG	R MAN	NY /			
Installer				10000	0956-52323			(2) KSM-IW20-V 09/13/24 NOTE	NCT TOM TR	132 DOF	þ <del></del>			
Location	1	Before	After	1 07 11 1011	Jes alter	SE	ND LIST OF	ASSIGNED TE	CH TO CU	STOME				
Mode Setting (Cod	J	***************************************	NO. DAY AND ADDRESS OF THE PARTY OF THE PART		No. of Visit						FEE			
	np(16°C-RE)/(10/12	-ME)			No. of Visit 1st Action FINAL INSTALLATION COSIDERATIONS OF CUSTOMER REQUISITION COSIDERATION CO						F			
SAC/PAC   Setting	1,	1 2200 - 24				T#	AC	A(9)						
Discharge Temper			<del>                                     </del>					(1975)						
Intake Temperatur				2)2 0 ST 5,					5 - 1,49 A					
Ampore	o (mgm)						Recomme	endation	1 2 12 12					
Wattage (Inverter)							recomm							
Voltage								4362						
SAC/PAC   Pressu	re (PSI)						1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	1835 ASSE SEC.	2 12					
Part Code			Des	cription			Qty	Unit Price	T A	mount				
							12 3 4 4 4		E s l					
								The contract						
	15	Proceso	NO 108	- aar	same of	mt B	productions	P10 1991 - 17 v						
		MS; NO	Mocessing too agre					and Mac In I						
Jay 1	No. 10 Personal Property of the Party of the		1 S 26 M				Jak avi i							
									A					
	7		* * *		2. 0	Carro 9	274 10 10		1 0 1 1 2					
						olorese x	T 1							
						in the state of	tu de la fil	e its and have '						
					····		<del> </del>							
			***************************************											
CD No.								Lahar	7,	-00	00			
SR No.								Labor	1,5	500	.00			
Repair Done	Findings Inst	elletion Re	ommenda	tion - inde	or serial:1	8652404-	15560, outd	Handling	less :	- sur	vey			
of the second se	senal#:186624 Amperes:9.6					• • • •	*		1	te	<u>E</u> _			
Repair Code	SAC18-2 - Installation - 1.0HP - 2.0HP Inverter and Non- inverter (includes 10ft.)						ludes 10ft, c	о <b>доta</b> ltube.	(5	00.00	))			
Date Attended	10 ft, royal cord, rubber insulation, ordinary bracks 09/14/2024 Date Finished 7/2024				,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		- In State Acc	Amount Paid	1					
Time Attended 12:00 am			Time Finished) am					Balance	77	,000	, 00			
-	orary receipt when pro	Control of the Contro			Check No.			Bank / Branch	1		and the			
Serviced by: 1st Q	uac .							nd its ASC to collect, st dicable laws and regul						
		received the	unit in good wo	repair charg orking conditi	es incurred/to on.	be incurred to	my unit and to the	ne terms and condition	s stated at the	back, and th	hat I			
		Created by			Conformed by:									
T1	unisian/a)	ERICA	ERICA C. CALIBOT				(0)	Customer		Customer				

## Kolin Philippines Int'I., Inc. SERVICE JOB REPORT 1854 Sta. Rita St., Guadalupe Nuevo, Makati City Tel. No.: 8852-6868 / Mobile: 0917-811-8982 / Email: service@kolinphil.com.ph Website: www.kolinphil.com.ph HO-00221835 HO-00219939 Previous SJR No. Customer United Resources Inc. Date 09-11-2024 Filinvest Cyberzone Bay City Diosdado Macapagal Boulevard . . Brgy. . PASAY 02:05 pm Address Start Time TY, Netro Mania... 02:05 pm **End Time** 0956-5232314 Janellen Lim / KMI Telephone No. Mobile No. Relayed by Mobile No. 0956-5232314 Contact Person Engr. Manny C Tel. No. Warranty Type Warranty Code Room Size INST LVL Job Class KSM-IW20-WCT10M1M32 FD Model Call Origin Joh Type 18652404-15366 S/N (I) 18662404-15560 Permit S/N (O) Parking? Appointment? O.R.? Ladder? Notes 1st Quad FOR INSTALL LOOK FOR ENGR. MANNY / KMI 09/04/2024 Dealer DOP 0956-5232314 (2) KSM-IW20-WCT10M1M32 DOP: 09/04/24 EDD: 09/13/24 NOTE; W/ PERMIT, CALL OR For Installation Installer Complaint SEND LIST OF ASSIGNED TECH TO CUSTOMER Location Before After PLS SCHED THIS FRIDAY, SEPT, 13 AS PER No. of Visit 1st Action FINAL INSTARTATIVES OPEN PRATICAL CO Mode Setting (Cool) CUSTOMER KINDLY ADVISE CLIENT AHEAD OF WAC | Setting Temp(16°C-RE)/(10/12-ME) TIME SAC/PAC | Setting Temp (17°) Discharge Temperature (High) Intake Temperature (High) Ampere Recommendation Wattage (Inverter) Voltage SAC/PAC | Pressure (PSI) Part Code Description Qty **Unit Price** Amount excess 1,000.00 royal cord (000, OC acus to Dreaker. SR No. Labor 100,00 Handling Findings - Installation of New Unit, ... Recommendation - indoor serial: 18652404 existing odu Repair Done outdoor serial#:18662404-15560, , , Repair Done - Unit installed, 10 ft pipe, L-type | othersge less bracket 282 Amporos: 9.6 SAC18-2 - Installation - 1.0HP - 2.0HP Inverter and Non-inverter (includes 10ft. cq@ptaffube, Repair Code 000.00 10 ft. royal cord, rubber insulation, ordinary bracket, drainhose / PVC drain pipe 3 Date Attended 09/14/2024 Date Finished?/2024 Amount Paid Time Attended 12:00 am Time Finished) am Balance 00.00 This serves as temporary receipt when properly filled up by authorized representative. Bank / Branch Check No. By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal Serviced by: 1st Quad information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations. I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.

Conformed by:

Customer

(Signature over printed name)

Created by:

Technician(s)

ERICA C. CALIBOT

CSR