



1-Oct-2024

MONACO MANUFACTURING CORPORATION

101 MATUTUM COR. MAUBAN ST., BRGY. MANRESA, QUEZON CITY

TEL: 8365-4562 loc 210

Sir/ Madam,

This is to bill you on the service job done to your unit for the month of SEPTEMBER 2024.

Details of the charges are stated below and a copy of the Service Job Report is attached for your references:

DATE ATTENDED	SJR#	QUANTITY/MODEL	SERVICE JOB DONE	AMOUNT
27-Jul-23	HO-00223098	(1) KAG-110RSINV	PARTS REPLACEMENT	7,315.00
TOTAL				P 7,315.00
LESS: DISCOUNT				(731.50)
TOTAL AMOUNT DUE				<u>P 6,583.50</u>

For any clarifications please feel free to call the Undersigned at the telephone number **8852-6473**

Note: If check payment, please prepare check payable to **Kolin Philippines International Inc.**

Account #: BDO - KALAYAAN


011808000428

Note: In case thru Bank Deposit under BDO Account, kindly indicate SJR# for your Bank Reference in the deposit slip and Fax to **(632) 8852-6473** or E-mail to: **kmi_asst@kolinphil.com.ph**

Prepared by:


Janellen S. Lim
KMI - Assistant

Noted by:


Mari Namarfel R. Flores
KMI - Supervisor

Received by:

Signature over printed name

 **Kolin Philippines Int'l., Inc.**

Plant and Head Office:

 Blk 3 Lt 5 Main Drive, FCIE Compound,
Brgy. Langkaan I, Dasmariñas, Cavite

 Tel.: (632) 8749-2118

 Fax (046) 402-0793

 www.kolinphil.com.ph / [kolinphilippines](http://kolinphilippines.com)

Operation Office:

1854 Sta. Rita St., Guadalupe Nuevo,
Makati City

Tel.: (632) 8851-2711, 12 or 15

Fax: (632) 8852-2170

Sales Dept. Fax: (632) 8852-4791



Customer	Monaco Manufacturing Corporation			Date	09-21-2024		
Address	101 Matutum cor. Mauban St., Bryg. Manresa, QUEZON CITY, Metro Manila			Start Time	12:02 pm		
				End Time	12:04 pm		
Telephone No.	8385-4562 LOC 224	Mobile No.	8385-4562 loc 224	Relayed by	NIEL VILLAFUERTE		
Contact Person	ANGELICA GOROSITO	Mobile No.		Tel. No.	8385-4562 LOC 224	Warranty Type	C
Warranty Code		Room Size		Job Class	TS	LVL	1
Model	KAG-110RSINV	Call Origin	SA	Job Type	FD		
S/N (I)	pls hide ON INSTALL	S/N (O)		Permit?	☐	Parking?	☐
Dealer	2ND FLR, OFFICE	DOP		Appointment?	☐	O.R.?	☐
Installer		Complaint	Dead Set	Notes	VILLAFUERTE BRING DISPLAY BOARD, PCB & ALL POSSIBLE PARTS		
Location	pls update location on Before	After					
Mode Setting (Cool)		No. of Visit	2nd Action	Tentative Sched	09/23/2024		
WAC Setting Temp (16°C-RE) (10/12-ME)		Findings					
SAC/PAC Setting Temp (17°)		defective display board					
Discharge Temperature (High)		and pcb main board					
Intake Temperature (High)							
Ampere		Recommendation					
Wattage (Inverter)							
Voltage							
SAC/PAC Pressure (PSI)							
Part Code	Description	Qty	Unit Price	Amount			
	pcb main board	1	5,500	5,500 ✓			
	display board	1	715	715 ✓			
	SILICON PASTE	1					
LIQUIDATED DATE: <u>IN 9/23/24</u>							
SR No.	4034			Labor	P 1,100		
Repair Done	replaced display board and pcb main board. unit ok			Handling	discounted 10%		
Repair Code				Others			
Date Attended	9-23-24	Date Finished	9-23-24	Total	P 7,315		
Time Attended	9:45	Time Finished	12:00	Amount Paid			
This serves as temporary receipt when properly filled up by authorized representative.				Check No.	Bank / Branch		
Served by: Garry Munday, Neil Villafuerte, Salomon				By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.			
				I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.			
Created by: LUIS REYES				Conformed by: ANGELICA GOROSITO			
Technician(s)				Customer (Signature over printed name)			