



17-Sep-2024

ATTY. PETER SUCHIANGCO

#119 AQUARIUS ST., CINCO HERMANOS SUBD., INDUSTRIAL VALLEY MARIKINA CITY

TEL: 0917-866-8293 / 0966-6242999 / 8638-0616

Sir/ Madam,

This is to bill you on the service job done to your unit for the month of AUGUST 2024.

Details of the charges are stated below and a copy of the Service Job Report is attached for your references:

DATE ATTENDED	SJR #	QUANTITY/MODEL	SERVICE JOB DONE	AMOUNT
14-Aug-24	HO-00217794	(1) KSM-IW29AE-5G1M	PARTS REPLACEMENT	/ 7,300.00
14-Aug-24	HO-00217809	(1) KSM-IW30-4F1M	PARTS REPLACEMENT	/ 5,650.00
14-Aug-24	HO-00217813	(1) KSM-IW20-4F1M	PARTS REPLACEMENT	/ 5,400.00
19-Aug-24	HO-00218853	(1) KSG-30B1M	PARTS REPLACEMENT	/ 3,065.00
21-Aug-24	HO-00219108	(1) KSG-25B1M	PARTS REPLACEMENT	/ 14,550.00
TOTAL				P 35,965.00
LESS: DISCOUNT				(2,517.55)
TOTAL AMOUNT DUE				P 33,447.45

For any clarifications please feel free to call the Undersigned at the telephone number **8852-6473**


Note: If check payment, please prepare check payable to **Kolin Philippines International Inc.**

Account #: BDO - KALAYAAN


011808000428

Note: In case thru Bank Deposit under BDO Account, kindly indicate SJR# for your Bank Reference in the deposit slip and Fax to **(632) 8852-6473** or E-mail to: **kmi_asst@kolinphil.com.ph**

Prepared by:


Janellen S. Lim
KMI - Assisitant

Noted by:


Mart Nathaniel R. Flores
KMI - Supervisor

Received by:

Signature over printed name

 Kolin Philippines Int'l., Inc.

Plant and Head Office:

Blk 3 Lt 5 Main Drive, FCIE Compound,
Brgy. Langkaan I, Dasmarinas, Cavite

Tel.: (632) 8749-2118

Fax (046) 402-0793

www.kolinphil.com.ph / kolinphilippines

Operation Office:

1854 Sta. Rita St., Guadalupe Nuevo,
Makati City

Tel.: (632) 8851-2711, 12 or 15

Fax: (632) 8852-2170

Sales Dept. Fax: (632) 8852-4791





SERVICE JOB REPORT

Date	08-13-2024
------	------------

Start Time	01:33 pm
------------	----------

End Time	01:37 pm
----------	----------

Relayed by	Islero
Wavelength	

Warranty type	C		
Job Class		IVI	

Job Class	1S	EVL	
Job Type	1S		

Appointment? ☐	O.R.? ☐	Ladder? ☐
---------------------------------------	--------------------------------	----------------------------------

For full out Recommendation

Pulled out unit with out flare nut and
segment using completion

Tentative Sched	05/20/2024
-----------------	------------

Findings

1981

Recommendation

evaluation

1. 1000

Unit Price	Amount
------------	--------

0.00	
------	--

4400.00	
---------	--

[illegible]

1991-1992

[illegible][illegible][illegible]

[illegible]

Labor	
Handling	2 400.00

Handling	25.00
Others	500.00

Others	100	100
Total	100	100

Amount Paid	7,300.00
-------------	----------

Balance	0.00
---------	------

Bank / Branch	7,300.00
---------------	----------

and its ASC to collect, store and process my personal
applicable laws and regulations.

the terms and conditions stated at the back, and that

Customer

Customer
(over printed name)

Kolin Philippine Int'l., Inc.

SERVICE JOB REPORT

1854 Sta. Rita St., Guadalupe Nuevo, Makati City
Tel. No.: 8852-6868 / Mobile: 0917-811-8982 / Email: service@kolinphil.com.ph
Website: www.kolinphil.com.ph

No. **HO-00217809**
Previous SJR No. **HO-00211344**

Customer	Suchianco Atty. Peter			Date	08-13-2024		
Address	#119 Aquarius St., Cinco Hermanos Subd., Industrial Valley, MARIKINA CITY, Metro Manila...			Start Time	01:48 am		
Telephone No.	8638-0816 / 8632-3340		Mobile No.	0966-6242999 / 0922-8149274		Relayed by	Islero
Contact Person	Arch. Manny Domondon	Mobile No.	0966-6242999		Tel. No.	Warranty Type	
Warranty Code				Room Size	Job Class		
Model	KSM-IW30-4F1M			Call Origin	Job Type		
S/N (I)	18111701-10589		S/N (O)			Permit?	Parking?
Dealer			DOP			Appointment?	O.R.?
Installer			Complaint	Others			
Location	DINING AREA	Before	After	Notes			
Mode Setting (Cool)				No. of Visit	2nd Action	Tentative Sched	08/20/2024
WAC Setting Temp (16°C-RE)/(10/12-ME)				Findings			
SAC/PAC Setting Temp (17°)							
Discharge Temperature (High)							
Intake Temperature (High)							
Ampere				Recommendation			
Wattage (Inverter)							
Voltage							
SAC/PAC Pressure (PSI)							
Part Code	Description			Qty	Unit Price	Amount	
D2024002070	Swing Motor MP2423M / 12VDC : Php500.00			1.00	500.00		
D8010499	Rear Case (IDU) : Php1,650.00			1.00	1650.00		
D8010503	Drain Pan : Php1,100.00			1.00	1100.00		
R6010210	Flare Nut 3/8			2.00	0.00		
00701201006	Stickless Tape 4"			1.00	200.00		
SR No.				Labor			
Repair Done	SR-HO-00039113			Handling	2,400.00		
Repair Code	Findings - Defective swing motor (pulit ang wire), rear case and drain pan defective due to mouse bite, dirty unit, no freon, leak test indoor outdoor no leak found, missing flare nut 3/8 2pcs			Others	0.00		
Date Attended	08/14/2024			Total	2,400.00		
Time Attended	08:10 am			Amount Paid	5,580.00		
This serves as temporary receipt when property filled up by authorized representative.				Check No.	5850		
Served by: Hernando Samarra				By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.			
				I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.			
Technician(s)				Created by:	Conformed by:		
RECHILLA CSR				Customer (Signature over printed name)			

Customer		Suchianco, Atty. Peter		Date		08-13-2024	
Address		#119 Aquarius St., Cinco Hermanos Subd., Industrial Valley, MARIKINA CITY, 1880		Start Time		01:54 pm	
ro Manila...				End Time		01:56 pm	
Telephone No.		8638-0616 / 8632-3340		Mobile No.		0966-8242999 / 0922-814927	
Contact Person		Arch. Manny Domon...		Tel. No.		Warranty Type	
Warranty Code				Room Size		Job Class	
Model		KSM-IW20-4F1M		Call Origin		SA	
S/N (I)		B071701-11774		S/N (O)		1808201-11111	
Dealer				DOP		05/25/2017	
Installer				Complaint		Others	
Location				Before		After	
Mode Setting (Cool)				No. of Visit		2nd Action	
WAC Setting Temp (16°C-RE)/(10/12-ME)				Tentative Sched		08/20/2024	
SAC/PAC Setting Temp (17°)				Findings			
Discharge Temperature (High)				Recommendation			
Intake Temperature (High)				BILLED			
Ampere				DATE		Signature	
Wattage (Inverter)							
Voltage							
SAC/PAC Pressure (PSI)							
Part Code		Description		Qty		Unit Price	
D2024401262		Fan Motor (IDU) RPG45B (YKFG-4-45-13)		1.00		3000.00	
R6010211		Flare Nut 1/4		1.00		0.00	
SR No.		SR-HO-00038111		Labor		2,400.00	
Repair Done		Findings - Noisy fan motor indoor, dirty unit, no freon, leak test indoor / o		Handling		0.00	
Repair Code		Refr & need flare nut		Others		0.00	
Date Attended		Date Finished		Total		5,400.00	
Time Attended		Time Finished		Amount Paid		0.00	
This serves as temporary receipt when property filled up by authorized representative.		Check No.		Bank / Branch		5,400.00	
Serviced by: Herwin Barrera		By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.					
		I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.					
Technician(s)		RECHILLA CSR		Conformed by:		Customer (Signature over printed name)	

Customer		Suchlanco, Atty. Peter		Date		08-19-2024	
Address		#119 Aquarius St., Cinco Hermanos Subd., Industrial Valley, MARIKINA CITY, Metro Manila...		Start Time		03:22 pm	
Telephone No.		8638-0816 / 8632-3340		Mobile No.		0966-6242995 / 0922-814827	
Contact Person		Arch. Manny Domond		Tel. No.		Warranty Type	
Warranty Code				Room Size		Job Class	
Model		KSG-30B1M		Call Origin		SA	
S/N (I)		10071004-13989		S/N (O)			
Dealer		DOP		11/27/2019		Notes	
Installer		Complaint		Others		IN SHOP PULL OUT INDOOR AND OUTDOOR UNIT WITH INDOOR PLATE FLARE NUTS	
Location		GROUND FLR HALL		Before		After	
Mode Setting (Cool)				No. of Visit		2nd Action	
WAC Setting Temp(16°C-RE)/(10/12-ME)				Tentative Sched		08/27/2024	
SAC/PAC Setting Temp (17°)				Findings			
Discharge Temperature (High)				Recommendation			
Intake Temperature (High)				BILLED			
Ampere				Voltage			
Wattage (Inverter)				SAC/PAC Pressure (PSI)			
Part Code		Description		Qty		Unit Price	
R33010021		Capacitor 3uF/450V Php165.00		1.00		165.00	
SR No.		SR-HO-00039485		Labor			
Repair Done		Findings - Under value fan capacitor 2 out (3uf) & dirty unit., Recommendation		Handling		2,400.00	
Repair Code		n - Replacement of fan capacitor 3uf, general cleaning & charging freon., Repair Done - Replaced 300 capacitor, general cleaning & charging freon.		Others		500.00	
Date Attended		Date Finished		Amount Paid		3,005.00	
Time Attended		Time Finished		Balance		0.00	
This serves as temporary receipt when properly filled up by authorized representative.		Check No.		Bank / Branch		3,005.00	
Serviced by: Hernando Camara		By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.		Created by:		Conformed by:	
Technician(s)		RECHILLA		Customer		(Signature over printed name)	

Customer		Suchianco, Atty. Peter		Date		08-20-2024	
Address		#119 Aquarius St., Cinco Hermanos Subd., Industrial Valley, MARIKINA CITY, LGU		Start Time		05:17 pm	
ro Manila...				End Time		05:20 pm	
Telephone No.		8638-0616 / 8632-3340		Mobile No.		0966-6242999 / 0922-514927	
Contact Person		Arch. Manny Domon		Mobile No.		0966-6242999	
Warranty Code				Tel. No.			
Model		KSG-25B1M		Room Size			
S/N (I)		FADED		Call Origin		IO	
S/N (O)		FADED		Job Class		TS LVL 1	
Dealer				Job Type		PO	
Installer				Permit? ☐ Parking? ☐ Appointment? ☐ O.R.? ☐ Ladder? ☐			
Location		HALL WAY 2ND FLOOR		DOP		09/21/2010	
Mode Setting (Cool)				Complaint		Others	
WAC Setting Temp (16°C-RE)/(10/12-ME)				Notes		SHOP PULL OUT INDOOR AND OUTDOOR UNIT	
SAC/PAC Setting Temp (17°)				No. of Visit		1st Action	
Discharge Temperature (High)				Tentative Sched		08/27/2024	
Intake Temperature (High)				Findings			
Ampere				Recommendation			
Wattage (Inverter)				BILLE			
Voltage				DATE 9/16/24			
SAC/PAC Pressure (PSI)							
Part Code		Description		Qty		Unit Price	
D0122123804		Compressor PH360X3CS-3KUL1		1.00		10000.00	
0499022000		Capacitor 2.0uF/450V		1.00		300.00	
05810007001		Strainer (S) 5/16x1/8		1.00		0.00	
TH9010202		Access Valve 1/4" (w/tube)		1.00		0.00	
SR No.				Labor			
Repair Done		SR-HO-00039482		Handling		3,750.00	
Repair Code		Findings - Defective compressor high ampere, under value fan capacitor 1.5uF		Others		500.00	
Date Attended		Repair Done - Replaced com		Total		14,550.00	
Time Attended		SAC08.1 - System Re-process with General Cleaning (1.0hp-3hp)		Amount Paid		14,550.00	
		08/21/2024		Balance		0.00	
		09/14/2024		Bank / Branch			
This serves as temporary receipt when property filled up by authorized representative.		Check No.					
Serviced by: Daniel Placencia		By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.					
		I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.					
Technician(s)		Created by: RECHILLA CSR		Conformed by: Customer (Signature over printed name)			

Send SR to Atty. Suchianco's office

1/13 9/16/24