



July 24, 2025

MS. GENNY CO / MR. KARL HUI
471 ELCANO ST., COR. SAN FERNANDO, BINONDO MANILA
TEL#: 0917-8564422

Dear Ma'am/Sir,

Kolin Marketing Inc., is extremely honored for your endorsement of Kolin brand and we are please to offer you with a special price/s for the following items.

A. EQUIPMENT & INSTALLATION

* OPTION 1 *

QTY	U/M	MODEL / DESCRIPTION	SRP	DISCOUNTED PRICE	AMOUNT
1	UNIT/S	MODEL: KSM-IW10-WCT10M1M32 KOLIN WALL MOUNTED CERTUS SERIES AIRCONDITIONER 9,800 Kj/h (1.0HP) REGULAR INVERTER W/ WIFI R-32	29,995.00	18,796.20	PHP 18,796.20
1	UNIT/S	MODEL: KA-150MCARINV32 KOLIN WINDOW TYPE CREO SERIES AIRCONDITIONER 12,800 Kj/h (1.5HP) FULL DC INVERTER R-32 WITH REMOTE (WxDxH) 17.7"x26.6"x13.8"	27,995.00	20,276.20	PHP 20,276.20
1	UNIT/S	MODEL: KAG-250WCINV KOLIN WINDOW TYPE QUAD SERIES AIRCONDITIONER 24,120 Kj/h (2.5HP) FULL DC INVERTER W/ WIFI R-32 (WxDxH) 26"x31.5"x17"	48,695.00	35,208.20	PHP 35,208.20
TOTAL UNIT COST				PHP	74,280.60
ESTIMATED COST OF INSTALLATION (please see attached)				PHP	33,400.00
OTHERS: DELIVERY CHARGE				PHP	600.00
TOTAL ESTIMATED COST OF THE PROJECT				PHP	108,280.60

TERMS OF PAYMENT:

FULL PAYMENT OF UNIT AND DELIVERY CHARGE. IF CHECK, SUBJECT FOR 3 DAYS CLEARING.

WARRANTY:

FOR SPLIT TYPE : ONE (1) YEAR FREE PARTS AND LABOR, THREE YEARS (3) MAIN PCB , TEN (10) YEARS WARRANTY ON COMPRESSOR.

NOTES: PRICES ARE SUBJECT TO CHANGE WITHOUT PRIOR NOTICE.

PRICES IS VAT INCLUSIVE.

** Cost of Installation is Package with the Unit(s), this cost cannot avail separately (cost will be based on actual works).

*** You may settle first payment for unit/s & delivery. Installation payment can be settled directly to installer after actual works.

We thank you for giving opportunity to offer our product and services, hoping we receive your purchase order.

If you need assistance, don't hesitate to call the under signed at 0917-807-8607 or email at kmi_asst@kolinphil.com.ph

** CURRENTLY NO AVAILABLE STOCKS FOR ANGLE BRACKET.

Very Truly Yours,

JANELLEN S. LIM
KMI-ASSISTANT

Noted by:
MARICAR M. HANILEY R. FLORES
KMI-SUPERVISOR

Approved By:
MS. EDITHA M. FLORES
AVP - FINANCE

Conforme:

SIGNATURE OVER PRINTED NAME

KMI-QUOTE-07-25-0565
LCY-24%/4K/1K/1.8K





GNASIT AIRCONDITIONING SERVICES

2173 PASIGLINE ST, STA ANA, ZONE 86, BGY 790, MANILA
MOBILE #: 0917-557-1506 / (02) 8353-1027

July 21, 2025

Ms.Genny Co
471 Elcano St.cor San Fernando
Binondo, Manila

Attention: Ms.Genny

Good day!

We are pleased to submit our quotation price for your aircon unit Installation
Here's the breakdown as your reference.

Recommendation: SPLIT TYPE (1HP)
Area: 8sqm (COPPER TUBE 56FT / ROYAL CORD 62FFT)

Installation Cost	Initial Charge	PHP 7,500.00
FREE: (COPPER TUBE & ROYAL CORD of 10ft/3meters)		
Additional Cost in existing of 10ft		
Cooper Tube	46ft/350	16,100.00
Royal Cord	52ft/100	5,200.00
Breaker (30amp)		1,000.00
Total Estimation		29,800.00

DINING AREA : (Recommendation 4HP)

(as per customer with waiver 2.5HP window type)

Installation cost	1,200.00
Bracket	600.00
TOTAL	1,800.00

MASTER BEDROOM (1.5HP window type)

Installation cost	1,200.00
Bracket	600.00
TOTAL	1,800.00

TOTAL ESTIMATION COST **PHP 33,400.00**

NOTE : (Carpentry, Masonry, Electrical are not include in the scope of work)

Mode of Payment

CASH

GCASH (0917-800-0725 MARIA CRISTINA T.)

GNASIT AIRCONDITIONING SERVICES (METROBANK ACCNT NO.231-3-231743856)



GNASIT AIRCONDITIONING SERVICES

2173 PASIGLINE ST, STA ANA, ZONE 86, BGY 790, MANILA

MOBILE #: 0917-557-1506 / (02) 8353-1027

(50% downpayment for the materials needed , and full payment upon the completion of work)

Should you approve the above offer...Please sign the conforme on the space below

If you have questions or concern regarding the quote, please don't hesitate to get in touch with us.
Call/TEXT 0917-557-1506, (02) 8353-1027

Sincerely,
Melvin B. Tisang

Conforme:



GNASIT AIRCONDITION SERVICES

2173 PASIGLINE ST, STA ANA, ZONE 86, BGY 790, MANILA

MOBILE #: 0917-517-1506 / (02)8353-1027

July 22,2025

Mr.KARL HUI
471 Elcano St.cor San Fernando
Binondo, Manila

Attention: Mr.Karl Hui,

Please be informed that the air-conditioner that you purchased is undersized and is probable that you may experience the following;

AREA	RECOMMENDATION	CUSTOMER'S CHOICE	REMARKS
1. DINING AREA(45.6sqm)	4HP	2.5 WINDOW TYPE	as per customer

1. Capacity of the unit to cool the ares will take longer or it will not cool the area at all that may lead to your dissatisfaction with the cooling performance of our unit.
2. Power consumption will be higher due to frequent running of compressor for not reaching the desired temperature within the normal parameter
3. Useful life of compressor will shortened due to excessive running beyond the normal run cycle.

Considering the above conditions,we regret to inform you that we cannot guarantee the efficient performance of unit.,,Also one year warranty for parts(compressor____year/years).

For your guidance and information

Prepared by:

Melvin B.Tisang

Conforme: