

MR. JR YAP
91 ECOLOGY VILL. GATE 6, MAGALLANES MAKATI CITY
TEL#: 0930-6177016

Dear Ma'am/Sir,

Kolin Marketing Inc., is extremely honored for your endorsement of Kolin brand and we are please to offer you with a special price/s for the following items.

A. EQUIPMENT & INSTALLATION

**** OPTION 1**

QTY	U/M	MODEL / DESCRIPTION	SRP	DISCOUNTED PRICE		AMOUNT
1	UNIT/S	MODEL: KSM-IW20-WCT10M1M32 KOLIN WALL MOUNTED CERTUS SERIES AIRCONDITIONER 18,990 Kj/h (2.0HP) REGULAR INVERTER R-32	41,995.00	27,916.20	PHP	27,916.20
TOTAL UNIT COST					PHP	27,916.20
ESTIMATED COST OF INSTALLATION (please see attached)					PHP	18,200.00
OTHERS: DELIVERY CHARGE					PHP	600.00
TOTAL ESTIMATED COST OF THE PROJECT					PHP	46,716.20

**** OPTION 2**

QTY	U/M	MODEL / DESCRIPTION	SRP	DISCOUNTED PRICE		AMOUNT
1	UNIT/S	MODEL: KSG-IWF-20WFY-8K1M32 KOLIN WALL MOUNTED PRIMUS GOLD AIRCONDITIONER 19,000 Kj/h (2.0HP) FULL DC INVERTER W/ WIFI R-32	59,595.00	38,292.20	PHP	38,292.20
TOTAL UNIT COST					PHP	38,292.20
ESTIMATED COST OF INSTALLATION (please see attached)					PHP	18,200.00
OTHERS: DELIVERY CHARGE					PHP	600.00
TOTAL ESTIMATED COST OF THE PROJECT					PHP	57,092.20

TERMS OF PAYMENT:

FULL PAYMENT OF UNIT AND DELIVERY CHARGE. IF CHECK, SUBJECT FOR 3 DAYS CLEARING.

WARRANTY:

FOR SPLIT TYPE : ONE (1) YEAR FREE PARTS AND LABOR, THREE YEARS (3) MAIN PCB , TEN (10) YEARS WARRANTY ON COMPRESSOR.

NOTES: PRICES ARE SUBJECT TO CHANGE WITHOUT PRIOR NOTICE.

PRICES IS VAT INCLUSIVE.

**** Cost of Installation is Package with the Unit(s), this cost cannot avail separately (cost will be based on actual works).**

We thank you for giving opportunity to offer our product and services, hoping we receive your purchase order.

If you need assistance, don't hesitate to call the under signed at 0917-807-8607 or email at kmi_asst@kolinphil.com.ph

Very Truly Yours,

JANELLEN S. LIM
KMI-ASSISTANT

Noted by:
MART NATHANIEL R. FLORES
KMI-SUPERVISOR

Approved By:

MS. EDITHA M. FLORES
AVP - FINANCE

KMI-QUOTE-05-25-0399
REG-24%/4K/7K

Conforme:

SIGNATURE OVER PRINTED NAME

Kolin Marketing, Inc.

1854 Sta. Rita St., Guadalupe Nuevo, Makati City

Tel.: (632) 8852-6473

Fax: (632) 8852-2170 / (632) 8852-4792

www.kolinphil.com.ph / kolinphilippines





ESTINOR AIRCONDITIONING SERVICES

8 C. Jose Extension St., Brgy. 144 Malibay, Pasay City

7621-7179; 8800-1401 / 0917-316-8463; 0925-651-7664

estinor.airconditioning.services@gmail.com | VAT Reg. TIN: 231-613-080-000

SURVEY FORM

Authorized Service Center: **KOLIN** **GREE** **AUX** **AUFIT** **EVEREST** **Hisense**

CUSTOMER:

91 ECOLOGY VILL. GATE 6 MAGALLANES MARATI

DATE:

ADDRESS:

09957918810

CONTACT INFO:

DESCRIPTION

AMOUNT (PHP)

KITCHEN / 24H
FIRST 10FT
EXCESS 14FT / 4M = 7,200
DUMMANTILE
BREAKER = 1,000
18,200

09306177010
JR YOP

RECOMMENDATION

ESTIMATED CHARGES

MODEL/UNIT

CAPACITY

LOCATION OF IDU / ODU

- * Windows with direct sunlight contact (min. 5in x 5in) - add 30% to the total heat load computed
* Windows with indirect sunlight contact (min. 5in x 5in) - add 15% to the total heat load computed

TOTAL HEAD LOAD AREA (L x W)	x	=	
TOTAL HEAT LOAD			
1 SQM	= 550BTU/H	x	
PERSON	= 300BTU/H	x	
REF < 6 CU.FT.	= 400BTU/H	x	
REF > 6 CU.FT.	= 800BTU/H	x	
LAPTOP	= 150BTU/H	x	
ORD. LIGHT	= 200BTU/H	x	
SPEC. LIGHT	= 400BTU/H	x	
HOLOGEN LIGHT	= 1,000BTU/H	x	
TV	= 200BTU/H	x	
DVD	= 150BTU/H	x	
PERSONAL COMP.	= 400BTU/H	x	
LASER PRINTER	= 500BTU/H	x	
INKJET PRINTER	= 250BTU/H	x	
PHOTOCOPIER	= 1,000BTU/H	x	
COOKING RANGE	= 1,500BTU/H	x	
TOTAL		=	

SURVEY FEE 500
PAID

NOTICE OF UNDERSTANDING

I, _____, certify that all requirements and provisions have been explained to me and hereby waives any liability to ESTINOR AIRCONDITIONING SERVICES resulting from incorrect or inadequate performance of the installation unit arising from:

1. The required standards for installation have not been completely met: 2. Recommended guidelines for capacity do not meet the standards:

- ☐ No proper service access for maintenance
☐ Reusing an existing substandard installed pipe size
☐ Unauthorized installer
☐ No proper ventilation for air conditioning unit
☐ Substandard power supply

- ☐ Undersized capacity that may result in poor cooling performance, high power consumption, high maintenance charge, limited warranty claims.

I also confirm that all details pertaining to the installation of my unit were clearly explained to me by authorized representative.

E.A.S. Authorized Representative

Customer's printed Name & Signature