



27-Jan-2025

MR. ARMANDO, VELASCO

7 ISON ST., BRGY. DOLORES (NEAR MCDO BAYAN), TAYTAY RIZAL

TEL: 8658-1449 / 0956-8752507

Sir/ Madam,

This is to inform you of your unsettled bill for the service job done to your unit for the month of JULY 2024. Details of the charges are stated below and a copy of the Service Job Report is attached for your references:

DATE ATTENDED	SJR #	QUANTITY/MODEL	SERVICE JOB DONE	AMOUNT
11-Jul-24	HO-00212949	(1) KFS-10BMINV	GENERAL CLEANING / REPAIR	900.00
11-Jul-24	HO-00212954	(1) KFS-20DINV	PARTS REPLACEMENT	13,689.00
TOTAL				P 14,589.00
LESS: DISCOUNT				(729.45)
TOTAL AMOUNT DUE				P / 13,859.55

For any clarifications please feel free to call the Undersigned at the telephone number **8852-6473**

Note: If check payment, please prepare check payable to **Kolin Philippines International Inc.**

Account #: BDO - KALAYAAN


011808000428

Note: In case thru Bank Deposit under BDO Account, kindly indicate SJR# for your Bank Reference in the deposit slip and Fax to **(632) 8852-6473** or E-mail to: **kmi_asst@kolinphil.com.ph**

Prepared by:


Janellen S. Lim
KMI - Assistant

Noted by:


Mar Namanial R. Flores
KMI - Supervisor

Received by:

Signature over printed name

 **Kolin Philippines Int'l., Inc.**

Plant and Head Office:
Blk 3 Lt 5 Main Drive, FCIE Compound,
Brgy. Langkaan I, Dasmariñas, Cavite

Tel.: (632) 8749-2118

Fax (046) 402-0793

 www.kolinphil.com.ph / kolinphilippines

Operation Office:
1854 Sta. Rita St., Guadalupe Nuevo,
Makati City

Tel.: (632) 8851-2711, 12 or 15

Fax: (632) 8852-2170

Sales Dept. Fax: (632) 8852-4791



Customer		Velasco, Armando		No.		HO-00212949	
Address		7 Isen St., Brgy. Dolores (Near Mcdo Bayan), TAYTAY, Rizal		Previous SJR No.		HO-00205113	
Telephone No.		(02)8658-1449		Date		07-10-2024	
Contact Person		Ritch		Start Time		04:32 pm	
Warranty Code		Mobile No. 0917-5524694		End Time		04:35 pm	
Model		KFS-10BMINV		Relayed by		talavera	
S/N (I)		15121412-10957		Warranty Type		K C	
Dealer		KMI		Room Size		Job Class TS LVL 1	
Installer		Complaint Not Cooling		Call Origin		SA	
Location		Right-side Room		Job Type		PO	
Mode Setting (Cool)		Before		S/N (O)		w/ pair of KFS-20	
WAC Setting Temp (16°C-RE)/(10/12-ME)		After		DOP		10/26/2015	
SAC/PAC Setting Temp (17°)		No. of Visit		Notes		SHOP Findings - , Recommendation - For pull out for shop repair . . . Repair Done - Pulled out with pressure 400PSI	
Discharge Temperature (High)		2nd Action		Tentative Sched		07/17/2024	
Intake Temperature (High)		Findings		Recommendation		BILLED	
Ampere		Voltage		SAC/PAC Pressure (PSI)		400PSI	
Part Code		Description		Qty		Unit Price	
00701201006		Stickless Tape 4"		1.00		200.00	
SR No.		SR-HO-00038027		Labor		1,000.00	
Repair Done		Findings - Broken plastic parts left side of rare case (kabitan ng tumilyo ng evaporator), Missing lock of fouver guide holder & dirty unit. . . Recommendation - For general cleaning		Handling		0.00	
Repair Code		KFS-1 - General Cleaning (Successful in door units)		Others		0.00	
Date Attended		07/11/2024		Total		1,200.00	
Time Attended		01:00 pm		Amount Paid		1,200.00	
This serves as temporary receipt when properly filled up by authorized representative.		Check No.		Balance		0.00	
Serviced by: Darrel Placientes		By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.		Bank / Branch		9900	
Technician(s)		Created by: RECHILLA		Conformed by:		Customer (Signature over printed name)	
		CSR					

Kolin Philippines Int'l., Inc.

185 St. Guadalupe Nuevo, Makati City
Tel: 888 / Mobile: 0917-811-8982 / Email: service@kolinphil.com.ph
Website: www.kolinphil.com.ph

SERVICE JOB REPORT

No. HO-00212954
Previous SJR No. HO-00208113

Customer	Velasco, Armando			Date	07-10-2024		
Address	7 Ison St., Brgy. Dolores (Near Medo Bayan), TAYTAY, Rizal			Start Time	04:39 pm		
Telephone No.	(02)8658-1449		Mobile No.	0956-8752507 / 0920-9148577		End Time	04:41 pm
Contact Person	Ritch	Mobile No.	0917-5524594	Tel. No.		Relayed by	talavera
Warranty Code		Room Size		Warranty Type	K-C		
Model	KFS-20DINV		Call Origin	SA	Job Class	TS	LVL
S/N (I)		S/N (O)	15151304-10166	Permit?	☐	Parking?	☐
Dealer	KMI	DOP	10/26/2015	Appointment?	☐	O.R.?	☐
Installer	Malvin Tisang	Complaint	Not Cooling				
Location		Before		After			
Mode Setting (Cool)		No. of Visit	2nd Action	Tentative Sched	07/17/2024		
WAC Setting Temp(16°C-RE)/(10/12-ME)		Findings					
SAC/PAC Setting Temp (17°)							
Discharge Temperature (High)							
Intake Temperature (High)							
Ampere		Recommendation					
Wattage (Inverter)							
Voltage							
SAC/PAC Pressure (PSI)							

Part Code	Description	Qty	Unit Price	Amount
CR0007130053	ELECTRONIC EXPANSION VALVE 3PS	2	1430.00	2860
CR3230158922	PCB OUTDOOR BOARD GEN. CLEANING	1	6000.00	6000
11050005	Freon 110a (11.3kg)	1	0.00	
		4		
				1500
				(1521) 1.17
				13189.00

BILLED
Date: 8/8/24

SR No.	REPLACED ELECTRONIC EXPANSION VALVE 3PS	Labor	5250
Repair Done	PCB OUTDOOR BOARD, GEN. CLEANING, SYSTEM REPROCESS	Handling	56250.00
Repair Code	Findings - Compressor no suction and discharge at letter B. Letter A no suction but discharge only, dirty unit, defective pcb outdoor board (hindi napaipahatay)	Others	500.00
Date Attended	07/11/2024	Total	15210.00
Time Attended	07/11/2024	Amount Paid	15210.00
		Balance	0.00

This serves as temporary receipt when properly filled up by authorized representative.		Check No.	Bank / Branch
Served by:	Carrel Paciente	By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.	
Technician(s)	RECHILLA	I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.	
	CSR	Created by:	Conformed by:
		Customer	(Signature over printed name)