



6-Jan-2025

ATTY. BENEDICT LINTONJUA

U-4A TWIN TOWER, AYALA AVE., BRGY. URDANETA BELAIR, MAKATI CITY

TEL: 0920-9509294

Sir/ Madam,

This is to bill you on the service job done to your unit for the month of DECEMBER 2024.
Details of the charges are stated below and a copy of the Service Job Report is attached for your references:

DATE ATTENDED	SJR #	QUANTITY/MODEL	SERVICE JOB DONE	AMOUNT
27-Dec-24	HO-00235898	(1) KFM-400F1J	REPLACED JUMPER WIRE	600.00
TOTAL AMOUNT DUE				P. 600.00

For any clarifications please feel free to call the Undersigned at the telephone number **8852-6473**

Note: If check payment, please prepare check payable to **Kolin Philippines International Inc.**

Account #: BDO - KALAYAAN 011808000428

Note: In case thru Bank Deposit under BDO Account, kindly indicate SJR# for your Bank Reference in the deposit slip and Fax to **(632) 8852-6473** or E-mail to: **kmi_asst@kolinphil.com.ph**

Prepared by:


Janelle S. Lim
KMI - Assistant

Noted by:


Mari Nathaniel R. Flores
KMI - Supervisor

Received by:

Signature over printed name

 **Kolin Philippines Int'l., Inc.**

Plant and Head Office:
Blk 3 Lt 5 Main Drive, FCIE Compound,
Brgy. Langkaan I, Dasmariñas, Cavite
Tel.: (632) 8749-2118
Fax (046) 402-0793
www.kolinphil.com.ph / kolinphilippines

Operation Office:
1854 Sta. Rita St., Guadalupe Nuevo,
Makati City
Tel.: (632) 8851-2711, 12 or 15
Fax: (632) 8852-2170
Sales Dept. Fax: (632) 8852-4791





Kolin Philippines Int'l., Inc.

1854 Sta. Rita St., Guadalupe Nuevo, Makati City
Tel. No.: 8852-6868 / Mobile: 0917-811-8982 / Email: service@kolinphil.com.ph
Website: www.kolinphil.com.ph

SERVICE JOB REPORT

No. HO-00235898
Previous SJR No. HO-00235306

Customer		Date	
Address		Start Time	
		End Time	
Telephone No.	Mobile No.	Relayed by	
Contact Person	Mobile No.	Tel. No.	Warranty Type
Warranty Code	Room Size	Job Class	LVL
Model	Call Origin	Job Type	
S/N (I)	S/N (O)	Permit? <input type="checkbox"/>	Parking? <input type="checkbox"/>
Dealer	DOP	Appointment? <input type="checkbox"/>	O.R.? <input type="checkbox"/>
Installer	Complaint	Ladder? <input type="checkbox"/>	
Location	Before	After	
Mode Setting (Cool)	No. of Visit	1st Action	Tentative Sched
WAC Setting Temp(16°C-RE)/(10/12-ME)	Findings		
SAC/PAC Setting Temp (17°)	BURN OUT JUMPER WIRE		
Discharge Temperature (High)	13°C		
Intake Temperature (High)	25°C		
Ampere	14A		
Wattage (Inverter)	Recommendation		
Voltage	CLEAN AIR FILTER REGULARLY		
SAC/PAC Pressure (PSI)	230V		
Part Code	Description	Qty	Unit Price
	R-22	1	
NOTE: PAYMENT FOR COLLECTION			
C/O KMI			
1/2/2024			
SR No.	Labor		600-
Repair Done	HANDLING		
Repair Code	OTHERS		
Date Attended	Date Finished	Total	600-
Time Attended	Time Finished	Amount Paid	
This serves as temporary receipt when properly filled up by authorized representative.		Check No.	Balance
Bank / Branch			
Serviced by: JOSELO BRASOS, ROYEL CUEVA		By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.	
BOYET REX LITO		I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.	
Created by: LUIS REBOLAS		Conformed by:	
Technician(s)		Customer (Signature over printed name)	