

MR. JORES MAGSOMBOL 93 LILAC ST., SSS VILLAGE MARIKINA CITY TEL#: 0967-3963544

Email: mydel40@gmail.com

Dear Ma'am/Sir,

Kolin Marketing Inc., is extremely honored for your endorsement of Kolin brand and we are please to offer you with a special price/s for the following items.

A. EQUIPMENT & INSTALLATION

* ODTION 2 *

QTY	U/M	MODEL / DESCRIPTION	SRP	DISCOUNTED		AMOUNT	
2	UNIT/S	MODEL: KSG-IWF-30WFY-8K1M32 KOLIN WALL MOUNTED PRIMUS GOLD AIRCONDITIONER 29,500 Kj/h (3.0HP) FULL DC INVERTER W/ WIFI R-32	76,595.00	51,212.20	PHP	102,424.40	
1	UNIT/S	MODEL: KSG-IWF-25WFY-8K1M32 KOLIN WALL MOUNTED PRIMUS GOLD AIRCONDITIONER 25,560 Kj/h (2.5HP) FULL DC INVERTER W/ WIFI R-32	68,995.00	45,436.20	РНР	45,436.20	
TOTAL	UNIT COST		PHP	147,860.60			
ESTIMATED COST OF INSTALLATION (please see attached)						\ 53,100.00	
OTHERS: DELIVERY CHARGE						600.00	
TOTAL ESTIMATED COST OF THE PROJECT						201,560.60	

TERMS OF PAYMENT:

FULL PAYMENT OF UNIT AND DELIVERY CHARGE. IF CHECK, SUBJECT FOR 3 DAYS CLEARING.

WARRANTY:

FOR FLOOR MOUNTED: ONE (1) YEAR FREE PARTS AND LABOR, FIVE (5) YEARS WARRANTY ON COMPRESSOR. FOR SPLIT TYPE: ONE (1) YEAR FREE PARTS AND LABOR, THREE YEARS (3) MAIN PCB , TEN (10) YEARS WARRANTY ON COMPRESSOR.

NOTES: *** Need to sign waiver agreement due to under capacity of unit choice.

PRICES ARE SUBJECT TO CHANGE WITHOUT PRIOR NOTICE.

PRICES IS VAT INCLUSIVE.

** Cost of Installation is Package with the Unit(s), this cost cannot avail separately (cost will be based on actual).

*** You may settle first payment for unit/s & delivery. Installation payment can be settled directly to installer after actual works.

We thank you for giving opportunity to offer our product and services, hoping we receive your purchase order.

If you need assistance, don't hesitate to call the under signed at 0917-807-8607 or email at kmi_asst@kolinphil.com.ph

Very Truly Yours,

KMI-ASSISTANT

Noted by:

MART NATHANIEL B. FLORES KMI-SUPERVISOR

KMI-QUOTE-07-25-0519 ADR-24%/7K

Approved By:

AVP FINANCE

Conforme:

SIGNATURE OVER PRINTED NAME

Kolin Marketing, Inc.

1854 Sta. Rita St., Guadalupe Nuevo, Makati City Tel.: (632) 8852-6473

Fax: (632) 8852-2170 / (632) 8852-4792

www.kolinphil.com.ph / kolinphilippines





June 24, 2025 Jores Magsombol 93 Lilac St. SSS Village, Marikina City 0967-3963544


mydel40@gmail.com

MODEL Qty

KSG-IWF-30WFY8K1M32 KSG-IWF-25WFY8K1M32 2

\neg	-10	Ar	2
-1	10	JIN	1

MING	AREA EXTENSION					Area	32	sqm
CU 1	2.5 HP Wall Mounted Inverter		KSG-IV	VF-2	5WFY8K1M32			
	Estimated Pipe Length =	10 ft						
	Estimated Royal Cord Length =	15 ft						
	Initial Charge						P	8,500.00
	Includes:							
	Labor							
	10ft Copper Tube							
	10ft Royal Cord							
	Outdoor Bracket (Wall)							
	Consumables							
	Installation Materials	Description	Qty	Pri	ce per qty	Subtotal		
	Royal Cord (comm. wire)	2.mm2 x 4C	5 ft	P	100.00/ft	₱ 500.00		
	Royal Cord (ACCU-Breaker)	3.5mm x 3c	5 ft	P	60.00/ft	₱ 300.00		
	Circuit Breaker waterproof	30A / 1Ph	1 pc/s	P	1,000.00/pc	₱ 1,000.00		
	PVC blue	3/4" x 10'	3 pc/s	P	150.00/pc	₱ 450.00	P	2,250.00
	Estimated Charges						P	10,750.0
AIN D	INING AREA					Area	60	sqm
:U 2	3.0 HP Wall Mounted Inverter		KSG-IV	VF-3	OWFY8K1M32			
		39 ft						
	Estimated Royal Cord Length =	44 ft						
	Initial Charge						P	8,500.00
	Includes:							
	Labor							
	10ft Copper Tube							
	10ft Royal Cord							
	Outdoor Bracket (Wall) Consumables							
	Installation Materials	Description	Qtv	Pri	ce per qty	Subtotal		
	Copper Tube	Ø 1/4" x Ø 5/8"	29 ft		400.00/ft	P 11,600.00		
	Royal Cord (comm. wire)	2.mm2 x 4C	34 ft	P	100.00/ft	₱ 3,400.00		
	Royal Cord (ACCU-Breaker)	3.5mm x 3c	5 ft	P	60.00/ft	₱ 300.00		
	Circuit Breaker waterproof	30A / 1Ph	1 pc/s	P	1,000.00/pc	P 1,000.00		
	PVC blue	3/4" x 10'	2 pc/s	P	150.00/pc	₱ 300.00	P	16,600.00
	Estimated Charges						P	25,100.0
:U 3	3.0 HP Wall Mounted Inverter		V00 III	<i>/</i> = 0				
.0 3		23 ft	NSG-IVI	/F-3	OWFY8K1M32			
	Estimated Royal Cord Length =							
	Initial Charge	20 11					•	8,500.00
	Includes:							0,000.00
	Labor							
	10ft Copper Tube							
	10ft Royal Cord							
	Outdoor Bracket (Wall)							
	Consumables							
	Installation Materials	Description	Ohr	Dri	ice per qty	Subtotal		
	Copper Tube	Ø 1/4" x Ø 5/8"	13 ft		400.00/ft	₱ 5,200.00		
	Royal Cord (comm. wire)	2.mm2 x 4C	18 ft		100.00/ft	₱ 1,800.00		
	Royal Cord (ACCU-Breaker)	3.5mm x 3c	5 ft		60.00/ft	P 300.00		
	Circuit Breaker waterproof	30A / 1Ph	1 pc/s		1,000.00/pc	P 1,000.00		
	On our Dicarci Waterproof		i puis					
	PVC blue	3/4" x 10'	3 pc/s	P	150.00/pc	₱ 450.00		8,750.00



Validity: This quotation is valid for a period of fifteen (15) days from the date thereof, subject to our confirmation thereafter.

Installation notes:

- 1 Location of indoor and outdoor units were agreed by the customer and Kolin's surveyor.
- 2 Mechanical Plans, Permits, Electrical permits not included.
- 3 ACU2 and ACU3 Need waiver due to undercapacity.
- 4 ACU1 With Existing 2.0hp wallmounted.
- 5 Expose coppertube and drainline in the area, Bring plywood 3/4 inch for indoor Backing all units.
- 6 Deflectors, masonry, carpentry, chipping & plastering (finishing & restoration) are not included in the installation.
- 7 Air conditioning drain line and Electrical power supply (feeder line) 220v/ 60hz/ 1ph, should be provided by customer's contractor.
- 8 Final charges will be based on actual installation.

Prepared by:

Jeoffrey Dadios
Field Surveyor

Reviewed by:

Engr. Kenneth Zamora
Service Supervisor Shop and
Field Operation

Customer Conformee:

Signature Over Printed Name

July 3, 2025 Jores Magsombol 93 Lilac St. SSS Village, Marikina City 0967-3963544 mydel40@gmail.com

Please be informed that the air-conditioner you intend to purchase is under capacity as compared to the following unit that we proposed:

Location	Area	Kolin's Recommendation	Customer's Choice	Remarks	
MAIN DINING	60 sam	KLG-IF40-5G1M32	KSG-IWF-30WFY8K1M32	Calculated 7.8hp	
WAIN DIVING	00 34111	2 UNITS	2 UNITS	under by 1.8hp	

Since the unit of your choice is under capacity, it is probable that you may experience the following;

- 1. Capacity of the unit to cool the area will take longer or it will not cool the area at all that may lead to your dissatisfaction with the cooling performance of our unit.
- 2. Power consumption will be higher due to frequent running of compressor for not reaching the desired temperature within the normal parameter.
- 3. Useful life of compressor will be shortened due to excessive running beyond the normal run cycle.

Considering the above conditions, we regret to inform you that we cannot guarantee the efficient performance of unit. Also, One (1) year warranty for parts (compressor-1year).

For your guidance and information

7/4/25

Prepared by:

Jeoffrey T. Dadios

Surveyor

Approved by:

Mr. Alvin de Rivera

Noted by:

Engr. Kenneth Zamora Service Supervisor - Field and Shop Operation

Customer Conforme:

Signature Over Printed Name