



June 18, 2025

MR. JAMES CO
5TH FLOOR, 820 LIBERTY HALL BUILDING, BENAVIDEZ ST. BINONDO MANILA
TEL#: 0917-5667856
Email: kmt.phil@yahoo.com

Dear Ma'am/Sir,

Kolin Marketing Inc., is extremely honored for your endorsement of Kolin brand and we are please to offer you with a special price/s for the following items.

A. EQUIPMENT & INSTALLATION

QTY	U/M	MODEL / DESCRIPTION	SRP	DISCOUNTED PRICE		AMOUNT
1	UNIT/S	MODEL: KLG-IF40-5G1M32 KOLIN FLOOR MOUNTED AIRCONDITIONER 37,980 Kj/h (3.0TR) FULL DC INVERTER R-32 SINGLE PHASE	113,195.00	79,028.20	PHP	79,028.20
TOTAL UNIT COST					PHP	/ 79,028.20
ESTIMATED COST OF INSTALLATION (please see attached)					PHP	/ 18,990.00
OTHERS: DELIVERY CHARGE					PHP	/ 600.00
TOTAL ESTIMATED COST OF THE PROJECT					PHP	98,618.20

TERMS OF PAYMENT:

FULL PAYMENT OF UNIT AND DELIVERY CHARGE. IF CHECK, SUBJECT FOR 3 DAYS CLEARING.

WARRANTY:

FOR FLOOR MOUNTED: ONE (1) YEAR FREE PARTS AND LABOR, FIVE (5) YEARS WARRANTY ON COMPRESSOR.

NOTES: PRICES ARE SUBJECT TO CHANGE WITHOUT PRIOR NOTICE.

PRICES IS VAT INCLUSIVE.


**** Cost of Installation is Package with the Unit(s), this cost cannot avail separately (cost will be based on actual).**

***** You may settle first payment for unit/s & delivery. Installation payment can be settled directly to installer after actual works.**

We thank you for giving opportunity to offer our product and services, hoping we receive your purchase order.

If you need assistance, don't hesitate to call the under signed at 0917-807-8607 or email at kmi_asst@kolinphil.com.ph


Very Truly Yours,


JANELLE S. LIM
KMI-ASSISTANT

Noted by:


MART NATHANIEL R. FLORES
KMI-SUPERVISOR


Approved By:


MS. EDITHA M. FLORES
AVP - FINANCE

KMI-QUOTE-06-25-0476
ECY-24%/7K

Conforme:

SIGNATURE OVER PRINTED NAME



Kolin Marketing, Inc.
1854 Sta. Rita St., Guadalupe Nuevo, Makati City
Tel.: (632) 8852-6473
Fax: (632) 8852-2170 / (632) 8852-4792
www.kolinphil.com.ph / kolinphilippines

JUNE 17, 2025
James Co
5th Floor, 820 Liberty Hall Building Benavidez St. Binondo Manila
0917-5667856
kmt.phil@yahoo.com

MODEL Qty
KLG-IF40-5G1M32 1

DANCING ROOM Area 222 sqm


ACU 4.0 HP Floor Standing Inverter *KLG-IF40-5G1M32*
Estimated Pipe Length = 10 ft
Estimated Royal Cord Length = 17 ft
Initial Charge ₱ 11,000.00

Includes:

- Labor
- 10ft Copper Tube
- 10ft Royal Cord
- Indoor Bracket (Floor)
- Consumables

Installation Materials	Description	Qty	Price per qty	Subtotal
Royal Cord (comm. wire)	2.mm2 x 4C	7 ft	₱ 100.00/ft	₱ 700.00
Royal Cord (ACCU-Breaker)	5.5mm x 3c	7 ft	₱ 70.00/ft	₱ 490.00
Circuit Breaker waterproof	40A / 1Ph	1 pc/s	₱ 1,000.00/pc	₱ 1,000.00
Outdoor bracket	Fabricated floor	1 pc/s	₱ 2,500.00/pc	₱ 2,500.00
Dismantle	4.0HP Floor Standing	1 set	₱ 3,000.00/set	₱ 3,000.00
PVC blue	3/4" x 10'	2 pc/s	₱ 150.00/pc	₱ 300.00
				₱ 7,990.00

Estimated Charges ₱ 18,990.00




Validity: This quotation is valid for a period of fifteen (15) days from the date thereof, subject to our confirmation thereafter.

Installation notes:

- 1 Location of indoor and outdoor units were agreed by the customer and Kolin's surveyor.
- 2 AC drain line will be tapped to the nearest drain provision provided by the customer's contractor.
- 3 With existing of 2 unit of 5tr floor , 1unit of 3tr and 2 units of 2hp windowtype.
- 4 **Customer need an installer with cutting and welding the window for the access of outdoor unit going outside location.**
- 5 Working days: Monday to Saturday, 8am- 5pm without parking. Need working permit. bring harness and rope.
- 6 Mechanical Plans, Permits, Electrical permits not included.
- 7 Deflectors, masonry, carpentry, chipping & plastering (finishing & restoration) are not included in the installation.
- 8 Air conditioning drain line and Electrical power supply (feeder line) **220v/ 60hz/ 1ph** , should be provided by customer's contractor.
- 9 **Final charges will be based on actual installation.**


Prepared by:


Jeffrey Dadios
Field Surveyor

Customer Conformer:

Signature Over Printed Name

Reviewed by:


Engr. Kenneth Zamora
Service Supervisor Shop and
Field Operation