



March 9, 2026

HUEY YING RESTAURANT
SEASIDE MACAPAGAL BLVD., BRGY. DAMPA, PASAY CITY
ATTN: MS. ANNA / MR. WILSON UY
TEL#: 0917-5640742

Dear Ma'am/Sir,

Kolin Marketing Inc., is extremely honored for your endorsement of Kolin brand and we are please to offer you with a special price/s for the following items.

A. EQUIPMENT & INSTALLATION

QTY	U/M	MODEL / DESCRIPTION	SRP	DISCOUNTED PRICE		AMOUNT
1	UNIT/S	MODEL: KL-IF40-G6H1M32 KOLIN FLOOR MOUNTED AIRCONDITIONER 38,466 Kj/h (3.0TR) FULL DC INVERTER R32 SINGLE PHASE	108,995.00	72,336.20	PHP	72,336.20
TOTAL UNIT COST					PHP	72,336.20
ESTIMATED COST OF INSTALLATION (please see attached)					PHP	45,865.00
OTHERS: DELIVERY CHARGE					PHP	600.00
TOTAL ESTIMATED COST OF THE PROJECT					PHP	118,801.20

TERMS OF PAYMENT:

FULL PAYMENT OF UNIT AND DELIVERY CHARGE. IF CHECK, SUBJECT FOR 3 DAYS CLEARING.

BANK DETAILS:

- ** You may settle first payment for unit/s & delivery. Installation payment can be settled directly to installer after actual works.
- * Unit/s & Delivery: Account Name - KOLIN MARKETING INC. / Account# - 011808002307 (BDO-KALAYAAN)
- * Installation: Will be provided by assigned installer.

WARRANTY:

FOR FLOOR MOUNTED (Inverter): ONE (1) YEAR FREE PARTS AND LABOR, FIVE (5) YEARS WARRANTY ON COMPRESSOR.

NOTES: PRICES ARE SUBJECT TO CHANGE WITHOUT PRIOR NOTICE.

PRICES IS VAT INCLUSIVE.

** Cost of Installation is Package with the Unit(s), this cost cannot avail separately (Final charges will be based on actual works).

We thank you for giving opportunity to offer our product and services, hoping we receive your purchase order.
If you need assistance, don't hesitate to call the under signed at 0917-807-8607 or email at kmi_astt@kolinphil.com.ph

Very Truly Yours,

JANELLEN S. LIM
KMI-ASSISTANT

Noted By:
MART NATHANIEL R. FLORES
KMI-SUPERVISOR

Approved By:
MS. EDITHA M. FLORES
AVP - FINANCE

KMI-QUOTE-03-26-0121
MMC-24%/10.5K

Conforme: _____
SIGNATURE OVER PRINTED NAME



Customer Name: HUIYI XING RESTAURANT Date: 3-7-26
 Address: SEASIDE MEXICAN RESTAURANT (MEXICAN RESTAURANT) SJR No.: 193102

Establishment Type: Residential Area Surveyed: _____
 Commercial Area Surveyed: DINING AREA

Recommended Product Model: KL-140-GOHIM32

Cooling Capacity Computation

Floor Area: 150 sqm.
 Ceiling Height: 2.4 mtr.

note: add 20% per meter in excess of 3 meters in the initial cooling capacity computed.

Floor Area:	<u>150</u>	x	550 Btu/h	<u>82,500</u> Btu/h
Ceiling Height (excess of 3 mtrs.):		x	20%	
Window Direct Sunlight		x	20% - 50%	<u>41,250</u> Btu/h
Total Cooling Capacity				<u>123,750</u> Btu/h

Add : Additional Heat Load

No. of Person	<u>180</u>	x	300 Btu/h	<u>54,000</u> Btu/h
No. of Ordinary Light (<40w)	<u>100</u>	x	200 Btu/h	<u>20,000</u> Btu/h
No. of Special Light (>40w)		x	400 Btu/h	
No. of Refrigerator (< 6 cu.ft.)		x	400 Btu/h	
No. of Refrigerator (> 6 cu.ft.)	<u>1</u>	x	800 Btu/h	<u>800</u> Btu/h
No. of Cooking Range		x	1500 Btu/h	
No. of Laptop Computer		x	150 Btu/h	
No. of Desktop Computer	<u>1</u>	x	400 Btu/h	<u>400</u> Btu/h
No. of Printer	<u>1</u>	x	500 Btu/h	<u>500</u> Btu/h
No. of Photocopier		x	1000 Btu/h	
Total Cooling Capacity				<u>126,000</u> Btu/h

??

Recommended Cooling Capacity

197,700 Btu/h

Note : Compressor warranty will be reduced to ___ yr. if air-conditioner purchased is lower than the recommended cooling capacity or pipe lay-out is beyond the maximum allowable length.

Scope of Work Agreement

- 1. Copper tube lay-out Expose Embedded
- 2. Chipping Included Not Included
- 3. Fabricated Bracket Yes Shop Site No
- 4. Service Ledge Yes No
- 5. Dismantling of existing Aircon Included Not Included
- 6. Ducting Yes No


Dimension : _____

- 7. Plastering, carpentry and restoration works are to be done by the customer.
- 8. Wiring of electrical supply from main panel to air-conditioning unit are to be done by the customer.
- 9. Processing of mechanical plan, working permit, electrical permit are to be done by the customer.

10. Other concern: DISMANTLE AIR CON UNIT OF NEW BUILDING AND ADD UNIT. NEED TO HAVE A W/PLATE OR HOLE ON THE WALL FOR THE W/PLATE GOING INSIDE THE CEILING. NIGHT STAFF (10PM - 6AM) WITH EXISTING OF - 4 (3114) / (3117) - 1/9 (H)

Plan Lay-out

No 003742



Indoor Unit Location : CENTRE OF ALKX SX MELAKSTAL
 Outdoor Unit Location : XO FLIGHT SX ME LCKSTAL
 Pipe Length : 60 FT
 Special Note : _____

Installation Cost Estimate			
Material Description	Qty.	Unit Cost	Total Cost
Copper Tube (excess of 10 ft.) 2330, 2430, 2520, 3520, 4620	50 FT	400	20000
Wire (Royal Cord-signal wire) (excess of 10ft.) 2.0mmx4C	17 FT	100	5700
Wire (Royal Cord - Breaker to ODU) 3.5mm / 5.5mm x 3C	7 FT	70	490
Circuit Breaker 20A, 30A, 40A/1ph, 40A/3ph	1	1000	1000
Bracket (ODU) <u>MONEY</u> (Imptd. / Fabricated) ; (Floor / Wall)	1	1500	1500
Bracket (WAC) Angle Type			
PVC Pipe (drain) 1/2" , 3/4"			
PVC Pipe (electrical) 3/4" , 1"			
Drain Pump			
Drain Hose <u>WHITE 1/2" NIGHT STIFF</u>	7 FT	200	1400
Dismantling Fee (existing air-conditioner) <u>3TR</u>	1	3500	3500
Initial Charge			11000
TOTAL ESTIMATE		P	45,860

- Note :
- Initial Charge includes labor, 10ft. Copper tube, 10ft. Royal cord, Outdoor Bracket (SAC), Indoor Bracket (PAC) and Consumable materials.
 - Survey fee will be deducted in the installation fee.

Prepared by:
ADRIAN NOGOY
 Signature Over Printed Name

REVIEWED BY:

 03/07/2026
 ENGR. ADRIAN NOGOY
 PROJECT ENGINEER-KPH

Customer Conforms:

 Signature Over Printed Name