



12-Sep-2025

SL AGRITECH CORPORATION

2302 STERLING PLACE, PASONG TAMO EXTN., BRGY. PIO DEL PILAR, MAKATI CITY

ATTN: MS. MAE-AN

TEL: 0917-8875714

Sir/ Madam,

This is to bill you on the service job done to your unit for the month of JUNE 2024.

Details of the charges are stated below and a copy of the Service Job Report is attached for your references:

DATE ATTENDED	SJR #	QUANTITY/MODEL	SERVICE JOB DONE	AMOUNT
21-Mar-24	HO-00192485	(1) KLG-IF70-2C1M	PARTS REPLACEMENT	600.00
21-Mar-24	HO-00192487	(1) KLG-IF40-2C1M	PARTS REPLACEMENT	4,500.00
21-Mar-24	HO-00192488	(1) KLG-IF40-2C1M	PARTS REPLACEMENT	2,050.00
21-Mar-24	HO-00192489	(1) KSM-IW15-6H1M	TROUBLESHOOTING	1,800.00
TOTAL				P 8,950.00
LESS: DISCOUNT				(626.50)
TOTAL AMOUNT DUE				P 8,323.50

Notes:

* If check payment, please prepare check payable to **Kolin Philippines International Inc.**


Account #: 011808000428 - BDO - KALAYAAN

* In case thru Bank Deposit under BDO Account, kindly indicate **(1) SJR#** as Reference No. on the deposit slip

Kindly send proof of payment to **viber 0917-8078607** or E-mail to: **kmi_asst@kolinphil.com.ph**

For any clarifications please feel free to call the Undersigned on this telephone number **8852-6473**.

Prepared by:


Janellen S. Lim
KMI - Assistant

Noted by:


Maril N. R. Flores
KMI - Supervisor

Received by:

Signature over printed name

 **Kolin Philippines Int'l, Inc.**

Plant and Head Office:

Blk 3 Lt 5 Main Drive, FCIE Compound,
Brgy. Langkaan I, Dasmariñas, Cavite

Tel: (632) 8749-2118

Fax (046) 402-0793

 www.kolinphil.com.ph / kolinphilippines

Operation Office:

1854 Sta. Rita St., Guadalupe Nuevo,
Makati City

Tel: (632) 8851-2711, 12 or 15

Fax: (632) 8852-2170

Sales Dept. Fax: (632) 8852-4791





TPNR 38717

2

[illegible]



+ PWR 38718

No.
Previous SJR No.

HQ-00182417

[illegible]

SERVICE JOB REPORT

1854 Sta. Rita St., Guadalupe Nuevo, Makati City
Tel. No.: 8852-6868 / Mobile: 0917-811-8982 / Email: service@kolinphil.com.ph
Website: www.kolinphil.com.ph    [kolinphilippines](https://www.facebook.com/kolinphilippines)

No.	HO-00192488
Previous SJR No.	HO-00182417

Customer	91 SL AGRITECH CORPORATION					Date	03-20-2024			
Address	2302 Sterling Place, Pasong Tamo Extn., Brgy. Pio Del Pilar, MAKATI CITY, Manila...					Start Time	01:48 pm			
Manila...						End Time	01:49 pm			
Telephone No.	8813-7828 LOC 227/ 813-7828 LOC. 227/ 58-28630917-8875714		Mobile No.			Relayed by	Meann 0917-8751093			
Contact Person	Ms. Mean	Mobile No.	...	Tel. No.	...	Warranty Type	C			
Warranty Code				Room Size		Job Class	TS	LVL	1	
Model	KLG-IF40-2C1M			Call Origin	MH	Job Type	FD			
S/N (I)	17231805-13280		S/N (O)			Permit? ☐	Parking? ☐	Appointment? ☐	O.R.? ☐	Ladder? ☐
Dealer	WZ		DOP	01/15/2019		Notes	Team Villafuerte			
Installer			Complaint	F1 Error Code						
Location	2/F Annex HR Department		Before	After						
Mode Setting (Cool)			Cool	No. of Visit	1st Action		Tentative Sched	03/25/2024		
WAC Setting Temp(16°C-RE)/(10/12-ME)			—	Findings						
SAC/PAC Setting Temp (17°)			17°C	F1 Error Code						
Discharge Temperature (High)			24°C	Defective indoor temp. sensor assembly						
Intake Temperature (High)			12°C							
Ampere			14.2A	Recommendation						
Wattage (Inverter)			—	For further action/repair, the possible parts						
Voltage			230V	Pending inspection of 2' pos of indoor unit						
SAC/PAC Pressure (PSI)			140PSi							

[illegible]

SR No.	35048			Labor	\$1,500.00
Repair Done	Replace indoor temp. sensor assembly			Handling	
	fill but still HS PC			Others	
Repair Code				Total	\$2,050.00
Date Attended	3-21-24	Date Finished	3-21-24	Amount Paid	
Time Attended	10:00 am	Time Finished	2:30 pm	Balance	for collection
This serves as temporary receipt when properly filled up by authorized representative.				Check No.	
				Bank / Branch	

Serviced by: Garry Munday, Neil Villafuerte Salmon		By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.	
LOPEZ	VISTAN	I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.	
MEDINA		Created by: MARNILLE NORTE CSR	Conformed by: GARRY MUNDAY Customer (Signature over printed name) 13/20/24
Technician(s)			

Customer		SL AGRITECH CORPORATION		No. Previous SJR No.		HO-00192489	
Address		2302 Sterling Place, Pasong Tamo Extn., Brgy. Pio Del Pilar, MAKATI CITY, Manila		Date		03-20-2024	
Telephone No.		8813-7828 LOC 227/ 813-7828 LOC. 227		Mobile No.		28630917-8875714	
Contact Person		Ms. Mean		Tel. No.		...	
Warranty Code		...		Room Size		...	
Model		KSM-IW15-6H1M		Call Origin		MH	
S/N (I)		18251812-11498		S/N (O)		...	
Dealer		DOP		11/27/2019		Notes Team Villafuerte	
Installer		Complaint		E3 Error Code		...	
Location		Annex Bldg -3/F Meeting Ro.		Before		After	
Mode Setting (Cool)		Cool		No. of Visit		1st Action	
WAC Setting Temp(16°C-RE)/(10/12-ME)		...		Tentative Sched		03/25/2024	
SAC/PAC Setting Temp (17°)		17°C		Findings		Undercharge refrigerant	
Discharge Temperature (High)		25°C		Intake Temperature (High)		25°C	
Ampere		1.5hp		S-5AP		Recommendation	
Wattage (Inverter)		...		Unit for observation		For pull out if the same	
Voltage		230V		problem occur		...	
SAC/PAC Pressure (PSI)		50 Psi		140 Psi		...	
Part Code		Description		Qty		Unit Price	
Amount		...		...		...	
SR No.		Labor		...		...	
Repair Done		Recharging of refrigerant / Leak test (Bubble test)		Handling		...	
Repair Code		indoor & outdoor / no leak found		Others		...	
Date Attended		3-21-24		Date Finished		3-21-24	
Time Attended		10:00 am		Time Finished		2:30 pm	
This serves as temporary receipt when properly filled up by authorized representative.		Check No.		Bank / Branch		...	
Serviced by: Garry Munday, Neil Villafuerte		By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.		Created by:		Conformed by:	
Lopez VISTAN		I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.		MARNILLE NORTE		Customer (Signature over printed name)	
MEDINA		Technician(s)		CSR		3/21/24	