

Kolin Philippines Int'l., Inc.

1854 Sta. Rita St., Guadalupe Nuevo, Makati City
 Tel. No.: 8852-6868 / Mobile: 0917-811-8982 / Email: service@kolinphil.com.ph
 Website: www.kolinphil.com.ph     

TPWR 37942

SERVICE JOB REPORT

No. HO-00187811
 Previous SJR No. HO-00184113

Customer	Uysipuo, Fred				Date	02-14-2024					
Address	654 Richmond St., Brgy. Greenhills East, MANDALUYONG CITY, Metro Manila				Start Time	08:36 am					
Telephone No.	88725-0026		Mobile No.	0917-8162271		End Time	08:38 am				
Contact Person	Charlene/ Fred	Mobile No.	0917-8162271	Tel. No.	02-88725-0026	Relayed by	Mart Flores- Kmi				
Warranty Code				Room Size			Job Class	TS	LVL	1	
Model	KSM-30MB1INV			Call Origin	IO		Job Type	FD			
S/N (I)	18011506-11391		S/N (O)	10901506-16505		Permit? <input type="checkbox"/>	Parking? <input type="checkbox"/>	Appointment? <input type="checkbox"/>	O.R.? <input type="checkbox"/>	Ladder? <input type="checkbox"/>	
Dealer				DOP			Notes	Lojero "only" back job ref number HO-00184113 (1) SAC- E1 (MASTER BEDROOM) CHARGEABLE			
Installer				Complaint	E1 Error Code		SCHEDULE ASAP KC REFERRAL TECH: VIP TEAM WITH PARKING KINDLY ADVISE CLIENT AHEAD OF TIME				
Location	Master's Bedroom		Before	After			No. of Visit	1st Action	Tentative Sched		02/16/2024
Mode Setting (Cool)			COOL								
WAC Setting Temp(16°C-RE)/(10/12-ME)				17°C	Findings						
SAC/PAC Setting Temp (17°)				10°C							
Discharge Temperature (High)				29°C							
Intake Temperature (High)				29AM							
Ampere					Recommendation						
Wattage (Inverter)											
Voltage				230 KIDPSI	FOR REPLACEMENT OF IPM						
SAC/PAC Pressure (PSI)											
Part Code	Description					Qty	Unit Price	Amount			
	IPM					1	IPM	6,000			
SR No.	#0-34854					Labor	1,000				
Repair Done	CHECK UP, REPLACED IPM					Handling					
Repair Code						Others					
Date Attended	2-15-24		Date Finished	2-15-24		Total	8,300				
Time Attended	9:00 AM		Time Finished	10:50AM		Amount Paid	FOR COLLECTION				
This serves as temporary receipt when properly filled up by authorized representative.					Check No.	Bank / Branch					
Serviced by: Richard Talavera, Ericaan Val Medina		By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.									
TALAVERA		VALUE		I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.							
MEDINA		GUTTER GATE		Created by:	Conformed by:						
Technician(s)				KATHY DE GUZMAN							
				CSR							
					Customer (Signature over printed name)						