

# Kolin Philippines Int'l., Inc.

1854 Sta. Rita St., Guadalupe Nuevo, Makati City  
 Tel. No.: 8852-6868 / Mobile: 0917-811-8982 / Email: service@kolinphil.com.ph  
 Website: www.kolinphil.com.ph 

## SERVICE JOB REPORT

Customer				Date	HO-00190625			
Address	Dynamic Youth Office Room 412 Liberty Hall, 820 Bonavides St., Brgy. Binondo, MANILA CITY, Metro M...			Start Time	HO-00181617 03-07-2024			
Telephone No.	Mobile No.		Mobile No.	End Time	10:30 am			
Contact Person	8245-7085	Mobile No.	Tel. No. 09296722589/09057361720	Relayed by	10:31 am			
Warranty Code	Trixie 0929-8722589		Room Size	Warranty Type	Engr. Kenneth Zamora			
Model			Call Origin	Job Class	C	LVL		
S/N (I)	KIG-SF40-WBR6H1M32	S/N (O)	20389303-10823	Permit? <input type="checkbox"/>	Parking? <input type="checkbox"/>	Appointment? <input type="checkbox"/>	O.R.? <input type="checkbox"/>	Ladder? <input type="checkbox"/>
Dealer	20379303-11323	DOP		Notes X				
Installer	KMI	Complaint	12/13/2023	Lopez * 2 SAC for installation * ECY REFERRAL * COLLECTION C/O KMI				
Location	Before	After	For Installation					
Mode Setting (Cool)	MULTI PURPOSE AREA 1		No. of Visit	1		Tentative Sched		
WAC   Setting Temp(16°C-RE)/(10/12-ME)				Findings 03/08/2024				
SAC/PAC   Setting Temp (17°)			For installation	1st Action				
Discharge Temperature (High)								
Intake Temperature (High)								
Ampere				Recommendation				
Wattage (Inverter)			For start-up					
Voltage			Wait for customer's call					
SAC/PAC   Pressure (PSI)								
Part Code	Description			Qty	Unit Price	Amount		
	S-tape			1				
	Royal cord 5.5mm x 3c			5ft.	\$70 x 5 ft. =	\$350.00		
	Breaker 40 amp koton			1	\$1,000	\$1,000.00		
	Drain hose			5ft.	\$25 x 5 =	\$125.00		
<b>LIQUIDATED</b>								
SR No.	05271	Initial Charge			Labor	\$11,000.00		
Repair Done	Installed unit			Handling				
				Others				
Repair Code				Total	\$12,475.00			
Date Attended	3-8-24	Date Finished	3-8-24	Amount Paid				
Time Attended	9:45 am	Time Finished	2:40 pm	Balance	\$12,475.00			
This serves as temporary receipt when properly filled up by authorized representative.				Check No.	For collection			
Serviced by:		By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.						
LOPEZ Fernando Lopez, Michael Viz		I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.						
GUTIERREZ BERMEO		Created by:		Conformed by:				
VISTAN		CSR		Customer (Signature over printed name)				

# Kolin Philippines Int'l., Inc.

1854 Sta. Rita St., Guadalupe Nuevo, Makati City  
Tel. No.: 0852-6868 / Mobile: 0917-811-8982 / Email: service@kolinphil.com.ph  
Website: www.kolinphil.com.ph 







## SERVICE JOB REPORT

Customer					Date	HO-00190627			
Address	Dynamic Youth Office Room 412 Liberty Hall, B20 Benavidez St., Brgy. Binondo, MANILA CITY, Metro Manila				Start Time	HO-00190627 03-07-2024			
Telephone No.	Mobile No.				End Time	10:31 am			
Contact Person	Mobile No.	Tel. No.			Relayed by	10:32 am			
Warranty Code	Room Size				Warranty Type	Engr. Kenneth Zamora			
Model	Call Origin				Job Class	C	LVL		
S/N (I)	KLG-SF40-WBR6H1M32	S/N (O)	10		Job Type	INST	2		
Dealer	26372363-108533	DOP	26382363-10824		Permit? <input type="checkbox"/>	Parking? <input type="checkbox"/>	Appointment? <input type="checkbox"/>	O.R.? <input type="checkbox"/>	Ladder? <input type="checkbox"/>
Installer	KMI	Complaint	12/13/2023		Lopez * 2 SAC for installation * ECY RFFFRAI * COLLECTION C/O KMI				
Location	Before	After	For Installation						
Mode Setting (Cool)	MULTI-PURPOSE AREA 2		No. of Visit	1		Tentative Sched			
WAC   Setting Temp(16°C-RE)/(10/12-ME)					Findings				
SAC/PAC   Setting Temp (17°)					1st Action 03/08/2024				
Discharge Temperature (High)					For installation				
Intake Temperature (High)									
Ampere					Recommendation				
Wattage (Inverter)					For start up				
Voltage					Wait for customer's call				
SAC/PAC   Pressure (PSI)									
Part Code	Description				Qty	Unit Price	Amount		
	5-tape				1	10			
	Royal cord 5.5mm x 3 C				5 ft.	\$70 x 5 ft.	\$350.00		
	Breaker 40amp koten				1	\$1,000.	\$1,000.00		
	Drain hose				5 ft.	\$25 x 5	\$125.00		
SR No.	LIQUIDATED 3/8/24								
Repair Done	Initial charge				Labor	\$11,500			
Repair Code					Handling				
Date Attended	3-8-24	Date Finished	3-8-24		Others				
Time Attended	9:45am	Time Finished	2:40pm		Total	\$12,475.00			
This serves as temporary receipt when properly filled up by authorized representative.				Check No.	Amount Paid				
Serviced by:		By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.							
LOPEZ Fernando Lopez / Michael Vicente		I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.							
MEDINA GUTIERREZ		Created by:		Conformed by:					
Technician(s)		CSR		Customer (Signature over printed name)					

# Kolin Philippines Int'l., Inc.

1854 Sta. Rita St., Guadalupe Nuevo, Makati City  
Tel. No.: 0852-6868 / Mobile: 0917-811-8982 / Email: service@kolinphil.com.ph  
Website: www.kolinphil.com.ph    

## SERVICE JOB REPORT

Customer					Date	HO-00190628		
Address	Dynamic Youth Office				Start Time	HO-00181617		
Room 412 Liberty Hall, 820 Benavidez St., Brgy. Binondo, MANILA CITY, Metro M...					End Time	03-07-2024		
Telephone No.			Mobile No.			Relayed by	10:33 am	
Contact Person	8245-7085	Mobile No.		Tel. No.	09296722589/09957384720	Warranty Type	Engr. Kenneth Zamora	
Warranty Code	Trixie		0929-6722589	Room Size		Job Class	C	LVL
Model				Call Origin		Job Type	FAB	1
S/N (I)	KLG-SF40-WBR6H1M32		S/N (O)		Permit? <input checked="" type="checkbox"/> Parking? <input type="checkbox"/> Appointment? <input type="checkbox"/>	O.R.? <input type="checkbox"/> Ladder? <input type="checkbox"/>		
Dealer			DOP	Notes X				
Installer	KMI		Complaint	12/13/2023 Lopez * 2 SAC for installation * ECY REFERRAL * COLLECTION C/O KMI				
Location			Before	Others				
Mode Setting (Cool)	MULTI-PURPOSE	AREA 1		No. of Visit		Tentative Sched		
WAC   Setting Temp(16°C-RE)/(10/12-ME)				Findings 1st Action For Fabrication of bracket Could be 03/08/2024				
SAC/PAC   Setting Temp (17°)								
Discharge Temperature (High)								
Intake Temperature (High)								
Ampere				Recommendation				
Wattage (Inverter)								
Voltage								
SAC/PAC   Pressure (PSI)								
Part Code	Description				Qty	Unit Price	Amount	
SR No.	Fabricated bracket				Labor		P 6,500.00	
Repair Done					Handling			
					Others			
Repair Code					Total		P 6,500.00	
Date Attended	3-8-24	Date Finished	3-8-24		Amount Paid		P 6,500.00	
Time Attended	9:45 am	Time Finished	2:40 pm		Balance		P 6,500.00 For collection	
This serves as temporary receipt when properly filled up by authorized representative.				Check No.	Bank / Branch			
Serviced by:		By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.						
Lopez Fernando  		I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.						
VISTAN  		Created by:		Conformed by:				
MEDINA  		CSR		 Customer (Signature over printed name)				

# Kolin Philippines Int'l., Inc.

1854 Sta. Rita St., Guadalupe Nuevo, Makati City  
 Tel. No.: 08852-6868 / Mobile: 0917-811-8982 / Email: service@kolinphil.com.ph  
 Website: www.kolinphil.com.ph      

## SERVICE JOB REPORT

No.  
 Previous SJR No.

HO-00190629  
 HO-00181617

Customer					Date	
Address	Dynamic Youth Office Room 412 Liberty Hall, 820 Benavidez St., Brgy. Binondo, MANILA CITY, Metro Manila				Start Time 03-07-2024 10:33 am	
Telephone No.			Mobile No.			Relayed by 10:34 am
Contact Person	8245-7085	Mobile No.		Tel. No. 0929-6722589/09957384720	Warranty Type	Engr. Kenneth Zamora
Warranty Code	Trixie 0929-6722589		Room Size			Job Class C LVL
Model			Call Origin			Job Type FAB 1
S/N (I)	KLG-SF40-WBR6H1M32	S/N (O)			Permit? <input type="checkbox"/> Parking? <input type="checkbox"/> Appointment? <input type="checkbox"/>	O.R.? <input type="checkbox"/> Ladder? <input type="checkbox"/>
Dealer			DOP	Notes X		
Installer	KMI		Complaint	12/13/2023 Lopez * 2 SAC for installation * ECY REFERRAL * COLLECTION C/O KMI		
Location			Before	After Others		
Mode Setting (Cool)	MULTI-PURPOSE AREA 2			No. of Visit		Tentative Sched
WAC   Setting Temp(16°C-RE)/(10/12-ME)				1st Action	Findings 03/08/2024	
SAC/PAC   Setting Temp (17°)				For fabrication of outdoor bracket		
Discharge Temperature (High)						
Intake Temperature (High)						
Ampere					Recommendation	
Wattage (Inverter)						
Voltage						
SAC/PAC   Pressure (PSI)						
Part Code	Description			Qty	Unit Price	Amount
SR No.					Labor	\$6,500.00
Repair Done	Fabricated bracket				Handling	
					Others	
Repair Code					Total	\$6,500.00
Date Attended	3-8-24	Date Finished	3-8-24	Amount Paid		
Time Attended	9:45 am	Time Finished	2:40 pm	Balance	\$6,500.00	
This serves as temporary receipt when properly filled up by authorized representative.				Check No.	Bank / Branch	For collection
Serviced by:		By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.				
LOPEZ Fernando Lopez Michael Vito Call:		I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.				
VISTAN MEDINA		Created by:		Conformed by:		
BERMEO Technician(s)		CSR		Customer (Signature over printed name)		