




No. **HO-00189815**
Previous SJR No. **HO-00183015**

Customer	The Gardens/AAA Gourmet Club Inc.				Date	02-29-2024		
Address	The Groove by Rockwell, E. Rodriguez Jr. Ave., Brgy. Ugong, PASIG CITY, Metro Manila...				Start Time	05:47 pm		
Telephone No.			Mobile No.	0917-6271227		End Time	05:53 pm	
Contact Person	Maam Bridgette	Mobile No.	0917-6271227	Tel. No.		Warranty Type	C	
Warranty Code				Room Size		Job Class	GC	LVL 1
Model	KSG-36C1T			Call Origin	SA	Job Type	FD	
S/N (I)	10491506-11133 (I)		S/N (O)	10501506-11145	Permit? <input type="checkbox"/> Parking? <input type="checkbox"/> Appointment? <input type="checkbox"/>	O.R.? <input type="checkbox"/> Ladder? <input type="checkbox"/>		
Dealer			DOP		Notes CUEVAS Noisy unit / fan motor shafting vibration and defective bushing For 2nd action for cleaning and for replacement of fan motor and rubber bushing Note: Bring fan motor with shafting and rubber bushing BRING ALL POSSIBLE PARTS WITH PERMIT			
Installer			Complaint	For GC				
Location	2	Before	After	Bring fan motor with shafting and rubber bushing BRING ALL POSSIBLE PARTS WITH PERMIT				
Mode Setting (Cool)				No. of Visit	2nd Action	Tentative Sched	03/05/2024	
WAC Setting Temp(16°C-RE)/(10/12-ME)	Findings							
SAC/PAC Setting Temp (17°)	NOISY AND DIRTY UNIT							
Discharge Temperature (High)								
Intake Temperature (High)								
Ampere	Recommendation							
Wattage (Inverter)	FOR 3RD ACTION							
Voltage	FOR REPAIR OF RUBBER BUSHING							
SAC/PAC Pressure (PSI)	AND FAN MOTOR							
Part Code	Description				Qty	Unit Price	Amount	
<i>PLATE-OUT UNIT</i>								
<i>NOISY. BRUISE. FAN MOTOR & RUBBER BUSHING</i>								
<i>PAYMENT UPON COMPLETION</i>								
<i>UNIT DISASSEMBLED</i>								
SR No.					Labor	2800-		
Repair Done	<i>EXTERNAL CLEANING ONLY</i>				Handling			
					Others			
Repair Code					Total	2800-		
Date Attended	3-5-24	Date Finished	3-5-24	Amount Paid				
Time Attended	10:50	Time Finished	12:30	Balance	2800-			
This serves as temporary receipt when properly filled up by authorized representative.				Check No.	Bank / Branch			
Serviced by: <i>Joselito Braes, Bayet Cuevas</i>		By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.						
<i>304/07</i>	<i>REY</i>	I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.						
<i>Albert</i>	<i>BNASOS</i>	Created by: RECHILLA CSR		Conformed by: <i>Ether</i> <i>Playlga 3-5-24</i>				
Technician(s)		Customer (Signature over printed name)						

No. HO-00190871
Previous SJR No. HO-00183015

Customer	The Gardens/AAA Gourmet Club Inc			Date	03-08-2024						
Address	The Groove by Rockwell, E. Rodriguez Jr. Ave., Brgy. Ugong, PASIG CITY, Metro Manila...			Start Time	03:12 pm						
Telephone No.			Mobile No.	0917-6271227		Relayed by	SHOP				
Contact Person	Maam Ethel	Mobile No.	Tel. No.			Warranty Type	C				
Warranty Code				Room Size			Job Class	DEL	LVL	1	
Model	KSG-36C11			Call Origin	ID		Job Type	FD			
S/N (I)	10491506-11133 (I)		S/N (O)	10501506-11145		Permit? <input type="checkbox"/> Parking? <input type="checkbox"/> Appointment? <input type="checkbox"/>	O.R.? <input type="checkbox"/> Ladder? <input type="checkbox"/>				
Dealer			DOP			Notes Balance Payment P1970.00 Bring OR					
Installer			Complaint	For Delivery Shop Repair							
Location	2	Before	After								
Mode Setting (Cool)				No. of Visit	1st Action	Tentative Sched		03/09/2024			
WAC Setting Temp(16°C-RE)/(10/12-ME)				Findings							
SAC/PAC Setting Temp (17°)											
Discharge Temperature (High)											
Intake Temperature (High)											
Ampere				Recommendation							
Wattage (Inverter)											
Voltage											
SAC/PAC Pressure (PSI)											
Part Code	Description				Qty	Unit Price	Amount				
	PLURBETR BUSHING				1	330-	330-				
1 UNIT PHASE-OUT UNIT / X10 PARTS AVAILABLE											
AC X1/ MAJOR 1/ REPAIR W/ SJR# 159815 4300-											
BALANCE W/ SJR # 190434 1970- - 											
PAID/NOT FOR COLLECTION C/O KM 											
New SJR# 190954 P/N# 08459 											
SR No.					Labor						
Repair Done	DELIVER AND INSPECT FAN properly				Handling						
	+ PLURBETR BUSHING				Others						
Repair Code					Total						
Date Attended	3-9-24	Date Finished	3-9-20	Amount Paid							
Time Attended	10:12	Time Finished	12:00	Balance							
This serves as temporary receipt when properly filled up by authorized representative.				Check No.	Bank / Branch						
Serviced by: Joselito Brasas, Bayet Cuevas		By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.									
Bayet		I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.									
Brafas		Created by: OSCAR F. BAGAT JR. CSR		Conformed by: Monty A. Perez							
Technician(s)		Customer (Signature over printed name)									