

2. General Cleaning (unit inspection, pressure washing, clean filter & drain)			
2.1 Single Indoor Unit (1 pair)	SAC02	1,500.00	900.00
2.2 Indoor unit or Outdoor unit	SAC03	750.00	n/a
2.3 Multi-Split (2 indoor units)	SAC04	2,000.00	1,200.00
2.4 w/ pump down	SAC05	2,500.00	n/a
2.5 GC + Minor repair	SAC06	2,100.00	1,300.00
2.6 GC + Major repair	SAC07	2,400.00	1,450.00
3. Minor Repair	SAC10	1,250.00	800.00
Minor adjustment/Replacement of filter net, louver, front panel, front case, capacitor, sensor, OLP, compressor wire, swing motor & display board			
4. Major Repair	SAC11	1,800.00	1,100.00
With parts replacement <b>not included</b> in minor repair			
Leak test, freon charge, repair drain			
5. Freon Charging (Flush out & recharge refrigerant)			
5.1 1.0 - 3.0hp (non-inverter & inverter)	SAC12	2,500.00	n/a
6. System Reprocessing			
System leak, compressor / evaporator / condenser replacement			
<b>Non-Inverter</b>			
6.1 1.0 - 2.0hp	SAC13	3,000.00	2,000.00
6.2 2.5 - 3.0hp	SAC14	3,000.00	2,000.00
6.3 System Reprocess + GC (1.0hp-3.0hp)	SAC08	3,750.00	n/a
<b>Inverter</b>			
6.4 1.0 - 2.0hp	SAC15	3,500.00	2,200.00
6.5 2.5 - 3.0hp	SAC16	3,500.00	2,200.00
6.6 System Reprocess + GC (1.0hp-3.0hp)	SAC09	4,250.00	n/a
7. Installation (includes 10ft. copper tube, control wires, breaker, ordinary bracket)			
7.1 Not covered by Promo	SAC17	7,000.00	n/a
7.2 Under Promo	SAC18	7,000.00	2,000.00
7.3 Mounting of IDU & ODU (will use materials of old unit)	SAC19	4,000.00	n/a
7.4 Dismantle & relocate IDU	SAC20	3,300.00	n/a
7.5 Dismantle & relocate ODU	SAC22	4,300.00	n/a

#### Floor Mounted Split Type

1. Check up (function & performance, visual check)	FAC01	600.00	400.00
2. General Cleaning (unit inspection, pressure washing, clean filter & drain)	FAC02	2,000.00	n/a
2.1 Indoor unit or Outdoor unit	FAC03	1,000.00	n/a
2.2 w/ pump down	FAC04	3,500.00	n/a
2.3 GC + Minor repair	FAC05	2,800.00	n/a
2.4 GC + Major repair	FAC06	3,200.00	n/a
3. Minor Repair	FAC09	1,500.00	1,000.00
Minor adjustment/Replacement of filter net, louver, front panel, front case, capacitor, sensor, OLP, compressor wire, swing motor & display board			
4. Major Repair	FAC10	2,300.00	1,300.00
With parts replacement <b>not included</b> in minor repair			
Leak test, freon charge, repair drain			
5. Freon Recharging (Flush out & recharge refrigerant)			
5.1 3.0 - 5.0 tonner (non-inverter & inverter)	FAC11	3,000.00	n/a
6. System Reprocessing			
System leak, compressor / evaporator / condenser replacement			