

LY SYCIP

38 TAMARIND ROAD, BRGY. SOUTH FORBES PARK, MAKATI CITY TEL#: 0917-8120433

Dear Ma'am/Sir,

Kolin Marketing Inc., is extremely honored for your endorsement of Kolin brand and we are please to offer you with a special price/s for the following items.

A. EQUIPMENT & INSTALLATION

QTY	U/M	I MODEL/DESCRIPTION I SRP I		DISCOUNTED		AMOUNT
1	UNIT/S	MODEL: KL-IF60-G6H1M32 KOLIN FLOOR MOUNTED AIRCONDITIONER 58,140 Kj/h (5.0TR) FULL DC INVERTER R32 SINGLE PHASE	165,995.00 112,156.20 PHP GLE PHASE		112,156.20	
TOTAL	TOTAL UNIT COST					112,156.20
ESTIMATED COST OF INSTALLATION (please see attached)					PHP	23,005.00
OTHERS: DELIVERY CHARGE					PHP	600.00
TOTAL	TOTAL ESTIMATED COST OF THE PROJECT					135,761.20

TERMS OF PAYMENT:

FULL PAYMENT OF UNIT AND DELIVERY CHARGE. IF CHECK, SUBJECT FOR 3 DAYS CLEARING.

WARRANTY:

FOR FLOOR MOUNTED (Inverter): ONE (1) YEAR FREE PARTS AND LABOR, FIVE (5) YEARS WARRANTY ON COMPRESSOR.

NOTES: PRICES ARE SUBJECT TO CHANGE WITHOUT PRIOR NOTICE.

PRICES IS VAT INCLUSIVE.

- ** Cost of Installation is Package with the Unit(s), this cost cannot avail separately (cost will be based on actual works).
- *** You may settle first payment for unit/s & delivery. Installation payment can be settled directly to installer after actual works.

We thank you for giving opportunity to offer our product and services, hoping we receive your purchase order.

If you need assistance, don't hesitate to call the under signed at 0917-807-8607 or email at kmi_asst@kolinphil.com.ph

Very Truly Yours,

JANELLEN S. MM KMI-ASSISTAN

Noted by:

MART MATHANIELR, FLORES

KMI-SUPERVISOR

KMI-QUOTE-08-25-0623 REG-24%/14K

MS. EDITHA M. FLORES

AVP - FINANCE

Conforme:

SIGNATURE OVER PRINTED NAME

Kolin Marketing, Inc.

1854 Sta. Rita St., Guadalupe Nuevo, Makati City Tel.: (632) 8852-6473

Fax: (632) 8852-2170 / (632) 8852-4792

www.kolinphil.com.ph / kolinphilippines





KOLIN Philippines International Inc. Survey Form

Nº 003678

Customer Name : 17 5701	<i>O</i> 41		Date	: 8-15	8-K-N	
Address: 38 TAWXIPID	ST: 15/100/ POPUE	Sts NALL.	SJR	No.: 7691	76	
Establishment Type : Residential	\angle	Area Surveyed	POPE	CAL ANTEN		
Commercial		Area Surveyed				
Recommended Product Model: 1	11-100 -00 HIM	131				
	Cooling Capacity Co	mputation				
Floor Area : sqm. Ceiling Height : sqm. mtr.	note: add 20% per m initial cooling ca	neter in excess of apacity computed		the		
Floor Area:	30	x	550 Btu/h	22,500	Btu/h	
Ceiling Height (excess of 3 mtrs.):	3.4	x	20%	5360	Btu/h	
Window Direct Sunlight		x	20% - 50%	2500.	Btu/h	
Total Cooling Capacity			\bigcirc	36,500	Btu/h	
Add : Additional Heat Load					Diam	
No. of Person	2-0	×	300 Btu/h	T 6000 3	Btu/h	
No. of Ordinary Light (<40w)	8	×	200 Btu/h	1600	Btu/h	
No. of Special Light (>40w)		×	400 Btu/h		Btu/h	
No. of Refrigerator (< 6 cu.ft.)	+	x	400 Btu/h		Btu/h	
No. of Refrigerator (> 6 cu.ft.)	1	×	800 Btu/h	806	Btu/h	
No. of Cooking Range		x /	1500 Btu/h	0	_ Btu/h	
No. of Laptop Computer		×	150 Btu/h		Btu/h	
No. of Desktop Computer		×	400 Btu/h		Btu/h	
No. of Printer		x	500 Btu/h		Btu/h	
No. of Photocopier		x	1000 Btu/h		Btu/h	
Total Cooling Capacity					Btu/h	
					Dtuni j	
Recommended Cooling Capacity					Btu/h	
Note : Compressor warranty will be reduce recommended cooling capacity or pi	ed to yr. if air-conc pe lay-out is beyond the	ditioner purchase maximum allow	d is lower the	an the		
	Scope of Work Ag	reement				
Copper tube lay-out	Expose	Embedded				
2. Chipping	Included	Not Included	ı			
3. Fabricated Bracket (Months)	Yes Shop	Site	No			
4. Service Ledge	Yes	No				
Dismantling of existing Aircon	Included	Not Included	I ~			
6. Ducting	Yes	No				
Dimension :						
7. Plastering, carpentry and restoration wor						
8. Wiring of electrical supply from main pan						
9. Processing of mechanical plan, working		are to be done b	y the custom	ner.		
10. Other concern;	W LAVOUR LAK	ACCEPT, 1	1-11-14F	15 1h		
THICH SX	CE ON EXIC	1110. 10	THAME	型		
ANT PENC	MIGHOL BEH	MANA I SA	TAY!	and:		
Obs him o	717					

						. 000010	, _
					 		-
 						 	
 	<u> </u>			ļļ			
FONE		. 6					
	山						
				<u> </u>		CL8	
4	N ACA						1
	1 1/5-1	W					-
				K			1
				 	1	 	
 	ļ -		-9.4	 -		 	
						<u> </u>	
 				 	 	 	
	<u> </u>						

Indoor Unit Location	:	CELL AL COUPE, EXME POCYLLOR
Outdoor Unit Location		XP THE TOXISTALL
Pipe Length	:	18h
Special Note	:	

Ins	stallation Cost Estimate			
Material Descript	Qty.	Unit Cost	Total Cost	
Copper Tube (excess of 10 ft.)	SET	400	12-00	
Wire (Royal Cord-signal wire) (excess of 10ft.)	2.0mmx4C	10FT	10-	1000
Wire (Royal Cord - Breaker to ODU)	3.5mm / 5.5mm x 3C	141-1	70	980
Circuit Breaker	20A, 30A, 40A/1ph, 40A/3ph		1000	1000
Bracket (ODU) Mobile	(Imptd. / Fabricated); (Floor / Wall)	1	100	MOU
Bracket (WAC)	Angle Type			
PVC Pipe (drain)	1/2" ,(3/4")	1	1/10	450
PVC Pipe (electrical)	3/4" , 1"			
Drain Pump	The Control of the Co			
Drain Pump Hose		7-17	1	4+(
Chipping Works	, mtr.			
Dismantling Fee (existing air-conditioner)	V~		14000	4000.
Initial Charge	* * * * * * * * * * * * * * * * * * * *		14000	
	P 23,0) c s · -		

Note:

- Initial Charge includes labor, 10ft. Copper tube, 10ft. Royal cord, Circuit breaker, Outdoor Bracket (SAC), Indoor Bracket (PAC) and Consumable materials.
- 2. Survey fee will be deducted in the installation fee.

Prepared by:

Signature Over Printed Name

Customer Conforme:

SEND TO CHOBNIEN Signature Over Printed Name