

TO : KOLIN AUTHORIZED SERVICE CENTERS
 FROM : KOLIN HEAD OFFICE
 SUBJECT : SAC INSTALLATION SUBSIDY & FLEX MATCH INSTALLATION COST
 DATE : OCTOBER 22, 2021
 REF. NO. : SVC-000-2021-0-046
 CC : DCO / BOO / SERVICE / SVC ACCTG / OP / KMI / SALES

Greetings!

Due to continuing increase of copper tube prices, KPII wants to extend support by increasing its installation subsidy for wall mount split type aircon.

Effective on November 01, 2021, the following shall be implemented:

SAC Capacity	Subsidy
1.0HP – 2.0HP	P3,000.00
2.5HP – 3.0HP	P3,500.00

We would like to also inform your office that we will be increasing the standard installation cost for Multi-Split Type Aircon (Flex Match Inverter)

Flex Match Inverter (1st pair)
 • Succeeding indoor unit

P 8,500.00
~~P 3,500.00 / unit~~
3,000

Inclusion:

10 ft. Copper tube (minimum thickness: 0.028")
 10 ft. Royal cord 2.0mm2 x 4C (communication wire)
 Labor
 Rubber insulation (insulation materials)
 Circuit breaker (weatherproof)
 Outdoor unit bracket
 Drain hose / PVC drain pipe
 Consumable materials like aertape, electrical tape, polyethylene tape, PVC elbow, PVC clamp, metal screw, log screw, etc.
 Vacuum and leak test of AC system
 Testing and commissioning

Additional charge to customer:

Copper tube in excess of 10 ft.
 1.0HP – 2.0HP P350.00 / ft.
 2.5HP – 3.0HP P400.00 / ft.
 Royal cord in excess of 10 ft. P 50.00 / ft.
 Electrical supply from main panel to ACCU breaker

Head Office:

1854 Sta. Rita St., Guadalupe Nuevo, Makati City
www.kolinphil.com.ph

Tel.: (632) 851-2711, 12 or 15

Fax: (632) 852-2170 / Sales Dept. Fax: (632) 852-4791

Kolin Plant:

Blk 3 Lt 5 Main Drive, FCIE Compound, Brgy,
 Langkaan I, Dasmariñas, Cavite

Tel.: (632) 749-2118

Fax: (046) 402-0793

