

ANNEX C

KOLIN PHILIPPINES INTERNATIONAL INC. TABLE OF STANDARD FEES AND CHARGES			
SERVICE JOBS	STANDARD FEE (OUT OF WARRANTY)	REBATES (REGULAR ASC)	REBATES (PREFERRED ASC)
Refrigerators/Chillers/Chest Freezers			
1. Check-up (function & performance, visual check)	450.00	350.00	350.00
2. Minor Repair (thermostat)	1,000.00	600.00	650.00
3. Major Repair (door gasket, fan motor, defrost heater & timer, thermodisk)	1,500.00	1,000.00	1,100.00
4. System Reprocess			
4.1 5cu. Ft. below	1,500.00	1,000.00	1,100.00
4.2 5cu. Ft. above	1,800.00	1,100.00	1,200.00
Window Type			
1. Check-up (function & performance,visual check)	450.00	350.00	350.00
2. General Cleaning (Unit inspection, Pressure washing, clean filter and drain)	800.00	470.00	470.00
Note: GC applicable only for units purchased until december 31, 2021			
2.1 GC + Minor Repair	1,250.00	740.00	750.00
2.2 GC + Major Repair	1,350.00	840.00	850.00
3. Minor Repair	900.00	540.00	570.00
Minor Adjustment/Replacement of filter net,louver,front panel front case,capacitor,sensor.OLP, comp.wire,swing motor & display board			
4. Major Repair	1,100.00	740.00	770.00
With parts replacement not included in minor repair			
Re-bearing of fan motor			
5. System Reprocessing			
System leak, compressor / evaporator/ condenser replacement			
5.1 0.6 - 1.5 hp	2,300.00	1,300.00	1,300.00
5.2 2.0 - 2.5 hp	2,300.00	1,300.00	1,300.00
5.3 System Reprocess + GC	2,600.00	N/A	N/A
6. Installation	1,000.00	N/A	N/A
Wall Mounted Split Type			
1. Check-up (function & performance,visual check)	450.00	350.00	350.00
2. General Cleaning (Unit inspection, pressure washing, clean filter & drain)			
Note: GC applicable only for units purchased until december 31, 2021			
2.1 Single Indoor Unit (1 pair)	1,500.00	900.00	900.00
2.2 Indoor unit or Outdoor unit	750.00	N/A	N/A
2.3 Multi-Split (2 indoor units)	2,000.00	1200.00	1,200.00
2.4 With pump down	2,500.00	N/A	N/A
2.5 GC + Minor Repair	2,100.00	1,300.00	1,350.00
2.6 GC + Major Repair	2,400.00	1,450.00	1,500.00
3. Minor Repair	1,250.00	800.00	900.00
Minor adjustment/Replacement of filter net,louver,front panel, front case,capacitor,sensor,OLP, comp. wire & swing motor & display board			
4. Major Repair	1,800.00	1,100.00	1,200.00
With parts replacement not included in minor repair			
Leak test, freon charge,repair drain			
5. Freon Recharging (Flush-out & recharge refrigerant)			
5.1 1.0 - 3.0hp (non-inverter & inverter)	2,500.00	N/A	N/A

ANNEX C

KOLIN PHILIPPINES INTERNATIONAL INC. TABLE OF STANDARD FEES AND CHARGES				
SERVICE JOBS		STANDARD FEE (OUT OF WARRANTY)	REBATES (REGULAR ASC)	REBATES (PREFERRED ASC)
6. System Reprocessing				
System Leak, compressor / evaporator / condenser replacement				
Non-Inverter				
6.1	1.0 - 2.0 hp	3,000.00	2,000.00	2,000.00
6.2	2.5 - 3.0 hp	3,000.00	2,000.00	2,000.00
6.3	System Reprocess + GC (1.0hp - 3.0hp)	3,750.00	N/A	N/A
Inverter				
6.4	1.0 - 2.0 hp	3,500.00	2,200.00	2,200.00
6.5	2.5 - 3.0 hp	3,500.00	2,200.00	2,200.00
6.6	System Reprocess + GC (1.0hp - 3.0hp)	4,250.00	N/A	N/A
7. Installation (includes 10ft. Copper tube, control wires, breaker, ordinary bracket, drain hose /PVC drain pipe 3/4, consumables, Flushing and Testing)				
7.1	1.0HP - 2.0HP	7,500.00	3,000.00	N/A
7.2	2.5HP - 3.0HP	8,500.00	3,500.00	N/A
7.3	Mounting of IDU & ODU (will use materials of old unit)	4,000.00	N/A	N/A
7.4	Dismantle & relocate IDU	3,300.00	N/A	N/A
Floor Mounted Split Type				
1.	Check-up (function & performance,visual check)	600.00	400.00	400.00
2.	General Cleaning (Unit inspection, pressure washing, clean filter & drain)	2,000.00	N/A	N/A
2.1	Indoor unit or Outdoor unit	1,000.00	N/A	N/A
2.2	With pump down	3,500.00	N/A	N/A
2.3	GC + Minor Repair	2,800.00	N/A	N/A
2.4	GC + Major Repair	3,200.00	N/A	N/A
3.	Minor Repair	1,500.00	1,000.00	1,100.00
Minor adjustment/Replacement of filter net,louver,front panel, front case,capacitor,sensor,OLP, comp. wire & swing motor & diplay board				
4.	Major Repair	2,300.00	1,300.00	1,400.00
With parts replacement not included in minor repair				
Leak test, freon recharge, repair drain				
5. Freon Recharging (Flush-out & recharge refrigerant				
5.1	3.0 - 5.0 tonner (non-inverter & inverter)	3,000.00	N/A	N/A
6. System Reprocessing				
System leak, compressor / evaporator /condenser replacement				
Non-Inverter				
6.1	3.0 tonner	3,500.00	2,200.00	2,200.00
6.2	5.0 tonner	3,500.00	2,200.00	2,200.00
6.3	System Reprocess + GC (1.0tr - 5.0tr)	4,500.00	N/A	N/A
Inverter				
6.4	3.0 tonner	4,000.00	2,400.00	2,400.00
6.5	4.5 - 5 tonner	4,000.00	2,400.00	2,400.00
6.6	System Reprocess + GC (3.0tr-5.0tr)	5,000.00	N/A	N/A
7. Installation (includes 10ft. Copper tube, control wires, rubber insulation, breaker, indoor bracket, drain hose / PVC drain pipe, consumables, Flushing and Testing)				
7.1	3.0 tonner	11,000.00	N/A	N/A
7.2	4.5 -5 tonner	14,000.00	N/A	N/A
7.3	Mounting of IDU & ODU (will use materials of old unit)	6,000.00	N/A	N/A
7.4	Dismantle & relocate IDU (2.5tr - 5.0tr)	4,500.00	N/A	N/A
7.5	Dismantle & relocate ODU (2.5tr - 3.0tr)	5,500.00	N/A	N/A
7.6	Dismantle & relocate ODU (4.5tr - 5.0tr)	6,000.00	N/A	N/A

KOLIN PHILIPPINES INTERNATIONAL INC. TABLE OF STANDARD FEES AND CHARGES			
SERVICE JOBS	STANDARD FEE (OUT OF WARRANTY)	REBATES (REGULAR ASC)	REBATES (PREFERRED ASC)
Floor Ceiling Split Type/Ceiling Cassette)			
1. Check-up (function & performance visual check)	600.00	400.00	400.00
2. General Cleaning (Unit inspection, pressure washing, clean filter & drain)	2,800.00	N/A	N/A
2.1 Indoor unit or Outdoor unit	1,400.00	N/A	N/A
2.2 With pump down	4,500.00	N/A	N/A
2.3 GC+ Minor Repair	3,700.00	N/A	N/A
2.4 GC + Major Repair	4,300.00	N/A	N/A
3. Minor Repair	1,800.00	1,100.00	1,200.00
Minor adjustment/Replacement of filter net, louver, front panel, front case,capacitor,sensor OLP,comp. wire & swing motor & display board			
4. Major Repair	3,000.00	1,700.00	1,800.00
With parts replacement not included in minor repair			
Leak test, freon charge, repair drain			
5. Freon Recharging (Flush-out & recharge refrigerant)			
5.1 2.5- 5.0 tonner (non-inverter & inverter)	3,000.00	N/A	N/A
6. System Reprocessing			
System leak, compressor /evaporator /condenser replacement			
Non-Inverter			
6.1 3.0 tonner	3,500.00	2,200.00	2,200.00
6.2 5 tonner	3,500.00	2,200.00	2,200.00
6.3 System Reprocess + GC	4,900.00	N/A	N/A
Inverter			
6.4 2.0 - 3.0 tonner	4,000.00	2,400.00	2,400.00
6.5 5 tonner	4,000.00	2,400.00	2,400.00
6.6 System Reprocess + GC	5,400.00	N/A	N/A
7. Installation (includes 10ft. Copper tube, control wires, rubber insulation, breaker, ordinary bracket, drain hose / PVC pipe, consumables, Flushing and Testing)			
7.1 2.5 tonner	12,000.00	N/A	N/A
7.2 3.0 tonner	12,000.00	N/A	N/A
7.3 4.0 -5.0 tonner	15,000.00	N/A	N/A
7.4 Mounting of IDU & ODU (will use materials of old unit)	7,000.00	N/A	N/A
7.5 Dismantle & relocate IDU (2.5tr - 5.0tr)	5,300.00	N/A	N/A
7.6 Dismantle & relocate ODU (2.5tr - 5.0tr)	6,000.00	N/A	N/A
7.7 Dismantle & relocate ODU (4.5tr - 5.0tr)	7,000.00	N/A	N/A
Flexmatch Inverter			
1. Check up (function & performance,visual check)	600.00	400.00	400.00
2. General Cleaning (Unit inspection, pressure washing, clean filter & drain)			
2.1 1st Pair	1,500.00	N/A	N/A
2.2 Succeeding Indoor Units	1,000.00	N/A	N/A
2.3 w/pump down	3,000.00	N/A	N/A
2.4 GC+ Minor Repair (1st pair)	2,200.00	N/A	N/A
2.5 GC + Major Repair (1st pair)	2,400.00	N/A	N/A
2.6 GC + Minor Repair (succeeding IDU)	1,600.00	N/A	N/A
2.7 GC + Major Repair (succeeding IDU)	1,900.00	N/A	N/A

ANNEX C

KOLIN PHILIPPINES INTERNATIONAL INC. TABLE OF STANDARD FEES AND CHARGES			
SERVICE JOBS	STANDARD FEE (OUT OF WARRANTY)	REBATES (REGULAR ASC)	REBATES (PREFERRED ASC)
3. Minor Repair	1,300.00	800.00	900.00
Minor adjusment/Replacement of filter net,louver,front panel, front case,capacitor,sensor,OLP,comp. wire & swing motor & display board			
4. Major Repair	1,800.00	1,100.00	1,200.00
With parts replacement not included in minor repair			
Leak test, freon charge,repair drain			
5. Freon Recharging (Flush-out & recharge refrigerant)	3,500.00	N/A	N/A
6. System Reprocessing			
System leak, compressor / evaporator / condenser replacement			
6.1 KFS-20DINV / KFS- 35DINV / KFS-20DAEM / KFS-30DAEM	4,000.00	N/A	N/A
6.2 KFS - 45DINV / KFS - 55DINV / KFS-40DAEM / KFS-50DAEM	4,500.00	N/A	N/A
6.3 System Reprocess + GC	5,250.00	N/A	N/A
7. Installation (includes 10ft copper tube, control wires, rubber insulation, breaker & ordinary bracket, drain hose/PVC pipe, consumables, Flushing and Testing)			
7.1 1st Pair	8,500.00	N/A	N/A
7.2 Succeeding Indoor Unit	3,000.00	N/A	N/A
7.3 Mounting of IDU & ODU (will use of old unit)	4,000.00	N/A	N/A
Air Curtain			
1. Check up (function & performance,visual check)	400.00	200.00	N/A
2. Repair / Replaced Parts	800.00	500.00	N/A
3. Installation	1,000.00	N/A	N/A
Small Appliance (Dehumidifier , Water Dispenser, Air Purifier, Heater)			
1. Check up (function & performance,visual check)	400.00	200.00	N/A
2. Repair / Replaced Parts	800.00	500.00	N/A
3. System Reprocess	1,500.00	N/A	N/A
LED TV			
1. Check up (function & performance,visual check)	400.00	200.00	N/A
2. Repair / Replaced Parts	1,000.00	500.00	N/A
Others			
1. Survey			
1.1 Split Type/Floor/Ceiling Mounted	500.00	N/A	N/A
2. Scaffolding Fee			
2.1 Mobilization	1,500.00	N/A	N/A
3. Start Up / Commisioning (per unit)			
3.1 Wall Mounted / Floor / Ceiling Type / Ceililng Cassette	2,500.00	N/A	N/A
3.2 Flex Match	3,000.00	N/A	N/A
4. Dismantling Fee			
4.1 1.0 - 3.0hp (wall mounted split type - 1pair)	2,500.00	N/A	N/A
4.2 2.5 -5.0 tr (floor mounted - 1 pair)	3,000.00	N/A	N/A
4.3 2.0 - 5.0 tr (floor ceiling / ceiling cassette - 1pair)	3,500.00	N/A	N/A
4.4 window type	500.00	N/A	N/A
5. Mobilization			
5.1 Pull-out and delivery			
5.1.1 within city limits	500.00	N/A	N/A
5.1.2 outside city limits (1-25kms)	700.00	N/A	N/A
5.1.3 outside city limits (25kms up)	800.00	N/A	N/A

KOLIN PHILIPPINES INTERNATIONAL INC. TABLE OF STANDARD FEES AND CHARGES			
SERVICE JOBS	STANDARD FEE (OUT OF WARRANTY)	REBATES (REGULAR ASC)	REBATES (PREFERRED ASC)
5.2 Field Servicing			
5.2.1 within city limits	N/A	N/A	N/A
5.2.2 outside city limits (1-25kms)	700.00	N/A	N/A
5.2.3 outside city limits (25kms up)	800.00	N/A	N/A
5.3 Delivery of Remote	150.00	N/A	N/A
6. Fabrication of Bracket			
6.1 Fabricated Bracket (IDU) - Ceiling Type	1,500.00	N/A	N/A
6.2 Fabricated Bracket (ODU) - Floor type	2,500.00	N/A	N/A
6.3 Fabricated Bracket (ODU) - Wall type	5,000.00	N/A	N/A
6.4 Fabricated Bracket (ODU) - Catwalk Type	6,500.00	N/A	N/A
6.5 Redesign Bracket (ODU)	1,500.00	N/A	N/A
7. Chipping works for copper pipe lilne / lay-out (per meter)	500.00	N/A	N/A
Guidelines			
1. Paid survey fee is deductible upon installation of unit.			
2. Paid check-up fee is deductible to succeeding repair;			
2.1 Succeeding occurs within three (3) months from check-up fee payment date			
2.2 Customer unit is for second (2nd) action of parts replacement			


Oliver M. Filoteo
Executive Vice President