

July 31, 2019

**HUTCHISON LOGISTICS INC.**

302C2 ECJ BLDG. REAL COR. ARZOBISPO ST. INTRAMUROS MANILA

Please be informed that the air-conditioner you intend to purchase is under capacity as compared to the following unit that we proposed:

Area	Kolin's Recommendation	Customer's Choice	Remarks
OFFICE	KLG-SF40-2C1M	KLG-SF70-4D3M	calculated 7.05hp
	2-UNITS	1-UNIT	under by 0.05hp

Since the unit of your choice is under capacity and also exceeding the maximum pipe length of 30m(99ft), it is probable that you may experience the following;

1. Capacity of the unit to cool the area will take longer or it will not cool the area at all that may lead to your dissatisfaction with the cooling performance of our unit.
2. Power consumption will be higher due to frequent running of compressor for not reaching the desired temperature within the normal parameter.
3. Useful life of compressor will be shortened due to excessive running beyond the normal run cycle.

Considering the above conditions, we regret to inform you that we cannot guarantee the efficient performance of unit. **Also, One (1) year warranty for parts One(Compressor- 1 year).**


For your guidance and information

Prepared by:



Jeffrey Dadios  
Field Surveyor

Noted by:



Engr. Noel Christopher Cortez  
Residential Project Engineer

Approved by:

For:  7/31

Mr. Ronaldo Ruiz  
National Service Manager

Customer Conforms:

\_\_\_\_\_  
Signature Over Printed Name

**Head Office:**

1854 Sta. Rita St., Guadalupe Nuevo, Makati City

[www.kolinphil.com.ph](http://www.kolinphil.com.ph)

Tel.: (632) 851-2711, 12 or 15

Fax: (632) 852-2170 / Sales Dept. Fax: (632) 852-4791

**Kolin Plant:**

Blk 3 Lt 5 Main Drive, FCIE Compound, Brgy,

Langkaan I, Dasmariñas, Cavite

Tel.: (632) 749-2118

Fax: (046) 402-0793

