

MAGELLAN COMMODITIES INC. ATTN: MS. BERYL ADOLFO Email: mcipaco.purchasing@gmail.com

Dear Ma'am/Sir,

Kolin Marketing Inc., is extremely honored for your endorsement of Kolin brand and we are please to offer you with a special price/s for the following items.

#### A. EQUIPMENT

\*\* OPTION 1 (RECOMMENDATION)

QTY	U/M	MODEL / DESCRIPTION	SRP	DISCOUNTED		AMOUNT
1	UNIT/S	MODEL: KSG-IWF-30WFY-8KIM32 KOLIN WALL MOUNTED PRIMUS GOLD AIRCONDITIONER 29,500 KJ/h (3.0HP) FULL DC INVERTER W/ WIFI R-32	10,000,00		РНР	52,744.10
TOTAL UNIT COST					PHP	52,744.10
ESTIMATED COST OF INSTALLATION (please see attached)					PHP	19,020.00
OTHERS: DELIVERY CHARGE				PHP	600.00	
TOTAL ESTIMATED COST OF THE PROJECT					PHP	72,364.10

\*\* OPTION 2 (CUSTOMER'S CHOICE)

QTY	U/M	MODEL / DESCRIPTION	SRP	DISCOUNTED		AMOUNT
1	MODEL: KSM-IW25-WCT10M1M32  UNIT/S  KOLIN WALL MOUNTED CERTUS AIRCONDITIONER  23,210 Kj/h (2.5HP) REGULAR INVERTER W/ WIFI R-32		49,995.00	34,996.10	РНР	34,996.10
TOTAL UNIT COST					PHP	34,996.10
ESTIMATED COST OF INSTALLATION (please see attached)					PHP	19,020.00
OTHERS: DELIVERY CHARGE					PHP	600.00
TOTAL ESTIMATED COST OF THE PROJECT					PHP	54,616.10

### TERMS OF PAYMENT:

FULL PAYMENT OF UNIT AND DELIVERY CHARGE. IF CHECK, SUBJECT FOR 3 DAYS CLEARING.

### WARRANTY:

FOR SPLIT TYPE: ONE (1) YEAR FREE PARTS AND LABOR, THREE YEARS (3) MAIN PCB, TEN (10) YEARS WARRANTY ON COMPRESSOR.

NOTES: PRICES ARE SUBJECT TO CHANGE WITHOUT PRIOR NOTICE.

PRICES IS VAT INCLUSIVE.

- \*\* Cost of Installation is Package with the Unit(s), this cost cannot avail separately.
- \*\* INSTALLATION C/O ASP (cost will be based on actual).

We thank you for giving opportunity to offer our product and services, hoping we receive your purchase order.

If you need assistance, don't hesitate to call the under signed at 0917-807-8607 or email at kmi\_asst@kolinphil.com.ph

Very Truly Yours,

JANELLEN S. NIM RMI-ASSISTANT

Noted by:

MART NATHANIEL R. FLORES KMI-SUPERVISOR

KMI-QUOTE-12-24-1016 REG-22%/7K/4K Approved By:

| A | 3 | W |

MS. EDITHA M. FLORES

AVP - FINANCE

Conforme:

SIGNATURE OVER PRINTED NAME

Kolin Marketing, Inc.

1854 Sta. Rita St., Guadalupe Nuevo, Makati City

Tel.: (632) 8852-6473

Fax: (632) 8852-2170 / (632) 8852-4792 www.kolinphil.com.ph / kolinphilippines







# **RKH Airconditioning Services**

Maintenance-Repair-Services-Installation #55 Star St. Brgy. Poblacion Mandaluyong City Tel. No.: 7914-52-49/09288987454/09169941262

Customer Name: Mayellan Commedi Tx	Date: 2. 9-2024				
Establisment Type: Residential	Area Surveyed :				
Commercial	Area Surveyed: OPTICE (ACCOUNTING)				
Recommended Product Model :					
Cooling	Capacity Computation				
Floor Area: 31.2 sqm.					
Ceiling Height:mtr.	10 10 4				
Floor Area: 31 · 23	x 550 Btu/h 17,176.5				
Ceiling Height (exces of 3 mtrs.)	x 20%				
Window Direct Sunlight 7, 176.	x 20%-50% 34xt. 3				
Total cooling Capacity	х				
Add: Additional Heat load	2008tu/h 1860				
*No. of Person	x 300Btd/11				
*No. of Ordinary light (<40w)					
*No. of Special light(>40)	x 400 Btu/h				
*No of Refrigerator	x 400 Btu/h				
*No. of Cooking Range	x 800 Btu/h x 150€ Btu/h				
*No. of Loptop Computer	x 1506 Btu/h				
No. of Desktop Computer	x 400 Btu/h				
*No. of T.V *No. of Printer	x 500 Btu/h				
*No. of Photocopier	x 1000 Btu/h				
Total Cooling Capacity	a l sho				
Recommended Cooling Capacity: 26,261	9 9000 = 511				
	yr. If air conditioner purchased is lower than the Recommended				
cooling capacity or pipe lay-out I beyond the maxin					
Scope of Work Agreement:					
*Copper tube lay-out Expose	Embedded				
*ChippingIncluded					
• Fabricated BracketYes	ShopSite _/_No				
*Service Ledge Yes					
*Dismantling Of Existing AirconIncluded					
*DuctingYes	No				
Dimension:					




## **RKH Airconditioning Services**

Maintenance-Repair-Services-Installation #55 Star St. Brgy. Poblacion Mandaluyong City Tel. No.: 7914-52-49/09288987454/09169941262

- \*Plastering, Carpentry and restoration works are to be done by the customer.
- \*Wiring of electrical supply from main panel to air-conditioning unit are to be done by the customer.
- \*Processing of mechanical plan, working permit, electrical permit are to be done by the customer.
- \*Other concern:

Plan Lay - outNO: 0007



Indoor Unit Location Outdoor Unit Location Pipe Length Special Note

tion	top of	MOOF	BELOW	M	MOON	

### INSTALLATION COST ESTIMATED:

**Total Cost** Unit Cost **Materials Description** Qty. \$400.00 \$6,800.00 \$100.00 \$2,300.00 Copper tube (% x 3/8, % x ½, % x 5/8,3/8 x 5/8,3/4 x 3/8,3/4 x ½) 17FT Wire (Royal Cord-signal wire) (Excess of 10ft.) 2.0mmx4C 23 PT Wire (Royal Cord- Breaker to ODU) 3.5mm / 5.5mm x 3C P70.00 \$ 420.00 \$ 1000.00 \$ 1000.00 bft Circuit Breaker 20A, 30A, 40A/1ph, 40A/3ph 1 PC Bracket(ODU) (Impt / Fabricated), (Floor/ Wall) Angel Type Bracket (WAC) 1/4", 1/4" PVC Pipe (Drain) 34",1" PVC Pipe (electrical) Drain Pump

Drain Pump Drain Pump Hose Chipping Worksmtr.

Dismantling Fee (existing airconditioner)

INITIAL CHARGE

TOTAL ESTIMATE: P 19,020,00

### Note;

Survey fee will be deducted in the Installation fee.