

December 9, 2024

STATE CENTER UNIT 1414, 333 JUAN LUNA ST., BINONDO MANILA TEL#: 0908-9526124

Dear Ma'am/Sir,

Kolin Marketing Inc., is extremely honored for your endorsement of Kolin brand and we are please to offer you with a special price/s for the following items.

A. EQUIPMENT & INSTALLATION

QTY	U/M	MODEL / DESCRIPTION	SRP	DISCOUNTED		AMOUNT
1	UNIT/S	MODEL: KSG-IWF-30WFY-8K1M32 KOLIN WALL MOUNTED PRIMUS GOLD AIRCONDITIONER 29,500 Kj/h (3.0HP) FULL DC INVERTER W/ WIFI R-32	76,595.00	52,744.10	РНР	52,744.10
TOTAL	TOTAL UNIT COST					
ESTIMATED COST OF INSTALLATION (please see attachments)						19,100.00
OTHERS: DELIVERY CHARGE					PHP	600.00
TOTAL ESTIMATED COST OF THE PROJECT						72,444.10

TERMS OF PAYMENT:

FULL PAYMENT OF UNIT AND DELIVERY CHARGE. IF CHECK, SUBJECT FOR 3 DAYS CLEARING.

WARRANTY:

FOR SPLIT TYPE: ONE (1) YEAR FREE PARTS AND LABOR, THREE YEARS (3) MAIN PCB, TEN (10) YEARS WARRANTY ON COMPRESSOR.

NOTES: *** Need to sign waiver agreement due to under capacity of unit choice.

PRICES ARE SUBJECT TO CHANGE WITHOUT PRIOR NOTICE.

PRICES IS VAT INCLUSIVE.

- * Cost of Installation is Package with the Unit(s), this cost cannot avail separately
- ** You may pay first for the unit costs, payment for installation to be paid after the actual works.
- *** Final overall installation cost will be based on actual.

We thank you for giving opportunity to offer our product and services, hoping we receive your purchase order.

If you need assistance, don't hesitate to call the under signed at 0917-807-8607 or email at kmi_asst@kolinphil.com.ph

Very Truly Yours,

JANELLEN'S, LIM

KMI-ASSISTANT

Noted by:

MART NATHANIEL R. FLORES

KMI-SUPERVISOR

KMI-QUOTE-12-24-1000 REG-22%/7K

MS. EDITHA M. FLORES

AVP -FINANCE

Conforme:

SIGNATURE OVER PRINTED NAME

Kolin Marketing, Inc.

1854 Sta. Rita St., Guadalupe Nuevo, Makati City Tel.: (632) 8852-6473

Fax: (632) 8852-2170 / (632) 8852-4792 www.kolinphil.com.ph / kolinphilippines



DECEMBER 05, 2024 STATE CENTER

State Center Bldg. Unit 1414, 333 Juan Luna St. Binondo, Manila

0908-9526124

MODEL

QUANTITY 1

19,100.00

KSG-IWF-30WFY-8K1M32

Revision 1 UNIT 1414

AREA 1						10	Area	~	35 sq.m
ACU	3.0hp Floor mounted Inverter	KSG-IWF-30WFY-8K1M32							
	Estimated Pipe Length	: 27	ft						
	Estimated Royal Cord Length	: 32	ft						
	Initial Charge							P	8,500.00
	Includes:								
	Labor								
	10ft Copper Tube								
	10ft Royal Cord								
	Outdoor Bracket								
	Other Consumable	S							
	Additional Charges	Description	Unit		Price Per Unit		Subtotal		
	Copper Tube	3/8"x 5/8"	17 ft	P	400.00 / ft	P	6,800.00		
	Royal Cord	2.mm2 x 4C	22 ft	P	100.00 / ft	P	2,200.00		
	Royal Cord (ODU-Breaker)	3.5mm2 x 3C	5 ft	P	60.00 / ft	P	300.00		
	Circuit Breaker(NEMA)	30A/ 1Ph	1 pc(s)	P	1,000.00 / pc	P	1,000.00		
	PVC (Drainline)	blue- 3/4"	2 pc(s)	P	150.00 / pc	P	300.00	P	10,600.00

Total Estimated Charges FCU 3.0HP WALLMOUNTED 3800 AREA 2 21.8 sqm AREA 1 35 sqm ROOM 2 3700 ROOM 1 13.3 sqm 7.7 sqm 4600 2100 3600

Validity: This quotation is valid for a period of fifteen (15) days from the date thereof, subject to our confirmation thereafter.

Note:

- 1 Location of indoor and outdoor units were agreed by the customer and Kolin's surveyor.
- 2 AC drain line will be tapped to the nearest drain provision provided by the customer's contractor.
- 3 Coppertube and drainline expose in the area.
- 4 Working days: Monday to Saturday, 8am-5pm without parking. Need working permit. 4 pax
- 5 Need waiver due to undercapacity.
- 6 Mechanical Plans, Permits, Electrical permits not included.
- 7 Deflectors, masonry, carpentry, chipping & plastering (finishing & restoration) are not included in the installation.
- 8 Electrical power supply (feeder line) 220v/60hz/1ph, is not included in the scope of work of Kolin.
- 9 Final charges will be based on actual installation.

Prepared by:	Customer Conformee:
Jeoffrey Dadios	
Field Surveyor	Signature Over Printed Name

Engr. Kenneth Jamora Service Supervisor Field and Shop Operation

Reviewed by

DECEMBER 05, 2024 STATE CENTER

State Center Bldg. Unit 1414, 333 Juan Luna St. Binondo, Manila 0908-9526124

Please be informed that the air-conditioner you intend to purchase is under capacity as compared to the following unit that we proposed:

Location	Area	Kolin's Recommendation	Customer's Choice	Remarks		
AREA 1- OFFICE	35 sqm	KLG-IF40-5G1M32	KSG-IWF-30WFY-8K1M32	Calculated 3.4hp, under by 0.4hp		

Since the unit of your choice is under capacity, it is probable that you may experience the following;

- 1. Capacity of the unit to cool the area will take longer or it will not cool the area at all that may lead to your dissatisfaction with the cooling performance of our unit.
- 2. Power consumption will be higher due to frequent running of compressor for not reaching the desired temperature within the normal parameter.
- 3. Useful life of compressor will be shortened due to excessive running beyond the normal run cycle.

Considering the above conditions, we regret to inform you that we cannot guarantee the efficient performance of unit. Also, One (1) year warranty for parts (compressor-10year).

For your guidance and information

Dec.6,2024

Prepared by:

Jeoffrey Dadios Surveyor

Approved by:

Mr. Alvin de Rivera

Service Manager

Noted by:

Engr. Kempeth Zamora Service Supervisor

Field and Shop Operation

Customer Conforme:

Signature Over Printed Name