

kolin

air conditioner

June 21, 2024

JAI BAUTISTA
9B ONE BEVERLY PLACE CONDO, #35 ANNAPOLIS ST., BRGY. GREENHILLS SAN JUAN
TEL#: 0917-8420712

Dear Ma'am/Sir,

Kolin Marketing Inc., is extremely honored for your endorsement of Kolin brand and we are please to offer you with a special price/s for the following items.

A. EQUIPMENT & INSTALLATION

QTY	U/M	MODEL / DESCRIPTION	SRP	DISCOUNTED PRICE		AMOUNT
1	UNIT/S	MODEL: KLM-IC40-AA1M32 KOLIN FLOOR/CEILING AIRCONDITIONER 37,980 Kj/h (3.0TR) DC INVERTER R-32	117,995.00	92,036.10 /	PHP	92,036.10
1	UNIT/S	MODEL: KSM-IW15-WCT10M1M32 KOLIN WALL MOUNTED CERTUS SERIES AIRCONDITIONER 12,660 Kj/h (1.5HP) REGULAR INVERTER R-32	32,495.00	21,346.10 /	PHP	21,346.10
TOTAL UNIT COST					PHP	113,382.20
ESTIMATED COST OF INSTALLATION (please see attached)					PHP	30,010.00
OTHERS: DELIVERY CHARGE					PHP	600.00
TOTAL ESTIMATED COST OF THE PROJECT					PHP	143,992.20

TERMS OF PAYMENT:

FULL PAYMENT OF UNIT AND DELIVERY CHARGE. IF CHECK, SUBJECT FOR 3 DAYS CLEARING.

WARRANTY:

FOR SPLIT TYPE : ONE (1) YEAR FREE PARTS AND LABOR, THREE YEARS (3) MAIN PCB , TEN (10) YEARS WARRANTY ON COMPRESSOR.
FOR FLOOR MOUNTED (Inverter): ONE (1) YEAR FREE PARTS AND LABOR, THREE (3) YEARS WARRANTY ON COMPRESSOR.

NOTES: PRICES ARE SUBJECT TO CHANGE WITHOUT PRIOR NOTICE.

PRICES IS VAT INCLUSIVE.

INSTALLATION C/O AUTHORIZED SERVICE CENTER.


**** Cost of Installation is Package with the Unit(s), this cost cannot avail separately.**

**** NO AVAILABLE STOCK FOR KSM-IW15-WCT10M1M32.**

We thank you for giving opportunity to offer our product and services, hoping we receive your purchase order.

If you need assistance, don't hesitate to call the under signed at 0917-807-8607 or email at kmi_asst@kolinphil.com.ph

Very Truly Yours,


JANELLEN S. LIM
KMI-ASSISTANT

Noted by;


MART NATHANIEL R. FLORES
KMI-SUPERVISOR

Approved By:


MS. EDITHA M. FLORES
AVP - FINANCE

Conforme:

SIGNATURE OVER PRINTED NAME

ANNIVERSARY
EST. 1996

KMI-QUOTE-06-24-0552
ECY-22%/4K

Kolin Marketing, Inc.

1854 Sta. Rita St., Guadalupe Nuevo, Makati City

www.kolinphil.com.ph

Tel.: (632) 8852-6473

Fax: (632) 8852-2170 / (632) 8852-4792

Bringing comfort to your home.

KOLIN Philippines International Inc.
Survey Form

No 003483

Customer Name: JSL B2-VISTA
Address: 13 ONE BEXLEY PLACE, CORPO, #35
Establishment Type: Residential ☒ Commercial ☐

Date: 6-10-24
SJR No.: 208890
Area Surveyed: LIVING / DINING
Area Surveyed: _____

Recommended Product Model: KLM-1C40-XX1M32

Cooling Capacity Computation

Floor Area: 41.3 sqm.
Ceiling Height: 2.9 mtr.

note: add 20% per meter in excess of 3 meters in the initial cooling capacity computed.

Floor Area:	<u>41.3</u>	x	550 Btu/h	<u>22715</u> Btu/h
Ceiling Height (excess of 3 mtrs.):	_____	x	20%	_____ Btu/h
Window Direct Sunlight	_____	x	20% - 50%	<u>4173</u> Btu/h
Total Cooling Capacity				<u>27758</u> Btu/h

Add : Additional Heat Load

No. of Person	<u>8</u>	x	300 Btu/h	<u>2400</u> Btu/h
No. of Ordinary Light (<40w)	<u>14</u>	x	200 Btu/h	<u>2800</u> Btu/h
No. of Special Light (>40w)	_____	x	400 Btu/h	_____ Btu/h
No. of Refrigerator (< 6 cu.ft.)	_____	x	400 Btu/h	_____ Btu/h
No. of Refrigerator (> 6 cu.ft.)	_____	x	800 Btu/h	_____ Btu/h
No. of Cooking Range	_____	x	1500 Btu/h	_____ Btu/h
No. of Laptop Computer	_____	x	150 Btu/h	_____ Btu/h
No. of Desktop Computer / TV	<u>1</u>	x	400 Btu/h	<u>400</u> Btu/h
No. of Printer	_____	x	500 Btu/h	_____ Btu/h
No. of Photocopier	_____	x	1000 Btu/h	_____ Btu/h
Total Cooling Capacity				<u>5600</u> Btu/h

Recommended Cooling Capacity

Note : Compressor warranty will be reduced to _____ yr. if air-conditioner purchased is lower than the recommended cooling capacity or pipe lay-out is beyond the maximum allowable length.


Scope of Work Agreement

- | | | |
|-----------------------------------|--|--|
| 1. Copper tube lay-out | ☒ Expose | ☐ Embedded |
| 2. Chipping | ☐ Included | ☐ Not Included |
| 3. Fabricated Bracket | ☐ Yes ☐ Shop | ☒ Site ☐ No |
| 4. Service Ledge | ☐ Yes | ☐ No |
| 5. Dismantling of existing Aircon | ☐ Included | ☐ Not Included |
| 6. Ducting | ☐ Yes | ☐ No |

Dimension : _____

- Plastering, carpentry and restoration works are to be done by the customer.
- Wiring of electrical supply from main panel to air-conditioning unit are to be done by the customer.
- Processing of mechanical plan, working permit, electrical permit are to be done by the customer.
- Other concern: CUSTOMER NEED TO PROVIDE POWER SUPPLY AT THE OUTSIDE BIKERAC.

WORKING DAY: MONDAY, JUNE 24, 2PM-5PM.
WITHOUT PARKING, NEED 4 PAX ON-SITE FABRICATION
WATER BIKERAC OUTSIDE UNIT CAN BE SEEN AT THE WINDOW.



Indoor Unit Location : CENTER OF SPACE LOWER OF WINDOW
 Outdoor Unit Location : AT THE BALCONY WEDGE, BACK
 Pipe Length : 10 FT / 3 METERS
 Special Note : _____

Installation Cost Estimate			
Material Description	Qty.	Unit Cost	Total Cost
Copper Tube (excess of 10 ft.) 2330, 2430, 2520, (3520) 4620			
Wire (Royal Cord-signal wire) (excess of 10ft.) 2.0mmx4C	1 FT	100	100
Wire (Royal Cord - Breaker to ODU) 3.5mm / 5.5mm x 3C	4 FT	120	480
Circuit Breaker 20A, 30A, 40A/1ph, 40A/3ph	1	1000	1000
Bracket (ODU) GALVANIZED (WAC) (Imptd. / Fabricated), (Floor / Wall)	1	1650	1650
Bracket (WAC) IMPROV. WALL FABRICATED Angle Type	1	1600	1600
PVC Pipe (drain) 1/2", 3/4"	1	150	150
PVC Pipe (electrical) 3/4", 1"			
Drain Pump			
Drain Pump Hose WHITE 10	1 FT	17	17
Chipping Works mtr.			
Dismantling Fee (existing air-conditioner)			
Initial Charge			12000
TOTAL ESTIMATE		P 17,665 =	

Note :

1. Initial Charge includes labor, 10ft. Copper tube, 10ft. Royal cord, Circuit breaker, Outdoor Bracket (SAC), Indoor Bracket (PAC) and Consumable materials.
2. Survey fee will be deducted in the installation fee.

Prepared by:

JEOPHANY D. JONES
 Signature Over Printed Name

Customer Conforms:

G. BASTIEN
 Signature Over Printed Name

KOLIN Philippines International Inc.
Survey Form

No 003484

Customer Name : JAL BONTISZ Date : 6-20-14
 Address : 913 ONE BEVERLY PLACE # 3C ANAPOLIS MD SJR No. : 208690
 Establishment Type : Residential ☒ Area Surveyed : 6459-1200m
 Commercial ☐ Area Surveyed : _____
 Recommended Product Model : KSM-1WN-WCH01m/m32

Cooling Capacity Computation

Floor Area : 13.4 sqm.
 Ceiling Height : 2.7 mtr.

note: add 20% per meter in excess of 3 meters in the initial cooling capacity computed.

Floor Area :	<u>13.4</u>	x	550 Btu/h	<u>7370</u> Btu/h
Ceiling Height (excess of 3 mtrs.) :		x	20%	
Window Direct Sunlight		x	20% - 50%	<u>1474</u> Btu/h
Total Cooling Capacity				<u>8844</u> Btu/h

Add : Additional Heat Load

No. of Person	<u>2</u>	x	300 Btu/h	<u>600</u> Btu/h
No. of Ordinary Light (<40w)	<u>10</u>	x	200 Btu/h	<u>2000</u> Btu/h
No. of Special Light (>40w)		x	400 Btu/h	
No. of Refrigerator (< 6 cu.ft.)		x	400 Btu/h	
No. of Refrigerator (> 6 cu.ft.)		x	800 Btu/h	
No. of Cooking Range		x	1500 Btu/h	
No. of Laptop Computer		x	150 Btu/h	
No. of Desktop Computer / TV	<u>4001</u>	x	400 Btu/h	<u>400</u> Btu/h
No. of Printer		x	500 Btu/h	
No. of Photocopier		x	1000 Btu/h	
Total Cooling Capacity				<u>3000</u> Btu/h

Recommended Cooling Capacity

11844 Btu/h

Note : Compressor warranty will be reduced to ____ yr. if air-conditioner purchased is lower than the recommended cooling capacity or pipe lay-out is beyond the maximum allowable length.

Scope of Work Agreement

- | | | |
|-----------------------------------|--|--|
| 1. Copper tube lay-out | ☒ Expose | ☐ Embedded |
| 2. Chipping | ☐ Included | ☐ Not Included |
| 3. Fabricated Bracket | ☐ Yes ☐ Shop | ☐ Site ☒ No |
| 4. Service Ledge | ☐ Yes | ☐ No |
| 5. Dismantling of existing Aircon | ☐ Included | ☒ Not Included |
| 6. Ducting | ☐ Yes | ☐ No |

Dimension :

- Plastering, carpentry and restoration works are to be done by the customer.
- Wiring of electrical supply from main panel to air-conditioning unit are to be done by the customer.
- Processing of mechanical plan, working permit, electrical permit are to be done by the customer.
- Other concern: CUSTOMER NEED TO PROVIDE POWER SUPPLY AT THE OUTDOOR UNIT AREA
EXPOSE CONDENSATE AT THE AREA

PLEASE SEE REFERENCE
SF. # 3483
(GUEST ROOM)

Indoor Unit Location :

Outdoor Unit Location :

Pipe Length :

Special Note :

RIGHT CORNER OF XH2

AT THE LODGE / RSL CONY

15 FT

Installation Cost Estimate

Material Description	Qty.	Unit Cost	Total Cost
Copper Tube (excess of 10 ft.)	2330, 2430, 2520, 3520, 4620	5 FT	350
Wire (Royal Cord-signal wire) (excess of 10ft.)	2.0mmx4C	14 FT	100
Wire (Royal Cord - Breaker to ODU)	3.5mm / 5.5mm x 3C	4 FT	60
Circuit Breaker	20A, 30A, 40A/1ph, 40A/3ph	1	1000
Bracket (ODU)	(Imptd) / Fabricated) : (Floor / Wall)		
Bracket (WAC)	Angle Type		
PVC Pipe (drain)	1/2" 3/4"	240	150
PVC Pipe (electrical)	3/4", 1"		
Drain Pump			
Drain Pump Hose	WHITE 1/2"	12 FT	120
Chipping Works	mtr.		
Dismantling Fee (existing air-conditioner)			400
Initial Charge			
TOTAL ESTIMATE			P 12,345

Note :

1. Initial Charge includes labor, 10ft. Copper tube, 10ft. Royal cord, Circuit breaker, Outdoor Bracket (SAC), Indoor Bracket (PAC) and Consumable materials.
2. Survey fee will be deducted in the installation fee.

Prepared by:

JEFFREY D. NIOS
Signature Over Printed Name

Customer Conforms:

G. BOUTIST
Signature Over Printed Name