



July 4, 2025

FILIPINO CHINESE CUISINE AND ECONOMIC ASSOCIATION, INC.
ATTN: MR. JAMES CO
5TH FLOOR, 820 LIBERTY HALL BUILDING BENAVIDEZ ST., BINONDO MANILA
TEL#: 0917-5667856

Dear Ma'am/Sir,

Kolin Marketing Inc., is extremely honored for your endorsement of Kolin brand and we are please to offer you with a special price/s for the following items.

A. EQUIPMENT & INSTALLATION

QTY	U/M	MODEL / DESCRIPTION	SRP	DISCOUNTED PRICE		AMOUNT
1	UNIT/S	MODEL: KL-IF60-G6H1M32 KOLIN FLOOR MOUNTED AIRCONDITIONER 58,140 Kj/h (5.0TR) FULL DC INVERTER R32 SINGLE PHASE	165,995.00	112,156.20	PHP	112,156.20
TOTAL UNIT COST					PHP	112,156.20
ESTIMATED COST OF INSTALLATION (please see attached)					PHP	21,990.00
OTHERS: DELIVERY CHARGE					PHP	600.00
TOTAL ESTIMATED COST OF THE PROJECT					PHP	134,746.20

TERMS OF PAYMENT:

FULL PAYMENT OF UNIT AND DELIVERY CHARGE. IF CHECK, SUBJECT FOR 3 DAYS CLEARING.

WARRANTY:

FOR FLOOR MOUNTED: ONE (1) YEAR FREE PARTS AND LABOR, FIVE (5) YEARS WARRANTY ON COMPRESSOR.

NOTES: PRICES ARE SUBJECT TO CHANGE WITHOUT PRIOR NOTICE.

PRICES IS VAT INCLUSIVE.

** *Cost of Installation is Package with the Unit(s), this cost cannot avail separately (cost will be based on actual).*

*** *You may settle first payment for unit/s & delivery. Installation payment can be settled directly to installer after actual works.*

We thank you for giving opportunity to offer our product and services, hoping we receive your purchase order.

If you need assistance, don't hesitate to call the under signed at 0917-807-8607 or email at kmi_asst@kolinphil.com.ph

Very Truly Yours,

JANELLEN S. LIM
KMI-ASSISTANT

Noted by:

MART NATHANIEL R. FLORES
KMI-SUPERVISOR

KMI-QUOTE-07-25-0523
ECY-24%/14K

Approved By:

MS. EDITHA M. FLORES
AVP - FINANCE

Conforme:

SIGNATURE OVER PRINTED NAME



JULY 04, 2025

James Co

5th Floor, 820 Liberty Hall Building Benavidez St. Binondo Manila

0917-5667856

kmt.phil@yahoo.com

MODEL	Qty
KL-IF60-G6H1M32	1

DANCING ROOM		Area	222 sqm
--------------	--	------	---------

ACU	6.0HP Floor Standing Inverter	KL-IF60-G6H1M32
-----	-------------------------------	-----------------

Estimated Pipe Length = 10 ft

Estimated Royal Cord Length = 17 ft

Initial Charge

Includes:

Labor

10ft Copper Tube


10ft Royal Cord

Indoor Bracket (Floor)

Consumables

Installation Materials	Description	Qty	Price per qty	Subtotal
Royal Cord (comm. wire)	2.mm2 x 4C	7 ft	₱ 100.00/ft	₱ 700.00
Royal Cord (ACCU-Breaker)	5.5mm x 3c	7 ft	₱ 70.00/ft	₱ 490.00
Circuit Breaker waterproof	40A / 1Ph	1 pc/s	₱ 1,000.00/pc	₱ 1,000.00
Outdoor bracket	Fabricated floor	1 pc/s	₱ 2,500.00/pc	₱ 2,500.00
Dismantle	4.0HP Floor Standing	1 set	₱ 3,000.00/set	₱ 3,000.00
PVC blue	3/4" x 10'	2 pc/s	₱ 150.00/pc	₱ 300.00
				<u>₱ 7,990.00</u>

Estimated Charges	₱ 21,990.00
-------------------	-------------



Total Estimated Charges

P 21,990.00

Validity: This quotation is valid for a period of fifteen (15) days from the date thereof, subject to our confirmation thereafter.


Installation notes:

- 1 Location of indoor and outdoor units were agreed by the customer and Kolin's surveyor.
- 2 AC drain line will be tapped to the nearest drain provision provided by the customer's contractor.
- 3 With existing of 2 unit of 5tr floor , 1unit of 3tr and 2 units of 2hp windowtype.
- 4 Customer need an installer with cutting and welding the window for the access of outdoor unit going outside location.**
- 5 Working days: Monday to Saturday, 8am- 5pm without parking.Need working permit.bring harness and rope.
- 6 Mechanical Plans, Permits, Electrical permits not included.
- 7 Deflectors, masonry, carpentry, chipping & plastering (finishing & restoration) are not included in the installation.
- 8 Air conditioning drain line and Electrical power supply (feeder line) **220v/ 60hz/ 1ph**, should be provided by customer's contractor.
- 9 Final charges will be based on actual installation.**

Prepared by:


Jeoffrey Dadios
Field Surveyor

Customer Conformee:


Signature Over Printed Name

Reviewed by:


Engr. Kenneth Zamora
Service Supervisor Shop and
Field Operation