

ATTY. DALTON LUCENARIO 88 APO ST., BRGY. LOURDES, QUEZON CITY

TEL#: 0920-9560805

Dear Ma'am/Sir,

Kolin Marketing Inc., is extremely honored for your endorsement of Kolin brand and we are please to offer you with a special price/s for the following items.

A. EQUIPMENT & INSTALLATION

QTY	U/M	MODEL / DESCRIPTION	SRP	DISCOUNTED		AMOUNT
		MODEL: KLG-IF40-5G1M32				
1 1	UNIT/S	KOLIN FLOOR MOUNTED AIRCONDITIONER	113,195.00	79,028.20	PHP	79,028.20
_		37,980 Kj/h (3.0TR) FULL DC INVERTER R-32 SINGLE PHASE				
		MODEL: KSG-IWF-30WFY-8K1M32				
1	UNIT/S	KOLIN WALL MOUNTED PRIMUS GOLD AIRCONDITIONER	76,595.00	51,212.20	PHP	51,212.20
		29,500 Kj/h (3.0HP) FULL DC INVERTER W/ WIFI R-32				
		MODEL: KSM-IW25-WCT10M1M32				
2	UNIT/S	KOLIN WALL MOUNTED CERTUS AIRCONDITIONER	49,995.00	33,996.20	PHP	67,992.40
		23,210 Kj/h (2.5HP) REGULAR INVERTER W/ WIFI R-32				
		MODEL: KSM-IW20-WCT10M1M32				
1	UNIT/S	KOLIN WALL MOUNTED CERTUS SERIES AIRCONDITIONER	41,995.00	27,916.20	PHP	27,916.20
		18,990 Kj/h (2.0HP) REGULAR INVERTER R-32				
		MODEL: KSM-IW15-WCT10M1M32				
1	UNIT/S	KOLIN WALL MOUNTED CERTUS SERIES AIRCONDITIONER	32,995.00	21,076.20	PHP	21,076.20
		12,660 Kj/h (1.5HP) REGULAR INVERTER R-32	250,000,000,000,000	11000 *********************************		12.71.2.40.51.7.24.51.7.2
TOTAL UNIT COST						247,225.20
ESTIMATED COST OF INSTALLATION (please see attached)					PHP	80,190.00
TOTAL	ESTIMATED	COST OF THE PROJECT			PHP	327,415.20

TERMS OF PAYMENT:

FULL PAYMENT OF UNIT AND DELIVERY CHARGE. IF CHECK, SUBJECT FOR 3 DAYS CLEARING.

WARRANTY:

FOR FLOOR MOUNTED: ONE (1) YEAR FREE PARTS AND LABOR, FIVE (5) YEARS WARRANTY ON COMPRESSOR. FOR SPLIT TYPE: ONE (1) YEAR FREE PARTS AND LABOR, THREE YEARS (3) MAIN PCB, TEN (10) YEARS WARRANTY ON COMPRESSOR.

NOTES: PRICES ARE SUBJECT TO CHANGE WITHOUT PRIOR NOTICE.

PRICES IS VAT INCLUSIVE.

** Cost of Installation is Package with the Unit(s), this cost cannot avail separately (cost will be based on actual).

We thank you for giving opportunity to offer our product and services, hoping we receive your purchase order.

If you need assistance, don't hesitate to call the under signed at 0917-807-8607 or email at kmi_asst@kolinphil.com.ph

Very Truly Yours,

JANELLEN S. HM KML-ASSISTANT

Noted by:

MART NATHANIEL R. FLORES KMI-SUPERVISOR

KMI-QUOTE-02-25-0107 ECY-24%/7K/4K

Approved By:

MS. EDITHA M. FL AVP - FINANCE

Conforme:

SIGNATURE OVER PRINTED NAME

Kolin Marketing, Inc.

1854 Sta. Rita St., Guadalupe Nuevo, Makati City

Tel.: (632) 8852-6473

Fax: (632) 8852-2170 / (632) 8852-4792 www.kolinphil.com.ph / kolinphilippines





FEBRUARY 12, 2025

Atty. Dalton Lucenario

88 Apo St. Brgy Lourdes, Quezon City

0917-5604389


Model	Qty
KLG-IF40-5G1M32	1
KSG-IWF-30WFY-8K1M32	1
KSM-IW25-WCT10M1M32	2
KSM- IW20-WCT10M1M32	1
KSM- IW15-WCT10M1M32	1

2ND FLOOR

	REA/ HALLWAY						Area ≈	79 sq.m
ACU 1	3.0hp Wallmounted Inverter	KSG-IWF-30WFY-8K1M32						
	Estimated Pipe Length	: 17	ft					
	Estimated Royal Cord Length	: 22	ft					
	Initial Charge						P	7,700.00
	Includes:							less outdoo
	Labor							Bracket
	10ft Copper Tube							inclusion
	10ft Royal Cord							
	Other Consumable	es						
	Additional Charges	Description	Unit		Price Per Unit		Subtotal	
	Copper Tube	3/8"x 5/8"	7 ft	P	350.00 / ft	P	2,450.00	
	Royal Cord	2.mm2 x 4C	12 ft	P	100.00 / ft	P	1,200.00	
	Royal Cord (ODU-Breaker)	3.5mm2 x 3C	5 ft	P	60.00 / ft	P	300.00	
	PVC (Drainline)	blue- 3/4"	1 pc	P	150.00 / pc	P	150.00	
	Drain Hose	White -1/2"	5 ft	Р	25.00 / ft	Р	125.00 P	4,225.00
	Estimated Charges						P	11,925.00
J 2	4.0hp Wallmounted Inverter KLG-IF40-5G1M32							
	Estimated Pipe Length	: 27	ft					
	Estimated Royal Cord Length	: 32	ft					
	Initial Charge						Р	11,000.00
	Includes:							
	Labor							
	10ft Copper Tube							
	10ft Royal Cord							
	Indoor Bracket							
	Other Consumables							
	Additional Charges	Description	Unit		Price Per Unit		Subtotal	
	Copper Tube	3/8"x 5/8"	17 ft	P	400.00 / ft	P	6,800.00	
	Royal Cord	2.mm2 x 4C	22 ft	P	100.00 / ft	P	2,200.00	
	Royal Cord (ODU-Breaker)	5.0mm2 x 3C	5 ft	P	70.00 / ft	P	350.00	
	PVC (Drainline)	blue- 3/4"	1 pc	P	150.00 / pc	P	150.00	
	Drain Hose	White -1/2"	5 ft	P	25.00 / ft	P	125.00 P	9,625.00

	E MARKETING OFFICE						Area ≈ 18.5 sq.m
U 3	2.5hp Wallmounted Inverter		KSM- IW2	5-WC	T10M1M32		
	Estimated Pipe Length	17	ft				
	Estimated Royal Cord Length	: 22	ft				
	Initial Charge						P 7,700.00
	Includes:						less outdoo
	Labor						Bracket
	10ft Copper Tube						inclusion
	10ft Royal Cord						m.mann
	Other Consumable	s					
	Additional Charges	Description	Unit		Price Per Unit		Subtotal
	Copper Tube	1/4"x 5/8"	7 ft	Р	400.00 / ft	Р	2,800.00
	Royal Cord	2.mm2 x 4C	12 ft	Р	100.00 / ft	P	1,200.00
	Royal Cord (ODU-Breaker)	3.5mm2 x 3C		P		P	300.00
	PVC (Drainline)			P	60.00 / ft		
	Drain Hose	blue- 3/4"	1 pc	0	150.00 / pc	Р	150.00
	Drain nose	White -1/2"	5 ft	P	25.00 / ft	Р	125.00 P 4,575.00
	Estimated Charges						P 12,275.00
O'S RO			UCBA DAVA	5 14/6	7401441400		Area ≈ 16.3 sq.m
.04	1.5hp Wallmounted Inverter Estimated Pipe Length	17		3-WC	T10M1M32		
		17	ft				
	Estimated Royal Cord Length	: 22	ft				
	Initial Charge						P 6,700.00
	Includes:						less outdoo
	Labor						Bracket
	10ft Copper Tube						inclusion
	10ft Royal Cord						
	Other Consumable	S					
	Additional Charges	Description	Unit		Price Per Unit		Subtotal
	Copper Tube	1/4"x 1/2"	7 ft	P	350.00 / ft	P	2,450.00
	Royal Cord	2.mm2 x 4C	12 ft	P	100.00 / ft	P	1,200.00
	Royal Cord (ODU-Breaker)	3.5mm2 x 3C	5 ft	P	60.00 / ft	P	300.00
	PVC (Drainline)	blue- 3/4"	1 pc	P	150.00 / pc	P	150.00
	Drain Hose	White -1/2"	5 ft	P	25.00 / ft	P	125.00 P 4,225.00
	Estimated Charges						P 10,925.00
							A 20
CU 5	2.5hp Wallmounted Inverter		VCBA IIA/2	E M/C	T10M1M32		Area ≈ 20 sq.m
.03	Estimated Pipe Length	17	ft	3-000	LIGINITIVISE		
	Estimated Pipe Length Estimated Royal Cord Length		ft				
		. 22	10				P 7,700.00
	Initial Charge						less outdoo
	Includes:						
	Labor						Bracket
	10ft Copper Tube						inclusion
	10ft Royal Cord						
	Other Consumable						
	Additional Charges	Description	Unit		Price Per Unit		Subtotal
	Copper Tube	1/4"x 3/8"	7 ft	Р	350.00 / ft	P	2,450.00
	Royal Cord	2.mm2 x 4C	12 ft	P	100.00 / ft	P	1,200.00
	Royal Cord (ODU-Breaker)	3.5mm2 x 3C	14 ft	Р	60.00 / ft	P	840.00
		blue- 3/4"	1 pc	P	150.00 / pc	P	150.00
	PVC (Drainline)	DIUC 3/ T					
	PVC (Drainline) Drain Hose	White -1/2"	7 ft	Р	25.00 / ft	P	175.00 P 4,815.00

BOARD ROOM Area ≈ 20 sq.m ACU 5 2.5hp Wallmounted Inverter KSM- IW25-WCT10M1M32 Estimated Pipe Length 17 ft Estimated Royal Cord Length: 22 ft Initial Charge 7,700.00 Includes: less outdoor Labor Bracket 10ft Copper Tube inclusion 10ft Royal Cord Other Consumables **Additional Charges** Description Unit Price Per Unit Subtotal Copper Tube 1/4"x 3/8" 7 ft 350.00 / ft 2,450.00 Royal Cord 2.mm2 x 4C 100.00 / ft 12 ft P P 1,200.00 Royal Cord (ODU-Breaker) 3.5mm2 x 3C 5 ft P 60.00 / ft P 300.00 PVC (Drainline) blue- 3/4" P 150.00 / pc 1 pc P 150.00 Drain Hose White -1/2" 5 ft P 25.00 / ft P 125.00 P 4,225.00 **Estimated Charges** 11,925.00



Validity: This quotation is valid for a period of fifteen (15) days from the date thereof, subject to our confirmation thereafter.

Note:

- 1. Location of indoor and outdoor units were agreed by the customer and Kolin's surveyor.
- 2. AC drain line will be tapped to the nearest drain provision provided by the customer's contractor.
- 3. Need for marking and site visit before installation.
- 4. Customer will provide a fabricated outdoor bracket and breaker, PVC 3 Inches for the hole in the roof, sealed after installation.
- 5. Customer also provide an access for future maintenance. Will open the roof for outdoor.
- 6. Working days: Monday to Saturday, 8am 5pm with parking.4 pax bring harness and rope.
- 7. Mechanical Plans, Permits, Electrical permits not included.
- 8. Deflectors, masonry, carpentry, chipping & plastering (finishing & restoration) are not included in the installation.
- 9. Electrical power supply (feeder line) 220v/60hz/1ph, is not included in the scope of work of Kolin.
- 10. Final charges will be based on actual installation.

Prepared by:	Customer Conformee:		
Jeoffrey Dadios			
Field Surveyor	Signature Over Printed Name		
in the same of the	3		

Service Supervisor Field and Shop Operation