



February 26, 2026

JOYCE APARTELLE - KALENTONG  
NO. 1 ROMUALDEZ ST., COR. GENERAL KALENTONG, MANDALUYONG CITY  
TEL#: 0928-7412093

Dear Ma'am/Sir,

Kolin Marketing Inc., is extremely honored for your endorsement of Kolin brand and we are please to offer you with a special price/s for the following items.

A. EQUIPMENT & INSTALLATION

QTY	U/M	MODEL / DESCRIPTION	SRP	DISCOUNTED PRICE		AMOUNT
1	UNIT/S	MODEL: KS-IW25-MCAI1201M32 KOLIN WALL MOUNTED CERTUS A/ SERIES AIRCONDITIONER 23,800 Kj/h (2.5HP) FULL DC INVERTER W/ WIFI R-32	50,995.00	31,756.20	PHP	31,756.20
TOTAL UNIT COST					PHP	31,756.20
ESTIMATED COST OF INSTALLATION (please see attached)					PHP	15,875.00
TOTAL ESTIMATED COST OF THE PROJECT					PHP	47,631.20

TERMS OF PAYMENT:

FULL PAYMENT OF UNIT AND DELIVERY CHARGE. IF CHECK, SUBJECT FOR 3 DAYS CLEARING.

BANK DETAILS:

- \* Unit/s & Delivery: Account Name - KOLIN MARKETING INC. / Account# - 011808002307 (BDO-KALAYAAN)
- \* Installation: Will be provided by assigned installer.
- \*\* *You may settle first payment for unit/s & delivery. Installation payment can be settled directly to installer after actual works.*

WARRANTY:

FOR SPLIT TYPE : ONE (1) YEAR FREE PARTS AND LABOR, THREE YEARS (3) MAIN PCB , TEN (10) YEARS WARRANTY ON COMPRESSOR.

NOTES: PRICES ARE SUBJECT TO CHANGE WITHOUT PRIOR NOTICE.

PRICES IS VAT INCLUSIVE.


\*\* *Cost of Installation is Package with the Unit(s), this cost cannot avail separately (cost will be based on actual works).*

We thank you for giving opportunity to offer our product and services, hoping we receive your purchase order.


If you need assistance, don't hesitate to call the under signed at 0917-807-8607 or email at [kmi\\_asst@kolinphil.com.ph](mailto:kmi_asst@kolinphil.com.ph)

Please be informed that there will be price increase starting March 1, 2026. Kindly inquire for updated price before placing purchase order.


Very Truly Yours,

  
JANELLEN S. LIM  
KMI-ASSISTANT

Noted By:

  
MARTYNHANJEL R. FLORES  
KMI-SUPERVISOR

Approved By:

  
MS. EDITHA M. FLORES  
AVP - FINANCE

Conforme:


\_\_\_\_\_  
SIGNATURE OVER PRINTED NAME

KMI-QUOTE-02-26-0094  
REG-24%/6.5K



Kolin Marketing, Inc.  
1854 Sta. Rita St., Guadalupe Nuevo, Makati City  
Tel.: (632) 8852-6473  
Fax: (632) 8852-2170 / (632) 8852-4792  
[www.kolinphil.com.ph](http://www.kolinphil.com.ph) / [kolinphilippines.com](http://kolinphilippines.com)





Indoor Unit Location : RIGHT SIDE, FRONT OF LOBBY DECK, SAME LOCATION  
 Outdoor Unit Location : IN FRONT OF PARKING AREA, SAME LOCATION  
 Pipe Length : 20 FT  
 Special Note : \_\_\_\_\_

Installation Cost Estimate			
Material Description	Qty.	Unit Cost	Total Cost
Copper Tube (excess of 10 ft.)	2330, 2430, 2520, 3520, 4620	10 FT	4000
Wire (Royal Cord-signal wire) (excess of 10ft.)	2.0mmx4C	15 FT	1500
Wire (Royal Cord - Breaker to ODU)	3.5mm / 5.5mm x 3C	5 FT	
Circuit Breaker	20A, 30A, 40A/1ph, 40A/3ph		
Bracket (ODU)	(Imptd. / Fabricated) ; (Floor / Wall)		
Bracket (WAC)	Angle Type		
PVC Pipe (drain)	1/2", 3/4"		
PVC Pipe (electrical)	3/4", 1"		
Drain Pump			
Drain Pump Hose	WHITE 1/2"	7 FT	175
Chipping Works	mtr.	13	
Dismantling Fee (existing air-conditioner)	2.5 H	200	200
Initial Charge	BRACKET (250-300)		2200
<b>TOTAL ESTIMATE</b>		<b>P</b>	<b>15,875-</b>

- Note :
- Initial Charge includes labor, 10ft. Copper tube, 10ft. Royal cord, Outdoor Bracket (SAC), Indoor Bracket (PAC) and Consumable materials.
  - Survey fee will be deducted in the installation fee.

Prepared by:  
 Signature Over Printed Name

REVIEWED BY:  
  
 02/24/2026  
 ENGR. ADRIAN MOGOY  
 PROJECT ENGINEER-KPII

Customer Conforme:  
  
 Signature Over Printed Name