



January 26, 2026

G.A. HOLDINGS, INC.
MS. GLORIA AGUIRRE
335 SAN BARTOLOME, BRGY. AYALA ALABANG, MUNTINLUPA CITY
TEL#: 0920-9098829

Dear Ma'am/Sir,

Kolin Marketing Inc., is extremely honored for your endorsement of Kolin brand and we are please to offer you with a special price/s for the following items.

A. EQUIPMENT & INSTALLATION

QTY	U/M	MODEL / DESCRIPTION	SRP	DISCOUNTED PRICE		AMOUNT
1	UNIT/S	MODEL: KL-IF60-G6HM32 KOLIN FLOOR MOUNTED AIRCONDITIONER 58,140 Kj/h (5.0TR) FULL DC INVERTER R32 SINGLE PHASE	165,995.00	112,156.20	PHP	112,156.20
TOTAL UNIT COST						PHP 112,156.20
ESTIMATED COST OF INSTALLATION (please see attached)						PHP 22,225.00
OTHERS: DELIVERY CHARGE						PHP 600.00
TOTAL ESTIMATED COST OF THE PROJECT						PHP 134,981.20

TERMS OF PAYMENT:

FULL PAYMENT OF UNIT AND DELIVERY CHARGE. IF CHECK, SUBJECT FOR 3 DAYS CLEARING.

BANK DETAILS:

* Unit/s & Delivery: Account Name - KOLIN MARKETING INC. / Account# - 011808002307 (BDO-KALAYAAN)

* Installation: Will be provided by assigned installer.

** You may settle first payment for unit/s & delivery. Installation payment can be settled directly to installer after actual works.

WARRANTY:

FOR FLOOR MOUNTED (Inverter): ONE (1) YEAR FREE PARTS AND LABOR, FIVE (5) YEARS WARRANTY ON COMPRESSOR.

NOTES: PRICES ARE SUBJECT TO CHANGE WITHOUT PRIOR NOTICE.

PRICES IS VAT INCLUSIVE.

** Cost of Installation is Package with the Unit(s), this cost cannot avail separately (cost will be based on actual works).

We thank you for giving opportunity to offer our product and services, hoping we receive your purchase order.

If you need assistance, don't hesitate to call the under signed at 0917-807-8607 or email at kmi_asst@kolinphil.com.ph

Very Truly Yours,

JANELLEN S. LIM
KMI-ASSISTANT


Noted by:
MARY-NATHANIEL R. FLORES
KMI-SUPERVISOR

Approved By:
MS. EDITHA M. FLORES
AVP - FINANCE

Conforme:

SIGNATURE OVER PRINTED NAME

KMI-QUOTE-01-26-0044
REG-24%/14K



KOLIN Philippines International Inc.
Survey Form

No. 003719

Customer Name: GLORIA X GINNE / G.A. HOLDINGS, INC. Date: 1-12-16
Address: 335 SLEX 3RD FLOOR BLDG. BAYAN MUNICIPAL SJR No.: 787390

Establishment Type: Residential
 Commercial

Area Surveyed: LIVING X Ws
Area Surveyed:

Recommended Product Model: KL-1T60-G6HVM32

Cooling Capacity Computation

Floor Area: 50 sqm.
Ceiling Height: 5.8 mtr.

note: add 20% per meter in excess of 3 meters in the initial cooling capacity computed.

Floor Area:	<u>50</u>	x	550 Btu/h	<u>30,000</u> Btu/h
Ceiling Height (excess of 3 mtrs.):	<u>5.8</u>	x	20%	<u>6,160</u> Btu/h 17248
Window Direct Sunlight		x	20% - 50%	<u>6,160</u> Btu/h
Total Cooling Capacity				<u>43,120</u> Btu/h 54208

Add : Additional Heat Load

No. of Person	<u>10</u>	x	300 Btu/h	<u>3000</u> Btu/h
No. of Ordinary Light (<40w)	<u>15</u>	x	200 Btu/h	<u>3000</u> Btu/h
No. of Special Light (>40w)		x	400 Btu/h	<u>0</u> Btu/h
No. of Refrigerator (< 6 cu.ft.)		x	400 Btu/h	<u>0</u> Btu/h
No. of Refrigerator (> 6 cu.ft.)		x	800 Btu/h	<u>0</u> Btu/h
No. of Cooking Range <u>1</u>	<u>1</u>	x	1500 Btu/h	<u>1500</u> Btu/h
No. of Laptop Computer		x	150 Btu/h	<u>0</u> Btu/h
No. of Desktop Computer <u>1</u>	<u>1</u>	x	400 Btu/h	<u>400</u> Btu/h
No. of Printer		x	500 Btu/h	<u>0</u> Btu/h
No. of Photocopier		x	1000 Btu/h	<u>0</u> Btu/h
Total Cooling Capacity				<u>7100</u> Btu/h 5.6

Recommended Cooling Capacity

37,020 Btu/h

6.9


Note : Compressor warranty will be reduced to yr. if air-conditioner purchased is lower than the recommended cooling capacity or pipe lay-out is beyond the maximum allowable length.

Scope of Work Agreement

1. Copper tube lay-out	<input checked="" type="checkbox"/> Expose	<input type="checkbox"/> Embedded
2. Chipping	<input type="checkbox"/> Included	<input checked="" type="checkbox"/> Not Included
3. Fabricated Bracket	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> Shop
4. Service Ledge	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
5. Dismantling of existing Aircon	<input checked="" type="checkbox"/> Included	<input type="checkbox"/> Not Included
6. Ducting	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No

Dimension : _____

7. Plastering, carpentry and restoration works are to be done by the customer.
8. Wiring of electrical supply from main panel to air-conditioning unit are to be done by the customer.
9. Processing of mechanical plan, working permit, electrical permit are to be done by the customer.
10. Other concern; DEMOLISH X TO REPLACE COPPER TUBE
COMMUNICATION WIRE, BRACKET X TO BRACKET



Indoor Unit Location : LEFT CUPBOARD, SAME LOCATION

Outdoor Unit Location : AT THE BACK, SAME LOCATION

Pipe Length : 10FT

Special Note :

Installation Cost Estimate

Material Description	Qty.	Unit Cost	Total Cost
Copper Tube (excess of 10 ft.) 2330, 2430, 2520, 3520, 4620			
Wire (Royal Cord-signal wire) (excess of 10ft.) 2.0mmx4C	SET	100	100
Wire (Royal Cord - Breaker to ODU) 3.5mm / 5.5mm x 3C	SET	70	350
Circuit Breaker 20A, 30A (20A/1ph), 40A/3ph	1	1000	1000
Bracket (ODU) (Imtd. / Fabricated) (Floor / Wall)	1	2500	2500
Bracket (WAC) Angle Type			
PVC Pipe (drain) 1/2" (3/4"			
PVC Pipe (electrical) 3/4", 1"			
Drain Pump			
Drain, Hose	SET	15	175
Chipping Works	mtr.		
Dismantling Fee (existing air-conditioner)	SET		300
Initial Charge			14,000
TOTAL ESTIMATE	P		22225

Note :

1. Initial Charge includes labor, 10ft. Copper tube, 10ft. Royal cord, Outdoor Bracket (SAC), Indoor Bracket (PAC) and Consumable materials.
2. Survey fee will be deducted in the installation fee.

Prepared by:

MECHENI D. D. 103
Signature Over Printed Name

Customer Confer:

John Doe
Signature Over Printed Name