

MR. TIMOTHY GO UNIT 3523, CONNOR BY ORTIGAS CONDOMINIUM, ANNAPOLIS ST. SAN JUAN TEL#: 0917-8988889

Dear Ma'am/Sir,

Kolin Marketing Inc., is extremely honored for your endorsement of Kolin brand and we are please to offer you with a special price/s for the following items.

A. EQUIPMENT & INSTALLATION

** RECOMMENDATION

		RECOMPLENDATION				
QTY	U/M	MODEL / DESCRIPTION	SRP	DISCOUNTED		AMOUNT
1	UNIT/S	MODEL: KSM-IW20-WCT10M1M32 KOLIN WALL MOUNTED CERTUS SERIES AIRCONDITIONER 18,990 Kj/h (2.0HP) REGULAR INVERTER R-32	41,995.00	27,916.20 1	PHP	27,916.20
TOTAL	UNIT COST				PHP	27,916.20
ESTIMATED COST OF INSTALLATION (please see attached)					PHP	12,095.00
TOTAL ESTIMATED COST OF THE PROJECT				PHP	40,011.20	

** CUSTOMER'S CHOICE

QTY	U/M	MODEL / DESCRIPTION	SRP	DISCOUNTED		AMOUNT
1	UNIT/S	MODEL: KSM-IW15-WCT10M1M32 KOLIN WALL MOUNTED CERTUS SERIES AIRCONDITIONER 12,660 Kj/h (1.5HP) REGULAR INVERTER R-32	32,995.00	21,076.20	PHP	21,076.20
TOTAL	UNIT COST				PHP	21,076.20
ESTIMATED COST OF INSTALLATION (please see attached)					PHP	12,095.00
TOTAL ESTIMATED COST OF THE PROJECT				PHP	33,171.20	

TERMS OF PAYMENT:

FULL PAYMENT OF UNIT AND DELIVERY CHARGE. IF CHECK, SUBJECT FOR 3 DAYS CLEARING.

WARRANTY:

FOR SPLIT TYPE : ONE (1) YEAR FREE PARTS AND LABOR, THREE YEARS (3) MAIN PCB , TEN (10) YEARS WARRANTY ON COMPRESSOR.

NOTES: *** Need to sign waiver agreement due to under capacity of unit choice.

PRICES ARE SUBJECT TO CHANGE WITHOUT PRIOR NOTICE.

PRICES IS VAT INCLUSIVE.

** Cost of Installation is Package with the Unit(s), this cost cannot avail separately (cost will be based on actual).

We thank you for giving opportunity to offer our product and services, hoping we receive your purchase order.

If you need assistance, don't hesitate to call the under signed at 0917-807-8607 or email at kmi_asst@kolinphil.com.ph

Very Truly Yours,

JANELLEN S. LIM KMI-ASSISTANT

Noted by:

KMI-SUPERVISOR

KMI-QUOTE-02-25-0151-rev

REG-24%/4K

MS. EDITHA M. FLORES AVP - FINANCE

Conforme:

SIGNATURE OVER PRINTED NAME

Kolin Marketing, Inc. 1854 Sta. Rita St., Guadalupe Nuevo, Makati City

Tel.: (632) 8852-6473

Fax: (632) 8852-2170 / (632) 8852-4792 www.kolinphil.com.ph / kolinphilippines





KOLIN Philippines International Inc. Survey Form

Nº 003607

Sustomer Name . 1744101114	60		Date :	3-12-	124	
	COPPORT BY ORUMS	(ohto)	SJR No	: 1977	9	
スタルスクラム C Establishment Type: Residentia	37. SSP JNXH .	Area Surveye	TIUU .	3523		
Commerci		Area Surveye				
	Limited in the second		-	vett Inii	00	
Recommended Product Model :	KSM-1M30-MCHON	1M32 /	asto Mels C	ANICE	W. 3. L	
Cooling Capacity Computation						
Floor Area : sqm			•			
Ceiling Height:mtr.	note: add 20% per n			9		
Floor Area :		×	550 Btu/h	12/00	Btu/h	
Ceiling Height (excess of 3 mtrs.):		x	20%		Btu/h	
Vindow Direct Sunlight		x	20% - 50%		Btu/h	
otal Cooling Capacity				12/00	Btu/h	
Add : Additional Heat Load						
lo. of Person	2	χ .	300 Btu/h	600	Btu/h	
lo. of Ordinary Light (<40w)	2	х	200 Btu/h	400	Btu/h	
lo. of Special Light (>40w)		x	400 Btu/h		Btu/h	
lo. of Refrigerator (< 6 cu.ft.)		×	400 Btu/h	400	Btu/h	
o. of Refrigerator (> 6 cu.ft.)		x	800 Btu/h		Btu/h	
o. of Cooking Range	1	×	1500 Btu/h	1500	Btu/h	
lo. of Laptop Computer		×	150 Btu/h		Btu/h	
lo. of Desktop Computer /		x	400 Btu/h	400	Btu/h	
lo. of Printer		x	500 Btu/h		Btu/h	
lo. of Photocopier		X	1000 Btu/h		Btu/h	
otal Cooling Capacity				3300.	Btu/h	
Recommended Cooling Capacity			17	-400	Btu/h	
			-		1757	
Note: Compressor warranty will be recommended cooling capac	reduced to yr. if air-con ity or pipe lay-out is beyond th			the		
	Scope of Work Ag	areement				
Comments			_			
Copper tube lay-out	Expose Included	Embedde				
Chipping Eabricated Bracket	harmoniand	Not Include				
3. Fabricated Bracket Yes Shop Site No 4. Service Ledge Yes No						
Dismantling of existing Aircon	Yes Included	No Not Include	ted *			
5. Ducting	Yes	No	JCG			
Dimension:						
Plastering, carpentry and restorat	ion works are to be done by th	e customer				
			ne by the custom	er		
 Wiring of electrical supply from m Processing of mechanical plan, w 						
	SX) CTEU A LITTORY					
o other concern,	PANGULVE IN THE	Es VI	-			
April 10 miles	WITH PERMIT PA		17 405 -10	WATTON		

	1		
	->>1		
	- []		
	3	45-	
		7.9	
	-15-		
2.6			
 '			
	-4-8		

Indoor Unit Location : UN OF WHOOV, WE'V COAF OF WHOOV

Pipe Length : ITT

Special Note :

In	stallation Cost Estimate			
Material Description			Unit Cost	Total Cost
Copper Tube (excess of 10 ft.)	2330, 2430, 2520, 3520, 4620	++1	350	29,50
Wire (Royal Cord-signal wire) (excess of 10ft.)	2.0mmx4C	14F1-	100	15400
Wire (Royal Cord - Breaker to ODU)	于厂	60	470	
Circuit Breaker	20A, 30A, 40A/1ph, 40A/3ph			
Bracket (ODU)	(Imptd. / Fabricated); (Floor) Wall)			
Bracket (WAC)	Angle Type	To the state of		
PVC Pipe (drain)	1/2" (3/4")	1		179
PVC Pipe (electrical)	3/4" , 1"			
Drain Pump				
Drain Pump Hose WHT /2		75	137-	17-5
Chipping Works	mtr.			
Dismantling Fee (existing air-conditioner)				
Initial Charge				7300
TOTAL ESTIMATE				75 -

Note

- Initial Charge includes labor, 10ft. Copper tube, 10ft. Royal cord, Circuit breaker, Outdoor Bracket (SAC), Indoor Bracket (PAC) and Consumable materials.
- 2. Survey fee will be deducted in the installation fee.

Prepared	by:
	110

Customer Conforme:

Signature Over Printed Name

Signature Over Printed Name