

May 9, 2025

MS. CLARISSA ORACION

NO. 41 GALATIAN ST. ORO VISTA SUBD., BRGY. CONCEPCION UNO, MARIKINA CITY

TEL#: 0933-3503662

Dear Ma'am/Sir,

Kolin Marketing Inc., is extremely honored for your endorsement of Kolin brand and we are please to offer you with a special price/s for the following items.

A. EQUIPMENT & INSTALLATION

QTY	U/M	MODEL / DESCRIPTION	SRP	DISCOUNTED PRICE		AMOUNT
1	UNIT/S	MODEL: KSM-IW15-WCT10M1M32 KOLIN WALL MOUNTED CERTUS SERIES AIRCONDITIONER 12,660 Kj/h (1.5HP) REGULAR INVERTER R-32	32,995.00	21,076.20	РНР	21,076.20
TOTAL UNIT COST					PHP	21,076.20
ESTIMATED COST OF INSTALLATION (please see attached)					PHP	9,945.00
OTHERS: DELIVERY CHARGE					PHP	600.00
TOTAL ESTIMATED COST OF THE PROJECT					PHP	31,621.20

TERMS OF PAYMENT:

FULL PAYMENT OF UNIT AND DELIVERY CHARGE. IF CHECK, SUBJECT FOR 3 DAYS CLEARING.

WARRANTY:

FOR SPLIT TYPE: ONE (1) YEAR FREE PARTS AND LABOR, THREE YEARS (3) MAIN PCB, TEN (10) YEARS WARRANTY ON COMPRESSOR.

NOTES: PRICES ARE SUBJECT TO CHANGE WITHOUT PRIOR NOTICE.

PRICES IS VAT INCLUSIVE.

** Cost of Installation is Package with the Unit(s), this cost cannot avail separately (cost will be based on actual works).

We thank you for giving opportunity to offer our product and services, hoping we receive your purchase order.

If you need assistance, don't hesitate to call the under signed at 0917-807-8607 or email at kmi_asst@kolinphil.com.ph

Very Truly Yours,

JANELLEN S. LIM

Noted by:

MART NATHAMIEL R. PLORES

KMI-QUOTE-05-25-0361-rev REG-24%/4K Approved By:

MS. EDITHA M. FLORES

AVP - FINANCE

Conforme:

SIGNATURE OVER PRINTED NAME

Kolin Marketing, Inc.

1854 Sta. Rita St., Guadalupe Nuevo, Makati City Tel.: (632) 8852-6473

Fax: (632) 8852-2170 / (632) 8852-4792 www.kolinphil.com.ph / kolinphilippines

KOLIN Philippines International Inc. Survey Form

Nº 003629

	172×C10H		Date	territoria de la constitución de	- N3"					
Address: No 4 GXLX-1X	KISTING!	11518 SMBD.	SJR	No.: 16 H	500					
TSAGY, CONCERC Establishment Type: Residential	7 - OT - W	Area Surveye	ed: 1.1	11NU XNDS						
Commercial	Ħ	Area Surveye			Hay to					
Recommended Product Model :	SM IWK-	MELLOWIMS								
Cooling Capacity Computation										
	3	,			The second second second					
Floor Area: sqm. Ceiling Height: mtr.		% per meter in excess oling capacity compu		the						
Floor Area:	it	x	550 Btu/h	dile	Btu/h					
Ceiling Height (excess of 3 mtrs.):		x	20%		Btu/h					
Window Direct Sunlight		x	20%-50%	1870	Btu/h					
Total Cooling Capacity				11,200	Btu/h					
Add : Additional Heat Load										
No. of Person	C-	×	300 Btu/h	1/000	Btu/h					
No. of Ordinary Light (<40w)	2	x	200 Btu/h	1000	Btu/h					
No. of Special Light (>40w)		x	400 Btu/h		Btu/h					
No. of Refrigerator (< 6 cu.ft.)		x	400 Btu/h		Btu/h					
No. of Refrigerator (> 6 cu.ft.)		×	800 Btu/h		Btu/h					
No. of Cooking Range	-	x	1500 Btu/h	-	Btu/h					
No. of Laptop Computer		^	150 Btu/h	 	Btu/h					
No. of Desktop Computer		^	400 Btu/h	400	Btu/h					
No. of Printer		^	500 Btu/h	700	Btu/h					
No. of Photocopier			1000 Btu/h							
		x	1000 Blu/II		Btu/h					
Total Cooling Capacity				TERR	Btu/h					
Recommended Cooling Capacity				1:4	Btu/h					
Note: Compressor warranty will be redu	ced to yr. if	air-conditioner purcha	ased is lower th							
recommended cooling capacity or	pipe lay-out is bey	ond the maximum all	owable length.							
	Scope of Wo	ork Agreement								
1. Copper tube lay-out	Expose	Embedde	ed							
2. Chipping	Included	Not Include	ded							
3. Fabricated Bracket		Shop Site	No							
1. Service Ledge	Yes	No								
5. Dismantling of existing Aircon	Included	Not Include	ded *							
5. Ducting	Yes	No								
Dimension :										
Plastering, carpentry and restoration w	orks are to be don	e by the customer								
Wiring of electrical supply from main p			ne by the custo	omer.						
Processing of mechanical plan, workin										
The state of the s	CIL WILL	DROXIDE AC	5012/01	6/4						
CAMPEL	D KYTCH	T SALP ST	AMS.							
THUE CO	或别见了少少	JAMO MATE	小年下	THE						
- K-2M2_			1	. 1						
01873Mar-2	HARRY A	WWVW I	MPG I GM	MIN - KO						

	-11											
									+			
<u>-</u>	+						<u>†</u> -		1 , 1		T	1
									1/_1			
				1	V	91	ACI	10/2010	1/20	>12H	EVA	
									/			
		25										
	1											
		<i> </i>	ļ				}-					ļ
			LNIA									-
			- AND	ft			<u>+</u> -		1			†
		5	1									1
		3	+du			1						
			1									
	1		The state of the s									1
			 		[] []		ļ					
		Xc	a\n\		sek ti							
	+	 	 	+		·						1
												1
												1

Indoor Unit Location : WP OF WINDOW, CEPTER

Outdoor Unit Location : POPER TO THE TOTAL WASHINGTON AT PARKING ACTOR

Pipe Length : 10 11

Special Note :

ln	stallation Cost Estimate			
Material Descrip	Qty.	Unit Cost	Total Cost	
Copper Tube (excess of 10 ft.)	2330, 2430, 2520, 3520, 4620			
Wire (Royal Cord-signal wire) (excess of 10ft.)	2.0mmx4C	7 ft	100	700
Wire (Royal Cord - Breaker to ODU)	(3.5mm) 5.5mm x 3C	7 ft	60	420
Circuit Breaker	20A, 30A, 40A/1ph, 40A/3ph	11	1000	1000
Bracket (ODU)	(Imptd. / Fabricated); (Floor / Wall)			11
Bracket (WAC)	Angle Type			
PVC Pipe (drain)	1/2" ,[3/4"]	1 pc	150	150
PVC Pipe (electrical)	3/4" , 1"			
Drain Pump				
Drain-Pump Hose WATE		77	TV	1175
Chipping Works	mtr.			
Dismantling Fee (existing air-conditioner)				
Initial Charge		, a		-5700 ·
	TOTAL ESTI	MATE	P 9,945	

Note

- Initial Charge includes labor, 10ft. Copper tube, 10ft. Royal cord, Circuit breaker, Outdoor Bracket (SAC), Indoor Bracket (PAC) and Consumable materials.
- 2. Survey fee will be deducted in the installation fee.

Prepared by:

Signature Over Printed Name

Customer Conforme:

Signature Over Printed Name