

ATTY. BOBBY SAN JOSE

UNIT 24D EASTON PLACE CONDO, 118 VALERO ST., SALCEDO VILLAG BRGY. BEL AIR, MAKATI CITY

Email: roberto.sanjose@cltpsj.com.ph

TEL#: 0923-9673736

Dear Ma'am/Sir,

Kolin Marketing Inc., is extremely honored for your endorsement of Kolin brand and we are please to offer you with a special price/s for the following items.

#### A. EQUIPMENT & INSTALLATION

QTY	U/M	MODEL / DESCRIPTION	SRP	DISCOUNTED		AMOUNT
1	UNIT/S	MODEL: KLG-IF40-5G1M32 KOLIN FLOOR MOUNTED AIRCONDITIONER 37,980 Kj/h (3.0TR) FULL DC INVERTER R-32 SINGLE PHASE	113,195.00	76,764.30	PHP	76,764.30
2	UNIT/S	MODEL: KSM-IW15-WCT10M1M32 KOLIN WALL MOUNTED CERTUS SERIES AIRCONDITIONER 12,660 Kj/h (1.5HP) REGULAR INVERTER W/ WIFI R-32	32,995.00	20,416.30	РНР	40,832.60
TOTAL UNIT COST					PHP	117,596.90
ESTIMATED COST OF INSTALLATION (please see attached)					PHP	60,210.00
OTHERS: DELIVERY CHARGE					PHP	600.00
TOTAL	ESTIMATED	COST OF THE PROJECT			PHP	178,406.90

### \* OPTION 2 \*

QTY	U/M	MODEL / DESCRIPTION	SRP	DISCOUNTED		AMOUNT
1	UNIT/S	MODEL: KLG-IF40-5G1M32 KOLIN FLOOR MOUNTED AIRCONDITIONER 37,980 Kj/h (3.0TR) FULL DC INVERTER R-32 SINGLE PHASE	113,195.00	76,764.30	РНР	76,764.30
2	UNIT/S	MODEL: KSG-IWF-15WFY-8K1M32 KOLIN WALL MOUNTED PRIMUS GOLD AIRCONDITIONER 12,960 Kj/h (1.5HP) FULL DC INVERTER W/ WIFI R-32	46,595.00	27,480.30	РНР	54,960.60
TOTAL UNIT COST					PHP	131,724.90
ESTIMATED COST OF INSTALLATION (please see attached)					PHP	60,210.00
OTHERS	: DELIVERY	CHARGE			PHP	600.00
TOTAL	ESTIMATED	COST OF THE PROJECT			PHP	192,534.90

## TERMS OF PAYMENT:

FULL PAYMENT OF UNIT AND DELIVERY CHARGE. IF CHECK, SUBJECT FOR 3 DAYS CLEARING.

## WARRANTY:

FOR SPLIT TYPE: ONE (1) YEAR FREE PARTS AND LABOR, THREE YEARS (3) MAIN PCB , TEN (10) YEARS WARRANTY ON COMPRESSOR.

# NOTES: PRICES ARE SUBJECT TO CHANGE WITHOUT PRIOR NOTICE.

PRICES IS VAT INCLUSIVE.

\*\* Cost of Installation is Package with the Unit(s), this cost cannot avail separately (cost will be based on actual works).

\*\*\* You may settle first payment for unit/s & delivery. Installation payment can be settled directly to installer after actual works.

We thank you for giving opportunity to offer our product and services, hoping we receive your purchase order.

If you need assistance, don't hesitate to call the under signed at 0917-807-8607 or email at kmi\_asst@kolinphil.com.ph

Very Truly Yours.

JANELLEN S. L KML-ASSISTANT

MART NAT KMI-SUPERVISOR

KMI-QUOTE-09-25-0656-rev DCG-26%/4K/7K

MS. EDITHA M. FLORES

- FINANCE AVI

Conforme:

SIGNATURE OVER PRINTED NAME

Kolin Marketing, Inc. 1854 Sta. Rita St., Guadalupe Nuevo, Makati City

Tel.: (632) 8852-6473

Fax: (632) 8852-2170 / (632) 8852-4792 www.kolinphil.com.ph / kolinphilippines





September 4, 2025
ATTY BOBBY SAN JOSE
Unit 24D Easton Place Condo, 118 Valero St. Salcedo Village, Brgy Bel Air Makati
0923-9673736
aida.delapaz@cltpsj.com.ph / markrealica@yahoo.com/ roberto.sanjose@cltpsj.com.ph

MODEL Qty
KLG-IF40-5G1M32 1
KSG-IWF-15WFY8K1M32 2

#### UNIT 24D

UKO	OM A			No.		Area	15	sqm
U 1	1.5 HP Wall Mounted Inverter		KSG-IW	/F-1	5WFY8K1M32	Arca	13	34III
	Estimated Pipe Length =	17 ft			JULY TONZINGE			
	Estimated Royal Cord Length =	22 ft						
	Initial Charge						<b>a</b>	7,500.00
	Includes:							7,500.00
	Labor							
	10ft Copper Tube							
	10ft Royal Cord							
	Outdoor Bracket (Floor) Consumables							
	Installation Materials	Description	Qtv	Pri	ice per qty	Subtotal		
	Copper Tube	Ø 1/4" x Ø 3/8"	7 ft		350.00/ft	₱ 2,450.00		
	Royal Cord (comm. wire)	2.mm2 x 4C	12 ft	₽	100.00/ft	<b>₱</b> 1,200.00		
	Royal Cord (ACCU-Breaker)	3.5mm x 3c	5 ft	₽	60.00/ft	₱ 300.00		
	Circuit Breaker waterproof	20A / 1Ph	1 pc/s	₽	1,000.00/pc	₱ 1,000.00		
	Dismantle	1.5HP Wall Mounted	1 set	₽	2,500.00/set	₱ 2,500.00		
	PVC blue	3/4" x 10'	2 pc/s	₽	150.00/pc	₱ 300.00	₽	7,750.00
	Estimated Charges						₽	15,250.0
	zoumated enaiges			200100				
/ING	DINING					Area	MARIO MARIO	
VING			KLG-IF4	0-50	G1M32	Area	MARIO MARIO	sqm
	DINING	13 ft	KLG-IF4	0-50	G1M32	Area	MARIO MARIO	
	DINING 4.0 HP Floor Standing Inverter	13 ft 18 ft	KLG-IF4	0-50	G1M32	Area	MARIO MARIO	
	DINING  4.0 HP Floor Standing Inverter Estimated Pipe Length =		KLG-IF4	10-50	G1M32	Area	34	sqm
	DINING  4.0 HP Floor Standing Inverter Estimated Pipe Length = Estimated Royal Cord Length =		KLG-IF4	10-50	G1M32	Area	34	sqm
	DINING  4.0 HP Floor Standing Inverter Estimated Pipe Length = Estimated Royal Cord Length = Initial Charge		KLG-IF4	0-50	G1M32	Area	34	sqm
	DINING  4.0 HP Floor Standing Inverter Estimated Pipe Length = Estimated Royal Cord Length = Initial Charge Includes:		KLG-IF4	0-50	G1M32	Area	34	sqm
	DINING  4.0 HP Floor Standing Inverter Estimated Pipe Length = Estimated Royal Cord Length = Initial Charge Includes: Labor		KLG-IF4	10-50	G1M32	Area	34	sqm
	DINING  4.0 HP Floor Standing Inverter Estimated Pipe Length = Estimated Royal Cord Length = Initial Charge Includes: Labor 10ft Copper Tube		KLG-IF4	10-50	G1M32	Area	34	
	DINING  4.0 HP Floor Standing Inverter Estimated Pipe Length = Estimated Royal Cord Length = Initial Charge Includes: Labor 10ft Copper Tube 10ft Royal Cord		KLG-IF4	0-50	G1M32	Area	34	sqm
	DINING  4.0 HP Floor Standing Inverter Estimated Pipe Length = Estimated Royal Cord Length = Initial Charge Includes: Labor 10ft Copper Tube 10ft Royal Cord Indoor Bracket (Floor)				G1M32	Area	34	sqm
	DINING  4.0 HP Floor Standing Inverter Estimated Pipe Length = Estimated Royal Cord Length = Initial Charge Includes: Labor 10ft Copper Tube 10ft Royal Cord Indoor Bracket (Floor) Consumables	18 ft		Pri			34	sqm
	DINING  4.0 HP Floor Standing Inverter Estimated Pipe Length = Estimated Royal Cord Length = Initial Charge Includes: Labor 10ft Copper Tube 10ft Royal Cord Indoor Bracket (Floor) Consumables Installation Materials	18 ft  Description	Qty	Pri ₱	ice per qty	Subtotal	34	sqm
	DINING  4.0 HP Floor Standing Inverter Estimated Pipe Length = Estimated Royal Cord Length = Initial Charge Includes: Labor 10ft Copper Tube 10ft Royal Cord Indoor Bracket (Floor) Consumables Installation Materials Copper Tube	Description Ø 3/8" x Ø 5/8"	Qty 3 ft	Pri p	ice per qty 400.00/ft	Subtotal ₱ 1,200.00	34	sqm
	DINING  4.0 HP Floor Standing Inverter Estimated Pipe Length = Estimated Royal Cord Length = Initial Charge Includes: Labor 10ft Copper Tube 10ft Royal Cord Indoor Bracket (Floor) Consumables Installation Materials Copper Tube Royal Cord (comm. wire)	Description Ø 3/8" x Ø 5/8" 2.mm2 x 4C	Qty 3 ft 8 ft	Pri P	ice per qty 400.00/ft 100.00/ft	Subtotal  ₱ 1,200.00  ₱ 800.00	34	sqm
	DINING  4.0 HP Floor Standing Inverter Estimated Pipe Length = Estimated Royal Cord Length = Initial Charge Includes: Labor 10ft Copper Tube 10ft Royal Cord Indoor Bracket (Floor) Consumables Installation Materials Copper Tube Royal Cord (comm. wire) Royal Cord (ACCU-Breaker)	Description Ø 3/8" x Ø 5/8" 2.mm2 x 4C 5.5mm x 3c	<b>Qty</b> 3 ft 8 ft 5 ft	Pri p p p	ice per qty 400.00/ft 100.00/ft 70.00/ft	Subtotal  ₱ 1,200.00  ₱ 800.00  ₱ 350.00  ₱ 1,000.00	34	sqm
	DINING  4.0 HP Floor Standing Inverter Estimated Pipe Length = Estimated Royal Cord Length = Initial Charge Includes: Labor 10ft Copper Tube 10ft Royal Cord Indoor Bracket (Floor) Consumables Installation Materials Copper Tube Royal Cord (comm. wire) Royal Cord (ACCU-Breaker) Circuit Breaker waterproof	Description Ø 3/8" x Ø 5/8" 2.mm2 x 4C 5.5mm x 3c 40A/1Ph	Qty 3 ft 8 ft 5 ft 1 pc/s	Pri P P P	ice per qty 400.00/ft 100.00/ft 70.00/ft 1,000.00/pc	Subtotal  ⇒ 1,200.00  ⇒ 800.00  ⇒ 350.00	34	sqm

BEDROOM B Area 14.4 sqm ACU 3 1.5 HP Wall Mounted Inverter KSG-IWF-15WFY8K1M32 Estimated Pipe Length 37 ft = Estimated Royal Cord Length = 42 ft **Initial Charge** ₱ 7,500.00 Includes: Labor 10ft Copper Tube 10ft Royal Cord Outdoor Bracket (Floor) Consumables **Installation Materials** Description Subtotal Qty Price per qty Copper Tube Ø 1/4" x Ø 3/8" 27 ft ₱ 350.00/ft ₱ 9,450.00 Royal Cord (comm. wire) 2.mm2 x 4C 32 ft ₱ 100.00/ft ₱ 3,200.00 Royal Cord (ACCU-Breaker) 3.5mm x 3c 5 ft ₱ 60.00/ft ₱ 300.00 Circuit Breaker waterproof 20A / 1Ph 1 pc/s ₱ 1,000.00/pc ₱ 1,000.00 **Rubber Insulation** 2 1/8" x 3/4" x 6' 5 pc/s ₱ 350.00/pc ₱ 1,750.00 Full thread 3/8" x 10' 1 pc/s ₱ 150.00/pc ₱ 150.00 3" Metal Clamp 8 pc/s ₱ 120.00/pc ₱ 960.00 Dismantle 1.5HP Wall Mounted 1 set ₱ 2,500.00/set ₱ 2,500.00 ₱ 19,310.00 **Estimated Charges** ₱ 26,810.00 3400-3000-3800-BEDROOM A 15 sqm 4000 FCU2 4.0HP FCU1 1.5HP FLOORMOUNTED

LIVING, DINING

UNIT 24D

34 sqm

FCU3 1.5HP WALLMOUNTED

**BEDROOM B** 14.4 sqm

38,00

WALLMOUNTED

Total Estimated Charges 9 60,210.00

Validity: This quotation is valid for a period of fifteen (15) days from the date thereof, subject to our confirmation thereafter.

## Installation notes:

- 1 Location of indoor and outdoor units were agreed by the customer and Kolin's surveyor.
- 2 AC drain line will be tapped to the nearest drain provision provided by the customer's contractor.
- 3 Need for marking and site visit before installation. Perform drain test. Dismantle first and markings.
- 4 Need to open wall for the lay out of coppertube ACU1 and ACU2.
- 5 Working days: Monday to Saturday, 8am-5pm with parking. Need working permit.
- 6 Mechanical Plans, Permits, Electrical permits not included.
- 7 Deflectors, masonry, carpentry, chipping & plastering (finishing & restoration) are not included in the installation.
- 8 Air conditioning drain line and Electrical power supply (feeder
- 9 Final charges will be based on actual installation.

Prepared by:

Jeoffrey Dadios Field Surveyor Customer Conformee:

Signature Over Printed Name

Reviewed by:

Service Supervisor Shop and

Field Operation