

kolin

Kolin Philippines International Inc.
LRK Bldg. Jose A. Santos Ave. Brgy. Lagundi, Mexico, Pampanga
Tel. No. 045-455- Mobile: 0917-5317409/email: info.pampanga@kolinphil.com
Website: www.kolinphil.com.ph

PAM SERVICE JOB REPORT #129

Customer		Delos Santos, Christine		No.		PAM-00001929	
Address		Aspire Prime Residences, Brgy. Dela Paz Norte, CITY OF SAN FERNANDO, Pampanga		Previous SJR No.			
Tel. No.				Date		02-04-2021	
Mobile No.		0915-8579183		Start Time		01:35 pm	
Contact Person		Christine		End Time		01:36 pm	
Mobile No.		0915-8579183		Relayed by		D	
Model		KSM-IW15-GH1V		Warranty Type		C	
S/N (I)		18202002-19510182		Job Class		INST	
S/N (O)		2002-12893		Job Type		60	
Dealer		STAR APPLIANCE		Permit? <input type="checkbox"/>		Parking? <input type="checkbox"/>	
Installer		DOP		Appointment? <input type="checkbox"/>		O.R.? <input type="checkbox"/>	
Complaint		For installation		Ladder? <input type="checkbox"/>			
Before		After		Notes:			
Mode Setting (Cool)				No. of Visit		Tentative Sched	
WAC Setting Temp (16°C-RE) / (10-ME)				Findings			
SAC/PAC Setting Temp (17°)				Recommendation			
Discharge Temperature (High)							
Intake Temperature (High)							
Ampere							
WAC Wattage (Inverter)							
Voltage							
SAC/PAC Pressure							
Part Code	Description	Qty	Unit Price	Amount			
	Stickless Tape	1		—			
	Circuit Breaker 20A	1		—			
	Insulated copper tube 1/4 x 1/2	10ft		—			
	Total Cond 4c	10ft		—			
	Bracket nail (S)	1		—			
	0.5x1.5 Drain hose	0		—			
	Piping Clamp (S)	3		—			
	Piping Clamp (A)	3		—			
FEB 05 2021							
SR No.	594	Labor	7.000				
Repair Done	INSTALLATION	Handling					
Repair Code	OKC	Others					
Date Attended	2-5-21	Total	7.000				
Date Finished	2-5-21	Amount Paid	7.000				
Time Attended		Balance					
Time Finished							
This serves as temporary receipt when properly filled up by authorized representative.		Check No.			Bank / Branch		
Serviced by:		By signing below, I allow KPII to collect, store & process my personal information as necessary to avail of service & fully understood that my personal information shall be used in accordance w/ Philippine Data Privacy Act & its implementing rules & regulations.					
RV JOMER		I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.					

kolin

Kolin Philippines International Inc.
 LRK Bldg. Jose A. Santos Ave. Brgy. Lagundi, Mexico, Pampanga
 Tel. No. 045-455-1111 Mobile: 0917-5317409/email: info.pampanga@kolinphil.com
 Website: www.kolinphil.com.ph

PAM SERVICE JOB REPORT #1840

Customer		Date		No.		Previous SJR No.	
Address		Start Time		End Time		Relayed by	
Tel. No.		Warranty Type		Job Class		Job Type	
Mobile No.		Permit? <input type="checkbox"/> Parking? <input type="checkbox"/> Appointment? <input type="checkbox"/> O.R.? <input type="checkbox"/> Ladder? <input type="checkbox"/>		Notes:			
Contact Person	Mobile No.	Tel. No.	Call Origin				
Model	S/N (I)		S/N (O)				
Dealer	DOP						
Installer	Complaint						
Before	After	No. of Visit	Tentative Sched				
Mode Setting (Cool)		Findings					
WAC Setting Temp (16°C-RE)/(10-ME)							
SAC/PAC Setting Temp (17°)							
Discharge Temperature (High)							
Intake Temperature (High)		Recommendation					
Ampere							
WAC Wattage (Inverter)							
Voltage							
SAC/PAC Pressure							
Part Code	Description	Qty	Unit Price	Amount			
	stockless Tape	1					
	Circuit Breaker	1					
	Copper tube 1/4 x 3/8	10ft					
	Royal Cord 200m2 x 4C	10ft					
	Bracket nail (2)	1					
	OR #6119						
	Piping Clamp	3					
	Piping Clamp	3					
JAN 15 2021							
SR No.	567	Labor		7.00			
Repair Done	in STRUCTION	Handling					
Repair Code	SAC	Others					
Date Attended	01-15-21	Date Finished	01-15-21	Amount Paid		7.00	
Time Attended	11:30	Time Finished	12:30	Balance			
This serves as temporary receipt when properly filled up by authorized representative.		Check No.	Bank / Branch				
Serviced by:		By signing below, I allow KPII to collect, store & process my personal information as necessary to avail of service & fully understood that my personal information shall be used in accordance w/ Philippine Data Privacy Act & its implementing rules & regulations.					
		I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.					