

M.E.R.C. AIRCON SERVICES

Lot 3 Blk 7 Tiongquiao St., cor. Gatchalian Subd., Manuyo 2, Las Piñas City 9. 26- 21
 Tel. Nos.: 8829-9034 / 7358-3451 9. 27- 21
 Cell. #: 0917-6257554 / 0908-8107749 / 0905-5185298 / 0961-2505930

200

SERVICE JOB REPORT

DATE: 9-27-21 No. 0058409

NAME: ACE SULANGSANGA
 Address: B01 & 142 CEDAR 2
 CARMONA ESTATES
 Contact No.: 0917

Model: KMC-1N70 - GATTIN

Serial No.:

Warranty Charge

Date of Purchase: 09664350190

Complaint: FOR INSTALLATION

Observation:

Service Performed:

COMPLETE INSTALLATION

MATERIALS	<input type="checkbox"/> NEEDED	<input type="checkbox"/> USED	AMOUNT
QTY.	DESCRIPTION	AMOUNT	
STANDARDS INSTALLATION			
1/4" COPPER PIPE			
1/4" ROYAL GRO			
3m. DRILL HOLE			8,500
1/4" WALL BRACKET			
ADDITIONAL			
1/4" COPPER PIPE (600MM) (1)			2,800
ROYAL GRO (600MM)			
18.27.2011 - 17.8.67			
(18.28.2011 - 19.8.67)			
			11,300
9. 25. 21			
Amish			
FO0050934			
SERVICED BY: JEFF	Materials		
GEN	Labor		
REMAR	TOTAL		

AMOUNT PAID:

CHECK NO.:

PAYMENT RECEIVED BY:

DATE:

DATE CALL RECEIVED:

TIME ARRIVED:

TIME FINISHED:

ACTUAL TIME:

TOTAL TIME:

This serves as temporary receipt when properly filled-up and signed by authorized M.E.R.C. representative.

IMPORTANT - PLEASE READ

(1) I hereby agree to the above charges incurred / to be incurred in repairs of my unit.

(2) This is to acknowledge above service rendered to my unit.

PRINT NAME AND SIGNATURE / DATE

• VOLTAGE FREQUENCY	200-220 V	50-60 HZ
• OPERATING CURRENT	230 V / 60Hz	
• STARTING CURRENT		
F. TEMPERATURE		
• ROOM/AMBIENT	≥ 10 °C	
• INTAKE/DISCHARGE		
• TEMPERATURE DIFFERENCE		
G. UNIT OPERATION/FUNCTIONS		

90 ANRS

7.5A

REMARKS/RECOMMENDATIONS:

CLEANING OF AIR FILTER TWICE A MONTH.
 GENERAL CLEANING OF UNIT EVERY 6 MONTHS

INSTALLED AND INSPECTED BY:

CUSTOMER:

505 J. Sison 8002