

Kolin Philippines International Inc.
1854 Sta. Rita St. - Guadalupe Nuevo
Makati City
Tel. No. 852-6868

kolin

SERVICE JOB REPORT

To: **0583098**
Backjob SJR No.

Customer		THE GARDENS AT THE GROVE BY ROCKWELL		Date	09/09/2019
Address		E RODRIGUEZ JR AVE CS BRGY UNDAUN BASIG		Time	04:07 pm
		09562559169/09178105110/531953		Relayed by	RUF0 C
Tel. No.	941-5835	Date of Purchase		Dealer	
Model	KFM-400F1J	Serial No.	NEED PERMIT	Warranty Type	C
Complaint	AC28 - For Gen. Cleaning		Job Class		
Remarks	M2/4 CONT./4 GCO UNIT ONLY/09-12/RUF0		Job Type		
SJR No.	Materials		☐ Used	☐ Needed	
Part No.	Description		Qty.	Unit Price	Amount
Findings				Labor	
Repair Done				Handling	
Repair Code				Total	
Date Attended	9-12-19	Date Finished			
Time Attended	9:10	Time Finished			
This serves as temporary receipt when properly filled up by authorized representative					
Serviced by: Pete. Gast. Evaluated by: Tracy. Tungay		Customer			
Technician		(Signature over printed name)			
C-SJR-00-030104		White-Customer		Blue-Accounting	Green-Service
		Yellow-Guard / Claim Stub			

per collected for need soft

P1,000.00